Smith & Wesson M&P; & Shield Series

Smith & Wesson • M&P9; M2.0, Shield, Shield Plus, Equalizer (9x19mm, .40 S&W;, .45 ACP)

Manufacturer:	Smith & Wesson	**Category:**	Pistols
Action Type:	Striker-Fired Duty & Concealed Carry	**Era / Service:**	Modern Duty & Concealed Carry (2005–Present)
Calibers:	9x19mm Parabellum, .40 S&W;, .45 ACP, 10mm Auto	**Covered Models:**	M&P9; M2.0 Full Size, M&P9; M2.0 Compact, M&P; Shield 9, M&P; Shield Plus, M&P45; M2.0, Equalizer

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: Sear Deactivation Lever Takedown • Apex Trigger & Sear Fitting • Striker Block Plunger Polishing • Extractor Roll Pin Inspection • Frame Chassis Bedding

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
SEAR DEACTIVATION LEVER	Yellow/green internal lever inside magazine well pushes down to drop sear without pulling trigger for takedown
TRIGGER PULL WEIGHT	5.5 to 6.5 lbs (M2.0 factory flat/curved) / 4.0 to 4.5 lbs (with Apex Forward Set Sear)
STRIKER BLOCK SAFETY	Dome-shaped steel plunger in slide; must be pushed upward to allow striker forward travel
FRAME SUB CHASSIS	Embedded stainless steel chassis embedded in Zytel polymer frame to resist torsional flex
BARREL TWIST	1:10" 5R rifling on M2.0 barrels for lead/jacketed bullet stability

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: Gritty Trigger Takeup / False Reset Click **Trigger pull has noticeable gritty drag before breaking; user feels double click during reset**	• Factory striker block safety plunger stamped with rough machining ridges. • Trigger bar candy-cane loop rubbing frame ejector block. • Fouling beneath rear sight dovetail pressing on striker block spring.	**Gunsmith Action: Drift out rear sight (or remove optic plate). Extract striker block plunger. Chuck plunger into lathe or hand drill; polish hemispherical dome with 2000-grit paper and Flitz compound to mirror finish. Stone bottom edge of trigger bar candy-cane loop.**
Stoppage 2: Slide Lock Lever Disengages Prematurely on Mag Insertion **Inserting fresh loaded magazine causes slide to automatically slam forward into battery without pressing slide release**	• Worn slide stop detent ball and spring on M&P; M2.0 slide stop assembly. • Rounding of the slide stop engagement notch in the slide. • Over-aggressive upward slam of magazine floorplate during tactical reload.	**Gunsmith Action: Inspect slide stop engagement notch under magnification. If edge is rounded, square notch with needle file. Replace slide stop lever assembly with updated M2.0 detent unit.**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY

S&W; M&P; 2.0 Detail Disassembly & Apex Trigger Installation	Apex Tactical Specialties	Complete walk-through of drifting roll pins, removing sear housing block, installing forward set sear and ultimate striker block, and tuning trigger overtravel.