

Codigos de Erro - Painel de Controle

CPMD 2023 - HP LaserJet Series

TechGuide IA — Consulta Inteligente de Manuais HP

Control Panel Message Document (CPMD) www.hp.com/support/ljM501 www.hp.com/support/ljM506 www.hp.com/support/ljM507
www.hp.com/support/ljM527mfp www.hp.com/support/ljM528mfp www.hp.com/support/ljE50045 www.hp.com/support/ljE50145
www.hp.com/support/ljE52545mfp www.hp.com/support/ljE52645mfp HP LaserJet Pro M501 HP LaserJet Enterprise M506, M507 HP
LaserJet Enterprise MFP M527, M528 HP LaserJet Managed E50145, MFP E52645 HP LaserJet Managed E50045, MFP E52545
HP LaserJet Enterprise M506, M507, MFP M527, MFP M528, Pro M501, Managed E50045, E50145, MFP E52545, MFP E52645 - Control
Panel Message Document (CPMD)

SUMMARY

This document provides error-code troubleshooting information

Legal information

Copyright and License

© Copyright 2022 HP Development Company, L.P. Reproduction, adaptation, or translation without prior written permission is prohibited, except as allowed under the copyright laws.

The information contained herein is subject

to change without notice.

The only warranties for HP products and

services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein. Edition 2, 2/2025

Trademark Credits

Adobe®, Adobe Photoshop®, Acrobat®, and PostScript® are trademarks of Adobe Systems Incorporated.

Apple and the Apple logo are trademarks of

Apple Inc., registered in the U.S. and other countries. macOS is a trademark of Apple Inc., registered in the U.S. and other countries. AirPrint is a trademark of Apple Inc., registered in the U.S. and other countries. Google™ is a trademark of Google Inc. Microsoft®, Windows®, and Windows Server® are U.S. registered trademarks of Microsoft Corporation. UNIX® is a registered trademark of The Open Group.

Table of contents

1 Document last updated ... 1 2 About this document ... 2 3 Control-panel message types ... 3 Error-code and control-panel-message troubleshooting overview ... 3 Error codes (types and structure) ... 3 4 How to search for printer documentation ... 6 WISE - How to access and use ... 6 Accessing WISE ... 6 Using WISE to search for error codes ... 10 Using WISE to access repair and replace videos for FRUs ... 12 5 Printer service information ... 17 6 Numerical control panel messages ... 18 10.XX.YZ error messages ... 18 10.wx.yz error messages ... 18

10.00.00 or 10.00.01 e-Label Memory Error ... 19

10.00.10 e-Label Missing Memory Error ... 22

10.00.11, 10.00.12 Supply Memory Error ... 23

10.00.15 Install <supply> ... 24

10.00.33 Used Supply In Use ... 24

10.00.34 Used supply in use ... 24

10.00.35 Incompatible supply in use ... 25

10.00.40 Genuine HP supplies installed ... 25

10.00.41 Unsupported Supply in Use ... 25

10.00.59 ... 25

10.00.60 Black cartridge low ... 26

10.00.69 Black cartridge very low ... 26

10.00.70 Printing past very low ... 26

10.00.91 Cartridge motor stall ... 26

10.23.15 Install <supply> ... 27

10.23.35 Incompatible <supply> ... 27

11.XX.YZ error messages ... 28 11.* errors ... 28

11.00.01 or 11.00.02 Internal clock error ... 28

13.XX.YZ error messages ... 30 13.* errors ... 30

13.00.00 ... 37

13.00.EE ... 38

13.A2.D2 ... 38

13.Ax.Dz ... 41 iii

13.A2.FF ... 44

13.A3.FF ... 47

13.A5.FF ... 50

13.B2.Az Jam in top cover ... 53 13.B2.D1 Jam in top cover ... 56 13.B2.Dz Jam in top cover ... 57 13.B2.E2 Jam in top cover ... 67 13.B2.FF Jam in top cover ... 68 13.B9.Az Fuser jam ... 68 13.B9.Bz Fuser Jam ... 72 13.B9.Cz ... 75 13.B9.Dz ... 78

13.B9.FF ... 82

13.D3.yz ... 84

13.D3.FF ... 85

13.E5.FF ... 88

13.EA.FF ... 88

13.FF.EE ... 88

13.EE.FF ... 88

13.FF.FF ... 88

20.XX.YZ error messages ... 89 20.* errors ... 89

20.00.00 Insufficient memory <device> ... 89

21.XX.YZ error messages ... 90

21.00.00 Page Too ComplexEvent log error message 21.00.00 ... 90

30.XX.YZ error messages ... 90 30.* errors ... 90

30.01.01 ... 90

30.01.08 Home position error ... 95

30.01.14 Scan system EEPROM error ... 101

30.01.36 Upgrade error ... 103

30.01.41 Scanner error ... 105

30.01.43 Scanner memory failure ... 107

30.01.44 Scanner error ... 109

30.01.45 Scanner Error ... 112

30.01.46 Scanner Error ... 114

30.03.14 ... 117

30.03.20 ... 117

30.03.22 Scanner failure ... 120

30.03.23 Scanner failure ... 120

30.03.30 Scanner Failure ... 121

30.03.45 Scanner Error To continue turn off then on ... 122

31.XX.YZ error messages ... 125 31.* errors ... 125

31.01.47 Document feeder not detected ... 125

31.03.14 ... 126

31.03.20 backside scanner not detected ... 127

31.03.22 Scanner calibration failure ... 129

iv

31.03.30 Document feeder pick motor error ... 129

31.03.31 Document feeder motor stall ... 130

31.03.32 ... 131

31.03.33 Backside scanner calibration area dirty ... 131

31.03.34 Background missing ... 132

31.13.00 Document feeder multi-pick error ... 132

31.13.01 ... 151

31.13.02 ... 170

31.13.13 ... 189

31.13.14 ... 190

32.XX.YZ error messages ... 209 32.* errors ... 209

32.08.A1, 32.08.A2, 32.08.A3 ... 210

32.1C.05 ... 210

32.1C.06 (event code) ... 210 32.1C.07 (event code) ... 210 32.1C.08 (event code) ... 211 32.1C.09 (event code) ... 211 32.1C.0A (event code) ... 211 32.1C.0D (event code) ... 211 32.1C.11 (event code) ... 212

32.1C.13, 32.1C.14 ... 212

32.1C.15 ... 212

32.1C.2E ... 212

32.1C.2F ... 212

32.1C.40 ... 213

32.1C.41 ... 213

32.1C.42 ... 213

32.1C.43 ... 213

32.1C.44 ... 213

32.1C.45 ... 213

32.1C.46 ... 214

32.1C.47 ... 214

32.1C.48 ... 214

32.1C.49 ... 214

32.1C.4A ... 214

32.1C.56 ... 215

32.1C.57 ... 215

32.1C.58 ... 215

32.1C.60 ... 215

32.1C.61 ... 215

32.1C.62 ... 216

32.1C.68 ... 216

32.1C.69 ... 216

32.1C.6A ... 216

32.1C.6D ... 216

33.XX.YZ error messages ... 217 33.* errors ... 217 v

33.01.xx ... 218

33.02.01 Used board/disk installed ... 219

33.02.02 ... 220

33.03.02 ... 220

33.03.03 Incompatible formatter installed ... 222

33.03.05 EFI Boot error ... 223

33.03.06 ... 225

33.04.01 Missing TPM ... 226

33.04.02 Missing TPM ... 226

33.04.03 Unknown TPM ... 227

33.04.05 ... 227

33.05.0X SureStart errors ... 228

33.05.0X SureStart errors ... 229

33.05.0z SureStart errors ... 229

33.05.1x Whitelisting errors ... 230

33.05.2x Intrusion detection errors ... 231

33.05.5z Intrusion detection errors ... 232

33.06.01 ... 233

40.XX.YZ error messages ... 233 40.* errors ... 233

40.00.01 USB I/O buffer overflow To continue, touch “OK” ... 233

40.00.02 Embedded I/O buffer overflow To continue, touch “OK” ... 234

40.00.03 EIO [x] buffer overflow To continue, touch “OK” ... 234

40.00.04 EIO [x] bad transmission To continue, touch “OK” ... 234

40.00.05 Embedded I/O bad transmission To continue, touch OK ... 234

40.08.0x USB storage accessory removed ... 234

41.XX.YZ error messages ... 235 41.* errors ... 235

41.01.YZ ... 235

41.02.00 Error ... 238

41.03.01, 41.03.A1, 41.03.B1, 41.03.C1 ... 239

41.03.02, 41.03.A2, 41.03.B2, 41.03.C2 Error ... 240

41.03.02 with slow printing ... 242

41.03.03, 41.03.A3, 41.03.B3, 41.03.C3 Error ... 248

41.03.04, 41.03.A4, 41.03.B4, 41.03.C4 ... 250

41.03.05, 41.03.A5, 41.03.B5, 41.03.C5 ... 252

41.03.0D, 41.03.AD, 41.03.BD, 41.03.CD ... 254

41.03.FZ Unknown Misprint Error ... 255

41.04.YZ Printer Error ... 256

41.05.YZ Unexpected type in tray <X> ... 259

41.XX.YZ Error To continue, touch "OK" ... 261 42.XX.YZ error messages ... 263

42.XX.YZ ... 263

42.B0.01 or 42.B0.02 ... 263 44.XX.XX error messages - M527 only ... 264 44.* errors ... 264

44.01.xx Error Event log message ... 265

44.03.xx Error Event log message ... 265

vi

44.10.xx Error Event log message (Multifunction product only.) ... 266

44.34.xx Error Event log message ... 266

44.34.03 Fax Modem Failure ... 266

44.34.E5 Fax Modem Failure ... 267

44.90.xx, 44.91.xx, 44.92.xx Error Event log message ... 267

47.XX.XX error messages ... 268 47.* errors ... 268

47.00.xx ... 268

47.01.xx ... 269

47.02.xx ... 269

47.03.xx ... 270

47.04.xx ... 270

47.05.xx ... 271

47.06.xx ... 271

48.XX.YY error messages ... 272 48.* errors ... 272 49.XX.YY error messages ... 272 49.XX.YY Error To continue turn off then on ... 272

49.2F.D8 ... 274

49.38.07 ... 275

49.38.0C ... 275

50.WX.YZ error messages ... 276 50.* errors ... 276 50.1X.YZ Fuser Error ... 277 50.2X.YZ Fuser Error ... 278 50.2F.00 Fuser Error ... 280 50.3X.YZ Fuser Error ... 284 50.4X.YZ Fuser Error ... 285 50.6X.YZ Fuser Error ... 286 50.7X.YZ Fuser Error ... 287 50.9X.YZ Fuser Error ... 288 51.XX.YZ, 52.XX.YZ error messages ... 292 51.* errors ... 292

51.00.10 ... 293

52.* errors ... 293

52.XX.00 ... 294

53.WX.YZ Error Messages ... 294 53.B0.0z ... 294 53.B1.0z ... 295 53.B2.0z ... 296 53.B3.0z ... 296 53.C1.0z Tray "Z" size mismatch. ... 297 54.XX.YZ error messages ... 298 54.* errors ... 298

54.06.21 error ... 299

55.XX.YZ, 56.XX.YZ error messages ... 299 vii

55.* errors ... 299

55.00.yy To continue turn off then on ... 300

55.0x.yy to.continue.off.on ... 304 56.* errors ... 305

56.00.yy to.continue.off.on ... 305

57.XX.YZ error messages ... 307 57.* errors ... 307

57.00.01 to.continue.off.on ... 308

57.00.02 to.continue.off.on ... 309

58.XX.YZ error messages ... 309 58.* errors ... 309

58.00.03 Error ... 310

58.00.04 Error ... 314

58.01.04 Error ... 314

58.02.04 Error ... 315

59.XX.YZ error messages ... 316 59.* errors ... 316

59.A2.02 ... 316

59.A2.0X ... 317

59.00.20 Error — To.continue.off.on ... 321

59.00.30 — To.continue.off.on ... 321

59.00.40 — To.continue.off.on ... 322

60.00.0Y, 62.00.00 error messages ... 323

60.00.0X Tray X lifting error ... 323

60.01.0X Tray X lifting error ... 327

62.00.00 To continue turn off then on. ... 331

65.X0.AZ error messages ... 332 65.* errors ... 332

65.80.A0, 65.80.A1: Output accessory Failure ... 332

66.WX.YZ error messages ... 333 66.* errors ... 333

66.00.20 ... 333

66.00.40 ... 333

66.00.50 ... 334

66.00.77 ... 334

66.00.79 ... 335

66.80.YY Stapler/Stacker failure ... 335

70.XX.YY error messages ... 338 70.* errors ... 338

70.00.00 Error To continue turn off then on ... 338

80.XX.YY, 81.XX.YY, 82.XX.YY error messages ... 340 80.* errors ... 340 80.0X.YY Embedded Jetdirect Error ... 343

81.09.00 Error ... 346

82.* errors ... 347

82.73.46, 82.73.47 ... 349

viii

98.0X.0Y error messages ... 350 98.* errors ... 350

98.00.0C ... 350

98.00.00 ... 353

98.00.01 or 98.01.00 Corrupt data in firmware volume ... 355

98.00.02 Corrupt data in the solutions volume ... 355

98.00.03 Corrupt data in the configuration volume ... 357

98.00.04 Corrupt data in the job data volume ... 358

99.XX.YY error messages ... 358 99.* errors ... 358

99.00.01 Upgrade not performed file is corrupt ... 359

99.00.02 Upgrade not performed timeout during receive ... 359

99.00.03 Upgrade not performed error writing to disk ... 360

99.00.04 Upgrade not performed timeout during receive ... 360

99.00.05 Upgrade not performed timeout during receive ... 361

99.00.06 Upgrade not performed error reading upgrade ... 361

99.00.07 Upgrade not performed error reading upgrade ... 362

99.00.08 Upgrade not performed error reading upgrade ... 363

99.00.09 Upgrade canceled by user ... 364

99.00.10 Upgrade canceled by user ... 364

99.00.11 Upgrade canceled by user ... 364

99.00.12 Upgrade not performed the file is invalid ... 364

99.00.13 Upgrade not performed the file is invalid ... 365

99.00.14 Upgrade not performed the file is invalid ... 365

99.00.2x ... 365

99.01.xx ... 366

99.02.01 ... 367

99.02.09 ... 367

99.07.22 Firmware install error ... 367

99.09.60 Unsupported disk ... 369

99.09.61 Unsupported disk ... 369

99.09.62 Unknown disk ... 370

99.09.63 Incorrect disk ... 377

99.09.64 Disk malfunction ... 378

99.09.65 Disk data error ... 379

99.09.66 No boot device. ... 379

99.09.67 Disk is not bootable please download firmware ... 380

99.39.64 eMMC Nonfunctional ... 381

99.39.67 eMMC Not Bootable ... 381

99.XX.YY ... 381

7 Alphabetical control panel messages ... 382 Alphabetical messages ... 382 Accept bad signature ... 382 Bad optional tray connection ... 382
<binname> full Remove all paper from bin ... 382 Canceling ... 382 Canceling...<jobname> ... 383 Cartridge Low ... 383 ix

Cartridge memory abnormal ... 383 Cartridge out ... 383 Checking engine ... 383 Checking paper path ... 384 Chosen personality not available
To continue touch "OK" ... 384 Cleaning ... 384 Cleaning do not grab paper ... 384 Clearing event log ... 384 Clearing paper path ... 385 Close
top cover ... 385 Cooling device ... 385 Creating cleaning page... ... 385 Data received To print last page press "OK" ... 386 Event log is empty
... 386 Expected drive missing ... 386 External device initializing ... 386 Face Down Tray Full ... 386 FIM Load Error Send full FIM on <X> port
... 393 Fuser Kit low ... 393 Fuser Kit very low To continue, touch "OK" ... 393 Genuine HP cartridge installed ... 394 Genuine HP supply
installed ... 394 HP Secure hard drive disabled ... 394 Incompatible <supply> ... 394 Incompatible supplies ... 395 Initializing... ... 395 Install
Black Cartridge ... 395 Install Fuser ... 395 Install supplies ... 396 Internal disk device failure To clear touch "OK" ... 396 Internal disk file
operation failed ... 396 Internal disk file system is full ... 396 Internal disk is write protected ... 397 Internal disk not found ... 397 Internal disk
not functional ... 397 Internal disk not initialized ... 398 Internal disk spinning up ... 398 Job not stapled due to mixed sizes ... 398 Load Tray
<X>: [Type], [Size] ... 398 Load Tray <X>: [Type], [Size] To use another tray, press "OK" ... 399 Loading program <XX> Do not power off ...
399 Manually feed: <Type><Size> ... 399 Manually feed: <Type><Size> To use another tray, press "OK" ... 399 Manually feed output stack
Then touch "OK" to print second side ... 400 Moving solenoid ... 400 Moving solenoid and motor ... 400 No job to cancel ... 400 NON HP
Supply Installed ... 400 Output Bin Full ... 401 x

Paused... ... 407 Performing Paper Path Test ... 407 Please Wait... ... 407 Printing Cleaning Page... ... 407 Printing Configuration... ... 408
Printing engine test... ... 408 Printing Event Log... ... 408 Printing File Directory... ... 408 Printing Font List... ... 408 Printing Help Page... ... 408
Printing Menu Map... ... 409 Printing Registration Page ... 409 Printing stopped... ... 409 Printing Supplies Status Page... ... 409 Printing Usage
Page... ... 409 Processing... ... 410 Processing... copy <x> of <y> ... 410 Processing duplex job Do not grab paper until job completes ... 410
Processing job from tray <x>... Do not grab paper until job completes ... 410 Ready ... 410 RAM disk device failure To clear press "OK" ... 410
RAM disk file operation failed To clear press "OK" ... 411 RAM disk file system is full To clear press "OK" ... 411 RAM disk is write protected
To clear press "OK" ... 411 RAM disk not initialized ... 411 Ready <IP Address> ... 411 Receiving Upgrade ... 412 Remove USB accessory ... 412
Replace <supply> ... 412 Replace supplies ... 412 Resend external accessory firmware ... 413 Resend Upgrade ... 413 Restore Factory
Settings ... 413 ROM disk device failed To clear press "OK" ... 413 ROM disk file operation failed To clear press "OK" ... 414 ROM disk file
system is full To clear press "OK" ... 414 ROM disk is write protected To clear press "OK" ... 414 ROM disk not initialized To clear press "OK"
... 414 Rotating Motor ... 414 Size Mismatch ... 415 Size mismatch in Tray <x> ... 415 Sleep mode on ... 415 Supplies low ... 415 Supply
memory warning ... 416 Supply low ... 416 Supply very low OR Supplies very low ... 416 The unit has corrupt data ... 417 Tray <X> empty:
[Type], [Size] ... 417 Tray <X> lifting ... 420 xi

Tray <X> open ... 420 Tray <X> overfilled ... 421 Type mismatch Tray <x> ... 421 Unsupported drive installed To continue, touch "OK" ... 421
Unsupported supply in use OR Unsupported supply installed To continue, touch "OK" ... 422 Unsupported tray configuration ... 422
Unsupported USB accessory detected Remove USB accessory ... 422 Upgrade Error ... 422 USB accessory not functional ... 422 USB hubs
are not fully supported Some operations may not work properly ... 423 USB is write protected To clear press "OK" ... 423 USB needs too much
power Remove USB and then turn off and on ... 423 USB not initialized ... 423 USB storage accessory removed Clearing any associated data
... 424 USB storage device failure To clear press "OK" ... 424 USB storage file operation failed To clear press "OK" ... 424 USB storage file
system is full To clear press "OK" ... 424 Used supply installed To continue, touch "OK" OR Used supply in use ... 425 Waiting for tray <x> to
lift ... 425 Windows Login Required to Use this Feature ... 425 Index ... 426 xii

1 Document last updated

The following is the last time this document was updated: Last update: February 27, 2025 Document last updated 1

2 About this document

This document provides error-code troubleshooting information. IMPORTANT: Procedures and part numbers change. For current information, use the browser-based format. Verify PDF is the most current before use. PDF part numbers must be verified with web-based error code information or parts look-up before parts are ordered. Choose the format that best meets your needs. Table 2-1 Content format types

Format Document title example Recommended use

Web-based Go to: Product Detail page > Error

Code Look-up

- Quick access to individual web-based error code troubleshooting TIP: Save Product Detail page

URL location in favorites

Web-Base Go To: WISE default Search page > Enter [Product] and error code ● Access to individual web-based error code troubleshooting ● Web-based: Most up-to-date information available PDF [Product] - Control Panel Message Document (CPMD) PDF ● Use when support portals are

NOT accessible at time of

service ● Use when a printable document is needed NOTE: Always refer to the printer service manual for removal and replacement procedures NOTE: For current information, use the Web-based format. 2 Chapter 2 About this document

3 Control-panel message types The control-panel messages and event code entries indicate the current printer status or situations that might require action. NOTE: Event log errors do not appear on the control-panel display. Open the event log to view or print the event log errors. A control-panel message displays temporarily and might require you (or the applicable user) to acknowledge the message by touching the OK button to resume printing or by touching the Stop button to cancel the job. With certain messages, the job might not finish printing, or the print quality might be affected. If the message is related to printing and the auto-continue feature is on, the printer will attempt to resume printing after the message has appeared for 10 seconds without acknowledgement. For some messages, restarting the printer might fix the problem. If a critical error persists, the printer might require service. Error-code and control-panel-message troubleshooting overview This section provides information on error codes and searching for information. Error codes (types and structure) Error codes and control-panel messages display on the printer control panel to indicate the current printer status or situations that might require action. Error codes are numerical, or alphanumeric, and have a set structure with six characters (example: 13.WX.YZ). ● The first two characters are numeric and represent the system component that is causing the error. For example, in error code 10.22.15, 10 = Supplies for HP LaserJets. ● The remaining four characters (W, X, Y, and Z values) further define the error. HP LaserJet and HP PageWide Enterprise error codes are documented in the control panel message document (CPMD) for each printer. The CPMD is a comprehensive list of error codes, diagnostic and troubleshooting steps to clear or resolve the error, and other helpful information such as service mode pins and part numbers. The CPMD is continually updated and republished with the latest information for the following error codes. Table 3-1 ERROR CODES: The first two characters Error code System Component System Error Description 10.WX.YZ Supplies (LaserJet) Supply error or supply memory error. 11.WX.YZ Real-time clock Internal error with the clock on the formatter. 13.WX.YZ Jam (LaserJet) Paper jam or open door jam error. Control-panel message types 3

Table 3-1 ERROR CODES: The first two characters (continued) Error code System Component System Error Description 15.WX.YZ Jam (PageWide) Paper jam or open door jam error. 17.WX.YZ Supplies (PageWide) Supply error or supply memory error. 20.WX.YZ Printer memory Insufficient memory or buffering error. 21.WX.YZ Page Page complexity causing a decompression error when trying to process job. 30.WX.YZ Scanner Flatbed scanner error occurring inside the unit. 31.WX.YZ Document feeder Document feeder, scanner, or jam error. 32.WX.YZ Backup, restore, or reset Backup, restore, or reset notification or error. 33.WX.YZ Security Backup, Disk, EFI BIOS, Firmware integrity (SureStart), or Trusted Platform Module (TPM) notification or error. 40.WX.YZ Input/Output (I/O) Partition manager, secure erase, or USB accessory error. 41.WX.YZ Fuser, Laser scanner, or Paper path Miscellaneous error including general and misprint or mismatch errors typically involving (but not limited to) the fuser, the laser scanner, or the paper path. 42.WX.YZ Firmware Firmware failure involving the Event Log, Shell, System Manager, or other component. 44.WX.YZ Firmware Firmware failure involving a digital sending component. 45.WX.YZ OXPd/Web Kit (PageWide) Informational notifications involving the OXPd Web Kit (communications log). 46.WX.YZ Engine (LaserJet) Engine communication error. 47.WX.YZ Firmware Job parser or printer calibration error. 48.WX.YZ Firmware PJA job accounting, job management, or job pipeline error. 49.WX.YZ Firmware Firmware communication error. 50.WX.YZ Fuser (LaserJet) Fuser error. 51.WX.YZ Laser scanner (LaserJet) Laser scanner beam error. 52.WX.YZ Laser scanner (LaserJet) Laser scanner startup error. 54.WX.YZ Sensor Sensor error (not jam related). 55.WX.YZ DC controller (LaserJet) DC controller communication error. 56.WX.YZ Paper handling (LaserJet) Paper input/output or accessory error. 57.WX.YZ Fan Fan error. 58.WX.YZ Sensor Engine sensor failure. 59.WX.YZ Motor (LaserJet) Motor error. 60.WX.YZ Tray motor error (LaserJet) Tray lifting or pick up error. 61.WX.YZ Engine (PageWide) Print engine error with the 8-bit data package. 4 Chapter 3 Control-panel message types

Table 3-1 ERROR CODES: The first two characters (continued) Error code System Component System Error Description 62.WX.YZ System (LaserJet) Print bar (PageWide) LaserJet internal system error. PageWide print system error. 63.WX.YZ Engine (LaserJet) General engine error (electrical, communication, etc.). 65.WX.YZ Connector Output accessory connection error. 66.WX.YZ Output accessory Output accessory error. 67.WX.YZ Input accessory Input accessory connection error 69.WX.YZ Duplexer Duplexer error. 70.WX.YZ DC controller (LaserJet) DC controller firmware error. 76.WX.YZ DC controller (LaserJet) Power supply fluctuations causes formatter and

DC controller communication issue and results

them not to be in synchronization. 80.WX.YZ Managed device Embedded Jetdirect error. 81.WX.YZ Near Field Communication (NFC) Wireless, Bluetooth or internal EIO error. 82.WX.YZ Memory (hard disk, EMMC, etc.) Disk hardware error. 90.WX.YZ Internal diagnostics Internal test of systems (i.e. disk, CPB, display) or interconnection error. 98.WX.YZ Hard disk Hard disk partition error. 99.WX.YZ Firmware installer Remote Firmware Upgrade (RFU), firmware install (engine or accessory), or disk error. Error codes (types and structure) 5

4 How to search for printer documentation

The CPMD, error codes, and other support documentation for each printer is available on the HP portals. For HP internal access to WISE, go to WISE. For HP channel partners access WISE, see Accessing WISE for HP channel partners (HP Partner Portal) on page 6 or {Xref Error! Target does not exist.}Accessing WISE for HP channel partners (CSDP). WISE is available to call agents, service technicians, and HP internal users. The level of detail available depends on your access credentials. To learn how to find support content in WISE, watch the video here.

WISE - How to access and use

Learn how to access and use Web-based Interactive Search Engines (WISE) to locate available support information. WISE is a repository of technical support documentation including service manuals, user guides, videos, and general support information.

Accessing WISE

Learn how to access Web-based Interactive Search Engines (WISE) if you are an HP channel partner or an internal HP user. Accessing WISE for HP channel partners (HP Partner Portal) Learn how to access WISE by accessing the HP Partner Portal if you are an HP Channel Partner. NOTE: If this is your first visit to the HP Partner Portal, you will be asked to create an account. Follow the setup directions using your HP Partner credentials. View a video of how to access WISE for HP channel partners 1. Sign-in to the HP Partner Portal (click <https://partner.hp.com> to access the sign-in page). Figure 4-1 HP Partner Portal sign-in page 6 Chapter 4 How to search for printer documentation

2. On the HP Partner Portal home page, click the Services & Support item. Figure 4-2 HP Partner Portal home page 3. Select the Technical Support (WISE) item. Figure 4-3 HP Partner Portal Service & Support page Accessing WISE for HP channel partners (HP Partner Portal) 7

4. Select the Technical Documentation item. Figure 4-4 HP Partner Portal Technical Support (WISE)page 5. Use the WISE portal to search for printer information. Figure 4-5 WISE portal home page

Accessing WISE for internal HP users

Learn how to access WISE if you are an internal HP user. 1. Open one of the Web-based Interactive Search Engines (WISE) URLs listed below. Americas (AMS) ● WISE - English ● WISE - Spanish ● WISE - Portuguese ● WISE - French 8 Chapter 4 How to search for printer documentation

Asia Pacific / Japan (APJ) ● WISE - English ● WISE - Japanese ● WISE - Korean ● WISE - Chinese (simplified) ● WISE - Chinese (traditional) ● WISE - Thai Europe / Middle East / Africa (EMEA) ● WISE - English 2. Select Commercial from the drop-down menu. Figure 4-6 Choose an experience 3. The WISE home page appears. Play the video: View a video of how access WISE (internal HP users) Accessing WISE for internal HP users 9

Using WISE to search for error codes

Learn how to use WISE to look up error codes. NOTE: The model used in the instructional videos is an example. The same steps apply to all printer models. You will need the printer type (e.g. HP LaserJet), model number (e.g. M607), and bundle option (e.g. dn, dh, z).

Search for error codes using the lookup widget

Learn how to search for a specific error code using the WISE Error Code Lookup widget. 1. Enter a printer model number (for example, M606) in the Go to a Product Detail page dialog box. TIP: To find a Product Detail Page (PDP) from a list of products by product type, select the ...or select your product from a list item just below the dialog box. 2. A drop-down list appears. Click on the full printer series name (for example, HP LaserJet Enterprise M606 series) in the list. NOTE: Selecting the series item from the drop-down list is recommended for the most accurate search return. 10 Chapter 4 How to search for printer documentation

3. Type the error code (for example, 13.E1.D3) in the Error Code Lookup field, and then select the search icon. 1 2 4. The error code troubleshooting content displays in the All Search Results area. Play the video: View a video of how to search for error codes using the Product Detail Page (PDP) or the Error Code Lookup tool.

Search for error codes from the WISE home page

Learn how to search for a specific error code from the WISE home page. 1. On the WISE home page, enter a printer model number (for example, M606) in the Search dialog box. Search for error codes from the WISE home page 11

2. A drop-down list appears. Click on the full printer series name (for example, HP LaserJet Enterprise M606 series) in the list. NOTE: Selecting the series item from the drop-down list is recommended for the most accurate search return. 3. Type the error code (for example, 13.E1.D3) in the Search keyword field, and then select the search icon. 1 2 4. The error code troubleshooting content displays in the All

Search Results area. Using WISE to access repair and replace videos for FRUs Learn how to use WISE to access repair and replace videos for FRUs. NOTE: The model used in the instructional videos is an example. The same steps apply to all printer models. 12 Chapter 4 How to search for printer documentation

You will need the printer type (e.g. HP LaserJet), model number (e.g. M607), and bundle option (e.g. dn, dh, z). Search for videos using the Product Detail Page (PDP) Learn how to search WISE for product specific information. Quickly review the steps and then play the video. 1. Enter a printer model number (for example, M606) in the Go to a Product Detail page dialog box. TIP: To find a Product Detail Page (PDP) from a list of products by product type, select the ...or select your product from a list item just below the dialog box. 2. A drop-down list appears. Click on the full printer series name (for example, HP LaserJet Enterprise M606 series) in the list. NOTE: Selecting the series item from the drop-down list is recommended for the most accurate search return. Search for videos using the Product Detail Page (PDP) 13

3. Select the link to Videos in the Other Content menu at the bottom-right of the screen. 4. Select the desired video from the list of videos. TIP: Select the Add Or Remove Hardware & Customer Self Repair filter under Troubleshooting to limit the search results to repair and replace videos. Play the video: View a video of how to search for the printer's Product Detail Page (PDP)

Search for videos using the WISE search function

Learn how to search WISE using the model number. Quickly review the steps and then play the video. 1. On the WISE home page, enter a printer model number (for example, M606) in the Search dialog box. 14 Chapter 4 How to search for printer documentation

2. A drop-down list appears. Click on the full printer series name (for example, HP LaserJet Enterprise M606 series) in the list. NOTE: Selecting the series item from the drop-down list is recommended for the most accurate search return. 3. Select the search icon. 4. To refine the search results, select the radio button labeled Videos in the upper-right portion of the screen. TIP: To refine video search results, type a part name in the keyword search bar, and then select the search icon. For example, entering the word fuser to the keyword search bar returns videos related to repair and replacement of the fuser. Search for videos using the WISE search function 15

Play the video: View a video of how to perform a model number search 16 Chapter 4 How to search for printer documentation

5 Printer service information

Service pin for printer

Last update: February 27, 2025 Service mode PIN numbers:

● M506, E50045: 10050615

NOTE: When possible, always update the printer firmware to the latest available version at HP.com as part of the troubleshooting performed for any of the following errors. Printer service information 17

6 Numerical control panel messages

Use the following numerical error message troubleshooting to resolve your issue. 10.XX.YZ error messages 10.wx.yz error messages Errors in the 10.* family are related to toner cartridges and other supply items that require regular replacement as part of routine printer maintenance. Order replacement supplies and install them as necessary. To order parts, go to <https://www.hp.com/buy/parts>. Use the following list to identify the supply item affected: NOTE: Not all printers have all of these supplies. ● 10.00.XX = Black toner cartridge ● 10.01.XX = Cyan toner cartridge ● 10.02.XX = Magenta toner cartridge ● 10.03.XX = Yellow toner cartridge ● 10.10.XX = Transfer roller ● 10.22.XX = Transfer Belt ● 10.23.XX = Fuser kit ● 10.31.XX = Toner collection unit ● 10.39.XX = Document feeder kit ● 10.99.XX = One or more supply items have been installed

Recommended action

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, contact your HP-authorized service or support provider, or contact HP support at www.hp.com/go/contactHP. To order parts, go to <https://www.hp.com/buy/parts>. 1. For toner cartridges: a. Remove and reinstall the cartridge. b. Check the electronic chip on the cartridge if it is visible. If the chip is damaged, replace the toner cartridge. 18 Chapter 6 Numerical control panel messages

c. If print quality is unacceptable, or if printing cannot continue, replace the toner cartridge. 2. For the transfer kit: a. Remove and then reinstall the transfer unit. b. If print quality is unacceptable, or if printing cannot continue, replace the transfer kit. 3. For the fuser kit: a. Remove and then reinstall the fuser. CAUTION: The fuser might be hot. b. If print quality is unacceptable, or if printing cannot continue, replace the fuser kit. 4. For the toner collection unit: a. Remove the toner collection unit and reinstall it. b. If the toner collection unit is nearly full, replace it with a new one. Using a toner collection unit until it is overfilled can damage the printer. 5. For the document feeder kit: a. Open the document feeder top cover and inspect the rollers for obvious dirt or wear. Clean the rollers if necessary. b. Install a new roller kit.

10.00.00 or 10.00.01 e-Label Memory Error

The printer is unable to read the cartridge data. This message indicates that the printer cannot read or write to the e-label of the toner cartridge. This error can cause the supplies status feature to be disabled.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Remove, and then reinstall the toner cartridge. 2. If the error reappears, turn the power off, and then on. 3. If the error persists, replace the toner cartridge. 4. If the error persists, please contact customer support at: www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Remove, and then reinstall the toner cartridge. 2. If the error reoccurs, use the power button to turn off the printer, and then turn on the printer. 3. Check the toner cartridge memory chip. If it is damaged, replace the toner cartridge.

10.00.00 or 10.00.01 e-Label Memory Error 19

4. If the error persists and the toner cartridge has not been replaced, replace the toner cartridge. 5. If the error persists, replace the Memory PCA. Table 6-1 Memory PCA part number

Printer models Part description Part number

M506 M507 M527 M528

E50045

E50145

E52545

E52645

Memory PC board assembly RM2-7955-000CN 6. If the error persists after replacing the Memory PCA, replace the High-voltage power supply (HVPS). Table 6-2 High-voltage power supply (HPVS) assembly part number

Part description Part number

High-voltage power supply (HPVS) assembly RM2-7945-000CN For instructions: See the Repair Service Manual for this product.

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Remove, and then reinstall the toner cartridge. 2. If the error reoccurs, use the power button to turn off the printer, and then turn on the printer. 3. Check the toner cartridge memory chip. If it is damaged, replace the toner cartridge. NOTE: Make sure not to touch the imaging drum when checking the cartridge memory chip. Fingerprints on the imaging drum can cause print-quality problems. 20 Chapter 6 Numerical control panel messages

Figure 6-1 Memory chip location 1. Memory chip 2. Imaging drum 4. If the error persists and the toner cartridge has not been replaced, replace the toner cartridge. 5. If the error persists, check the e-label reader inside the unit. 6. Check if the error persists, and then check whether the Memory PCA has been replaced. If the Memory PCA has not been replaced, replace the Memory PCA. Table 6-3 Memory PCA part number

Printer models Part description Part number

M506 M507 M527 M528

E50045

E50145

E52545

E52645

Memory PC board assembly RM2-7955-000CN 7. If the error persists, disconnect and reconnect the connections between the DC controller and the HVPS. Ensure that the cables are connected and seated correctly before replacing any part. Recommended action for onsite

technicians 21

8. If the error persists, replace the HVPS. Table 6-4 High-voltage power supply (HPVS) assembly part number

Part description Part number

High-voltage power supply (HPVS) assembly RM2-7945-000CN For instructions: See the Repair Service Manual for this product. 9. If the error persists, replace the DC Controller. Table 6-5 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

For instructions: See the Repair Service Manual for this product.

10.00.10 e-Label Missing Memory Error

The printer is unable to detect the e-label. This message indicates that the printer has determined that the e-label is missing. This error can cause the supplies status feature to be disabled.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Remove and then reinstall the indicated toner cartridge. 2. If the message displays again, turn the printer off and then on using the power button. 3. Check the cartridge memory tag. If it is damaged, replace the toner cartridge. 4. If the error persists, replace the indicated toner cartridge. 22 Chapter 6 Numerical control panel messages

10.00.11, 10.00.12 Supply Memory Error

The printer is unable to read the toner cartridge e-label. The Supply Memory Error can also display on the control panel of an HP LaserJet Enterprise or HP LaserJet Managed printer after performing a partial clean or cold reset three or four times in succession. This issue causes the following symptoms: ● The customer is unable to print with the existing toner cartridge. ● The toner cartridge cannot be used in another printer.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Remove and the reinstall the indicated print cartridge. 2. If the message displays again, turn the printer off then on. 3. Ensure that a genuine HP toner cartridge is installed in the printer and the cartridge is under warranty. NOTE: If you believe this is a genuine HP supply, go to www.hp.com/go/anticonterfeit. 4. Install a genuine HP Toner cartridge. 5. If the error persists, please contact customer support at: www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Ensure that the printer has FutureSmart firmware version 4.10 or later.

10.00.11, 10.00.12 Supply Memory Error 23

2. Request the customer to limit a partial clean or cold reset and perform it only when required. NOTE: Performing a partial clean or cold reset three to four times in succession will log in a

10.00.11 event code error and render the toner cartridge unusable.

3. Remove and ensure that a genuine HP toner cartridge is installed in the printer and the cartridge is under warranty. NOTE: If this is not a genuine HP toner cartridge, inform the customer to install a genuine HP toner cartridge. 4. Install the toner cartridge and see if the error persists. 5. If the error persists, replace the customer's existing toner cartridge under warranty. Table 6-6

Part description Toner cartridge part number

HP 89A Black Original LaserJet Toner Cartridge CF289A HP 89X High Yield Black Original LaserJet Toner Cartridge CF289X HP 89Y Extra High Yield Black Original LaserJet Toner

Cartridge

CF289Y

HP Black contract LaserJet Toner CF289YC HP Black Managed LaserJet Toner Cartridge W9008MC

10.00.15 Install <supply>

The indicated supply has been removed or installed incorrectly.

10.00.15 (event code) Black Toner cartridge

Recommended action

Follow these troubleshooting steps in the order presented. ■ Replace or install the indicated supply.

10.00.33 Used Supply In Use

A used supply is installed in the printer (end of life).

10.00.33 (event code) Black toner cartridge

Recommended action

Follow these troubleshooting steps in the order presented. ■ No action necessary. If you believe this is a genuine HP supply, go to www.hp.com/go/anticonterfeit. Using a cartridge that is near its end-of-life can cause this event code.

10.00.34 Used supply in use

The toner cartridge is used. 24 Chapter 6 Numerical control panel messages

10.00.34 (event code) Black toner cartridge

Recommended action

Follow these troubleshooting steps in the order presented. ■ If you believe this is a genuine HP supply, go to www.hp.com/go/anticonterfeit. NOTE: Removing a cartridge from one printer and then installing it in a different printer (for testing functionality) will cause this event code.

10.00.35 Incompatible supply in use

An incompatible cartridge is in use.

10.00.35 (event code) Black toner cartridge

Recommended action

Follow these troubleshooting steps in the order presented. ■ Install the correct HP print cartridge for this printer. NOTE: The toner cartridge is not compatible with the printer.

10.00.40 Genuine HP supplies installed

A genuine HP print cartridge has been installed.

10.00.40 (event code) Black toner cartridge

Recommended action

There is no action needed for this message. ■ No action necessary.

10.00.41 Unsupported Supply in Use

The installed toner cartridge is for a different printer.

10.00.41 (event code) Black toner cartridge

Recommended action

Follow these troubleshooting steps in the order presented. ■ Remove the toner cartridge, and then install the correct cartridge for this printer.

10.00.59

Black cartridge has been replaced with non-new cartridge This is an Event Log Only message.

Recommended action

There is no action needed for this message. Recommended action 25

■ No action necessary.

10.00.60 Black cartridge low

The black cartridge is low.

Recommended action

Follow these troubleshooting steps in the order presented. ■ If print quality is no longer acceptable, replace the print cartridge. TIP: HP recommends that they have replacement supplies available to install when the print quality is no longer acceptable.

10.00.69 Black cartridge very low

The black cartridge is very low.

Recommended action

Follow these troubleshooting steps in the order presented. ■ If print quality is no longer acceptable, replace the print cartridge. TIP: Advise the customer that HP recommends that they have replacement supplies available to install when the print quality is no longer acceptable.

10.00.70 Printing past very low

The printer indicates when a supply level is very low. The actual remaining toner cartridge life might vary. You do not need to replace the toner cartridge at this time unless print quality is no longer acceptable. After an HP supply has reached the very low threshold, the HP premium protection warranty ends.

10.00.70 (event code) Black toner cartridge

Recommended action

Follow these troubleshooting steps in the order presented. ■ If print quality is no longer acceptable, the customer must order and pay for a replacement toner cartridge. Advise the customer that HP recommends that they have replacement supplies available to install when the print quality is no longer acceptable.

10.00.91 Cartridge motor stall

Cartridge motor stall.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Replace the toner cartridge. 26 Chapter 6 Numerical control panel messages

10.23.15 Install <supply>

The indicated supply has been removed or installed incorrectly.

10.23.15 (event code) Fuser kit

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents or onsite technicians Follow these troubleshooting steps in the order presented. ■ Replace or install the indicated supply. Table 6-7 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product.

10.23.35 Incompatible <supply>

The indicated supply is not compatible with this printer.

10.23.35 (event code) Fuser kit

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented.

10.23.15 Install <supply> 27

■ Install a supply that is designed for this printer. Table 6-8 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. CAUTION: The fuser might be hot. Be careful when removing the fuser. 11.XX.YZ error messages 11.* errors Errors in the 11.* family are related to the printer real-time clock.

Recommended action for customers

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. 1. Set the time and date on the printer control panel. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Set the time and date on the printer control panel. 2. If the error persists, remove and reinstall the formatter. Make sure it is fully seated. 3. If the error still persists, replace the formatter.

11.00.01 or 11.00.02 Internal clock error

The printer real time clock has experienced an error. 01=dead clock 02=dead real time clock 28 Chapter 6 Numerical control panel messages

Recommended action for customers

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. 1. Set the time and date on the printer control panel. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Make sure to set the time and date on the control panel whenever the printer is turned off and then turned on. 2. If the error persists, perform a Partial Clean using the Preboot menu or the Embedded Web Server

(EWS).

NOTE: A Partial Clean erases all custom settings, PINs, passwords, third-party solutions, firmware files, and the operating system. It automatically reboots the printer and restores the firmware files from the repository. 3. If the error persists, try to update the firmware. 4. If the error persists, dispatch a service technician to replace the formatter. Use the following table to order the correct part number for your printer. Table 6-9 Formatter PCA part numbers

Product models Part description Part number

M501dn Formatter PC board J8H61-67901 M501dn (China) Formatter PC board J8H61-67902 M501n Formatter PC board J8H60-67901 M501n (China) Formatter board assembly J8H60-67902 M506n/ M506dn E50045n/ E50045dn Formatter PC board assembly F2A68-67915 M506x E50045x Formatter PC board assembly F2A68-67916 M507

E50145

Formatter PC board 1PV87-60001 M527

E52545

Formatter PC board assembly F2A76-67910 M528

E52645

Formatter PC board 1PV64-60002 Recommended action for customers 29

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Make sure to set the time and date on the control panel whenever the printer is turned off and then turned on. 2. If the error persists, remove and reinstall the formatter making sure it is seated correctly. 3. If the error persists, perform a Partial Clean using the Preboot menu or the Embedded Web Server

(EWS).

NOTE: A Partial Clean erases all custom settings, PINs, passwords, third-party solutions, firmware files, and the operating system. It automatically reboots the printer and restores the firmware files from the repository. 4. If the error still persists, update the firmware. 5. If the error persists, replace the formatter. Table 6-10 Formatter PCA part numbers

Product models Part description Part number

M501dn Formatter PC board J8H61-67901 M501dn (China) Formatter PC board J8H61-67902 M501n Formatter PC board J8H60-67901 M501n (China) Formatter board assembly J8H60-67902 M506n/ M506dn E50045n/ E50045dn Formatter PC board assembly F2A68-67915 M506x E50045x Formatter PC board assembly F2A68-67916 M507

E50145

Formatter PC board 1PV87-60001 M527

E52545

Formatter PC board assembly F2A76-67910 M528

E52645

Formatter PC board 1PV64-60002 For instructions: See the Repair Service Manual for this product. 13.XX.YZ error messages 13.* errors Errors in the 13.* family are related to jams. 30 Chapter 6 Numerical control panel messages

More than 1000 unique error codes are possible. Use the following information to understand the jam code. Not all codes apply to all printers. Message format: 13.WX.YZ ● W represents the jam location. ● X represents the sensor or door that triggered the jam. ● Y represents the jam condition (delay, stay, wrap, etc.) ● Z represents the paper source, fuser mode, or destination Table 6-11 Potential values for W and X

W Jam location X Sensor or door

A Input area 0 Envelope feeder A Input area 1 Tray 1 feed (unless Tray 1 feed is the registration sensor) A Input area 2 Tray 2 feed (unless Tray 2 feed is the registration sensor) A Input area 3 Tray 3 feed A Input area 4 Tray 4 feed A Input area 5 Tray 5 feed A Input area 6 Tray 6 feed A Input area 7 Optional tray exit sensor A Input area A Door 1 A Input area B Door 2 A Input area C Door 3 A Input area D Door 4 A Input area E Door 5

A Input area F Multiple sensors or doors

B Image area 0 Media sensor for forbidden transparencies B Image area 2 Registration/top of page B Image area 3 Top of page B Image area 4 Loop B Image area 5 Fuser input B Image area 9 Fuser output B Image area A Door 1 B Image area B Door 2

B Image area F Multiple sensors or doors

C Switchback area (between the fuser and the output bin)

1 Intermediate switchback sensor

13.* errors 31

Table 6-11 Potential values for W and X (continued)

W Jam location X Sensor or door

C Switchback area (between the fuser and the output bin)

2 Switchback media stay sensor

C Switchback area (between the fuser and the output bin)

3 Paper delivery sensor

D Duplex area 1 Duplex switchback D Duplex area 2 Duplex delivery D Duplex area 3 Duplex refeed D Duplex area A Door 1 (if different than the imaging area) D Duplex area B Door 2 (if different than the imaging area)

D Duplex area F Multiple sensors or doors

E Output or intermediate paper transport unit

(IPTU) area

1 Output bin full sensor

E Output or intermediate paper transport unit

(IPTU) area 2 IPTU feed sensor 1

E Output or intermediate paper transport unit

(IPTU) area 3 IPTU sensor 2

E Output or intermediate paper transport unit

(IPTU) area 4 IPTU sensor 3

E Output or intermediate paper transport unit

(IPTU) area 5 IPTU bin full sensor 4

E Output or intermediate paper transport unit

(IPTU) area

6 Output sensor

E Output or intermediate paper transport unit

(IPTU) area A Door 1

E Output or intermediate paper transport unit

(IPTU) area

F Multiple sensors or doors

F Multiple subsystems (occurs when paper is stuck in several areas)

F Multiple sensors or doors

1 Jetlink input device 4 Tray 4 feed sensor 1 Jetlink Input device 5 Tray 5 feed sensor 1 Jetlink Input device 6 Tray 6 feed sensor 1 Jetlink Input device 7 Tray 7 feed sensor 1 Jetlink Input device 8 Tray 8 feed sensor 1 Jetlink Input device 9 Tray 9 feed sensor 1 Jetlink Input device A Door 1 1 Jetlink Input device B Door 2

1 Jetlink Input device F Multiple sensors or doors

2 Buffer pass unit 0 Buffer pass inlet sensor 2 Buffer pass unit 9 Buffer pass exit sensor 32 Chapter 6 Numerical control panel messages
Table 6-11 Potential values for W and X (continued)

W Jam location X Sensor or door

2 Buffer pass unit A Door 1 3 Page insert unit 0 Page insertion inlet sensor 3 Page insert unit 1 Page insertion tray 1 feed sensor 3 Page insert unit 2 Page insertion tray 2 feed sensor 3 Page insert unit 3 Page insertion tray 3 feed sensor 3 Page insert unit 4 Page insertion tray 4 feed sensor 3 Page insert unit 7 Output path feed sensor 3 Page insert unit 9 Page insertion exit sensor 3 Page insert unit A Door 1 4 Punch unit 0 Puncher inlet sensor 4 Punch unit 1 Puncher jam sensor 4 Punch unit 9 Puncher exit sensor 4 Punch unit A Door 1 5 Folding unit 0 Folder inlet sensor 5 Folding unit 1 Folder sensor 5 Folding unit 9 Folder exit sensor 5 Folding unit A Door 1 6 Stacker unit 0 Stacker inlet sensor 6 Stacker unit 4 Stacker outlet sensor 6 Stacker unit 7 Stacker switchback entrance sensor 6 Stacker unit 8 Stacker switchback registration sensor 6 Stacker unit 9 Stacker switchback lower sensor 7 Multi-bin mailbox (MBM) unit 0 MBM inlet sensor 7 Multi-bin mailbox (MBM) unit 1 MBM middle sensor 7 Multi-bin mailbox (MBM) unit 9 Stapler sensor 7 Multi-bin mailbox (MBM) unit A Door 1 7 Multi-bin mailbox (MBM) unit B Door 2 7 Multi-bin mailbox (MBM) unit C Door 3 7 Multi-bin mailbox (MBM) unit F Multiple sensors or doors 8 Stapler/stacker (SS) unit 0 SS inlet sensor 8 Stapler/stacker (SS) unit 1 SS Bin Z 8 Stapler/stacker (SS) unit 3 SS unit middle sensor 8 Stapler/stacker (SS) unit 4 SS unit outlet sensor 1 8 Stapler/stacker (SS) unit 5 SS unit outlet sensor 2 13.* errors 33

Table 6-11 Potential values for W and X (continued)

W Jam location X Sensor or door

8 Stapler/stacker (SS) unit 9 Stapler sensor 8 Stapler/stacker (SS) unit A Door 1 8 Stapler/stacker (SS) unit B Door 2 9 Booklet maker unit 0 Booklet maker input sensor 9 Booklet maker unit 2 Booklet maker feed sensor 2 9 Booklet maker unit 2 Booklet maker feed sensor 3 9 Booklet maker unit 4 Booklet maker delivery sensor 9 Booklet maker unit 5 Booklet maker vertical paper path sensor 9 Booklet maker unit 6

Booklet unit front staple sensor 9 Booklet maker unit 7 Booklet unit rear staple sensor 9 Booklet maker unit 8 Booklet unit outlet sensor 9 Booklet maker unit A Door 1 9 Booklet maker unit B Door 2 9 Booklet maker unit C Door 3

9 Booklet maker unit F Multiple sensors or doors

0 Unknown 0 Unknown Table 6-12 Potential values for Y (jam condition)

Y Jam condition

0 Unknown

1 Unexpected sheet (duplex)

2 Staple jam

3 Jam caused by an open door (duplex) 4 Stay jam (the page never left the tray – duplex) A Stay jam (the page never left the tray – simplex)

B Multifeed

C Wrap D Delay (the page did not reach the sensor within the expected time – simplex)

E Door open

F Residual (paper is detected in the paper path when it should not be there) The information represented by the value for Z depends on where the paper is in the paper path. 34 Chapter 6 Numerical control panel messages

Table 6-13 Potential values for Z (source, fuser mode, or destination) Paper location Z Source, fuser mode, or destination When paper has not reached the fuser, Z represents the paper source. 1 Tray 1 Z represents the paper source. 2 Tray 2 Z represents the paper source. 3 Tray 3 Z represents the paper source. 4 Tray 4 Z represents the paper source. 5 Tray 5 Z represents the paper source. 6 Tray 6 Z represents the paper source. D Duplexer Z represents the paper source. E Envelope feeder When paper has reached the fuser, is in the duplex path, or in the output path, Z represents the fuser mode.

Jams can occur when there is a mismatch between

the actual paper and the fuser mode setting. 0 Photo 1, 2, or 3 Designated 2 or 3 Z represents the fuser mode. 1 Normal (automatically sensed rather than based on the paper type set at the control panel) Z represents the fuser mode. 2 Normal (based on the paper type set at the control panel) Z represents the fuser mode. 3 Light 1, 2, or 3 Z represents the fuser mode. 4 Heavy 1 Z represents the fuser mode. 5 Heavy 2 Z represents the fuser mode. 6 Heavy 3 Z represents the fuser mode. 7 Glossy 1 Z represents the fuser mode. 8 Glossy 2 Z represents the fuser mode. 9 Glossy 3 Z represents the fuser mode. A Glossy Film Z represents the fuser mode. B Transparency Z represents the fuser mode. C Label Z represents the fuser mode. D Envelope 1, 2, or 3 Z represents the fuser mode. E Rough When paper has entered the output bin, Z represents the output bin, numbered from top to bottom.

0 Unknown bin

Z represents the output bin 1 Bin 1 Z represents the output bin 2 Bin 2 Z represents the output bin 3 Bin 3 Z represents the output bin 4 Bin 4 Z represents the output bin 5 Bin 5 13.* errors 35

Table 6-13 Potential values for Z (source, fuser mode, or destination) (continued) Paper location Z Source, fuser mode, or destination Z represents the output bin 6 Bin 6 Z represents the output bin 7 Bin 7 Z represents the output bin 8 Bin 8 Z represents the output bin 9 Bin 9

All paper locations E Door open jam

All paper locations F Residual jam

All paper locations 0 Forbidden OHT jam (when Y=2)

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Follow the instructions on the control panel to clear the jam. Check for paper in all possible jam locations. 2. Verify that no doors are open. 3. Check the paper tray to make sure paper is loaded correctly. The paper guides should be adjusted to the correct size, and the tray should not be filled above the maximum fill marks or tabs. 4. Make sure the type and quality of the paper being used meets the HP specifications for the printer. 5. Use a damp, lint-free cloth to clean the rollers in the appropriate tray. Replace rollers that are worn. 6. Open all doors and covers and ensure the paper path is completely clear of paper or obstructions. 7. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. To prevent future paper jams in the printer, follow these recommendations: ● Use only paper that meets HP specifications for this printer. For

more information, refer to the printer User Guide or search for the "HP LaserJet Printers - Print Media Guide" (c06117757). ● Make sure the printing environment is within recommended specifications. ● Do not use paper that is wrinkled, folded, or damaged. ● Do not overload the tray with paper. ● Make sure that the paper guides in the tray are adjusted correctly for the size of paper. ● Make sure that the tray is fully inserted in the printer. ● If printing on heavy, embossed, or perforated paper, use the manual feed feature and feed sheets one at a time. 36 Chapter 6 Numerical control panel messages

● Open the Trays menu on the printer control panel. Verify that the tray is configured correctly for the paper type and size. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Follow the instructions on the control panel to clear the jam. Check for paper in all possible jam locations. 2. Verify that no doors are open. 3. Check the paper tray to make sure paper is loaded correctly. The paper guides should be adjusted to the correct size, and the tray should not be filled above the maximum fill marks or tabs. 4. Verify that the paper meets specifications for this printer. 5. Use a damp, lint-free cloth to clean the rollers in the appropriate tray. Replace rollers that are worn. 6. If the issue persists, open the Administration > Troubleshooting > Diagnostic Tests > Component Test menu, and perform the appropriate pickup/feed motor drive test. Replace the pickup assembly if the test fails. 7. Verify the sensors are functioning correctly. If the sensors fail the test, first verify that all connections on the DC controller are correctly seated. If possible, replace the sensor or assembly it is associated with. 8. If the sensors pass the test, look for blockage or damaged parts and replace any damaged parts. 9. If the error persists, elevate the case using the Standard Support Process.

13.00.00

Generic jam event code.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Check the printer for a paper jam. a. Open toner cartridge access and output door. b. Remove any paper present. c. Check all paper trays for jammed or wrinkled paper and remove as needed. 2. If the error persists, please contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Check the printer for a paper jam. Check all sensor locations and the complete paper path. 2. Use the Manual sensors test or Tray/Bin manual sensors test to isolate a faulty door switch or sensor. Recommended action for call-center agents and onsite technicians 37

3. Replace parts as needed.

13.00.EE

Unknown door open.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Make sure that all of the doors and covers are closed.

13.A2.D2

Tray 2 paper feed jam. This jam occurs when the paper does not reach the pre-feed sensor (SR11) in the designated amount of time after the start of paper pickup from Tray 2. This is a no-pick jam from tray 2.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Verify the customer has followed the on the steps control panel for clearing the jam. 2. Open Tray 2, then remove any jammed paper, and then close the tray. 3. Open and close the upper TOP cover to allow the printer to attempt to clear the jam. 4. Remove the paper from the tray and check that the paper tray size guides are properly set and that the tray is not over filled with paper. Figure 6-2 Paper Tray guides 38 Chapter 6 Numerical control panel messages

Figure 6-3 Paper Tray overfill guide 5. Make sure that the Tray 2 pickup, feed, and separation roller are installed correctly and show no damage or wear. 6. Clean or replace the pickup and/or feed rollers as needed. Use a damp, lint-free cloth to gently clean the rollers. Part number: F2A68-67913 7. Verify that the paper in use meets the printer's specifications. 8. If the error persists, please contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Verify the customer has followed the steps control panel for clearing the jam. 2. Open Tray 2, then remove any jammed paper, and then close the tray. 3. Open and close the upper top cover to allow the printer to attempt to clear the jam. Recommended action for call-center agents and onsite technicians 39

4. Remove the paper from the tray and check that the paper tray size guides are properly set and that the tray is not over filled with paper. Figure 6-4 Paper Tray guides Figure 6-5 Paper Tray overfill guide 5. Make sure that the Tray 2 pickup, feed, and separation roller are installed correctly and show no damage or wear. 6. Clean or replace the pickup and/or feed rollers as needed. Use a damp, lint-free cloth to gently clean the rollers. Part number: F2A68-67913 7. Verify that the paper in use meets the printer's specifications. 8. Open the following menus: ● Administration ● Troubleshooting 40 Chapter 6 Numerical control panel messages

● Diagnostic Tests 9. Run the Tray 2 pickup/feed motor drive test to verify that the feed motor is functioning correctly. If it is not, replace the pickup assembly. 10. Test SR11 using the Tray/Bin Manual sensor test to verify that the sensor is functioning correctly. 11. If SR11 fails the

test, elevate the issue using the Standard Support Process for a possible printer replacement. NOTE: On-site technicians should check the following connections on the DC Controller before elevating the issue. (J157–SR11) (J110 and J144 — Tray 2 feed drive assy and solenoid) 13.Ax.Dz Optional tray paper feed jam. This jam occurs when the paper does not reach the tray pre-feed sensor PS432 for trays 3–5 in the designated amount of time after the start of paper pickup from Tray. This is a no-pick jam from the specified tray. X = The tray feed sensor where the jam occurred. Z = The tray being used to print the job. ● 13.A3.D3, 13.A3.D4, 13.A3.D5 = Tray 3: Paper did not reach Tray 3 paper Feed Sensor (PS432) when pulling from Tray 3-5 ● 13.A4.D4, 13.A4.D5 = Tray 4: Paper did not reach Tray 4 paper Feed Sensor (PS432) when pulling from Tray 4-5 ● 13.A5.D5 = Tray 5 Paper did not reach Tray 5 paper Feed Sensor (PS432) when pulling from Tray 5

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Verify that the customer has followed the on the steps control panel for clearing the jam. 2. Open and close the upper TOP cover to allow the printer to attempt to clear the jam. 3. Open the specified tray then remove any jammed paper. Remove the paper from the tray and check that the paper tray size guides are properly set and that the tray is not over filled with paper. 13.Ax.Dz 41

Figure 6-6 Paper Tray guides Figure 6-7 Paper Tray overfill guide 4. Make sure that the tray pickup, feed, and separation rollers are installed correctly and show no damage or wear. 5. Clean or replace the pickup and/or feed rollers as needed. Part number: F2A68-67913 Use a damp, lint-free cloth to gently clean the rollers. 6. Verify that the paper in use meets the printer's specifications. 7. If the error persists, please contact customer support. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Verify that the customer has followed the on the steps control panel for clearing the jam. 2. Open and close the upper TOP cover to allow the printer to attempt to clear the jam. 42 Chapter 6 Numerical control panel messages

3. Open the specified tray then remove any jammed paper. Remove the paper from the tray and check that the paper tray size guides are properly set and that the tray is not over filled with paper. Figure 6-8 Paper Tray guides Figure 6-9 Paper Tray overfill guide 4. Make sure that the tray pickup, feed, and separation rollers are installed correctly and show no damage or wear. 5. Clean or replace the pickup and/or feed rollers as needed. Part number: F2A68-67913 Use a damp, lint-free cloth to gently clean the rollers. 6. Verify that the paper in use meets the printer's specifications. 7. Open the following menus: ● Administration Recommended action for call-center agents and onsite technicians 43 ● Troubleshooting ● Diagnostic Tests 8. Run the tray pickup/feed motor drive test to verify that the feed motor is functioning correctly. If it is not, replace the pickup assembly. 9. Test all PS432 sensors in the HCI using the Tray/Bin Manual sensor test to verify that the sensors are functioning correctly. 10. If either of the previous steps fail, elevate the issue using the Standard Support Process for a possible printer replacement. NOTE: On-site technicians should check ALL the connections on the Paper Feed Controller PCA before elevating the issue.

13.A2.FF

Residual paper Jam in Tray 2. This jam occurs when residual paper is detected at the Tray 2 feed sensor (SR11).

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Make sure to follow the steps on the control panel on how to clear the jam. 2. Open Tray 2, remove any jammed paper, and then close the tray. 3. Open and close the upper right door to allow the printer to attempt to clear the jam. 4. Remove the paper from the specified tray and check that the paper tray size guides are set correctly and that the tray is not overfilled with paper. Figure 6-10 Paper Tray guides 44 Chapter 6 Numerical control panel messages

Figure 6-11 Paper Tray overfill guide 5. Make sure that the Tray 2 pickup, feed, and separation rollers are installed correctly and show no damage or wear. 6. Clean or replace the pickup and/or feed rollers as needed. Part number: F2A68-67913 Use a damp, lint-free cloth to gently clean the rollers. 7. Verify that the paper in use meets the printer's specifications. 8. If the error persists, contact customer support. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Open Tray 2, remove any jammed paper, and then close the tray. 2. Open and close the upper right door to allow the printer to attempt to clear the jam. Recommended action for call-center agents and onsite technicians 45

3. Remove the paper from the tray and check that the paper tray size guides are set correctly and that the tray is not overfilled with paper. Figure 6-12 Paper Tray guides Figure 6-13 Paper Tray overfill guide 4. Make sure that the Tray 2 pickup, feed, and separation rollers are installed correctly and show no damage or wear. 5. Clean or replace the pickup and/or feed rollers as needed. Part number: F2A68-67913 Use a damp, lint-free cloth to gently clean the rollers. 6. Check the connectors at the sensor, feed motor, and the DC controller PCA. 7. Open the following menus: ● Administration ● Troubleshooting 46 Chapter 6 Numerical control panel messages

● Diagnostic Tests 8. Test SR11 using the Tray/Bin Manual sensor test to verify that the sensors are functioning correctly. 9. Run the Tray 2 pickup/feed motor drive test to verify that the feed motor is functioning correctly (listen for the motor to activate). If it is not, replace the pickup assembly. 10. If either of the previous steps fail, elevate the issue using the Standard Support Process for a possible printer replacement. NOTE: On-site technicians should check the following connections on the DC Controller before elevating the issue. (J157–SR11) (J110 and J144) — Tray 2 feed drive assembly and solenoid.

13.A3.FF

Residual paper Jam in Tray 3. This jam occurs when residual paper is detected at the Tray 3 feed sensor (PS432).

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Make sure to follow the steps on the control panel on how to clear the jam. 2. Open the tray specified on the control panel, remove any jammed paper, and then close the tray. 3. Open and close the upper right door to allow the printer to attempt to clear the jam. 4. Remove the paper from the specified tray and check that the paper tray size guides are set correctly and that the tray is not overfilled with paper. Figure 6-14 Paper Tray guides

13.A3.FF 47

Figure 6-15 Paper Tray overfill guide 5. Make sure that the specified tray pickup, feed, and separation rollers are installed correctly and show no damage or wear. 6. Clean or replace the pickup and/or feed rollers as needed. Part number: F2A68-67913 Use a damp, lint-free cloth to gently clean the rollers. 7. Verify that the paper in use meets the printer's specifications. 8. If the error persists, contact customer support. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Open Tray 4, remove any jammed paper, and then close the tray. 2. Open and close the upper right door to allow the printer to attempt to clear the jam. 48 Chapter 6 Numerical control panel messages

3. Remove the paper from the tray and check that the paper tray size guides are properly set and that the tray is not over filled with paper. Figure 6-16 Paper Tray guides Figure 6-17 4. Make sure that the Tray 4 pickup, feed, and separation roller are installed correctly and show no damage or wear. 5. Clean or replace the pickup and/or feed rollers as needed. Part number: F2A68-67913 Use a damp, lint-free cloth to gently clean the rollers. 6. Check the connectors at the sensor, feed motor, and the DC controller PCA. 7. Open the following menus: ● Administration ● Troubleshooting Recommended action for call-center agents and onsite technicians 49

● Diagnostic Tests 8. Test PS432 using the Tray/Bin Manual sensor test to verify that the sensor is functioning correctly. 9. Run the Tray 4 pickup/feed motor drive test to verify that the feed motor is functioning correctly (listen for the motor to activate). If it is not, replace the optional paper feeder assembly. 10. If either of the previous steps fail, elevate the issue to HP for a possible printer replacement. NOTE: On-site technicians should check ALL connections on the Paper feed controller PCA before elevating the issue.

13.A5.FF

Residual paper jam in Tray 5. This jam occurs when residual paper is detected at the Tray 5 feed sensor (PS432).

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Make sure to follow the steps on the control panel on how to clear the jam. 2. Open the tray specified on the control panel, remove any jammed paper, and then close the tray. 3. Open and close the upper right door to allow the printer to attempt to clear the jam. 4. Remove the paper from the specified tray and check that the paper tray size guides are set correctly and that the tray is not overfilled with paper. Figure 6-18 Paper Tray guides 50 Chapter 6 Numerical control panel messages

Figure 6-19 Paper Tray overfill guide 5. Make sure that the specified tray pickup, feed, and separation rollers are installed correctly and show no damage or wear. 6. Clean or replace the pickup and/or feed rollers as needed. Part number: F2A68-67913 Use a damp, lint-free cloth to gently clean the rollers. 7. Verify that the paper in use meets the printer's specifications. 8. If the error persists, contact customer support. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Open Tray 5, remove any jammed paper, and then close the tray. 2. Open and close the upper right door to allow the printer to attempt to clear the jam. Recommended action for call-center agents and onsite technicians 51

3. Remove the paper from the tray and check that the paper tray size guides are properly set and that the tray is not over filled with paper. Figure 6-20 Paper Tray guides Figure 6-21 Paper Tray overfill guide 4. Make sure that the Tray 5 pickup, feed, and separation roller are installed correctly and show no damage or wear. 5. Clean or replace the pickup and/or feed rollers as needed. Part number: F2A68-67913 Use a damp, lint-free cloth to gently clean the rollers. 6. Check the connectors at the sensor, feed motor, and the DC controller PCA. 7. Open the following menus: ● Administration ● Troubleshooting 52 Chapter 6 Numerical control panel messages

● Diagnostic Tests 8. Test PS432 using the Tray/Bin Manual sensor test to verify that the sensors are functioning correctly. 9. Run the Tray 5 pickup/feed motor drive test to verify that the feed motor is functioning correctly (listen for the motor to activate). If it is not, replace the optional paper feeder assembly. 10. If either of the previous steps fail, elevate the issue using the Standard Support Process for a possible printer replacement. NOTE: On-site technicians should check ALL connections on the Paper feed controller PCA before elevating the issue.

13.B2.Az Jam in top cover Paper STAY jam in the top cover at the image area. Paper present at SR2 after a specified time limit has passed.

● 13.B2.A1

This jam occurs when the registration sensor (SR2) detects paper present longer than the expected time based on the paper size when printing from the Tray 1.

● 13.B2.A2

This jam occurs when the registration sensor (SR2) detects paper present longer than the expected time based on the paper size when printing from the Tray 2.

● 13.B2.A3

This jam occurs when the registration sensor (SR2) detects paper present longer than the expected time based on the paper size when printing from the Tray 3.

● 13.B2.A4

This jam occurs when the registration sensor (SR2) detects paper present longer than the expected time based on the paper size when printing from the Tray 4.

● 13.B2.A5

This jam occurs when the registration sensor (SR2) detects paper present longer than the expected time based on the paper size when printing from the Tray 5.

● 13.B2.AD

This jam occurs when the registration sensor (SR2) detects paper present longer than the expected time based on the paper size when printing from the Duplexer.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Open the top cover and check for paper jammed in the feed area. 2. Ensure that the paper being printed on is not glossy paper. Glossy paper is not supported on this printer and will cause this issue. 13.B2.Az Jam in top cover 53

3. Verify that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. Figure 6-22 Paper Tray guides Figure 6-23 Paper Tray overfill guide 4. Ensure the type and quality of the paper that the customer is using meet HP specifications. 5. Check under the toner cartridge at the transfer area, make sure everything is properly seated and that there are no damaged parts. 6. If the error persists, please contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Open the top cover and check for paper jammed in the feed area. 2. Ensure the customer is not trying to print on glossy paper. Glossy paper is not supported on this printer and will cause this issue. 54 Chapter 6 Numerical control panel messages

3. Verify that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. 4. Ensure the type and quality of the paper that the customer is using meet HP specifications. 5. Check under the toner cartridge at the transfer area, make sure everything is properly seated and that there are no damaged parts. 6. Test the registration sensor (TOP sensor) (SR2) to ensure that it moves freely. 7. Open the following menus: ● Administration ● Troubleshooting ● Diagnostic Tests 8. Test the registration sensor (TOP sensor) (SR2) using the Tray/Bin manual sensor test to verify that the sensor is functioning correctly. 9. Test the paper width sensors SR1a and SR2b. 10. If either of the sensors steps fail, elevate the issue using the Standard Support Process for a possible printer replacement. NOTE: On-site technicians should check the following connections on the DC controller PCA to ensure they are properly seated and connected before elevating the issue. (J151, J110, J144) 11. If the sensors are functioning properly, run a few pages to check where the leading edge of the paper actually stops. 12. Test and check the registration assembly and look for damage, if it is faulty replace the registration assembly. Part Number (M501/M506/E50045/M527/E52545): RM2-5671-000CN Part Number (M507/E50145/M528/E52645): RM2-2577-000CN 13. Look for blockage or damaged parts that stops the paper from continuing on through the printer. Check the fuser, if the fuser or any other part is found to be defective replace the part. Table 6-14 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 14. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement. Recommended action for call-center agents and onsite technicians 55

13.B2.D1 Jam in top cover Paper delay jam in top cover at image area. Paper did not reach SR2 in specified time. Paper did not reach the registration sensor in the designated amount of time printing from Tray 1.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Open the top cover and check for paper jammed in the feed area. 2. Ensure the customer is not trying to print on glossy paper. Glossy paper is not supported on this printer and will cause this issue. 3. Verify that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. 4. Ensure the type and quality of the paper being used meets the HP specifications for the printer. 5. Check the page count of the printer. If it is above 100,000 pages replace the feed and separation rollers. Part Number: F2A68-67914 6. Check for worn or damaged tray feed and separation rollers, replace the rollers as needed. Part Number: F2A68-67914 7. If the error persists, please contact customer support. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Open the top cover and check for paper jammed in the feed area. 2. Ensure the customer is not trying to print on glossy paper. Glossy paper is not supported on this printer and will cause this issue. 3. Verify that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. 4. Ensure the type and quality of the paper that the customer is using meets the HP specifications for the printer. 5. Check the page count of the printer. If it is above 100,000 pages replace the feed and separation rollers. Part Number: F2A68-67914 6. Check for worn or damaged tray feed and separation rollers, replace the rollers as needed. Part Number: F2A68-67914 56 Chapter 6 Numerical control panel messages

7. Open the following menus: ● Administration ● Troubleshooting ● Diagnostic Tests 8. Test the top of page sensor (SR2) and the paper width sensors SR1a and SR2b. 9. If any of the sensors fail, elevate the issue using the Standard Support Process for a possible printer replacement. NOTE: On-site technicians should check the following connections on the DC controller PCA to ensure they are properly seated and connected before elevating the issue. (J151, J110, J144) 10. If the sensors are functioning properly, run a few pages to check where the leading edge of the paper actually stops. 11. Check that the registration assembly is functioning correctly, if not replace the registration assembly. Part Number (M501/M506/E50045/M527/E52545): RM2-5671-000CN Part Number (M507/E50145/M528/E52645): RM2-2577-000CN 12. Ask the customer if they hear a grinding or clunking noise when printing. If a noise is heard run the diagnostics on fuser and pickup motors.. a. Open the following menus: ● Administration ● Troubleshooting ● Diagnostic Tests b. Run the Component test for the fuser and the pickup motors. If either is grinding or clunking replace the main motor. Part number: RM2-8684-000CN 13.B2.Dz Jam in top cover Paper delay jam in top cover at image area. Paper did not reach SR2 in specified time.

● 13.B2.D2

Paper did not reach the Registration sensor in the designated amount of time printing from Tray 2.

● 13.B2.D3

Paper did not reach the Registration sensor in the designated amount of time printing from Tray 3.

● 13.B2.D4

Paper did not reach the Registration sensor in the designated amount of time printing from Tray 4. 13.B2.Dz Jam in top cover 57

● 13.B2.D5

Paper did not reach the Registration sensor in the designated amount of time printing from Tray 5.

● 13.B2.DD

Paper did not reach the Registration sensor in the designated amount of time printing duplexed.

Recommended action for customers

Follow these troubleshooting steps in the order presented. View this video for more information. How to Clear Paper Jams in the Toner-Cartridge Area for HP LaserJet Pro M501, Enterprise M50x, MFP/Flow M52x, Managed E50145, E52645 1. Press the top-cover-release button on the left side of the printer. Figure 6-24 Press the release button 2. Open the front door on the printer. 58 Chapter 6 Numerical control panel messages

3. Remove the toner cartridge. 4. Lift the jam-access cover and slowly remove any jammed paper. Be careful not to tear the paper. Recommended action for customers 59

5. Reinsert the toner cartridge. 6. Close the front door. 7. Verify that glossy paper is not being used. NOTE: Glossy paper is not supported on this printer and will cause this issue. Please see HP LaserJet Enterprise M506, MFP M527 - Supported paper sizes and types for more

information. 60 Chapter 6 Numerical control panel messages

8. Verify that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. NOTE: To print a Configuration Page from the front panel, select ReportsConfiguration/Status PagesConfiguration Page. 9. Ensure the type and quality of the paper being used meets the HP specifications for the printer. 10. Check the page count of the printer. If it is above 100,000 pages replace the feed and separation rollers. The page count is listed on the Configuration Page. Parts can be ordered at <https://parts.hp.com>. Trays 2X Roller Kit part number: RM2-5752-000CN 11. Check for worn or damaged tray feed and separation rollers or separation pad. Replace the rollers as needed. Parts can be ordered at <https://parts.hp.com>. Recommended action for customers 61

Trays 2X Roller Kit part number: RM2-5752-000CN 12. If the error persists, please contact customer support.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. View this video for more information. How to Clear Paper Jams in the Toner-Cartridge Area for HP LaserJet Pro M501, Enterprise M50x, MFP/Flow M52x, Managed E50145, E52645 1. Press the top-cover-release button on the left side of the printer. Figure 6-25 Press the release button 2. Open the front door on the printer. 62 Chapter 6 Numerical control panel messages

3. Remove the toner cartridge. 4. Lift the jam-access cover and slowly remove any jammed paper. Be careful not to tear the paper.

Recommended action for call-center agents 63

5. Reinsert the toner cartridge. 6. Close the front door. 7. Verify that glossy paper is not being used. NOTE: Glossy paper is not supported on this printer and will cause this issue. Please see HP LaserJet Enterprise M506, MFP M527 - Supported paper sizes and types for more information. 64 Chapter 6 Numerical control panel messages

8. Verify that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. NOTE: To print a Configuration Page from the front panel, select ReportsConfiguration/Status PagesConfiguration Page. 9. Ensure the type and quality of the paper being used meets the HP specifications for the printer. 10. Check the page count of the printer. If it is above 100,000 pages replace the feed and separation rollers. The page count is listed on the Configuration Page. Parts can be ordered at <https://parts.hp.com>. Trays 2X Roller Kit part number: RM2-5752-000CN 11. Check for worn or damaged tray feed and separation rollers or separation pad. Replace the rollers as needed. Parts can be ordered at <https://parts.hp.com>. Recommended action for call-center agents 65

Trays 2X Roller Kit part number: RM2-5752-000CN

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. View this video for more information. How to Clear Paper Jams in the Toner-Cartridge Area for HP LaserJet Pro M501, Enterprise M50x, MFP/Flow M52x, Managed E50145, E52645 1. Open the top cover and check for paper jammed in the feed area. 2. Ensure the customer is not trying to print on glossy paper. Glossy paper is not supported on this printer and will cause this issue. 3. Verify that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. 4. Ensure the type and quality of the paper that the customer is using meets the HP specifications for the printer. 5. Check the page count of the printer. If it is above 100,000 pages replace the feed and separation rollers. Part Number: RM2-5752-000CN 6. Check for worn or damaged tray feed and separation rollers, replace the rollers as needed. Part Number: RM2-5752-000CN 7. Open the following menus: ● Administration ● Troubleshooting ● Diagnostic Tests 8. Test the top of page sensor (SR2) and the paper width sensors SR1a and SR2b. 9. If any of the sensors fail, elevate the issue using the Standard Support Process for a possible printer replacement. NOTE: On-site technicians should check the following connections on the DC controller PCA to ensure they are properly seated and connected before elevating the issue. (J151, J110, J144) 10. If the sensors are functioning properly, run a few pages to check where the leading edge of the paper actually stops. 11. Check that the registration assembly is functioning correctly, if not replace the registration assembly. Part Number (M501/M506/E50045/M527/E52545): RM2-5671-000CN Part Number (M507/E50145/M528/E52645): RM2-2577-000CN 12. Check for a grinding or clunking noise when printing. If a noise is heard run the diagnostics on fuser and pickup motors. Capture a sound clip of the noise and attach to the case. 66 Chapter 6 Numerical control panel messages

a. Open the following menus: ● Administration ● Troubleshooting ● Diagnostic Tests b. Run the Component test for the fuser and the pickup motors. If either is making a grinding or clunking sound, replace the main motor. Part number: RM2-9531-000CN 13.B2.E2 Jam in top cover Paper jam in top cover at image area due to door open.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Make sure that all of the doors and covers are closed and re-send the job. 2. If the error persists, please contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Make sure that all of the doors and covers are closed and re-send the job. 2. M527/M528 MFP All Models & M506/M507 Duplex Models - Ensure that the black plastic attached to the rear door is present. If it is broken or missing, replace the Rear Door Assembly. Figure 6-26 Rear Door Assembly Door, rear (M501/M506/E50045/M507/E50145 duplex models) : RM2-5711-000CN Door, rear (M501/M506/E50045/M507/E50145 simplex models): RM2-5712-000CN Door, rear (M527/E52545/M528/E52645) : RM2-5711-000CN For Instructions: See the Repair Service Manual for this product. 3. If all doors are closed and message still persists, Test SW2 top cover open detection switch using the diagnostic tests. 13.B2.E2 Jam in top cover 67

4. If the sensor fails the test, elevate the issue using the Standard Support Process for a possible printer replacement. NOTE: On-site technicians should check the following connections on the DC controller PCA to ensure they are properly seated and connected before elevating the issue. (J151, J110, J144) 13.B2.FF Jam in top cover Paper residual jam in top cover at image area. Paper present at SR2 at power on or after clearing jam.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Open the top cover and check for paper jammed in feed area. 2. Check under the toner cartridge at the transfer area for any paper or obstructions. 3. If the error persists, please contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Open the top cover and check for paper jammed in feed area. 2. Check under the toner cartridge at the transfer area, make sure that everything is properly seated. 3. Test the top of page sensor (SR2). 4. If the sensor fails the test, elevate the issue using the Standard Support Process for a possible printer replacement. NOTE: On-site technicians should check the following connections on the DC controller PCA to ensure they are properly seated and connected before elevating the issue. (J151, J110, J144) 13.B9.Az Fuser jam Fuser delivery stay jam. Paper stay jam at fuser area. Paper present at SR13 after specified time limit. This jam code can be caused by: ● An accordion paper jam at the fuser exit. ● Something blocking the paper before reaching the output rollers. ● The output bin rollers are not turning. Because there is very little distance from the fuser exit to the output bin, paper stopped at the rollers can cause a fuser jam. ● A sticky fuser exit flag. If the flag is stuck or even delayed momentarily in the activated position, it can cause this jam. 68 Chapter 6 Numerical control panel messages

● When multiple pages are set for duplex printing, the Duplex paper delivery assembly component might also cause this error.

● 13.B9.A1

Paper Stay jam is detected when printing from Tray 1.

● 13.B9.A2

Paper Stay jam is detected when printing from Tray 2.

● 13.B9.A3

Paper Stay jam is detected when printing from Tray 3.

● 13.B9.A4

Paper Stay jam is detected when printing from Tray 4.

● 13.B9.A5

Paper Stay jam is detected when printing from Tray 5.

● 13.B9.AD

Paper Stay jam is detected when printing from the Duplexer.

Recommended action for customers

Follow these troubleshooting steps in the order presented. CAUTION: Be careful: the fuser is HOT. Allow it to cool if you need to remove debris from in and around the pressure heating components. 1. Open the top and rear covers and then clear any jammed paper. 2. Ensure that the paper meets HP printer specifications. 3. Make sure that the paper being printed on is not a glossy paper. Glossy paper is not supported on this printer and will cause this issue. Recommended action for customers 69

4. Verify that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. Figure 6-27 Paper Tray guides Figure 6-28 Paper Tray overfill guide 5. Verify in which of the following conditions a duplex print job causes a jam for all jobs: (Duplex print job or Duplex printing means the printer supports printing on both sides of a paper.) ● When using a single page for duplex printing. or ● When multiple pages are set for duplex printing. 6. Remove the toner cartridge and open the rear door and verify that there is no debris from a previous jam stuck in the fuser or the rollers leading into or out of the fuser. 7. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. 70 Chapter 6 Numerical control panel messages

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. CAUTION: Be careful: the fuser is HOT. Allow it to cool if you need to remove debris from in and around the pressure heating components. 1. Open the top and rear covers and then clear any jammed paper. 2. Ensure sure that the paper meets HP printer specifications. 3. Ensure the customer is not trying to print on glossy paper. Glossy paper is not supported on this printer and will cause this issue. 4. Ensure that the customer has verified that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. 5. Identify if the jam occurs during duplex print jobs (or duplex printing). 6. Check if the jam occurs when multiple sheets of paper are set for duplex printing. 7. If the paper jam occurs for multiple page duplex jobs, replace the duplex paper delivery assembly for M527/M528 MFP All Models and M506/M507 Duplex Models. ● Part number for Duplex paper delivery assembly: RM2-5683-000CN ● For instructions to remove and replace a part, refer the Service Repair manual: pdf_584095_en-US-6.pdf 8. Check if the error persists after replacing the duplex paper assembly ● If

the error does not persist, there is no need to continue troubleshooting. ● If the error persists, see the next step. 9. Check the fuser delivery sensor for proper functionality and movement. 10. Remove the toner cartridge and open the rear door and verify that there is no debris from a previous jam stuck in the fuser or the rollers leading into or out of the fuser. 11. Confirm the output bin rollers are turning. Recommended action for call-center agents and onsite technicians 71

12. For M527/M528 MFP All Models and M506/M507 Duplex Models - Ensure that the black plastic attached to the rear door is present. If it is broken or missing, replace the rear door assembly. Figure 6-29 Rear Door Assembly Door, rear (M501/M506/E50045/M507/E50145 duplex models) : RM2-5711-000CN Door, rear (M501/M506/E50045/M507/E50145 simplex models): RM2-5712-000CN Door, rear (M527/E52545/M528/E52645) : RM2-5711-000CN For Instructions: , refer the Repair Service Manual for this product. 13. Perform a Manual Sensor Test and check SR13 the fuser delivery sensor. If found faulty then replace the fuser assembly. Table 6-15 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN For instructions : , see the Repair Service Manual for this product. 13.B9.Bz Fuser Jam A multifeed jam has occurred ion the fuser.

● 13.B9.B1

Paper multifeed jam is detected when printing from Tray 1.

● 13.B9.B2

Paper multifeed jam is detected when printing from Tray 2.

● 13.B9.B3

72 Chapter 6 Numerical control panel messages

Paper multifeed jam is detected when printing from Tray 3.

● 13.B9.B4

Paper multifeed jam is detected when printing from Tray 4.

● 13.B9.B5

Paper multifeed jam is detected when printing from Tray 5.

Recommended action for customers

Follow these troubleshooting steps in the order presented. CAUTION: Be careful: the fuser is HOT. Allow it to cool if you need to remove debris from in and around the pressure heating components. 1. Open the top and rear covers and then clear any jammed paper. 2. Ensure that the paper meets HP printer specifications. 3. Make sure that the paper being printed on is not a glossy paper. Glossy paper is not supported on this printer and will cause this issue. 4. Verify that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. Figure 6-30 Paper Tray guides Recommended action for customers 73

Figure 6-31 Paper Tray overfill guide 5. Remove the toner cartridge and open the rear door and verify that there is no debris from a previous jam stuck in the fuser or the rollers leading into or out of the fuser. 6. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians

Follow these troubleshooting steps in the order presented. CAUTION: Be careful: the fuser is HOT. Allow it to cool if you need to remove debris from in and around the pressure heating components. 1. Open the top and rear covers and then clear any jammed paper. 2. Ensure sure that the paper meets HP printer specifications. 3. Ensure the customer is not trying to print on glossy paper. Glossy paper is not supported on this printer and will cause this issue. 4. Ensure that the customer has verified that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. 5. Check the fuser delivery sensor for proper functionality and movement. 6. Remove the toner cartridge and open the rear door and verify that there is no debris from a previous jam stuck in the fuser or the rollers leading into or out of the fuser. 7. Confirm the output bin rollers are turning. 74 Chapter 6 Numerical control panel messages

8. For M527/M528 MFP All Models and M506/M507 Duplex Models - Ensure that the black plastic attached to the rear door is present. If it is broken or missing, replace the rear door assembly. Figure 6-32 Rear Door Assembly Door, rear (M501/M506/E50045/M507/E50145 duplex models) : RM2-5711-000CN Door, rear (M501/M506/E50045/M507/E50145 simplex models): RM2-5712-000CN Door, rear (M527/E52545/M528/E52645) : RM2-5711-000CN For Instructions: , refer the Repair Service Manual for this product. 9. Perform a Manual Sensor Test and check SR13 the fuser delivery sensor. If found faulty then replace the fuser assembly. Table 6-16 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN For instructions : , see the Repair Service Manual for this product. 13.B9.Cz Fuser wrap jam. This jam occurs when the paper disappears from the fuser output sensor before a designated amount of time after the paper reached the fuser output sensor (SR13). (The printer has determined that the paper is being wrapped around the fuser roller.) Z = Fuser mode ● 13.B9.C1 (event code) Fuser wrap jam when Auto Sense (Normal). 13.B9.Cz 75

● 13.B9.C2 (event code) Fuser wrap jam when Normal. ● 13.B9.C3 (event code) Fuser wrap jam when Light 1 or Light 2 (see event log secondary jam information for specific code). ● 13.B9.C4 (event code) Fuser wrap jam when Heavy 1. ● 13.B9.C5 (event code) Fuser wrap jam when Heavy 2. ● 13.B9.C6 (event code) Fuser wrap jam when Heavy paper 3. ● 13.B9.CB (event code) Fuser wrap jam when Transparency. ● 13.B9.CC (event code) Fuser wrap jam when Label. ● 13.B9.CD (event code) Fuser wrap jam when Envelope 1 or Envelope 2 (see event log secondary jam information for specific code).

Recommended action for customers

Follow these troubleshooting steps in the order presented. CAUTION: Be careful: the fuser is HOT. Allow it to cool if you need to remove debris from in and around the pressure heating components. 1. Open the top and rear covers and then clear any jammed paper. 2. Ensure that the paper meets HP printer specifications. 3. Make sure that the paper being printed on is not a glossy paper. Glossy paper is not supported on this printer and will cause this issue. 76 Chapter 6 Numerical control panel messages

4. Verify that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. Figure 6-33 Paper Tray guides Figure 6-34 Paper Tray overfill guide 5. Remove the toner cartridge and open the rear door and verify that there is no debris from a previous jam stuck in the fuser or the rollers leading into or out of the fuser. 6. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Open the top and rear covers and then clear any jammed paper. 2. Ensure sure that the paper meets HP printer specifications. If the customer paper is within specifications, but curls up on the output bin, you can recommend: ● Open input tray and rotate new paper so the top page is now the bottom page. Recommended action for call-center agents and onsite technicians 77

● Explain that the paper curls and it is better if it curls down than up for printing to avoid fuser wrap jams. 3. Check to see if the paper jam is found wrapped around the fuser roller. If so and the paper is within HP specifications for this printer replace the fuser assembly. Table 6-17 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 13.B9.Dz Fuser delivery delay jam. Paper did not reach Fuser sensor SR13 specified time.

● 13.B9.D1

Fuser delivery delay jam when printing from Tray 1.

● 13.B9.D2

Fuser delivery delay jam when printing from Tray 2.

● 13.B9.D3

Fuser delivery delay jam when printing from Tray 3.

● 13.B9.D4

Fuser delivery delay jam when printing from Tray 4.

● 13.B9.D5

Fuser delivery delay jam is detected when printing from Tray 5.

● 13.B9.DD

Fuser delivery delay jam when printing with the Duplexer. The following are possible causes and areas that should be investigated. ● The paper jam is found wrapped around the fuser roller. In this case it is a sign of a worn out fuser. ● The paper jam is found underneath the toner cartridge or in the transfer area. In this case it could be the drum drive or the white collar that holds the toner cartridge in position has broken or even a damaged or defective toner cartridge. ● Fuser drive or fuser delivery issue. 78 Chapter 6 Numerical control panel messages ● The Duplex paper delivery assembly component might also cause this error when multiple pages are set for duplex printing.

Recommended action for customers

Follow these troubleshooting steps in the order presented. CAUTION: Be careful: the fuser is HOT. Allow it to cool if you need to remove debris from in and around the pressure heating components. 1. Open the top and rear covers and then clear any jammed paper. 2. Ensure that the paper meets HP printer specifications. 3. Make sure that the paper being printed on is not a glossy paper. Glossy paper is not supported on this printer and will cause this issue. 4. Verify that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. Figure 6-35 Paper Tray guides Recommended action for customers 79

Figure 6-36 Paper Tray overfill guide 5. Verify in which of the following conditions a duplex print job causes a jam for all jobs: (Duplex print job or Duplex printing means the printer supports printing on both sides of a paper.) ● When using a single page for duplex printing. or ● When multiple pages are set for duplex printing. 6. Remove the toner cartridge and open the rear door and verify that there is no debris from a previous jam stuck in the fuser or the rollers leading into or out of the fuser. 7. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Determine where the jam is located. Follow these troubleshooting steps in the order presented. 1. Open the top cover and check under the toner cartridge for paper or debris. 2. Open the rear output bin and check for paper or obstructions. Paper stopped in the toner/transfer area (stopped before the fuser) Follow these troubleshooting steps in the order presented. 1. Open the top cover and check under the toner cartridge for paper or obstructions. 2. Ensure the toner cartridge and transfer roller are seated properly. If damaged replace the toner cartridge or the transfer roller. Transfer roller part number: RM2-2039-000CN 3. Check the toner cartridge guides and the transfer roller assembly, If either are damaged elevate the issue using the Standard Support Process for a possible printer replacement. 4. Inspect the white plastic collar that cradles the drum cartridge that is positioned around the drum drive gear. If the collar portion is broken and/or missing a section it will allow the cartridge to insert further than designed to and not allow the drum drive to engage with the toner cartridge. elevate the issue using the Standard Support Process for a

possible printer replacement. 80 Chapter 6 Numerical control panel messages

5. If the collar is not broken, test the main drive motor using the diagnostic test. If the test fails, elevate the issue using the Standard Support Process for a possible printer replacement.

Paper stopped in or at the fuser

Follow these troubleshooting steps in the order presented. CAUTION: Be careful: the fuser is HOT. Allow it to cool if you need to remove debris from in and around the pressure heating components. 1. Remove the fuser and inspect the fuser sleeve, pressure roller and the delivery roller for blockage and/or damage. Replace the fuser as needed. Table 6-18 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 2. Verify that the fuser inlet guide is not detached or broken. Replace the fuser as needed. 3. Open the following menus: ● Administration ● Troubleshooting ● Diagnostic Tests 4. Test the fuser delivery sensor (SR13) using the manual sensor test. Verify the sensor is functioning correctly. If it is not, replace the fuser. 5. Run the fuser motor drive test to verify that the fuser drive and gears are functioning correctly. If they are not, elevate the issue using the Standard Support Process for a possible printer replacement. Paper did not stop in the fuser or at the toner/transfer area Follow these troubleshooting steps in the order presented. 1. Check the paper path between the transfer area and the fuser. 2. If the paper has stopped in this area and will not progress beyond the feed-guide assembly clean the area and retest. If issue persists, elevate the issue using the Standard Support Process for a possible printer replacement.

Paper stopped after exiting the fuser

Follow these steps to resolve a 13.B2.D2 error. Paper stopped in or at the fuser 81

1. Open the top cover and check under the toner cartridge for paper or obstructions. 2. Ensure the toner cartridge and transfer roller are seated properly. If damaged replace the toner cartridge or the transfer roller. Transfer roller part number: RM2-2039-000CN 3. Check the toner cartridge guides and the transfer roller assembly, If either are damaged elevate the issue using the Standard Support Process for a possible printer replacement. 4. Identify if the jam occurs during duplex print jobs (or duplex printing). 5. Check if the jam occurs when multiple sheets of paper are set for duplex printing. 6. If the paper jam occurs for multiple page duplex jobs, replace the duplex paper delivery assembly for M527/M528 MFP All Models and M506/M507 Duplex Models. ● Part number for Duplex paper delivery assembly: RM2-5683-000CN ● For instructions to remove and replace a part, refer the Service Repair manual: pdf_584095_en-US-6.pdf 7. If the error persists after replacing the duplex paper assembly and if the printer is under warranty, elevate the issue using the Standard Support Process.

13.B9.FF

Residual paper jam at the fuser output sensor. Paper present at SR13 after specified time limit or on power up.

Recommended action for customers

Follow these troubleshooting steps in the order presented. CAUTION: Be careful: the fuser is HOT. Allow it to cool if you need to remove debris from in and around the pressure heating components. 1. Open the top and rear covers and then clear any jammed paper. 2. Ensure that the paper meets HP printer specifications. 3. Make sure that the paper being printed on is not a glossy paper. Glossy paper is not supported on this printer and will cause this issue. 82 Chapter 6 Numerical control panel messages

4. Verify that the tray guides have been set to the proper size and that the same size is reflected on the Configuration Page. Figure 6-37 Paper Tray guides Figure 6-38 Paper Tray overfill guide 5. Remove the toner cartridge and open the rear door and verify that there is no debris from a previous jam stuck in the fuser or the rollers leading into or out of the fuser. 6. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Open the top and rear cover and clear the jam in the indicated area. 2. Close the covers to allow the printer to attempt to clear the jam. 3. Verify the paper meets the HP specification for the printer. Recommended action for call-center agents and onsite technicians 83

4. Open the following menus: ● Administration ● Troubleshooting ● Diagnostic Tests 5. Test the fuser delivery sensor (SR13) using the manual sensor test. Verify the sensor is functioning correctly. If it is not, replace the fuser. Table 6-19 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 6. Run the fuser motor drive test to verify that the fuser drive and gears are functioning correctly. If they are not, elevate the issue using the Standard Support Process for a possible printer replacement. 7. Remove the fuser and inspect the fuser sleeve, pressure roller, and delivery roller for blockage and/or damage. Replace the fuser as needed. Table 6-20 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN For instructions: See the Repair Service Manual for this product. 13.D3.yz The paper jammed while attempting to duplex.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Make sure that the customer is using a HP genuine cartridge. Retest with another working or new cartridge. 84 Chapter 6 Numerical control panel messages

2. Verify the media meets HP specification for the printer. NOTE: Glossy Media is NOT supported on this printer. 3. Perform the continuous test in simplex mode at least 50 pages to make sure that issue is occurring while printing duplex printing only. 4. Send duplex jobs from multiple trays to see if the issue is TRAY specific or not. If the jam occurs from a specific tray, troubleshoot pick and feed issues for that tray. 5. Make sure the tray is set-up correctly through the control panel. If the tray is set to ANY Size ANY Type, set it to the specific size and type the customer is trying to print on. 6. Check and clean the status charge eliminator; it is located next to the transfer roller. 7. Ensure all the connections to the duplexer on the DC controller are properly seated, but DO NOT replace the DC controller. 8. Ensure that the black plastic guide attached to the rear door assembly is present. If it is broken or missing, replace the rear door assembly. Part number: RM2-5726-000CN 9. If the issue persists, elevate the issue using the Standard Support Process.

13.D3.FF

Power on jam, duplex refeed sensor. A residual jam is detected at the duplex refeed sensor at power on or after clearing printer.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Go to the following support document and follow the instructions: HP LaserJet Enterprise MFP M527 - 13.D3 jam error in the duplexer. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

13.D3.FF 85

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Troubleshoot the error by following the instructions in this document: HP LaserJet Enterprise MFP M527 - 13.D3 jam error in the duplexer. 3. Ensure that the duplex refeed sensor moves freely. If the printer has been turned on its side or service performed the sensor flag could have become dislodged causing the power on jam. a. Remove tray 2 (cassette tray) from the printer. b. Press on the green latch on the right side of the roller to release the duplex pan. c. Check if the lever behind the roller is not stuck and can move freely. Figure 6-39 Duplex refeed sensor 4. If the error persists, dispatch a service technician to clean the sensor correctly. NOTE: The sensor cannot be replaced.

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Ensure that the duplex refeed sensor moves freely. NOTE: If the printer has been turned on its side or service performed, the sensor flag could be dislodged causing the power on jam. a. Remove tray 2 (cassette tray) from the printer. b. Turn the printer on to its side to view the tray pick/feed area and duplex sensor. 86 Chapter 6 Numerical control panel messages

c. Ensure the duplex refeed sensor moves freely and is not dislodged. Figure 6-40 Duplex refeed sensor d. If the sensor is adjusted, test the printer to verify functionality. 2. If the sensor moves freely, check connector J141 on the DC Controller to ensure it is seated correctly and not damaged. 3. If the error persists, clean the sensor using a small clean swab or blow air carefully to remove any dust particles. NOTE: Paper and toner dust might block the sensor windows. 4. If the error persists, replace the DC Controller. Use the following table to order the correct part number for simplex or duplex printer models. Table 6-21 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

For instructions: See the Repair Service Manual for this product. Recommended action for onsite technicians 87

5. If the error persists after replacing the DC Controller, follow the standard process to escalate the error.

13.E5.FF

A power on jam has occurred.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Check the printer for a paper jam. Check all the sensor locations and the complete paper path. 2. Use the manual sensors test or Tray/Bin manual sensors test to isolate a faulty door switch or sensor.

13.EA.FF

A door jam has occurred.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Check the printer for a paper jam. Check all the sensor locations and the complete paper path. 2. Use the manual sensors test or Tray/Bin manual sensors test to isolate a faulty door switch or sensor.

13.FF.EE

A power on jam has occurred.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Check the printer for a paper jam. Check all the sensor locations and the complete paper path. 2. Use the manual sensors test or Tray/Bin manual sensors test to isolate a faulty door switch or sensor.

13.EE.FF

A door jam has occurred.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Check the printer for a paper jam. Check all the sensor locations and the complete paper path. 2. Use the manual sensors test or Tray/Bin manual sensors test to isolate a faulty door switch or sensor.

13.FF.FF

A power on residual paper jam has occurred. 88 Chapter 6 Numerical control panel messages

This error has no specific sensor designated. It could be any sensor in the paper feed path.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Check the printer for a paper jam. 2. Look for paper present or obstructions in the paper path. View the event log to determine if other jam errors are occurring and troubleshoot those errors. 3. Use the manual sensors test or Tray/Bin manual sensors test to isolate a faulty door switch or sensor. 4. Replace parts as determined by sensor tests or obstructions. If sensor can not be replaced, elevate the issue for a possible printer replacement. 20.XX.YZ error messages 20.* errors Errors in the 20.* family are related to the printer memory. The page might require more memory than the printer has available.

Recommended action

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, contact your HP-authorized service or support provider, or contact HP support at www.hp.com/go/contactHP. 1. Touch the OK button to continue. 2. Reduce the page complexity. 3. Add product memory.

20.00.00 Insufficient memory <device>

The printer does not have enough memory to print the page. Event log message 20.00.00. The printer received more data than can fit in the available memory. You might have tried to transfer too many macros, soft fonts, or complex graphics.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to print the transferred data. Some data might be lost. Reduce the page complexity or add printer memory. Recommended action 89

21.XX.YZ error messages

21.00.00 Page Too ComplexEvent log error message 21.00.00

The printer displays this message to indicate that the page decompression process was too slow for the printer.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to continue. There might be some data loss on the page that was being formatted when the error occurred. 30.XX.YZ error messages 30.* errors Errors in the 30.* family are related to the flatbed scanner.

Recommended action

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, contact your HP-authorized service or support provider, or contact HP support at www.hp.com/go/contactHP. 1. Calibrate the scanner. Open these menus: Device Maintenance > Calibrate-Cleaning > Calibrate Scanner. 2. Clean the scanner glass and glass strips. 3. Perform the tests for scanner diagnostics. Open these menus: Administration > Troubleshooting > Diagnostic Tests > Scanner Tests. 4. Upgrade the firmware. For the latest firmware versions, go to HP FutureSmart - Latest Firmware Versions 5. Check all connections on the scanner control board and from the scanner control board to the formatter and the DC controller or the engine control board. If all connections are good, replace the scanner control board. 6. Replace the formatter. 7. If the error persists, replace the scanner assembly.

30.01.01

The flatbed cover sensor was interrupted. The scanner flatbed cover is open. This message appears only in the event log and is not posted on the control panel. The control panel will read Flatbed Cover Open. 90 Chapter 6 Numerical control panel messages

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. NOTE: This error message should automatically clear. 1. If the error message reoccurs or will not clear from the control panel, check the sensor in the flatbed assembly is damaged or stuck. 2. Access the Manual Sensor Test on the printer control panel to verify the functionality of the Flatbed cover sensor. a. From the Home screen on the control panel, scroll to and touch Administration (FutureSmart 3 firmware) or Support Tools (FutureSmart 4 firmware). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following menus: Troubleshooting > Diagnostics > Manual Sensor Test . Recommended action for customers 91

c. Select Flatbed cover. Figure 6-41 Flatbed cover option in Manual Sensor Test menu on the printer control panel d. Open and close the flatbed cover. NOTE: The Flatbed cover sensor counter under the sensor name should increment by one (from "0" to "1", for example) each time the cover is opened or closed. e. Check the control panel display to verify the sensor is activated and incremented by one each time you open and close the flatbed cover. 3. If the flatbed cover sensor is not activated/triggered and the counter is not incremented, replace the image scanner assembly. Table 6-22 Kit-Image Scanner Whole Unit (Image scanner assembly) part number

Part description Part number

Image scanner assembly (includes white backing and retention clips)

F2A76-67914

For instructions: See the Repair Service Manual for this product.

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. NOTE: This error message should automatically clear. 92 Chapter 6 Numerical control panel messages

1. If the error message reoccurs or will not clear from the control panel, check the sensor in the flatbed assembly is damaged or stuck. 2. To verify if the flatbed cover sensor is damaged and to check the functionality of the sensor, access the Manual Sensor Test on the printer control panel. a. From the Home screen on the control panel, scroll to and touch Administration (FutureSmart 3 firmware) or Support Tools (FutureSmart 4 firmware). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following menus: Troubleshooting > Diagnostics > Manual Sensor Test . c. Select Flatbed cover. Figure 6-42 Flatbed cover option in Manual Sensor Test menu on the printer control panel d. Open and close the flatbed cover. NOTE: The Flatbed cover sensor counter under the sensor name should increment by one (from "0" to "1", for example) each time the cover is opened or closed. e. Check the control panel display to verify the sensor is activated and incremented by one each time you open and close the flatbed cover. Recommended action for onsite technicians 93
3. If the flatbed cover sensor is not activated/triggered and the counter is not incremented, replace the image scanner assembly. Table 6-23 Kit-Image Scanner Whole Unit (Image scanner assembly) part number

Part description Part number

Image scanner assembly (includes white backing and retention clips)

F2A76-67914

For instructions: See the Repair Service Manual for this product. 4. If the error persists, check the cables on the scanner control board (SCB) for loose connections. Attempt to disconnect and reconnect all the cables on the SCB. Figure 6-43 Scanner control board (SCB) connections Table 6-24 Scanner control board (SCB) connections callout descriptions

Callout Description

1 Staple power

2 SCB power (24v) 3 Cable, PAB to SCAM communication (HDMI) 4 Flatbed sensors (Document feeder open and flatbed paper length-and cave LED) 5 Flatbed (S1) flat flexible cable (scanner data and flatbed motor) 6 Document feeder (S2) flat flexible cable (Scanner data) 94 Chapter 6 Numerical control panel messages

Table 6-24 Scanner control board (SCB) connections callout descriptions (continued)

Callout Description

7 Document feeder motors (Feed and deskew) 8 Document feeder sensors (Prescan, Paper present receiver and top hatch)

9 Document feeder ultra sonic sensor receiver and deskew

sensor 10 Letter/Legal (LTR/LGL) Input tray sensor

11 Ultra sonic sensor transmitter

5. Ensure that all the cables on the SCB are connected and seated correctly before replacing any part. 6. If the error persists, replace the scanner control board (SCB). Table 6-25 Scanner control board assembly part number

Part description Part number

Scan control PC board assembly part number B5L47-67903 For instructions: See the Repair Service Manual for this product.

30.01.08 Home position error

The scanner optic failed to return to the home position.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Print a Configuration Page to check if the latest version of the printer firmware is installed. If the latest printer firmware version is not installed, update the firmware. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 3. Observe the movement of the optics assembly. 4.

If the error persists (optics assembly fails to move correctly) after the firmware update, perform a Continuous Scan diagnostic test using the printer control panel to test the functionality of the scan optics.

30.01.08 Home position error 95

a. From the Home screen on the control panel, scroll to and touch Support Tools (FutureSmart 4 firmware). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following menus: Troubleshooting > Diagnostic Tests. c. Select Continuous Scan. Figure 6-44 Continuous Scan option in the Diagnostic Tests menu 96 Chapter 6 Numerical control panel messages

d. Select Start to run the test. Figure 6-45 Start the Continuous Scan test e. Check if the scan head moves from the home position through the scan, and back to the home position. NOTE: The scan head should actuate, moving from the home position through a scan, and back to the home position. This process will repeat until interrupted. 5. If the scan head does not actuate or operate correctly, replace the image scanner assembly (ISA). Table 6-26 Kit-Image Scanner Whole Unit (Image scanner assembly) part number

Part description Part number

Image scanner assembly (includes white backing and retention clips)

F2A76-67914

For instructions: See the Repair Service Manual for this product.

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Print a Configuration Page to check if the latest version of the printer firmware is installed. If the latest printer firmware version is not installed, update the firmware. Recommended action for onsite technicians 97

For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 3. Observe the movement of the optics assembly. 4. If the error persists (optics assembly fails to move correctly) after the firmware update, perform a Continuous Scan diagnostic test using the printer control panel to test the functionality of the scan optics. a. From the Home screen on the control panel, scroll to and touch Support Tools (FutureSmart 4 firmware). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following menus: Troubleshooting > Diagnostic Tests. c. Select Continuous Scan. Figure 6-46 Continuous Scan option in the Diagnostic Tests menu 98 Chapter 6 Numerical control panel messages

d. Select Start to run the test. Figure 6-47 Start the Continuous Scan test e. Check if the scan head moves from the home position through the scan, and back to the home position. NOTE: The scan head should actuate, moving from the home position through a scan, and back to the home position. This process will repeat until interrupted. 5. If the scan head does not actuate or operate correctly, remove and reconnect all the cables on the scanner control board (SCB). Recommended action for onsite technicians 99

6. Ensure that all the cables on the SCB are connected and seated correctly before replacing any part. Figure 6-48 Scanner control board (SCB) connections Table 6-27 Scanner control board (SCB) connections callout descriptions

Callout Description

1 Staple power

2 SCB power (24v) 3 Cable, PAB to SCAM communication (HDMI) 4 Flatbed sensors (Document feeder open and flatbed paper length-and cave LED) 5 Flatbed (S1) flat flexible cable (scanner data and flatbed motor) 6 Document feeder (S2) flat flexible cable (Scanner data) 7 Document feeder motors (Feed and deskew) 8 Document feeder sensors (Prescan, Paper present receiver and top hatch)

9 Document feeder ultra sonic sensor receiver and deskew

sensor 10 Letter/Legal (LTR/LGL) Input tray sensor

11 Ultra sonic sensor transmitter

100 Chapter 6 Numerical control panel messages

7. If the error persists, replace the image scanner assembly (ISA). Table 6-28 Kit-Image Scanner Whole Unit (Image scanner assembly) part number

Part description Part number

Image scanner assembly (includes white backing and retention clips)

F2A76-67914

For instructions: See the Repair Service Manual for this product. 8. If the error persists after the SCB cables are connected correctly, replace the scanner control board (SCB). Table 6-29 Scanner control board assembly part number

Part description Part number

Scan control PC board assembly part number B5L47-67903 For instructions: See the Repair Service Manual for this product.

30.01.14 Scan system EEPROM error

Scanner control board (SCB) EEPROM error.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn off the printer, and then turn on the printer using the power button. 2. Print a Configuration Page to check if the latest version of the printer firmware is installed. If the latest printer firmware version is not installed, update the firmware. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 3. If the error persists, dispatch a service technician to replace the scanner control board (SCB). Table 6-30 Scanner control board assembly part number

Part description Part number

Scan control PC board assembly part number B5L47-67903

30.01.14 Scan system EEPROM error 101

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn off the printer, and then turn on the printer using the power button. 2. Print a Configuration Page to check if the latest version of the printer firmware is installed. If the latest printer firmware version is not installed, update the firmware. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 3. If the error persists, disconnect and reconnect all the cables on the scanner control board (SCB). 4. Ensure that all the cables on the SCB are connected and seated correctly before replacing any part. Figure 6-49 Scanner control board (SCB): Sensor connections Table 6-31 SCB sensor callout descriptions

Callout Description

1 Flatbed sensor/motor

2 Flatbed FFC

3 ADF sensor

4 ADF FFC

5 ADF Motor

5. If the error persists after the SCB cables are connected correctly, replace the scanner control board (SCB). Table 6-32 Scanner control board assembly part number

Part description Part number

Scan control PC board assembly part number B5L47-67903 For instructions: See the Repair Service Manual for this product. 102 Chapter 6 Numerical control panel messages

30.01.36 Upgrade error

Scanner control board (SCB) upgrade error.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, attempt to upgrade the firmware. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Update the printer firmware. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 3. If the error persists, dispatch a service technician with the following part to replace the scanner control board (SCB). Table 6-33 Scanner control board assembly part number

Part description Part number

Scan control PC board assembly part number B5L47-67903

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, remove and reconnect all the cables on the scanner control board (SCB).

30.01.36 Upgrade error 103

3. Ensure that all connections are seated correctly before replacing any part. Figure 6-50 Scanner control board (SCB) connections Table 6-34 Scanner control board (SCB) connections callout descriptions

Callout Description

1 Staple power

2 SCB power (24v) 3 Cable, PAB to SCAM communication (HDMI) 4 Flatbed sensors (Document feeder open and flatbed paper length-and cave LED) 5 Flatbed (S1) flat flexible cable (scanner data and flatbed motor) 6 Document feeder (S2) flat flexible cable (Scanner data) 7 Document feeder motors (Feed and deskew) 8 Document feeder sensors (Prescan, Paper present receiver and top hatch)

9 Document feeder ultra sonic sensor receiver and deskew

sensor 10 Letter/Legal (LTR/LGL) Input tray sensor

11 Ultra sonic sensor transmitter

4. If the error persists, update the printer firmware. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 104 Chapter 6 Numerical control panel messages

5. If the error persists after a firmware upgrade, replace the scanner control board (SCB). Table 6-35 Scanner control board assembly part number

Part description Part number

Scan control PC board assembly part number B5L47-67903 For instructions: See the Repair Service Manual for this product.

30.01.41 Scanner error

The formatter lost connections with the scanner control board (SCB) or communication was corrupted.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Check the voltage of the unit on the regulatory sticker. Ensure that the voltage of the outlet matches the voltage of the printer. NOTE: This event is directly related to a 220V printer being plugged into a 110V outlet. 2. Turn the printer off, and then on. 3. If the error persists, attempt to upgrade the firmware. NOTE: A fix has been implemented in FutureSmart 3.8 firmware version. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 4. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Check the voltage of the unit on the regulatory sticker. Ensure that the voltage of the outlet matches the voltage of the printer. NOTE: This event is directly related to a 220V printer being plugged into a 110V outlet. 2. Upgrade the firmware. NOTE: A fix has been implemented in FutureSmart 3.8 firmware version. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 3. Turn the printer off, and then on. 4. If the issue persists, dispatch a service technician to continue troubleshooting.

30.01.41 Scanner error 105

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Check the voltage of the unit on the regulatory sticker. Ensure that the voltage of the outlet matches the voltage of the printer. NOTE: This event is directly related to a 220V printer being plugged into a 110V outlet. 2. Upgrade the firmware. NOTE: A fix has been implemented in FutureSmart 3.8 firmware version. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 3. Turn off the printer, and then turn on the printer. 4. If the error persists, turn the product off, and then disconnect and reconnect all the cable connections between the formatter and the SCB. 5. Ensure that all the cables on the formatter and the SCB are connected correctly and seated correctly. 6. If the error persists, remove and reconnect all the cables on the scanner control board (SCB). 7. Ensure that all connections are seated correctly before replacing any part. Figure 6-51 Scanner control board (SCB): Sensor connections Table 6-36 SCB sensor callout descriptions

Callout Description

1 Flatbed sensor/motor

2 Flatbed FFC

3 ADF sensor

4 ADF FFC

5 ADF Motor

106 Chapter 6 Numerical control panel messages

8. If the error persists after the SCB cables are connected correctly, replace the scanner control board (SCB). Table 6-37 Scanner control board assembly part number

Part description Part number

Scan control PC board assembly part number B5L47-67903 For instructions: See the Repair Service Manual for this product. 9. After replacing the SCB, turn on the printer. 10. If the issue persists, replace the document feeder. Use the following table to order the correct part number for the printer model. Table 6-38 ADF part number

Description Part number

ADF Whole Unit Enterprise B5L47-67908 ADF Whole Unit Workflow B5L47-67909 For instructions: See the Repair Service Manual for this product.

30.01.43 Scanner memory failure

Scan memory error.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, perform a Partial Clean using the Preboot menu or the Embedded Web Server

(EWS).

NOTE: A Partial Clean erases all custom settings, PINs, passwords, third-party solutions, firmware files, and the operating system. It automatically reboots the printer and restores the firmware files from the repository. 3. If the error persists, try to update the firmware. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16).

30.01.43 Scanner memory failure 107

4. If the error persists, dispatch a service technician to replace the scanner control board (SCB). Table 6-39 Scanner control board assembly part number

Part description Part number

Scan control PC board assembly part number B5L47-67903

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn off the printer, and then turn on the printer. 2. If the error persists, perform a Partial Clean using the Preboot menu or the Embedded Web Server

(EWS).

NOTE: A Partial Clean erases all custom settings, PINs, passwords, third-party solutions, firmware files, and the operating system. It automatically reboots the printer and restores the firmware files from the repository. 3. If the error persists, try to update the firmware. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 4. Disconnect and reconnect all the cable connections between the formatter and the SCB. 5. Ensure that all the cables on the formatter and the SCB are connected correctly and seated correctly. 6. If the error persists, replace the scanner control board (SCB). Table 6-40 Scanner control board assembly part number

Part description Part number

Scan control PC board assembly part number B5L47-67903 For instructions: See the Repair Service Manual for this product. 7. If the error persists after replacing the SCB, replace the formatter. Use the following table to order the correct part number for your printer. Table 6-41 Formatter PCA part numbers

Product models Part description Part number

M501dn Formatter PC board J8H61-67901 M501dn (China) Formatter PC board J8H61-67902 M501n Formatter PC board J8H60-67901 M501n (China) Formatter board assembly J8H60-67902 M506n/ M506dn Formatter PC board assembly F2A68-67915 M506x Formatter PC board assembly F2A68-67916 108 Chapter 6 Numerical control panel messages

Table 6-41 Formatter PCA part numbers (continued)

Product models Part description Part number

M527

E52545

Formatter PC board assembly F2A76-67910 M528

E52645

Formatter PC board 1PV64-60002 For instructions: See the Repair Service Manual for this product.

30.01.44 Scanner error

Scanner control board (SCB) communication error.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Update the printer firmware to the latest version available at HP Customer Support - Software and Driver Downloads (<https://support.hp.com/drivers>). 2. Turn the printer off, and then on. 3. If the error persists, dispatch a service technician to replace the following parts in the order presented to resolve the issue. IMPORTANT: Do not send the SCB and the formatter. Table 6-42 Part numbers to resolve the issue

Product models Part description Part number

M527 M528

E52545

Image scanner assembly (includes white backing and retention clips)

F2A76-67914

M527c/ M527z ADF Whole Unit Workflow B5L47-67909 M527dn/ M527f ADF Whole Unit Enterprise B5L47-67908

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented.

30.01.44 Scanner error 109

1. Update the printer firmware to the latest version available at HP Customer Support - Software and Driver Downloads (<https://support.hp.com/drivers>). 2. Turn the printer off, and then on. 3. If the error persists, turn off the printer, and then disconnect and reconnect all the cable connections between the formatter and the SCB. Use the image below for SCB connections. Figure 6-52 Scanner control board (SCB) connections Table 6-43 Scanner control board (SCB) connections callout descriptions

Callout Description

1 Staple power

2 SCB power (24v) 3 PAB to SCAM communication (HDMI) 4 Flatbed sensors (document feeder open and flatbed paper length-and cave LED) 5 Flatbed (S1) flat flexible cable (scanner data and flatbed motor) 6 Document feeder (S2) flat flexible cable (scanner data) 7 Document feeder motors (feed and skew) 8 Document feeder sensors (prescan, paper present receiver and top hatch)

9 Document feeder ultra sonic sensor receiver and skew

sensor 110 Chapter 6 Numerical control panel messages

Table 6-43 Scanner control board (SCB) connections callout descriptions (continued)

Callout Description

10 LTR/LGL (letter/legal) Input tray sensor

11 Ultra sonic sensor transmitter

4. Ensure that all the cables on the formatter and the SCB are connected correctly and seated correctly. 5. If the error persists, replace the image scanner assembly. Table 6-44 Kit-Image Scanner Whole Unit (Image scanner assembly) part number

Part description Part number

Image scanner assembly (includes white backing and retention clips)

F2A76-67914

For instructions: See the Repair Service Manual for this product. 6. If the issue persists, replace the automatic document feeder assembly. Table 6-45 ADF part numbers

Product models Part description Part number

M527c/ M527z ADF Whole Unit Workflow B5L47-67909 M527dn/ M527f ADF Whole Unit Enterprise B5L47-67908 For instructions: See the Repair Service Manual for this product. 7. If the error persists after replacing the ADF, replace the scanner control board (SCB). Table 6-46 Scanner control board assembly part number

Part description Part number

Scan control PC board assembly part number B5L47-67903 For instructions: See the Repair Service Manual for this product. 8. If the error persists after replacing the SCB, replace the formatter. Use the following table to order the correct part number for your printer. Table 6-47 Formatter PCA part numbers

Product models Part description Part number

M501dn Formatter PC board J8H61-67901 M501dn (China) Formatter PC board J8H61-67902 M501n Formatter PC board J8H60-67901 M501n (China) Formatter board assembly J8H60-67902 Recommended action for onsite technicians 111

Table 6-47 Formatter PCA part numbers (continued)

Product models Part description Part number

M506n/ M506dn Formatter PC board assembly F2A68-67915 M506x Formatter PC board assembly F2A68-67916 M527

E52545

Formatter PC board assembly F2A76-67910 M528

E52645

Formatter PC board 1PV64-60002 For instructions: See the Repair Service Manual for this product.

30.01.45 Scanner Error

Scanner firmware assertion failure

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Update the printer firmware to the latest version available at HP Customer Support - Software and Driver Downloads (<https://support.hp.com/drivers>). 2. Turn the printer off, and then on. 3. If the error persists, dispatch a service technician to replace the required part and resolve the issue. IMPORTANT: Do not send the SCB and the formatter. Table 6-48 Part numbers to resolve the issue

Product models Part description Part number

M527c/ M527z ADF Whole Unit Workflow B5L47-67909 M527dn/ M527f ADF Whole Unit Enterprise B5L47-67908

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Update the printer firmware to the latest version available at HP Customer Support - Software and Driver Downloads (<https://support.hp.com/drivers>). 112 Chapter 6 Numerical control panel messages
2. Turn the printer off, and then on. 3. If the error persists, turn off the printer, and then disconnect and reconnect all the cable connections on the formatter and the SCB. Use the image below for SCB connections. Figure 6-53 Scanner control board (SCB) connections Table 6-49 Scanner control board (SCB) connections callout descriptions

Callout Description

1 Staple power

2 SCB power (24v) 3 Cable, PAB to SCAM communication (HDMI) 4 Flatbed sensors (Document feeder open and flatbed paper length-and cave LED) 5 Flatbed (S1) flat flexible cable (scanner data and flatbed motor) 6 Document feeder (S2) flat flexible cable (Scanner data) 7 Document feeder motors (Feed and skew) 8 Document feeder sensors (Prescan, Paper present receiver and top hatch)

9 Document feeder ultra sonic sensor receiver and skew

sensor 10 Letter/Legal (LTR/LGL) Input tray sensor

11 Ultra sonic sensor transmitter

Recommended action for onsite technicians 113

4. Ensure that all the cables on the formatter and the SCB are connected correctly and seated correctly before replacing a part. 5. If the issue persists, replace the automatic document feeder assembly. Table 6-50 ADF part numbers

Product models Part description Part number

M527c/ M527z ADF Whole Unit Workflow B5L47-67909 M527dn/ M527f ADF Whole Unit Enterprise B5L47-67908 For instructions: See the Repair Service Manual for this product. 6. If the issue persists after replacing the ADF, replace the scanner control board (SCB). Table 6-51 Scanner control board assembly part number

Part description Part number

Scan control PC board assembly part number B5L47-67903 For instructions: See the Repair Service Manual for this product. 7. If the error persists after replacing the SCB, replace the formatter. Use the following table to order the correct part number for your printer. Table 6-52 Formatter PCA part numbers

Product models Part description Part number

M501dn Formatter PC board J8H61-67901 M501dn (China) Formatter PC board J8H61-67902 M501n Formatter PC board J8H60-67901 M501n (China) Formatter board assembly J8H60-67902 M506n/ M506dn Formatter PC board assembly F2A68-67915 M506x Formatter PC board assembly F2A68-67916 M527

E52545

Formatter PC board assembly F2A76-67910 M528

E52645

Formatter PC board 1PV64-60002 For instructions: See the Repair Service Manual for this product.

30.01.46 Scanner Error

Scanner firmware error. 114 Chapter 6 Numerical control panel messages

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Update the printer firmware to the latest version available at HP Customer Support - Software and Driver Downloads (<https://support.hp.com/drivers>). 2. Turn the printer off, and then on. 3. If the error persists, dispatch a service technician with a scanner control board (SCB) to troubleshoot the issue and replace the part, if applicable. Table 6-53 Scanner control board assembly part number

Part description Part number

Scan control PC board assembly part number B5L47-67903

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Update the printer firmware to the latest version available at HP Customer Support - Software and Driver Downloads (<https://support.hp.com/drivers>). 2. Turn the printer off, and then on. Recommended action for customers 115

3. If the error persists, turn off the printer, and then disconnect and reconnect all the cable connections between the formatter and the SCB. Use the image below for SCB connections. Figure 6-54 Scanner control board (SCB) connections Table 6-54 Scanner control board (SCB) connections callout descriptions

Callout Description

1 Staple power

2 SCB power (24v) 3 Cable, PAB to SCAM communication (HDMI) 4 Flatbed sensors (Document feeder open and flatbed paper length-and cave LED) 5 Flatbed (S1) flat flexible cable (scanner data and flatbed motor) 6 Document feeder (S2) flat flexible cable (Scanner data) 7 Document feeder motors (Feed and deskew) 8 Document feeder sensors (Prescan, Paper present receiver and top hatch)

9 Document feeder ultra sonic sensor receiver and deskew

sensor 10 Letter/Legal (LTR/LGL) Input tray sensor

11 Ultra sonic sensor transmitter

4. Ensure that all the cables on the formatter and the SCB are connected and seated correctly before replacing a part. 116 Chapter 6 Numerical control panel messages

5. If the error persists, replace the scanner control board (SCB). Table 6-55 Scanner control board assembly part number

Part description Part number

Scan control PC board assembly part number B5L47-67903 For instructions: See the Repair Service Manual for this product.

30.03.14

A scanner EEPROM (NVM) error has occurred. A non-fatal error has occurred.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. ■ This is an informational message only, no action is required.

30.03.20

The firmware cannot communicate with the PCA on the assembly.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Update the printer firmware to the latest version available at HP Customer Support - Software and Driver Downloads (<https://support.hp.com/drivers>). 2. Turn the printer off, and then on. 3. If the error persists, dispatch a service technician to replace the following part and troubleshoot the issue. IMPORTANT: Do not send the SCB and the formatter.

30.03.14 117

Table 6-56 Part numbers to resolve the issue

Part description Part number

Image scanner assembly (includes white backing and retention clips)

F2A76-67914

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Update the printer firmware to the latest version available at HP Customer Support - Software and Driver Downloads (<https://support.hp.com/drivers>). 2. Turn the printer off, and then on. 3. If the error persists, turn off the printer, and then disconnect and reconnect all the cable connections between the SCB and the image scanner assembly. Use the image below for SCB connections. Figure 6-55 Scanner control board (SCB) connections Table 6-57 Scanner control board (SCB) connections callout descriptions

Callout Description

1 Staple power

2 SCB power (24v) 3 Cable, PAB to SCAM communication (HDMI) 4 Flatbed sensors (Document feeder open and flatbed paper length-and cave LED) 118 Chapter 6 Numerical control panel messages

Table 6-57 Scanner control board (SCB) connections callout descriptions (continued)

Callout Description

5 Flatbed (S1) flat flexible cable (scanner data and flatbed motor) 6 Document feeder (S2) flat flexible cable (Scanner data) 7 Document feeder motors (Feed and deskew) 8 Document feeder sensors (Prescan, Paper present receiver and top hatch)

9 Document feeder ultra sonic sensor receiver and deskew

sensor 10 Letter/Legal (LTR/LGL) Input tray sensor

11 Ultra sonic sensor transmitter

Figure 6-56 M527: Scanner to Formatter cable connections 4. Ensure that all the cables on the formatter and the SCB are connected and seated correctly before replacing a part. 5. If the error is still present, check to see if there is power or if the green LED lights on the SCB are illuminated. If no power is available, check the SCB, DC controller (J108), and LVPS connector. 6. If the issue persists after the connectors are connected correctly, perform the appropriate task: ● If the connectors are connected correctly and there is power on the SCB, replace the image scanner assembly (ISA). Table 6-58 Kit-Image Scanner Whole Unit (Image scanner assembly) part number

Part description Part number

Image scanner assembly (includes white backing and retention clips)

F2A76-67914

For instructions: See the Repair Service Manual for this product. ● If the connectors are connected correctly and there is no power on the SCB, replace the image scanner assembly (ISA), and then replace the scanner control board (SCB). Recommended action for onsite technicians 119

Table 6-59 Image scanner assembly and Scanner control board part numbers

Part description Part number

Image scanner assembly (includes white backing and retention clips)

F2A76-67914

Scan control PC board assembly part number B5L47-67903 – For instructions: See the Repair Service Manual for this product. – For instructions: See the Repair Service Manual for this product.

30.03.22 Scanner failure

Front side illumination calibration failure. The scan module cannot see the illumination module, or the illumination is marginal. The optical assembly might not be parked under the calibration strip.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Upgrade the firmware. 3. Check the event log for other scanner errors, and then resolve those errors. 4. Reseat the image scanner FFC connection. 5. Under the troubleshooting menu, run a "Continuous Scan" single sided to verify that the flatbed scan assembly moves freely and the scanner bulb is illuminated. 6. Replace the image scanner assembly. For instructions: See the Repair Service Manual for this product. Part number: F2A76-67909

30.03.23 Scanner failure

Calibration error.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 120 Chapter 6 Numerical control panel messages

2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Upgrade the firmware. 3. Check the event log for other scanner errors. If the errors are present, resolve those errors. 4. Reseat the image scanner FFC connection. 5. Under the troubleshooting menu, run a "Continuous Scan" single sided to verify that the flatbed scan assembly moves freely and the scanner bulb is illuminated. 6. Replace the image scanner assembly. For instructions: See the Repair Service Manual for this product. Part number: F2A76-67909

30.03.30 Scanner Failure

Flatbed motor shutdown. The scanner control board (SCB) cannot communicate with the flatbed scanner motor.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. As the printer turns on, verify that the scan head moves. 2. Verify that the drive belt is in the correct position. 3. Under the troubleshooting menu, run a "Continuous Scan" single sided to verify that the flatbed scan assembly moves freely and the scanner bulb is illuminated. 4. Run diagnostics test on the flatbed scanner to see if the scan bar moves. (For this test, run the continuous scan from the scanner test menu) 5. Check the cable connection to the scanner control board (SCB). 6. Replace the image scanner assembly. For instructions: See the Repair Service Manual for this product. Part number: F2A76-67909 Recommended action 121

30.03.45 Scanner Error To continue turn off then on

Scanner control board (SCB) firmware assertion failure. SCB firmware assertion controls the scan head motor.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Update the printer firmware to the latest version available at HP Customer Support - Software and Driver Downloads (<https://support.hp.com/drivers>). For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 2. Turn off the printer, and then turn on the printer. 3. If the error persists, dispatch a technician with the following parts to perform the service. NOTE: Do not send the formatter. Table 6-60 Scanner control board assembly and Image scanner assembly part numbers

Part description Part number

Scan control PC board assembly part number B5L47-67903 Image scanner assembly (includes white backing and retention clips)

F2A76-67914

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Update the printer firmware to the latest version available at HP Support or HP Software and Driver Downloads page. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 2. Turn the printer off, and then on. 3. Check the event log for other scanner errors. If the errors are present, resolve those errors. a. From the Home screen of the control panel, select Administration or Support Tools. b. Select Troubleshooting, and then select Event Log to access the Event Log The Event Log will show the last 50 recorded events. 122 Chapter 6 Numerical control panel messages

4. If the error persists, turn the product off, and then disconnect and reconnect all the cables between the scanner control board (SCB) and scanner assembly. Use the image below for SCB connections. Use the image below for SCB connections. Callout 6 is the most likely connector related to this error Figure 6-57 Scanner control board (SCB) connections Table 6-61 Scanner control board (SCB) connections callout descriptions

Callout Description

1 Staple power

2 SCB power (24v) 3 PAB to SCAM communication (HDMI) 4 Flatbed sensors (document feeder open and flatbed paper length-and cave LED) 5 Flatbed (S1) flat flexible cable (scanner data and flatbed motor) 6 Document feeder (S2) flat flexible cable (scanner data) 7 Document feeder motors (feed and deskew) 8 Document feeder sensors (prescan, paper present receiver and top hatch)

9 Document feeder ultra sonic sensor receiver and deskew

sensor 10 LTR/LGL (letter/legal) Input tray sensor

11 Ultra sonic sensor transmitter

Recommended action for onsite technicians 123

5. Verify the cables between scanner and scanner control board (SCB) are connected. (connection 6 — ADF (side 2) FFC). Also check the connection from the ADF to the PCA on the scanner. (Image 2) Figure 6-58 SCB connections 6. Replace the scanner control board (SCB). For instructions: See the Repair Service Manual for this product. Scanner control board, part number: B5L47-67903 (M527, M528). 7. If replacing the SCB does not resolve the issue, replace the image scanner assembly. For instructions: See the Repair Service Manual for this product. Part number: F2A76-67909 8. Replace the Low Voltage Power Supply. (LVPS). For instructions: See the Repair Service Manual for this product. Table 6-62 Parts

Description Part number

Low-voltage power supply (LVPS) 110V-127V (M527) RM2-7951-000CN Low-voltage power supply (LVPS) 220V-240V (M527) RM2-7952-000CN Low-voltage power supply (LVPS) 110V-127V (M501/M506) RM2-7941-000CN Low-voltage power supply (LVPS) 220V-240V (M501/M506) RM2-7942-000CN 9. If the issue persists, replace the automatic document feeder assembly. For instructions: See the Repair Service Manual for this product.

Part number

● Document feeder (M527c/z) kit: B5L47-67907 ● Document feeder (M527dn/f) kit: B5L47-67906 ● Document feeder (M528dn/f/c/z) kit: B5L47-67907 124 Chapter 6 Numerical control panel messages

● Document feeder (E52545c) kit: B5L47-67907 ● Document feeder (E52545dn) kit: B5L47-67906 ● Document feeder (E52645dn/c) kit: B5L47-67907 31.XX.YZ error messages 31.* errors Errors in the 31.* family are related to the document feeder.

Recommended action

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, contact your HP-authorized service or support provider, or contact HP support at www.hp.com/go/contactHP. 1. Verify the document feeder top cover is completely closed when feeding pages through it. 2. Verify the document feeder input tray is not overloaded and that the guides are adjusted correctly. 3. Open the document feeder top cover and check the rollers. Clean or replace them if necessary. 4. Clean the scanner glass and all the calibration strips. 5. Calibrate the scanner. Open these menus: Device Maintenance > Calibrate-Cleaning > Calibrate Scanner. 6. Clean the scanner glass and glass strips, and clean the white strips used for calibration. 7. Perform the tests for scanner diagnostics. Open these menus: Administration > Troubleshooting > Diagnostic Tests > Scanner Tests. Look for tests related to the document feeder, such as the Jam Cover Sensor test. 8. Upgrade the firmware. For the latest firmware versions, go to HP FutureSmart - Latest Firmware Versions 9. Check all connections from the document feeder to the scanner control board, and reseal them if necessary. 10. If the error persists, replace the document feeder assembly.

31.01.47 Document feeder not detected

The document feeder was not detected. The document feeder might not be connected. The flatbed glass is still available for scanning.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 31.* errors 125

2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off and then on. 2. If the issue persists, replace the document feeder. For instructions: See the Repair Service Manual for this product.

Part number

● Document feeder (M527c/z) kit: B5L47-67907 ● Document feeder (M527dn/f) kit: B5L47-67906 NOTE: Before replacing the document feeder, technicians should verify that the connections between the document feeder and the printer are fully seated. The following connections: 6 — ADF (side 2) FFC, 7 — ADF Motors (feed and deskew), 8 — ADF Sensors (pre-scan, media presence and top hatch), 9 — ADF ultra-sonice sensor receiver and deskew sensor)

31.03.14

Backside scanner EEPROM (NVM) error. A non-fatal error has occurred.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Validate that the error code is persistent. 3. If image quality is a problem, ask for an example image. 4. Replace the document feeder assembly. For instructions: See the Repair Service Manual for this product.

Part numbers

● Document feeder (M527c/z) kit: B5L47-67907 ● Document feeder (M527dn/f) kit: B5L47-67906 ● Document feeder (M528dn/f/c/z) kit: B5L47-67907 126 Chapter 6 Numerical control panel messages

● Document feeder (E52545c) kit: B5L47-67907 ● Document feeder (E52545dn) kit: B5L47-67906 ● Document feeder (E52645dn/c) kit: B5L47-67907

31.03.20 backside scanner not detected

Backside scanner is not detected.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. IMPORTANT: Before troubleshooting please review the appropriate Service Action Advisory for the specific region needed. ● HP LaserJet Enterprise MFP M527, M528, M577, M578, Managed MFP E52545, E52645, E57540, PageWide Enterprise MFP 586, Managed MFP E58650 - 31.03.20 error when duplexing from ADF, Workflow models (All regions, Service Action Advisory) ● HP LaserJet Enterprise MFP M527, M528, M577, M578, Managed MFP E52545, E52645, E57540, PageWide Enterprise MFP 586, Managed MFP E58650 - 31.03.20 error when duplexing from ADF, Non-workflow models (AMS, Service Action Advisory) ● HP LaserJet Enterprise MFP M527, M528, M577, M578, Managed MFP E52545, E52645, E57540, PageWide Enterprise MFP 586, Managed MFP E58650 - 31.03.20 error when duplexing from ADF, Non-Workflow models (APJ/EMEA, Service Action Advisory) 1. Turn the printer off, and then on. 2. If the error persists, service is required. Dispatch a technician with the appropriate document feeder assembly.

Part numbers

● Document feeder (M527c/z) kit: B5L47-67907 ● Document feeder (M527dn/f) kit: B5L47-67906 ● Document feeder (M528dn/f/c/z) kit: B5L47-67907 ● Document feeder (E52545c) kit: B5L47-67907 ● Document feeder (E52545dn) kit: B5L47-67906 ● Document feeder (E52645dn/c) kit: B5L47-67907

31.03.20 backside scanner not detected 127

Recommended action for onsite technicians

Use the following steps to resolve the issue. 1. Turn the printer off, and then on. 2. Verify the cables between scanner and scanner control board (SCB) are connected. (connection 6 — ADF (side 2) FFC). Also check the connection from the ADF to the PCA on the scanner. (Image 2) Figure 6-59 SCB connections Figure 6-60 Scanner connection 3. Ensure the FFC cable routing from the ADF has been installed correctly and is not bent, torn or the edge nicked. NOTE: If this occurs after the installation of a new ADF, remove the FFC, check for damage and re route. 4. Replace the document feeder assembly. For instructions: See the Repair Service Manual for this product. 128 Chapter 6 Numerical control panel messages

Part numbers

● Document feeder (M527c/z) kit: B5L47-67907 ● Document feeder (M527dn/f) kit: B5L47-67906 ● Document feeder (M528dn/f/c/z) kit: B5L47-67907 ● Document feeder (E52545c) kit: B5L47-67907 ● Document feeder (E52545dn) kit: B5L47-67906 ● Document feeder (E52645dn/c) kit: B5L47-67907 5. If the issue persists, replace the SCB. For instructions: See the Repair Service Manual for this product. Scanner control board, part number: B5L47-67903

31.03.22 Scanner calibration failure

Backside illumination calibration failure.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Upgrade the firmware. 3. Verify the cables between scanner and scanner control board (SCB) are connected. 4. Replace the document feeder assembly. For instructions: See the Repair Service Manual for this product.

Part number

● Document feeder (M527c/z) kit: B5L47-67907 ● Document feeder (M527dn/f) kit: B5L47-67906

31.03.30 Document feeder pick motor error

The document feeder pick motor is not turning.

Recommended action for customers

Follow these troubleshooting steps in the order presented.

31.03.22 Scanner calibration failure 129

1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Verify that the paper meets the HP printer specifications. 2. Make sure that the input tray is not overloaded and the tray guides are correctly aligned to both edges of the paper. 3. Check the event log for the document feeder errors, and resolve those errors first. 4. Open and close the top cover to see if the pick motor turns without posting this error. If the motor turns, then the motor is good. 5. Verify that the motor cables are connected. (Connection 7 — ADF Motor feed and deskew). 6. Re-seat the document feeder connections to the scanner control board (SCB). 7. Replace the document feeder assembly. For instructions: See the Repair Service Manual for this product.

Part number

● Document feeder (M527c/z) kit: B5L47-67907 ● Document feeder (M527dn/f) kit: B5L47-67906

31.03.31 Document feeder motor stall

The document feeder feed motor is not turning.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Verify that the paper meets the HP printer specifications. 2. Make sure that the input tray is not overloaded and the tray guides are correctly aligned to both edges of the paper. 3. Check the event log for document feeder errors, and then resolve those errors first. 4. Verify that the motor cables are connected. (Connection 7 — ADF Motor feed and deskew). 5. Re-seat the document feeder connections to the scanner control board (SCB). 130 Chapter 6 Numerical control panel messages

6. Replace the document feeder assembly. For instructions: See the Repair Service Manual for this product.

Part number

● Document feeder (M527c/z) kit: B5L47-67907 ● Document feeder (M527dn/f) kit: B5L47-67906

31.03.32

The document feeder de-skew motor is not turning.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Verify that the paper meets the HP printer specifications. 2. Make sure that the input tray is not overloaded. 3. Check the event log for document feeder errors, and then resolve those errors first. 4. Verify that the motor cables are connected. (Connection 7 — ADF feed and deskew motor) 5. Re-seat the document feeder connections to the scanner control board (SCB) cables. 6. Replace the document feeder assembly. For instructions: See the Repair Service Manual for this product.

Part number

● Document feeder (M527c/z) kit: B5L47-67907 ● Document feeder (M527dn/f) kit: B5L47-67906

31.03.33 Backside scanner calibration area dirty

The white area used for backside scanner calibration is dirty.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

31.03.32 131

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Clean white strip on platen glass (side 2 glass). 2. Clean the scanner glass. 3. If issue remains replace the document feeder assembly. For instructions: See the Repair Service Manual for this product.

Part number

● Document feeder (M527c/z) kit: B5L47-67907 ● Document feeder (M527dn/f) kit: B5L47-67906

31.03.34 Background missing

The removable white backing for the backside scanner is either missing or not fully snapped into place.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Remove the white backing and clean it. 2. Clean the backside scanner glass. 3. If issue remains replace the document feeder assembly. For instructions: See the Repair Service Manual for this product.

Part number

● Document feeder (M527c/z) kit: B5L47-67907 ● Document feeder (M527dn/f) kit: B5L47-67906

31.13.00 Document feeder multi-pick error

A multiple pick error was reported by the document feeder assembly (ADF). Issue might be described as the following: ● Picking multiple documents ● Picking more than one page ● Multiple sheets pulled from ADF 132 Chapter 6 Numerical control panel messages

● Multiple pages picked

Recommended action for customer

Follow these troubleshooting steps in the order presented. For further troubleshooting, please view this video: Fixing 31.13.01/.02 ADF Jam Errors on HP PageWide MFP/LaserJet MFP M500 and M600 Printers 1. Open the automatic document feeder cover, pull all the sheets back into the tray and then resume the job. 2. Lift the document-feeder input tray and remove any jammed paper. Recommended action for customer 133

3. Lower the document-feeder input tray and then close the document feeder cover. NOTE: Verify that the latch on the top of the document-feeder cover is completely closed. 4. Ensure that the paper meets the document feeder (ADF) specifications for the printer. This document outlines the supported weights and sizes of the ADF including best practices: Go to or search for document: HP LaserJet and PageWide Array Enterprise and Managed 500 and 600 - Use the automatic document feeder (ADF): 5. Ensure that the input tray is not overloaded and that the tray guides are set to the correct size. Make sure that the paper stack is correctly aligned at the center of the input tray when paper is loaded in the tray. The correct position of the loaded paper is parallel with the direction of travel into the document feeder paper path. Figure 6-61 Set the ADF guides NOTE: To avoid jams, make sure the guides in the document-feeder input tray are adjusted against the document, without bending the document. To copy narrow documents, use the flatbed scanner. Remove all staples and paper clips from original documents. NOTE: Original documents that are printed on heavy, glossy paper can jam more frequently than originals that are printed on plain paper. 6. Check the Document Feeder Kit consumable status. 134 Chapter 6 Numerical control panel messages

a. Navigate to and select Supplies on the control panel. b. Select Document Feeder Kit. c. See if the Document Feeder Kit status is OK, Low, or Very Low. d. Recommend that the customer replace the Document Feeder Kit if the status is Low or Very Low. Part number: W5U23A/HP 200 ADF Roller Replacement Kit. To order parts, go to <https://store.hp.com> 7. Check and clean the document feeder pickup rollers and separation rollers by removing any visible lint or dust from each of the rollers and using a clean lint-free cloth moistened with warm Recommended action for customer 135

water. View the How to Clean the Pick Rollers in HP LaserJet and PageWide Printers for detailed instructions. NOTE: Lift up the roller assembly to access and clean the second roller 8. If necessary, replace the Document Feeder Kit rollers and separation pad. Part number: W5U23A/HP 200 ADF Roller Replacement Kit To order parts, go to <https://store.hp.com> 9. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agent

Follow these troubleshooting steps in the order presented. For further troubleshooting, please view this video: Fixing 31.13.01/.02 ADF Jam Errors on HP PageWide MFP/LaserJet MFP M500 and M600 Printers 1. Open the automatic document feeder cover, pull all the sheets back into the tray and then resume the job. 136 Chapter 6 Numerical control panel messages

2. Lift the document-feeder input tray and remove any jammed paper. a. Lift the document feeder input tray b. Remove any paper found under the tray. c. Lower the document-feeder input tray and then close the document feeder cover. NOTE: Verify that the latch on the top of the document-feeder cover is completely closed. 3. For 31.13.02, check for any paper jams or remnants under the document feeder (ADF) blocking in the paper path Recommended action for call-center agent 137

a. Open the ADF and remove any paper found. b. Check for any paper remnants blocking the sensor as well as wiping any paper dust off the glass in the region shown below. If significant debris has accumulated over the circular mirror (used for paper edge sensing) this can cause a paper jam error. 1 2 Callout 1: Check for paper blocking this area. Callout 2: Clean this area with a damp lint free cloth. c. Close the document feeder. 4. Ensure that the paper meets the document feeder (ADF) specifications for the printer. This document outlines the supported weights and sizes of the ADF including best practices: Go to or search for document: HP LaserJet and PageWide Array Enterprise and Managed 500 and 600 - Use the automatic document feeder (ADF): 138 Chapter 6 Numerical control panel messages

5. Ensure that the input tray is not overloaded and that the tray guides are set to the correct size. Make sure that the paper stack is correctly aligned at the center of the input tray when paper is loaded in the tray. The correct position of the loaded paper is parallel with the direction of travel into the document feeder paper path. Figure 6-62 Set the ADF guides NOTE: To avoid jams, make sure the guides in the

document-feeder input tray are adjusted against the document, without bending the document. To copy narrow documents, use the flatbed scanner. Remove all staples and paper clips from original documents. NOTE: Original documents that are printed on heavy, glossy paper can jam more frequently than originals that are printed on plain paper. 6. Check the Document Feeder Kit consumable status. a. Navigate to and select Supplies on the control panel. b. Select Document Feeder Kit. Recommended action for call-center agent 139

c. See if the Document Feeder Kit status is OK, Low, or Very Low. d. If the status is Low or Very Low, recommend that the customer replace the Document Feeder Kit. Part number: W5U23A/HP 200 ADF Roller Replacement Kit. To order parts, go to <https://store.hp.com> NOTE: Above statement applies to Warranty customers; for Contractual customers, please parts predict or replace the (ADF maintenance replacement roller kit) - W5U23-67901 7. Check and clean the document feeder pickup rollers and separation rollers by removing any visible lint or dust from each of the rollers and using a clean lint-free cloth moistened with warm water. View the How to Clean the Pick Rollers in HP LaserJet and PageWide Printers for detailed instructions. NOTE: Lift up the roller assembly to access and clean the second roller . 140 Chapter 6 Numerical control panel messages

8. If necessary, replace the Document Feeder Kit rollers and separation pad. Part number: W5U23-67901 ADF maintenance replacement roller kit NOTE: Note: Should a grinding noise be reported or heard in conjunction with the pick/feed of paper through the ADF, replace the document feeder (ADF) unit. Document Feeder whole unit (ADF) part number: ● Flow models part number: B5L47-67909 ● Non-Flow models part number: B5L47-67908

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. For further troubleshooting, please view this video: Fixing 31.13.01/.02 ADF Jam Errors on HP PageWide MFP/LaserJet MFP M500 and M600 Printers 1. Open the automatic document feeder cover, pull all the sheets back into the tray and then resume the job. 2. Lift the document-feeder input tray and remove any jammed paper. a. Lift the document feeder input tray Recommended action for onsite technicians 141

b. Remove any paper found under the tray. c. Lower the document-feeder input tray and then close the document feeder cover. NOTE: Verify that the latch on the top of the document-feeder cover is completely closed. 3. For 31.13.02, check for any paper jams or remnants under the document feeder (ADF) blocking in the paper path a. Open the ADF and remove any paper found. 142 Chapter 6 Numerical control panel messages

b. Check for any paper remnants blocking the sensor as well as wiping any paper dust off the glass in the region shown below. If significant debris has accumulated over the circular mirror (used for paper edge sensing) this can cause a paper jam error. 1 2 Callout 1: Check for paper blocking this area. Callout 2: Clean this area with a damp lint free cloth. c. Close the document feeder. 4. Ensure that the paper meets the document feeder (ADF) specifications for the printer. This document outlines the supported weights and sizes of the ADF including best practices: Go to or search for document: HP LaserJet and PageWide Array Enterprise and Managed 500 and 600 - Use the automatic document feeder (ADF): 5. Ensure that the input tray is not overloaded and that the tray guides are set to the correct size. Make sure that the paper stack is correctly aligned at the center of the input tray when paper is Recommended action for onsite technicians 143

loaded in the tray. The correct position of the loaded paper is parallel with the direction of travel into the document feeder paper path. Figure 6-63 Set the ADF guides NOTE: To avoid jams, make sure the guides in the document-feeder input tray are adjusted against the document, without bending the document. To copy narrow documents, use the flatbed scanner. Remove all staples and paper clips from original documents. NOTE: Original documents that are printed on heavy, glossy paper can jam more frequently than originals that are printed on plain paper. 6. Check the Document Feeder Kit consumable status. a. Navigate to and select Supplies on the control panel. b. Select Document Feeder Kit. 144 Chapter 6 Numerical control panel messages

c. See if the Document Feeder Kit status is OK, Low, or Very Low. d. If the status is Low or Very Low, recommend that the customer replace the Document Feeder Kit. Part number: W5U23A/HP 200 ADF Roller Replacement Kit. To order parts, go to <https://store.hp.com> NOTE: Above statement applies to Warranty customers; for Contractual customers, please parts predict or replace the (ADF maintenance replacement roller kit) - W5U23-67901 7. Check and clean the document feeder pickup rollers and separation rollers by removing any visible lint or dust from each of the rollers and using a clean lint-free cloth moistened with warm water. View the How to Clean the Pick Rollers in HP LaserJet and PageWide Printers for detailed instructions. NOTE: Lift up the roller assembly to access and clean the second roller . 8. If necessary, replace the Document Feeder Kit rollers and separation pad. Part number: W5U23-67901/(ADF maintenance replacement roller kit) Recommended action for onsite technicians 145

9. Inspect the ADF pick success sensor, cleaning both the REDI (paper pick success) sensor window and REDI (PAPER PICK SUCCESS) sensor reflector. If there is any dust or fiber remnants, clean by using a can of compressed air to blow out and clean. Figure 6-64 ADF REDI sensor 1 — REDI sensor window 2 — REDI sensor reflector 3 — ADF hatch 10. Check the REDI sensor reflector on flatbed. If there is any dust or fiber remnants, clean it by using a can of compressed air to blow out and clean. (related issue, ADF jam without paper inside) 1 2 Callout 1: Check for paper blocking this area. Callout 2: Clean this area with a damp lint free cloth. 146 Chapter 6 Numerical control panel messages

11. Verify that the connections between the automatic document feeder and the SCB are correctly seated. Figure 6-65 SCB connections 12. Using the Manual Scanner Sensor Test verify functionality of the ADF Paper Path Pick Success sensor. a. Navigate to and select Support Tools. Recommended action for onsite technicians 147

b. Select Troubleshooting. c. Select Diagnostic Tests. 148 Chapter 6 Numerical control panel messages

d. Select Continue. e. Select Manual Sensor Test. Recommended action for onsite technicians 149

f. Select ADF Paper Path Deskew. g. Select ADF Paper Path Pick Success. (Only in FLOW-MODELS) NOTE: Pass is indicated if the working sensor advances the test count. Fail is indicated if the test count is not advancing. h. Close the ADF cover and ensure that is secure and closed correctly. 150 Chapter 6 Numerical control panel messages

13. Open and close the ADF cover to trigger the ADF Paper Path Pick Success sensor. NOTE: Pass is indicated if the working sensor advances the test count. Fail is indicated if the test count is not advanced. 14. If the ADF Paper Path Pick Success test fails to advance the count, replace the document feeder. For instructions: See the Repair Service Manual for this product.

Part number

● Flow models part number: B5L47-67907 ● Non-Flow models part number: B5L47-67906 NOTE: Note: Should a grinding noise be reported or heard in conjunction with the pick/feed of paper through the ADF, replace the document feeder (ADF) unit. Document Feeder whole unit (ADF) part number: ● Flow models part number: B5L47-67909 ● Non-Flow models part number: B5L47-67908

31.13.01

Document feeder job error, pick error. Paper pick was initiated, but the page didn't make it to the pick success sensor. Sensor location 4 ADF Pick error.

31.13.01 151

ADF Pick Jam

Recommended action for customer

Follow these troubleshooting steps in the order presented. For further troubleshooting, please view this video: Fixing 31.13.01/.02 ADF Jam Errors on HP PageWide MFP/LaserJet MFP M500 and M600 Printers 1. Open the automatic document feeder cover, pull all the sheets back into the tray and then resume the job. 2. Lift the document-feeder input tray and remove any jammed paper. 152 Chapter 6 Numerical control panel messages

3. Lower the document-feeder input tray and then close the document feeder cover. NOTE: Verify that the latch on the top of the document-feeder cover is completely closed. 4. Ensure that the paper meets the document feeder (ADF) specifications for the printer. This document outlines the supported weights and sizes of the ADF including best practices: Go to or search for document: HP LaserJet and PageWide Array Enterprise and Managed 500 and 600 - Use the automatic document feeder (ADF): 5. Ensure that the input tray is not overloaded and that the tray guides are set to the correct size. Make sure that the paper stack is correctly aligned at the center of the input tray when paper is loaded in the tray. The correct position of the loaded paper is parallel with the direction of travel into the document feeder paper path. Figure 6-66 Set the ADF guides NOTE: To avoid jams, make sure the guides in the document-feeder input tray are adjusted against the document, without bending the document. To copy narrow documents, use the flatbed scanner. Remove all staples and paper clips from original documents. NOTE: Original documents that are printed on heavy, glossy paper can jam more frequently than originals that are printed on plain paper. 6. Check the Document Feeder Kit consumable status. Recommended action for customer 153

a. Navigate to and select Supplies on the control panel. b. Select Document Feeder Kit. c. See if the Document Feeder Kit status is OK, Low, or Very Low. d. Recommend that the customer replace the Document Feeder Kit if the status is Low or Very Low. Part number: W5U23A/HP 200 ADF Roller Replacement Kit. To order parts, go to <https://store.hp.com> 7. Check and clean the document feeder pickup rollers and separation rollers by removing any visible lint or dust from each of the rollers and using a clean lint-free cloth moistened with warm 154 Chapter 6 Numerical control panel messages

water. View the How to Clean the Pick Rollers in HP LaserJet and PageWide Printers for detailed instructions. NOTE: Lift up the roller assembly to access and clean the second roller 8. If necessary, replace the Document Feeder Kit rollers and separation pad. Part number: W5U23A/HP 200 ADF Roller Replacement Kit To order parts, go to <https://store.hp.com> 9. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agent

Follow these troubleshooting steps in the order presented. For further troubleshooting, please view this video: Fixing 31.13.01/.02 ADF Jam Errors on HP PageWide MFP/LaserJet MFP M500 and M600 Printers 1. Open the automatic document feeder cover, pull all the sheets back into the tray and then resume the job. Recommended action for call-center agent 155

2. Lift the document-feeder input tray and remove any jammed paper. a. Lift the document feeder input tray b. Remove any paper found under the tray. c. Lower the document-feeder input tray and then close the document feeder cover. NOTE: Verify that the latch on the top of the document-feeder cover is completely closed. 3. For 31.13.02, check for any paper jams or remnants under the document feeder (ADF) blocking in the paper path 156 Chapter 6 Numerical control panel messages

a. Open the ADF and remove any paper found. b. Check for any paper remnants blocking the sensor as well as wiping any paper dust off the glass in the region shown below. If significant debris has accumulated over the circular mirror (used for paper edge sensing) this can cause a paper jam error. 1 2 Callout 1: Check for paper blocking this area. Callout 2: Clean this area with a damp lint free cloth. c. Close the document feeder. 4. Ensure that the paper meets the document feeder (ADF) specifications for the printer. This document outlines the supported weights and sizes of the ADF including best practices: Go to or search for document: HP LaserJet and PageWide Array Enterprise and Managed 500 and 600 - Use the automatic document feeder (ADF): Recommended action for call-center agent 157

5. Ensure that the input tray is not overloaded and that the tray guides are set to the correct size. Make sure that the paper stack is correctly aligned at the center of the input tray when paper is loaded in the tray. The correct position of the loaded paper is parallel with the direction of travel into the document feeder paper path. Figure 6-67 Set the ADF guides NOTE: To avoid jams, make sure the guides in the document-feeder input tray are adjusted against the document, without bending the document. To copy narrow documents, use the flatbed scanner. Remove all staples and paper clips from original documents. NOTE: Original documents that are printed on heavy, glossy paper can

jam more frequently than originals that are printed on plain paper. 6. Check the Document Feeder Kit consumable status. a. Navigate to and select Supplies on the control panel. b. Select Document Feeder Kit. 158 Chapter 6 Numerical control panel messages

c. See if the Document Feeder Kit status is OK, Low, or Very Low. d. If the status is Low or Very Low, recommend that the customer replace the Document Feeder Kit. Part number: W5U23A/HP 200 ADF Roller Replacement Kit. To order parts, go to <https://store.hp.com> NOTE: Above statement applies to Warranty customers; for Contractual customers, please parts predict or replace the (ADF maintenance replacement roller kit) - W5U23-67901 7. Check and clean the document feeder pickup rollers and separation rollers by removing any visible lint or dust from each of the rollers and using a clean lint-free cloth moistened with warm water. View the How to Clean the Pick Rollers in HP LaserJet and PageWide Printers for detailed instructions. NOTE: Lift up the roller assembly to access and clean the second roller . Recommended action for call-center agent 159

8. If necessary, replace the Document Feeder Kit rollers and separation pad. Part number: W5U23-67901 ADF maintenance replacement roller kit NOTE: Note: Should a grinding noise be reported or heard in conjunction with the pick/feed of paper through the ADF, replace the document feeder (ADF) unit. Document Feeder whole unit (ADF) part number: ● Flow models part number: B5L47-67909 ● Non-Flow models part number: B5L47-67908

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. For further troubleshooting, please view this video: Fixing 31.13.01/02 ADF Jam Errors on HP PageWide MFP/LaserJet MFP M500 and M600 Printers 1. Open the automatic document feeder cover, pull all the sheets back into the tray and then resume the job. 2. Lift the document-feeder input tray and remove any jammed paper. a. Lift the document feeder input tray 160 Chapter 6 Numerical control panel messages

b. Remove any paper found under the tray. c. Lower the document-feeder input tray and then close the document feeder cover. NOTE: Verify that the latch on the top of the document-feeder cover is completely closed. 3. For 31.13.02, check for any paper jams or remnants under the document feeder (ADF) blocking in the paper path a. Open the ADF and remove any paper found. Recommended action for onsite technicians 161

b. Check for any paper remnants blocking the sensor as well as wiping any paper dust off the glass in the region shown below. If significant debris has accumulated over the circular mirror (used for paper edge sensing) this can cause a paper jam error. 1 2 Callout 1: Check for paper blocking this area. Callout 2: Clean this area with a damp lint free cloth. c. Close the document feeder. 4. Ensure that the paper meets the document feeder (ADF) specifications for the printer. This document outlines the supported weights and sizes of the ADF including best practices: Go to or search for document: HP LaserJet and PageWide Array Enterprise and Managed 500 and 600 - Use the automatic document feeder (ADF): 5. Ensure that the input tray is not overloaded and that the tray guides are set to the correct size. Make sure that the paper stack is correctly aligned at the center of the input tray when paper is 162 Chapter 6 Numerical control panel messages

loaded in the tray. The correct position of the loaded paper is parallel with the direction of travel into the document feeder paper path. Figure 6-68 Set the ADF guides NOTE: To avoid jams, make sure the guides in the document-feeder input tray are adjusted against the document, without bending the document. To copy narrow documents, use the flatbed scanner. Remove all staples and paper clips from original documents. NOTE: Original documents that are printed on heavy, glossy paper can jam more frequently than originals that are printed on plain paper. 6. Check the Document Feeder Kit consumable status. a. Navigate to and select Supplies on the control panel. b. Select Document Feeder Kit. Recommended action for onsite technicians 163

c. See if the Document Feeder Kit status is OK, Low, or Very Low. d. If the status is Low or Very Low, recommend that the customer replace the Document Feeder Kit. Part number: W5U23A/HP 200 ADF Roller Replacement Kit. To order parts, go to <https://store.hp.com> NOTE: Above statement applies to Warranty customers; for Contractual customers, please parts predict or replace the (ADF maintenance replacement roller kit) - W5U23-67901 7. Check and clean the document feeder pickup rollers and separation rollers by removing any visible lint or dust from each of the rollers and using a clean lint-free cloth moistened with warm water. View the How to Clean the Pick Rollers in HP LaserJet and PageWide Printers for detailed instructions. NOTE: Lift up the roller assembly to access and clean the second roller . 8. If necessary, replace the Document Feeder Kit rollers and separation pad. Part number: W5U23-67901/(ADF maintenance replacement roller kit) 164 Chapter 6 Numerical control panel messages

9. Inspect the ADF pick success sensor, cleaning both the REDI (paper pick success) sensor window and REDI (PAPER PICK SUCCESS) sensor reflector. If there is any dust or fiber remnants, clean by using a can of compressed air to blow out and clean. Figure 6-69 ADF REDI sensor 1 — REDI sensor window 2 — REDI sensor reflector 3 — ADF hatch 10. Check the REDI sensor reflector on flatbed. If there is any dust or fiber remnants, clean it by using a can of compressed air to blow out and clean. (related issue, ADF jam without paper inside) 1 2 Callout 1: Check for paper blocking this area. Callout 2: Clean this area with a damp lint free cloth. Recommended action for onsite technicians 165

11. Verify that the connections between the automatic document feeder and the SCB are correctly seated. Figure 6-70 SCB connections 12. Using the Manual Scanner Sensor Test verify functionality of the ADF Paper Path Pick Success sensor. a. Navigate to and select Support Tools. 166 Chapter 6 Numerical control panel messages

b. Select Troubleshooting. c. Select Diagnostic Tests. Recommended action for onsite technicians 167

d. Select Continue. e. Select Manual Sensor Test. 168 Chapter 6 Numerical control panel messages

f. Select ADF Paper Path Deskew. g. Select ADF Paper Path Pick Success. (Only in FLOW-MODELS) NOTE: Pass is indicated if the working sensor advances the test count. Fail is indicated if the test count is not advancing. h. Close the ADF cover and ensure that is secure and closed correctly. Recommended action for onsite technicians 169

13. Open and close the ADF cover to trigger the ADF Paper Path Pick Success sensor. NOTE: Pass is indicated if the working sensor advances the test count. Fail is indicated if the test count is not advanced. 14. If the ADF Paper Path Pick Success test fails to advance the count, replace the document feeder. For instructions: See the Repair Service Manual for this product.

Part number

● Flow models part number: B5L47-67907 ● Non-Flow models part number: B5L47-67906 NOTE: Note: Should a grinding noise be reported or heard in conjunction with the pick/feed of paper through the ADF, replace the document feeder (ADF) unit. Document Feeder whole unit (ADF) part number: ● Flow models part number: B5L47-67909 ● Non-Flow models part number: B5L47-67908

31.13.02

Document feeder job error, feed jam. The paper passed the pick success sensor, and then jammed in the document feeder paper path. Between sensor location 4 and 5 Issue might be described as the following: 170 Chapter 6 Numerical control panel messages

● ADF paper jam ● Automatic document feeder jam ● Jams in document feeder

Recommended action for customer

Follow these troubleshooting steps in the order presented. For further troubleshooting, please view this video: Fixing 31.13.01/.02 ADF Jam Errors on HP PageWide MFP/LaserJet MFP M500 and M600 Printers 1. Open the automatic document feeder cover, pull all the sheets back into the tray and then resume the job. 2. Lift the document-feeder input tray and remove any jammed paper. Recommended action for customer 171

3. Lower the document-feeder input tray and then close the document feeder cover. NOTE: Verify that the latch on the top of the document-feeder cover is completely closed. 4. Ensure that the paper meets the document feeder (ADF) specifications for the printer. This document outlines the supported weights and sizes of the ADF including best practices: Go to or search for document: HP LaserJet and PageWide Array Enterprise and Managed 500 and 600 - Use the automatic document feeder (ADF): 5. Ensure that the input tray is not overloaded and that the tray guides are set to the correct size. Make sure that the paper stack is correctly aligned at the center of the input tray when paper is loaded in the tray. The correct position of the loaded paper is parallel with the direction of travel into the document feeder paper path. Figure 6-71 Set the ADF guides NOTE: To avoid jams, make sure the guides in the document-feeder input tray are adjusted against the document, without bending the document. To copy narrow documents, use the flatbed scanner. Remove all staples and paper clips from original documents. NOTE: Original documents that are printed on heavy, glossy paper can jam more frequently than originals that are printed on plain paper. 6. Check the Document Feeder Kit consumable status. 172 Chapter 6 Numerical control panel messages

a. Navigate to and select Supplies on the control panel. b. Select Document Feeder Kit. c. See if the Document Feeder Kit status is OK, Low, or Very Low. d. Recommend that the customer replace the Document Feeder Kit if the status is Low or Very Low. Part number: W5U23A/HP 200 ADF Roller Replacement Kit. To order parts, go to <https://store.hp.com> 7. Check and clean the document feeder pickup rollers and separation rollers by removing any visible lint or dust from each of the rollers and using a clean lint-free cloth moistened with warm water. Recommended action for customer 173

water. View the How to Clean the Pick Rollers in HP LaserJet and PageWide Printers for detailed instructions. NOTE: Lift up the roller assembly to access and clean the second roller 8. If necessary, replace the Document Feeder Kit rollers and separation pad. Part number: W5U23A/HP 200 ADF Roller Replacement Kit To order parts, go to <https://store.hp.com> 9. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agent

Follow these troubleshooting steps in the order presented. For further troubleshooting, please view this video: Fixing 31.13.01/.02 ADF Jam Errors on HP PageWide MFP/LaserJet MFP M500 and M600 Printers 1. Open the automatic document feeder cover, pull all the sheets back into the tray and then resume the job. 174 Chapter 6 Numerical control panel messages

2. Lift the document-feeder input tray and remove any jammed paper. a. Lift the document feeder input tray b. Remove any paper found under the tray. c. Lower the document-feeder input tray and then close the document feeder cover. NOTE: Verify that the latch on the top of the document-feeder cover is completely closed. 3. For 31.13.02, check for any paper jams or remnants under the document feeder (ADF) blocking in the paper path Recommended action for call-center agent 175

a. Open the ADF and remove any paper found. b. Check for any paper remnants blocking the sensor as well as wiping any paper dust off the glass in the region shown below. If significant debris has accumulated over the circular mirror (used for paper edge sensing) this can cause a paper jam error. 1 2 Callout 1: Check for paper blocking this area. Callout 2: Clean this area with a damp lint free cloth. c. Close the document feeder. 4. Ensure that the paper meets the document feeder (ADF) specifications for the printer. This document outlines the supported weights and sizes of the ADF including best practices: Go to or search for document: HP LaserJet and PageWide Array Enterprise and Managed 500 and 600 - Use the automatic document feeder (ADF): 176 Chapter 6 Numerical control panel messages

5. Ensure that the input tray is not overloaded and that the tray guides are set to the correct size. Make sure that the paper stack is correctly aligned at the center of the input tray when paper is loaded in the tray. The correct position of the loaded paper is parallel with the direction of travel into the document feeder paper path. Figure 6-72 Set the ADF guides NOTE: To avoid jams, make sure the guides in the document-feeder input tray are adjusted against the document, without bending the document. To copy narrow documents, use the flatbed scanner. Remove all staples and paper clips from original documents. NOTE: Original documents that are printed on heavy, glossy paper can jam more frequently than originals that are printed on plain paper. 6. Check the Document Feeder Kit consumable status. a. Navigate to and select Supplies on the control panel. b. Select Document Feeder Kit. Recommended action for call-center agent 177

c. See if the Document Feeder Kit status is OK, Low, or Very Low. d. If the status is Low or Very Low, recommend that the customer replace the Document Feeder Kit. Part number: W5U23A/HP 200 ADF Roller Replacement Kit. To order parts, go to <https://store.hp.com> NOTE: Above statement applies to Warranty customers; for Contractual customers, please parts predict or replace the (ADF maintenance replacement roller kit) - W5U23-67901 7. Check and clean the document feeder pickup rollers and separation rollers by removing any visible lint or dust from each of the rollers and using a clean lint-free cloth moistened with warm water. View the How to Clean the Pick Rollers in HP

LaserJet and PageWide Printers for detailed instructions. NOTE: Lift up the roller assembly to access and clean the second roller . 178

Chapter 6 Numerical control panel messages

8. If necessary, replace the Document Feeder Kit rollers and separation pad. Part number: W5U23-67901 ADF maintenance replacement roller kit NOTE: Note: Should a grinding noise be reported or heard in conjunction with the pick/feed of paper through the ADF, replace the document feeder (ADF) unit. Document Feeder whole unit (ADF) part number: ● Flow models part number: B5L47-67909 ● Non-Flow models part number: B5L47-67908

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. For further troubleshooting, please view this video: Fixing 31.13.01/.02 ADF Jam Errors on HP PageWide MFP/LaserJet MFP M500 and M600 Printers 1. Open the automatic document feeder cover, pull all the sheets back into the tray and then resume the job. 2. Lift the document-feeder input tray and remove any jammed paper. a. Lift the document feeder input tray Recommended action for onsite technicians 179

b. Remove any paper found under the tray. c. Lower the document-feeder input tray and then close the document feeder cover. NOTE: Verify that the latch on the top of the document-feeder cover is completely closed. 3. For 31.13.02, check for any paper jams or remnants under the document feeder (ADF) blocking in the paper path a. Open the ADF and remove any paper found. 180 Chapter 6 Numerical control panel messages

b. Check for any paper remnants blocking the sensor as well as wiping any paper dust off the glass in the region shown below. If significant debris has accumulated over the circular mirror (used for paper edge sensing) this can cause a paper jam error. 1 2 Callout 1: Check for paper blocking this area. Callout 2: Clean this area with a damp lint free cloth. c. Close the document feeder. 4. Ensure that the paper meets the document feeder (ADF) specifications for the printer. This document outlines the supported weights and sizes of the ADF including best practices: Go to or search for document: HP LaserJet and PageWide Array Enterprise and Managed 500 and 600 - Use the automatic document feeder (ADF): 5. Ensure that the input tray is not overloaded and that the tray guides are set to the correct size. Make sure that the paper stack is correctly aligned at the center of the input tray when paper is Recommended action for onsite technicians 181

loaded in the tray. The correct position of the loaded paper is parallel with the direction of travel into the document feeder paper path. Figure 6-73 Set the ADF guides NOTE: To avoid jams, make sure the guides in the document-feeder input tray are adjusted against the document, without bending the document. To copy narrow documents, use the flatbed scanner. Remove all staples and paper clips from original documents. NOTE: Original documents that are printed on heavy, glossy paper can jam more frequently than originals that are printed on plain paper. 6. Check the Document Feeder Kit consumable status. a. Navigate to and select Supplies on the control panel. b. Select Document Feeder Kit. 182 Chapter 6 Numerical control panel messages

c. See if the Document Feeder Kit status is OK, Low, or Very Low. d. If the status is Low or Very Low, recommend that the customer replace the Document Feeder Kit. Part number: W5U23A/HP 200 ADF Roller Replacement Kit. To order parts, go to <https://store.hp.com> NOTE: Above statement applies to Warranty customers; for Contractual customers, please parts predict or replace the (ADF maintenance replacement roller kit) - W5U23-67901 7. Check and clean the document feeder pickup rollers and separation rollers by removing any visible lint or dust from each of the rollers and using a clean lint-free cloth moistened with warm water. View the How to Clean the Pick Rollers in HP LaserJet and PageWide Printers for detailed instructions. NOTE: Lift up the roller assembly to access and clean the second roller . 8. If necessary, replace the Document Feeder Kit rollers and separation pad. Part number: W5U23-67901/(ADF maintenance replacement roller kit) Recommended action for onsite technicians 183

9. Inspect the ADF pick success sensor, cleaning both the REDI (paper pick success) sensor window and REDI (PAPER PICK SUCCESS) sensor reflector. If there is any dust or fiber remnants, clean by using a can of compressed air to blow out and clean. Figure 6-74 ADF REDI sensor 1 — REDI sensor window 2 — REDI sensor reflector 3 — ADF hatch 10. Check the REDI sensor reflector on flatbed. If there is any dust or fiber remnants, clean it by using a can of compressed air to blow out and clean. (related issue, ADF jam without paper inside) 1 2 Callout 1: Check for paper blocking this area. Callout 2: Clean this area with a damp lint free cloth. 184 Chapter 6 Numerical control panel messages

11. Verify that the connections between the automatic document feeder and the SCB are correctly seated. Figure 6-75 SCB connections 12. Using the Manual Scanner Sensor Test verify functionality of the ADF Paper Path Pick Success sensor. a. Navigate to and select Support Tools. Recommended action for onsite technicians 185

b. Select Troubleshooting. c. Select Diagnostic Tests. 186 Chapter 6 Numerical control panel messages

d. Select Continue. e. Select Manual Sensor Test. Recommended action for onsite technicians 187

f. Select ADF Paper Path Deskew. g. Select ADF Paper Path Pick Success. (Only in FLOW-MODELS) NOTE: Pass is indicated if the working sensor advances the test count. Fail is indicated if the test count is not advancing. h. Close the ADF cover and ensure that is secure and closed correctly. 188 Chapter 6 Numerical control panel messages

13. Open and close the ADF cover to trigger the ADF Paper Path Pick Success sensor. NOTE: Pass is indicated if the working sensor advances the test count. Fail is indicated if the test count is not advanced. 14. If the ADF Paper Path Pick Success test fails to advance the count, replace the document feeder. For instructions: See the Repair Service Manual for this product.

Part number

● Flow models part number: B5L47-67907 ● Non-Flow models part number: B5L47-67906 NOTE: Note: Should a grinding noise be reported or heard in conjunction with the pick/feed of paper through the ADF, replace the document feeder (ADF) unit. Document Feeder whole unit (ADF) part number: ● Flow models part number: B5L47-67909 ● Non-Flow models part number: B5L47-67908

31.13.13

The document feeder jam access door is open.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Verify that the jam access cover is closed.

31.13.13 189

2. Verify that the flag is not broken off. Open and close the jam cover, and if the sensor status does not change then replace the ADF. 3. Open the following menus: ● Administration ● Troubleshooting ● Diagnostic Tests ● Scanner Tests 4. Actuate the pick-success sensor. If the sensor does not show functionality when tested, verify the connector for the ultra-sonice sensor (connectors 9 and 11) on the scanner control board is connected. If the sensor still fails, replace the document feeder. For instructions: See the Repair Service Manual for this product.

Part number

● Document feeder (M527c/z) kit: B5L47-67907 ● Document feeder (M527dn/f) kit: B5L47-67906

31.13.14

Document feeder job error: over current. This is a feed jam in the document feeder, and the motor is not turning.

Recommended action for customer

Follow these troubleshooting steps in the order presented. For further troubleshooting, please view this video: Fixing 31.13.01/.02 ADF Jam Errors on HP PageWide MFP/LaserJet MFP M500 and M600 Printers 190 Chapter 6 Numerical control panel messages

1. Open the automatic document feeder cover, pull all the sheets back into the tray and then resume the job. 2. Lift the document-feeder input tray and remove any jammed paper. 3. Lower the document-feeder input tray and then close the document feeder cover. NOTE: Verify that the latch on the top of the document-feeder cover is completely closed. Recommended action for customer 191

4. Ensure that the paper meets the document feeder (ADF) specifications for the printer. This document outlines the supported weights and sizes of the ADF including best practices: Go to or search for document: HP LaserJet and PageWide Array Enterprise and Managed 500 and 600 - Use the automatic document feeder (ADF): 5. Ensure that the input tray is not overloaded and that the tray guides are set to the correct size. Make sure that the paper stack is correctly aligned at the center of the input tray when paper is loaded in the tray. The correct position of the loaded paper is parallel with the direction of travel into the document feeder paper path. Figure 6-76 Set the ADF guides NOTE: To avoid jams, make sure the guides in the document-feeder input tray are adjusted against the document, without bending the document. To copy narrow documents, use the flatbed scanner. Remove all staples and paper clips from original documents. NOTE: Original documents that are printed on heavy, glossy paper can jam more frequently than originals that are printed on plain paper. 6. Check the Document Feeder Kit consumable status. a. Navigate to and select Supplies on the control panel. 192 Chapter 6 Numerical control panel messages

b. Select Document Feeder Kit. c. See if the Document Feeder Kit status is OK, Low, or Very Low. d. Recommend that the customer replace the Document Feeder Kit if the status is Low or Very Low. Part number: W5U23A/HP 200 ADF Roller Replacement Kit. To order parts, go to <https://store.hp.com> 7. Check and clean the document feeder pickup rollers and separation rollers by removing any visible lint or dust from each of the rollers and using a clean lint-free cloth moistened with warm Recommended action for customer 193

water. View the How to Clean the Pick Rollers in HP LaserJet and PageWide Printers for detailed instructions. NOTE: Lift up the roller assembly to access and clean the second roller 8. If necessary, replace the Document Feeder Kit rollers and separation pad. Part number: W5U23A/HP 200 ADF Roller Replacement Kit To order parts, go to <https://store.hp.com> 9. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agent

Follow these troubleshooting steps in the order presented. For further troubleshooting, please view this video: Fixing 31.13.01/.02 ADF Jam Errors on HP PageWide MFP/LaserJet MFP M500 and M600 Printers 1. Open the automatic document feeder cover, pull all the sheets back into the tray and then resume the job. 194 Chapter 6 Numerical control panel messages

2. Lift the document-feeder input tray and remove any jammed paper. a. Lift the document feeder input tray b. Remove any paper found under the tray. c. Lower the document-feeder input tray and then close the document feeder cover. NOTE: Verify that the latch on the top of the document-feeder cover is completely closed. 3. For 31.13.02, check for any paper jams or remnants under the document feeder (ADF) blocking in the paper path Recommended action for call-center agent 195

a. Open the ADF and remove any paper found. b. Check for any paper remnants blocking the sensor as well as wiping any paper dust off the glass in the region shown below. If significant debris has accumulated over the circular mirror (used for paper edge sensing) this can cause a paper jam error. 1 2 Callout 1: Check for paper blocking this area. Callout 2: Clean this area with a damp lint free cloth. c. Close the document feeder. 4. Ensure that the paper meets the document feeder (ADF) specifications for the printer. This document outlines the supported weights and sizes of the ADF including best practices: Go to or search for document: HP LaserJet and PageWide Array Enterprise and Managed 500 and 600 - Use the automatic document feeder (ADF): 196 Chapter 6 Numerical control panel messages

5. Ensure that the input tray is not overloaded and that the tray guides are set to the correct size. Make sure that the paper stack is correctly aligned at the center of the input tray when paper is loaded in the tray. The correct position of the loaded paper is parallel with the direction of travel into the document feeder paper path. Figure 6-77 Set the ADF guides NOTE: To avoid jams, make sure the guides in the

document-feeder input tray are adjusted against the document, without bending the document. To copy narrow documents, use the flatbed scanner. Remove all staples and paper clips from original documents. NOTE: Original documents that are printed on heavy, glossy paper can jam more frequently than originals that are printed on plain paper. 6. Check the Document Feeder Kit consumable status. a. Navigate to and select Supplies on the control panel. b. Select Document Feeder Kit. Recommended action for call-center agent 197

c. See if the Document Feeder Kit status is OK, Low, or Very Low. d. If the status is Low or Very Low, recommend that the customer replace the Document Feeder Kit. Part number: W5U23A/HP 200 ADF Roller Replacement Kit. To order parts, go to <https://store.hp.com> NOTE: Above statement applies to Warranty customers; for Contractual customers, please parts predict or replace the (ADF maintenance replacement roller kit) - W5U23-67901 7. Check and clean the document feeder pickup rollers and separation rollers by removing any visible lint or dust from each of the rollers and using a clean lint-free cloth moistened with warm water. View the How to Clean the Pick Rollers in HP LaserJet and PageWide Printers for detailed instructions. NOTE: Lift up the roller assembly to access and clean the second roller . 198 Chapter 6 Numerical control panel messages

8. If necessary, replace the Document Feeder Kit rollers and separation pad. Part number: W5U23-67901 ADF maintenance replacement roller kit NOTE: Note: Should a grinding noise be reported or heard in conjunction with the pick/feed of paper through the ADF, replace the document feeder (ADF) unit. Document Feeder whole unit (ADF) part number: ● Flow models part number: B5L47-67909 ● Non-Flow models part number: B5L47-67908

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. For further troubleshooting, please view this video: Fixing 31.13.01/.02 ADF Jam Errors on HP PageWide MFP/LaserJet MFP M500 and M600 Printers 1. Open the automatic document feeder cover, pull all the sheets back into the tray and then resume the job. 2. Lift the document-feeder input tray and remove any jammed paper. a. Lift the document feeder input tray Recommended action for onsite technicians 199

b. Remove any paper found under the tray. c. Lower the document-feeder input tray and then close the document feeder cover. NOTE: Verify that the latch on the top of the document-feeder cover is completely closed. 3. For 31.13.02, check for any paper jams or remnants under the document feeder (ADF) blocking in the paper path a. Open the ADF and remove any paper found. 200 Chapter 6 Numerical control panel messages

b. Check for any paper remnants blocking the sensor as well as wiping any paper dust off the glass in the region shown below. If significant debris has accumulated over the circular mirror (used for paper edge sensing) this can cause a paper jam error. 1 2 Callout 1: Check for paper blocking this area. Callout 2: Clean this area with a damp lint free cloth. c. Close the document feeder. 4. Ensure that the paper meets the document feeder (ADF) specifications for the printer. This document outlines the supported weights and sizes of the ADF including best practices: Go to or search for document: HP LaserJet and PageWide Array Enterprise and Managed 500 and 600 - Use the automatic document feeder (ADF): 5. Ensure that the input tray is not overloaded and that the tray guides are set to the correct size. Make sure that the paper stack is correctly aligned at the center of the input tray when paper is Recommended action for onsite technicians 201

loaded in the tray. The correct position of the loaded paper is parallel with the direction of travel into the document feeder paper path. Figure 6-78 Set the ADF guides NOTE: To avoid jams, make sure the guides in the document-feeder input tray are adjusted against the document, without bending the document. To copy narrow documents, use the flatbed scanner. Remove all staples and paper clips from original documents. NOTE: Original documents that are printed on heavy, glossy paper can jam more frequently than originals that are printed on plain paper. 6. Check the Document Feeder Kit consumable status. a. Navigate to and select Supplies on the control panel. b. Select Document Feeder Kit. 202 Chapter 6 Numerical control panel messages

c. See if the Document Feeder Kit status is OK, Low, or Very Low. d. If the status is Low or Very Low, recommend that the customer replace the Document Feeder Kit. Part number: W5U23A/HP 200 ADF Roller Replacement Kit. To order parts, go to <https://store.hp.com> NOTE: Above statement applies to Warranty customers; for Contractual customers, please parts predict or replace the (ADF maintenance replacement roller kit) - W5U23-67901 7. Check and clean the document feeder pickup rollers and separation rollers by removing any visible lint or dust from each of the rollers and using a clean lint-free cloth moistened with warm water. View the How to Clean the Pick Rollers in HP LaserJet and PageWide Printers for detailed instructions. NOTE: Lift up the roller assembly to access and clean the second roller . 8. If necessary, replace the Document Feeder Kit rollers and separation pad. Part number: W5U23-67901/(ADF maintenance replacement roller kit) Recommended action for onsite technicians 203

9. Inspect the ADF pick success sensor, cleaning both the REDI (paper pick success) sensor window and REDI (PAPER PICK SUCCESS) sensor reflector. If there is any dust or fiber remnants, clean by using a can of compressed air to blow out and clean. Figure 6-79 ADF REDI sensor 1 — REDI sensor window 2 — REDI sensor reflector 3 — ADF hatch 10. Check the REDI sensor reflector on flatbed. If there is any dust or fiber remnants, clean it by using a can of compressed air to blow out and clean. (related issue, ADF jam without paper inside) 1 2 Callout 1: Check for paper blocking this area. Callout 2: Clean this area with a damp lint free cloth. 204 Chapter 6 Numerical control panel messages

11. Verify that the connections between the automatic document feeder and the SCB are correctly seated. Figure 6-80 SCB connections 12. Using the Manual Scanner Sensor Test verify functionality of the ADF Paper Path Pick Success sensor. a. Navigate to and select Support Tools. Recommended action for onsite technicians 205

b. Select Troubleshooting. c. Select Diagnostic Tests. 206 Chapter 6 Numerical control panel messages

d. Select Continue. e. Select Manual Sensor Test. Recommended action for onsite technicians 207

f. Select ADF Paper Path Deskew. g. Select ADF Paper Path Pick Success. (Only in FLOW-MODELS) NOTE: Pass is indicated if the working sensor advances the test count. Fail is indicated if the test count is not advancing. h. Close the ADF cover and ensure that is secure and closed correctly. 208 Chapter 6 Numerical control panel messages

13. Open and close the ADF cover to trigger the ADF Paper Path Pick Success sensor. NOTE: Pass is indicated if the working sensor advances the test count. Fail is indicated if the test count is not advanced. 14. If the ADF Paper Path Pick Success test fails to advance the count, replace the document feeder. For instructions: See the Repair Service Manual for this product.

Part number

● Flow models part number: B5L47-67907 ● Non-Flow models part number: B5L47-67906 NOTE: Note: Should a grinding noise be reported or heard in conjunction with the pick/feed of paper through the ADF, replace the document feeder (ADF) unit. Document Feeder whole unit (ADF) part number: ● Flow models part number: B5L47-67909 ● Non-Flow models part number: B5L47-67908 32.XX.YZ error messages 32.* errors Errors in the 32.* family are related to either product start events or to backup and restore events.

Recommended action

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, contact your HP-authorized service or support provider, or contact HP support at www.hp.com/go/contactHP. 1. Turn the printer off, and then on. 2. Retry the job. 32.* errors 209

32.08.A1, 32.08.A2, 32.08.A3

An event related to starting the printer.

32.08.A1 (event code)

Shutdown event. Boot after abnormal shutdown.

32.08.A2 (event code)

Boot from normal shutdown event.

32.08.A3 (event code)

Regular boot event.

Recommended action

There is no action needed for this message. ■ No action necessary.

32.1C.05

The restore job ticket was submitted with invalid credentials.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Verify the credentials that were submitted. 2. Check the domain, user name, and password. 32.1C.06 (event code) The backup job ticket was submitted with invalid credentials.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Verify the credentials that were submitted. 2. Check the domain, user name, and password. 32.1C.07 (event code) Backup restore permissions error. There was an error during the creation, read, or write of the restore file.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Retry the job. 210 Chapter 6 Numerical control panel messages

32.1C.08 (event code) Not enough disk space to perform backup/restore, or a network share issue. There was an error during the creation, read, or write of the backup file.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Retry the job. 2. Remove stored jobs and retry. 3. If the error persists, try using a larger capacity storage device for the share location and check the network share settings. 4. Check the network share or try setting up a new shared network drive or folder. 32.1C.09 (event code) Tried to restore a backup file that was not valid for this printer. The data in the backup file specified in the restore job ticket is no longer valid due to a corruption of the data, or the data is no longer present.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Use a valid backup file. 32.1C.0A (event code) Backup file is invalid. The data in the backup file specified in the restore job ticket is no longer valid due to a corruption of the data, or the data is no longer present.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Use a valid backup file. 2. Reboot, and then observe the state of the printer. 3. If the error persists, perform a partition clean from the Preboot menu. 32.1C.0D (event code) Backup/restore failed, auto-reboot failed, or the printer might be busy.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Reboot, and then retry the backup/restore. 32.1C.08 (event code) 211 32.1C.11 (event code) Backup/restore time-out while communicating with the engine. The backup operation was aborted because the printer is busy.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Wait until the printer is idle, and then try again.

32.1C.13, 32.1C.14

Not enough space exists to perform the backup. The backup was aborted because the disk is at a critical level or full. Scheduled backup failure.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Free up disk space, and then try again.

32.1C.15

The restore operation was aborted because the backup file was created by a previous version of firmware no longer supported by the feature.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Use the current backup file.

32.1C.2E

The restore operation was aborted because the printer is busy.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Wait until the printer is idle, and then retry. 2. Turn the printer off then on, and then retry.

32.1C.2F

Reset failure.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Turn the printer off, and then on. Retry the job. 212 Chapter 6 Numerical control panel messages

32.1C.40

The backup operation completed successfully (informational).

Recommended action

See recommended action. ■ No action necessary.

32.1C.41

The backup operation encountered an error (informational).

Recommended action

See recommended action. ■ No action necessary.

32.1C.42

The backup operation completed, but with a warning message (informational).

Recommended action

See recommended action. ■ No action necessary.

32.1C.43

A component in the backup file is not supported by the current version of firmware and will not be restored (informational).

Recommended action

See recommended action. ■ No action necessary.

32.1C.44

A component in the backup file is not transferable to another printer and will not be restored (informational).

Recommended action

See recommended action. ■ No action necessary.

32.1C.45

Some data was not included in the backup file (informational).

Recommended action

See recommended action.

32.1C.40 213

■ No action necessary.

32.1C.46

An expected component could not be found and was thus not backed up. Because components should be known on backups, this code is a warning (informational).

Recommended action

See recommended action. ■ No action necessary.

32.1C.47

Some data was not restored from the backup file (informational).

Recommended action

See recommended action. ■ No action necessary.

32.1C.48

The backup job ticket was submitted using an invalid network path.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Check that a shared folder was provided as part of the network path and not left blank. 2. Check that the server and the shared folder exists. 3. Check that you (or the applicable user) has permission to access the shared

folder on the provided server.

32.1C.49

The backup job ticket was submitted with a bad encryption. NOTE: This would only apply to a web services call to perform a backup with a blank PIN

Recommended action

Follow these troubleshooting steps in the order presented. ■ Verify that the encryption personal identification number (PIN) meets the restrictions for the printer.

32.1C.4A

An error occurred when creating the temporary directories used to store the backup files in transition to and from the compressed (ZIP) file.

Recommended action

Follow these troubleshooting steps in the order presented. 214 Chapter 6 Numerical control panel messages

1. Retry the job. 2. If this does not resolve the issue, turn the printer off then on again and retry the job. 3. If the error persists, perform a Format Disk procedure using the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - .

32.1C.56

Reset aborted. Backup/restore in progress (informational).

Recommended action

See recommended action. ■ No action necessary.

32.1C.57

Reset aborted (informational).

Recommended action

See recommended action. ■ No action necessary.

32.1C.58

Unknown reset error (informational).

Recommended action

See recommended action. ■ No action necessary.

32.1C.60

The restore operation completed successfully (informational).

Recommended action

See recommended action. ■ No action necessary.

32.1C.61

The restore operation encountered an error.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Review the printer's event log to see specific details about the failure.

32.1C.56 215

32.1C.62

The restore operation completed, but with a warning message.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Review the error log to see specific details about the failure.

32.1C.68

The restore job ticket was submitted using an invalid network path.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Check that a shared folder was provided as part of the network path and not left blank. 2. Check that the server and the shared folder exist. 3. Check that you (or the applicable user) has permission to access the shared folder on the provided server. 4. Check that the path includes the compressed .ZIP file name as part of the path.

32.1C.69

The restore job ticket was submitted with a bad encryption personal identification number (PIN).

Recommended action

Follow these troubleshooting steps in the order presented. ■ Verify the encryption personal identification number (PIN) is the same PIN used to encrypt the backup file.

32.1C.6A

An error occurred when creating the temporary directories used to store the restore files in transition to and from the compressed (ZIP) file.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Retry the job.

32.1C.6D

An unusual error occurred when running the restore operation.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Retry the job. 216 Chapter 6 Numerical control panel messages

33.XX.YZ error messages 33.* errors Errors in the 33.* family are related to the printer's storage system or the formatter. The component might have been previously installed in another printer and is therefore locked to that other printer. Or, the component might be incorrect for this printer.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the issue persists, investigate if the hard disk drive (HDD) or formatter are the original ones. If recently swapped or replaced, turn the printer off, install the original HDD and/or formatter, and then turn the printer on. 3. If the issue persists, locate and notate the complete 33.WX.YZ error message as displayed on the control panel of the printer and contact your HP-authorized service or support provider, or contact customer support at <http://www.hp.com/go/contactHP>.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn off the printer, and then turn on the printer. 2. If the issue persists, investigate if the hard disk drive (HDD) or formatter are the original ones. If recently swapped or replaced, turn the printer off, install the original HDD and/or formatter, and then turn the printer on. 3. If the formatter/HDD were recently replaced and the original is unavailable verify the correct formatter/HDD are installed by referencing the part numbers. 4. If the issue persists, locate and notate the complete 33.WX.YZ error message as displayed on the control panel of the printer. Reference support content for the specific error and take the necessary action. 5. If the error cannot be cleared and you are unable to get the complete error code from the printer, perform a Partial Clean procedure using

the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . CAUTION: A Partial Clean procedure automatically restores the firmware files from the repository, but all custom settings, PINs, passwords, third-party solutions, firmware files, and the operating system are completely lost. 6. If the error persists, download and from the Preboot menu install the latest version of printer firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 7. If the error persists, elevate the case using the Standard Support Process. 33.* errors 217

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn off the printer, and then turn on the printer. 2. If the issue persists, investigate if the hard disk drive (HDD) or formatter are the original ones. If recently swapped or replaced, turn the printer off, install the original HDD and/or formatter, and then turn the printer on. 3. If the formatter/HDD were recently replaced and the original is unavailable verify the correct formatter/HDD are installed by referencing the part numbers. 4. If the issue persists, locate and notate the complete 33.WX.YZ error message as displayed on the control panel of the printer. Reference support content for the specific error and take the necessary action. 5. If the error cannot be cleared and you are unable to get the complete error code from the printer, perform a Partial Clean procedure using the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . CAUTION: A Partial Clean procedure automatically restores the firmware files from the repository, but all custom settings, PINs, passwords, third-party solutions, firmware files, and the operating system are completely lost. 6. If the error persists, download and from the Preboot menu install the latest version of printer firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 7. If the error persists, elevate the case using the Standard Support Process.

33.01.xx

A save or restore process has occurred. ● 33.01.01 (event code) A restore process has occurred. ● 33.01.02 (event code) A save process has occurred. ● 33.01.03 (event code) Save recover functionality OK after previously being disabled.

Recommended action

See recommended action. ■ No action necessary. 218 Chapter 6 Numerical control panel messages

33.02.01 Used board/disk installed

Used board or disk installed. An encrypted board or disk with existing data previously locked to a different printer has replaced the original. If you continue, data is permanently lost. IMPORTANT: Do not install used formatter boards in HP LaserJet, HP PageWide Enterprise or Managed printers. Only replace the formatter when specifically directed to do so during troubleshooting using the Control Panel Message Document (CPMD). If you see the 33.02.01 event code, it means a used board has been installed, and the settings may be incorrect. For more information go to, or search for: HP LaserJet Enterprise, HP LaserJet Managed, HP PageWide Enterprise, HP PageWide Managed - 33.02.01 error or printer name and/or product number changes after replacing the formatter (c06360930).

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. If the 33.02.01 event occurred after updating printer firmware reference support document entitled, "HP FutureSmart - '33.02.01 Used board/disk installed' error received after updating the firmware from HP FutureSmart 4.8.1 or 4.9 to a newer version" (c06488003) 2. If the 33.02.01 is unrelated to a firmware upgrade, perform the following. a. Turn the printer off, and then on. b. If the issue persists, turn the printer off, reinstall the original formatter board or hard disk drive. c. If the issue persists, install a new formatter board or hard disk drive (HDD). Table 6-63 HDD part numbers

Description Part number

320 GB HDD CF235-67901

320 GB HDD (government option) CF235-67920 Table 6-64 Formatter part numbers

Description Part number

Formatter assembly kit CF235-67902 Formatter assembly kit (China) CF235-67903

33.02.01 Used board/disk installed 219

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. If this error appears after updating the firmware, go to WISE and search for the following document: HP FutureSmart - '33.02.01 Used board/disk installed' error received after updating the firmware from HP FutureSmart 4.8.1 or 4.9 to a newer version (c06488003). 2. If the 33.02.01 is unrelated to a firmware upgrade, perform the following. a. Turn the printer off, and then on. b. If the issue persists, turn the printer off, reinstall the original formatter board or hard disk drive. c. If the issue persists, install a new formatter board or hard disk drive (HDD). Table 6-65 HDD part numbers

Description Part number

320 GB HDD CF235-67901

320 GB HDD (government option) CF235-67920 For instructions: See the Service Manual for this printer. Table 6-66 Formatter part numbers

Description Part number

Formatter assembly kit CF235–67902 Formatter assembly kit (China) CF235–67903 3. If the issue persists, elevate using your region's support process.

33.02.02

Save Recover Status Error

The save or recover is disabled, (one or both disabled) (Event Log Only)

Recommended action

There is no action needed for this message. ■ No action necessary.

33.03.02

Data size mismatch. Unable to recover DCC NVRAM.

Recommended action for customers

- Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 220 Chapter 6 Numerical control panel messages
2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, replace the scanner control board (SCB) and return the part to HP for evaluation. Table 6-67 Scanner control board (SCB) part number

Part description Part number

Scanner control PC board assembly B5L47-67903 For instructions: See the Repair Service Manual for this product.

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, turn off the printer, and then disconnect and reconnect all the cables of the scanner control board (SCB). Use the image below for SCB connections. Figure 6-81 Scanner control board (SCB) connections Recommended action for call-center agents 221

Table 6-68 Scanner control board (SCB) connections callout descriptions

Callout Description

1 Staple power

2 SCB power (24v) 3 Cable, PAB to SCAM communication (HDMI) 4 Flatbed sensors (Document feeder open and flatbed paper length-and-cave LED) 5 Flatbed (S1) flat flexible cable (scanner data and flatbed motor) 6 Document feeder (S2) flat flexible cable (Scanner data) 7 Document feeder motors (Feed and deskew) 8 Document feeder sensors (Prescan, Paper present receiver and top hatch)

9 Document feeder ultra sonic sensor receiver and deskew

sensor 10 Letter/Legal (LTR/LGL) Input tray sensor

11 Ultra sonic sensor transmitter

3. Ensure that all the cables on the scanner control board (SCB) are connected and seated correctly before replacing any part. 4. If the error persists, replace the scanner control board (SCB). Table 6-69 Scanner control board (SCB) part number

Part description Part number

Scanner control PC board assembly B5L47-67903 For instructions: See the Repair Service Manual for this product.

33.03.03 Incompatible formatter installed

This is an EFI BIOS event to prevent booting with the wrong formatter installed.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 222 Chapter 6 Numerical control panel messages

■ Turn the printer off, and then install the correct formatter in the printer. For instructions: See the Repair Service Manual for this product. Table 6-70 Part numbers

Description Part number

Formatter PCA (M501dn) J8H61-67901 Formatter PCA (M501dn; China) J8H61-67902 Formatter PCA (M501n) J8H60-67901 Formatter PCA (M501n; China) J8H60-67902 Formatter PCA kit (M506n/dn) F2A68-67915 Formatter PCA kit (M506x) F2A68-67916 Formatter PCA kit (M527) F2A76-67910

33.03.05 EFI Boot error

EFI BIOS event showing that a replacement formatter Recover attempt was unsuccessful.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

This issue is caused by an unsuccessful formatter recovery after a formatter has been replaced. Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, perform a Partial Clean using the Preboot menu or the Embedded Web Server

(EWS).

NOTE: A Partial Clean erases all custom settings, PINs, passwords, third-party solutions, firmware files, and the operating system. It automatically reboots the printer and restores the firmware files from the repository. 3. If the error persists, update the printer firmware. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 4. If the error persists after a firmware update, dispatch a service technician to replace the formatter. Use the following table to order the correct part number for your printer.

33.03.05 EFI Boot error 223

Table 6-71 Formatter PCA part numbers

Product models Part description Part number

M501dn Formatter PC board J8H61-67901 M501dn (China) Formatter PC board J8H61-67902 M501n Formatter PC board J8H60-67901 M501n (China) Formatter board assembly J8H60-67902 M506n/ M506dn E50045n/ E50045dn Formatter PC board assembly F2A68-67915 M506x E50045x Formatter PC board assembly F2A68-67916 M507

E50145

Formatter PC board 1PV87-60001 M527

E52545

Formatter PC board assembly F2A76-67910 M528

E52645

Formatter PC board 1PV64-60002

Recommended action for onsite technicians

This issue is caused by an unsuccessful formatter recovery after a formatter has been replaced. Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, perform a Partial Clean using the Preboot menu or the Embedded Web Server

(EWS).

NOTE: A Partial Clean erases all custom settings, PINs, passwords, third-party solutions, firmware files, and the operating system. It automatically reboots the printer and restores the firmware files from the repository. 3. If the error persists, update the printer firmware. For instructions, go to HP Enterprise, HP Managed - Update the printer firmware (ish_4158468-4158516-16). 4. If the error persists, remove and reinstall the formatter board. 5. If the error persists, replace the formatter. Use the following table to order the correct part number for your printer. Table 6-72 Formatter PCA part numbers

Product models Part description Part number

M501dn Formatter PC board J8H61-67901 M501dn (China) Formatter PC board J8H61-67902 224 Chapter 6 Numerical control panel messages

Table 6-72 Formatter PCA part numbers (continued)

Product models Part description Part number

M501n Formatter PC board J8H60-67901 M501n (China) Formatter board assembly J8H60-67902 M506n/ M506dn E50045n/ E50045dn
Formatter PC board assembly F2A68-67915 M506x E50045x Formatter PC board assembly F2A68-67916 M507

E50145

Formatter PC board 1PV87-60001 M527

E52545

Formatter PC board assembly F2A76-67910 M528

E52645

Formatter PC board 1PV64-60002 For instructions: See the Repair Service Manual for this product. 6. If the error persists after replacing the formatter, elevate the case using the Standard Support Process.

33.03.06

The memory PCA was not detected on startup.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on again. 2. If the error persists, turn the printer off, disconnect the power cord, and remove the formatter cover. Press firmly on the memory PCA cable connection to the formatter. 3. If the error persists, replace the memory PCA assembly. Table 6-73 Part numbers

Description Part Number

Memory PCA (M506) RM2-7955-000CN

33.03.06 225

Table 6-73 Part numbers (continued)

Description Part Number

Memory PCA (M527) RM2-7955-000CN

33.04.01 Missing TPM

A Trusted Platform Module is missing from a printer that previously had a TPM installed. TPM accessory (optional): This system is using a TPM module installed as an accessory to protect data and it is not present. The original TPM must be returned or you can select the Stop Using option in the preboot TPM sub-menu. All data will be cryptographically erased and a reload of firmware from USB might be required. TPM Standard (Standard on product): This system is using a TPM module installed at the factory to protect data and it is not present. Verify that the TPM is seated firmly on the formatter, in case of shifting during shipment. If the TPM has been removed for a formatter replacement, put the original TPM on the board. If the original TPM cannot be reinstalled or has become damaged, DO NOT replace any parts. Replace the printer.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off. 2. Reinstall the missing TPM module into the printer. NOTE: If the TPM accessory was installed, you can also go to the Administration menu and under TPM, select the Stop Using option if you no longer want to use the TPM accessory. 3. Restart the printer.

33.04.02 Missing TPM

The wrong TPM is installed on a printer that previously had a different TPM installed. TPM Optional device: This system is using a TPM module to protect data and it is not present. The original TPM module must be returned or you may select the Stop Using option in the preboot TPM sub-menu.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off. 2. Reinstall the original TPM module into the printer. 3. Restart the printer. 4. Go to the Administration menu and under TPM and select the Enable and Use option. NOTE: To no longer use the TPM device, go to the Administration menu and under TPM and select the Stop Using option. 226 Chapter 6 Numerical control panel messages

33.04.03 Unknown TPM

A used TPM has been installed on a printer that has not previously had a TPM installed. TPM Optional device: This system is using a TPM module to protect data and it is not present. The TPM module currently installed is used to protect data in another device. The original TPM module must be returned or you can start using this TPM module by selecting the Enable and Use option in the preboot TPM sub-menu. You can also stop using a TPM altogether.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off and remove the TPM module. The printer will not be protected. 2. If choosing to protect the printer with the used TPM, refer to the "Install a new or re-enable an existing TPM after disabling a previous TPM" section of the <http://h10032.www1.hp.com/ctg/Manual/c04499622> (c04499622).

33.04.05

TPM (Trusted Platform Module) Security Error This system contains a TPM module that is not supported on the device or belongs to another device. TPM is unique for each device. For units that shipped with a TPM on board standard (most newer models): If the original TPM installed in the factory is unavailable or damaged, DO NOT replace any parts. Follow the recommended action.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order they are listed. The technician will need to re-establish the trusted platform module state in the printer. NOTE: Never replace the TPM on a unit that shipped with one. The TPM that can be ordered is only available for adding a level of security on a device that never had a TPM paired from the factory. A new TPM cannot be installed for security reasons. 1. Do not replace the formatter or HDD. It will not solve this issue. 2. Perform a Format Disk procedure, select Continue in the Pre-boot menu, and then reboot the device. ● If the unit boots to a 33.04.05 error, reseal the eMMC or HDD. ● If the unit continues to boot to a 33.04.05 error, continue to the next step.

33.04.03 Unknown TPM 227

3. Perform a Format Disk procedure again, and then reboot the device. ● If the unit boots to a 99.09.67 error, reboot the device, and then update the firmware. This should resolve the issue. ● If the unit continues to boot to a 33.04.05 error, continue to the next steps. 4. Remove the TPM and eMMC or HDD, open Startup Options, and then perform a Cold Reset. WARNING! When removing the TPM, take extreme care as the connector on the TPM board can become dislodged and break. If this happens, a printer replacement will be required. 5. Reinstall the eMMC or HDD, open the Pre-boot menu, select Manage Disk, select Boot Device, and then select Erase Unlock. ● If unit boots to a 99.09.67 error, reboot the device, and then update the firmware. This should resolve the issue. ● If the unit continues to boot to a 33.04.05 error, continue to the next step. 6. Reseat the TPM and eMMC or HDD, perform a Format Disk, open Diagnostics, and then run diagnostics for all

components. ● If the Diagnostics fail, elevate the case to ATS and include all details. ● If Diagnostics passes, continue to the next steps. 7. Remove the TPM and eMMC or HDD, open Startup Options, and then perform a Cold Reset. 8. Reinstall the eMMC or HDD, open the Pre-boot menu, select Manage Disk, select Boot Device, select Erase Unlock, and then reboot the device. ● If the unit boots to a 99.09.67 error, reboot and then update the firmware. This should resolve the issue. ● If the unit continues to boot to a 33.04.05 error, continue to the next step. 9. Include the following information in the CDAX case notes, and then elevate the case to ATS. No additional feedback is needed. NOTE: Ensure that all original printer parts are installed on the unit at the time of elevation. ● Printer serial number. ● Collect the Diagnostic log file (.jdp file). ● Information when the 33.04.05 error displayed on the printer control panel. ● Parts replaced prior to the error displaying on the printer control panel.

33.05.0X SureStart errors

The printer detected and recovered from a corrupted version of BIOS. ● 33.05.01 Boot code corrupt (Event code) ● 33.05.02 Boot code corrupt (Event code) ● 33.05.03 Boot code corrupt (Event code) 228 Chapter 6 Numerical control panel messages

Recommended action

See recommended action. ■ No action necessary.

33.05.0X SureStart errors

The newly downloaded firmware failed to cryptographically validate the BIOS code. ● 33.05.04 Security alert ● 33.05.04 Upgrade corrupt - (Event code) ● 33.05.05 Security alert ● 33.05.05 Boot code corrupt - (Event code) ● 33.05.06 Security alert ● 33.05.06 Upgrade corrupt - (Event code) ● 33.05.07 Security alert ● 33.05.07 Upgrade corrupt - (Event code)

Recommended action

Follow these troubleshooting steps in the order presented. ■ Download a firmware bundle to the device from the Preboot menu. For more information on SureStart, go to HP LaserJet Enterprise, go to: See the Repair Service Manual for this product.

33.05.0z SureStart errors

A SureStart error has occurred. The printer detected and recovered from a corrupted version of BIOS. ● 33.05.01 Boot code corrupt (event code) ● 33.05.02 Boot code corrupt (event code) ● 33.05.03 Boot code corrupt (event code) The newly downloaded firmware failed to cryptographically validate the BIOS code. ● 33.05.04 Security alert ● 33.05.04 Upgrade corrupt (event code) ● 33.05.05 Security alert ● 33.05.05 Boot code corrupt (event code) ● 33.05.06 Security alert ● 33.05.06 Upgrade corrupt (event code) Recommended action 229 ● 33.05.07 Security alert ● 33.05.07 Upgrade corrupt (event code) ● 33.05.08 Invalid boot attempt (event code) ● 33.05.09 Downgrade attempted (event code)

Recommended action

Follow these troubleshooting steps in the order presented. ● For 33.05.01, 33.05.02, and 33.05.03 errors: No action is necessary. ● For all other errors: Download a firmware bundle to the printer from the Preboot menu. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions NOTE: For more information on SureStart, search for: "SureStart Whitelisting and Intrusion Detection Troubleshooting Manual" (c04863614) .

33.05.1x Whitelisting errors

An error occurred with a firmware file digital signature or an error with the certificate used to validate the firmware file certificate. ● 33.05.10 Security alert ● 33.05.10 Firmware verification Error: XX (Event code) ● 33.05.11 Security alert ● 33.05.11 Firmware verification Error: XX (Event code) ● 33.05.12 Security alert ● 33.05.12 Firmware verification Error: XX (Event code)

Recommended action

Follow these troubleshooting steps in the order presented. 1. Perform a Format Disk procedure. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) . 2. If the device does not reboot to Ready, download a firmware bundle to the device from the Preboot menu. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions NOTE: Performing a Format Disk procedure is required before downloading a firmware bundle. For more information on SureStart, go to: (Doc ID: c04863614). HP SureStart Whitelisting and Intrusion

Detection Troubleshooting Manual

230 Chapter 6 Numerical control panel messages

33.05.2x Intrusion detection errors

The intrusion detection system has encountered an error. The intrusion detection memory process determined an unauthorized change in system memory. ● 33.05.21 Security alert ● 33.05.21 Potential intrusion (Event code) The intrusion detection memory process heartbeat was not detected. ● 33.05.22 Security alert ● 33.05.22 Cannot scan for potential intrusions (Event code) The intrusion detection memory process did not initialize. ● 33.05.23 Security alert ● 33.05.23 Intrusion detection not initialized (Event code) ● 33.05.24 Intrusion detection initialization error (Event code)

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off then on. 2. Make sure that the printer is in a Ready state. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off then on. 2. Make sure that the printer is in a Ready state. NOTE: Selecting Continue from the Preboot menu will not resolve the error. The printer must be turned off, and then on to clear the error allowing the printer to reboot to a Ready state. NOTE: With firmware version 3.7, when selecting Continue from the Preboot menu after encountering a 33.05.2z or 33.05.5z error, the following message displays: "A disk or boot error has occurred. Clear Error. Press Any Key" This message should be ignored. Information on the Intrusion Detection error. For more information on SureStart, go to: HP SureStart Whitelisting and Intrusion Detection Troubleshooting Manual (Doc ID: c04863614).

33.05.2x Intrusion detection errors 231

33.05.5z Intrusion detection errors

The intrusion detection system has encountered an error. The intrusion detection memory process determined an unauthorized change in system memory. ● 33.05.51 Security alert ● 33.05.51 Potential intrusion (Event code) The intrusion detection memory process heartbeat was not detected. ● 33.05.52 Security alert ● 33.05.52 Cannot scan for potential intrusions (Event code) The intrusion detection memory process did not initialize. ● 33.05.53 Security alert ● 33.05.53 Intrusion detection not initialized (Event code) ● 33.05.54 Intrusion detection initialization error (Event code)

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off then on. 2. Make sure that the printer is in a Ready state. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off then on. 2. Make sure that the printer is in a Ready state. NOTE: Selecting Continue from the Preboot menu will not resolve the error. The printer must be turned off, and then on to clear the error allowing the printer to reboot to a Ready state. NOTE: With firmware version 3.7, when selecting Continue from the Preboot menu after encountering a 33.05.2z or 33.05.5z error, the following message displays: "A disk or boot error has occurred. Clear Error. Press Any Key" This message should be ignored. Information on the Intrusion Detection error. For more information on SureStart, go to: HP SureStart Whitelisting and Intrusion Detection Troubleshooting Manual (Doc ID: c04863614).

33.06.01

The firmware is not able to detect the correct memory chip on the formatter. This issue occurs because the wrong formatter was installed in the printer.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Remove the formatter that was installed and reinstall the original or order the correct formatter for the printer. 3. Reinstall all the parts including HDD/eMMC, TPM and any additional accessories. 4. Reload firmware from a USB stick using the pre-boot menu if necessary. Make sure that you download the file for the correct printer model. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 40.XX.YZ error messages 40.* errors Errors in the 40.* family are related to input/output accessories, such as USB storage devices, Jetdirect cards, or EIO cards or on-board network functions.

Recommended action

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, contact your HP-authorized service or support provider, or contact HP support at www.hp.com/go/contactHP. 1. Touch the OK button to clear the error. 2. Remove and then reinstall the accessory.

40.00.01 USB I/O buffer overflow To continue, touch "OK"

The USB buffer has overflowed.

Recommended action

Follow these troubleshooting steps in the order presented.

33.06.01 233

1. Touch the OK button to print the transferred data (some data might be lost). 2. Check the host configuration.

40.00.02 Embedded I/O buffer overflow To continue, touch "OK"

The product has experienced a JetDirect buffer overflow.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Touch the OK button to print the transferred data (some data might be lost). 2. Check the host configuration.

40.00.03 EIO [x] buffer overflow To continue, touch “OK”

Too much data was sent to the EIO card in the specified slot (x). An incorrect communications protocol might be in use.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to print the transferred data (some data might be lost).

40.00.04 EIO [x] bad transmission To continue, touch “OK”

The connection between the product and the USB device has been broken.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Touch the OK button to clear the error message and continue printing. 2. Remove, and then reinstall the USB device.

40.00.05 Embedded I/O bad transmission To continue, touch OK

The USB device has been removed.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Touch the OK button to clear the error message (data will be lost). 2. Install the USB device.

40.08.0x USB storage accessory removed

The USB storage accessory has been removed. x = 0 or 1; information code. Secure file erase is enabled. 234 Chapter 6 Numerical control panel messages

Recommended action

See recommended action. ■ No action necessary. 41.XX.YZ error messages 41.* errors Errors in the 41.* family are related to printing problems, such as a mismatch between the paper that is in the printer and the paper the printer is configured to use.

Recommended action

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Verify the tray is loaded with the correct paper type, and that the guides are adjusted correctly. 2. Verify the paper type and size settings on the control panel match the paper in the tray. 3. Verify the paper type and size settings in the print driver match the paper in the tray. 4. Use the Tray/Bin manual sensor test to verify the media switch in the cassette is working correctly. 5. Turn the printer off and then on. 6. If the issue persists, replace the DC controller.

41.01.YZ

An unknown misprint error occurred on the printer. Event log error message: 41.01.YZ. Y = Type, Z = Tray ● Y = 0: Photo Media (1, 2, or 3) ● Y = 1: Auto Sense (Normal) ● Y = 2: Normal (typed not from Auto Sense) ● Y = 3: Light media 1, 2, or 3 mode ● Y = 4: Heavy media 1 ● Y = 5: Heavy media 2 ● Y = 6: Heavy media 3 ● Y = 7: Glossy media 1 ● Y = 8: Glossy media 2 ● Y = 9: Glossy media 3 Recommended action 235

● Y = A: Glossy film

● Y = B: OHT

● Y = C: Label ● Y = D: Envelope 1, 2, or 3 mode ● Y = E: Rough ● Y = F: Other mode ● Z = 0: From unknown tray ● Z = 1: From Tray 1 ● Z = 2: From Tray 2 ● Z = 3: From Tray 3 ● Z = 4: From Tray 4 ● Z = 5: From Tray 5 ● Z = 6: From Tray 6 ● Z = 7: From Tray 7 ● Z = 8: From Tray 8 ● Z = 9: From Tray 9 ● Z = D: From duplex

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, attempt to remove and reinstall the toner cartridge. Ensure that the printer is using genuine HP toner cartridges. a. Make sure to turn the printer off, and then wait 30 seconds. b. Press the top-cover-release button on the left side of the printer. c. Open the front door (or toner-cartridge door). d. Grasp the handle of the toner cartridge to remove the toner cartridge from the printer. e. Check if a genuine HP toner cartridge is installed. A genuine HP toner cartridge has the word “HP” on it, or has the HP logo on it. For more information on identifying HP cartridges go to

<http://www.hp.com/go/learnaboutsupplies>. f. Align the toner cartridge with the tracks inside the printer, and then install the toner cartridge until it is firmly seated. g. Close the front door. 236 Chapter 6 Numerical control panel messages

h. Use the power button to turn on the printer. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Touch OK to clear the error. 2. If the error is not cleared, turn off the printer, and then turn on the printer. 3. If the error persists, visually inspect the toner cartridge, and then reinstall the toner cartridge. a. Open the front door to remove the toner cartridge. b. Check the toner cartridge and ensure it is a genuine HP toner cartridge. c. Swap out the toner cartridge to test it. d. Install the toner cartridge until it is firmly seated, and then close the front door. 4. Ensure that the toner cartridges are HP original cartridges and that the cartridges are seated correctly before replacing any other parts. 5. If the error persists, replace the laser/scanner assembly. Table 6-74 Laser scanner assembly part number

Part description Part number

Assembly- Laser scanner RM2-4860-000CN For instructions: See the Repair Service Manual for this product.

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Touch OK to clear the error. 2. If the error is not cleared, turn off the printer, and then turn on the printer. 3. If the error persists, visually inspect the toner cartridge, and then reinstall the toner cartridge. Ensure that the toner cartridges are HP original cartridges and that the cartridges are seated correctly before replacing any other parts. a. Open the front door to remove the toner cartridge. b. Check the toner cartridge and ensure it is a genuine HP toner cartridge. c. Install the toner cartridge until it is firmly seated, and then close the front door. 4. If the error reoccurs, check the wire harness from the laser/scanner to the DC controller. a. Make note of all the connectors on the laser/scanner assembly and DC controller. Recommended action for call-center agents 237

b. Disconnect and reconnect the cables. Ensure that the connectors are correctly connected and seated before replacing any part. 5. If the error persists, replace the laser/scanner assembly. Table 6-75 Laser scanner assembly part number

Part description Part number

Assembly- Laser scanner RM2-4860-000CN For instructions: See the Repair Service Manual for this product. 6. If the error persists after replacing the laser/scanner assembly, replace the DC controller. Table 6-76 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

For instructions: See the Repair Service Manual for this product.

41.02.00 Error

A beam detected misprint error occurred.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. To clear the error message, touch OK. 238 Chapter 6 Numerical control panel messages

2. If the error persists, turn the printer off, and then on. 3. Verify that the toner cartridge is in good condition and the shutter works correctly. Swap the toner cartridge to test as needed. 4. If the error returns, check the wire harness from the laser/scanners to the DC controller. 5. If the error persists, replace the laser/scanner assembly and the laser/scanner cable. For instructions: See the Repair Service Manual for this product. Part number: RM2-5528-000CN

41.03.01, 41.03.A1, 41.03.B1, 41.03.C1

The printer detected a different paper size than expected. Paper Size mismatch (0,A,B) or inter-page gap (C) error from Tray 1.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Print the configuration page to verify the size and type to which the trays are set. 3. Make sure that the tray is loaded with the correct paper size and that the sliding paper guides are correctly adjusted to the correct paper size. 4. Print internal pages from all trays to verify that this error only occurs when printing from the PC. 5. Set Tray 1 Size to ANY, and attempt to print again. 6. Verify that the error is not occurring as a result of an unexpected paper size trigger caused by a multi-page feed. 7. Verify that the toner cartridge and the transfer roller are seated correctly. 8. Check the tray 1 rollers and make sure they are not worn smooth, or coated with paper dust or other debris. If the rollers are causing the issue, replace the tray 1 roller kit. Part number: Tray 1 Roller kit - F2A68-67914 9. If the error persists, please contact customer support. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Print the configuration page to verify the size and type to which the trays are set. 3. Set Tray 1 Size to ANY and attempt to print again. 4. Make sure that the tray is loaded with the correct paper size and that the sliding paper guides are correctly adjusted to the correct paper size.

41.03.01, 41.03.A1, 41.03.B1, 41.03.C1 239

5. Verify that the error is not occurring as a result of an unexpected paper size trigger caused by a multi-page feed. 6. Print internal pages from all trays to verify that this error only occurs when printing from the PC. If the error only occurs from the PC, check the print driver settings and ensure they are correct. 7. Verify that the toner cartridge and the transfer roller are seated correctly. 8. Check the rollers and make sure they are not worn smooth, or coated with paper dust or other debris. If the rollers are causing the issue, replace the roller kit. Part number: Roller kit - F2A68-67914 9. Remove and reconnect the connectors for the paper path sensors, intermediate-transfer belt, and the DC controller PCA. 10. Test the registration assembly motor and clutch. If they do not function correctly replace the registration assembly. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test Part Number (M501/M506/E50045/M527/E52545): RM2-5671-000CN Part Number (M507/E50145/M528/E52645): RM2-2577-000CN 11. Check the paper path sensors for correct operation and ensure that they do not stick at all. If the issue persists, elevate the issue using the Standard Support Process for a possible printer replacement. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test 12. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement.

41.03.02, 41.03.A2, 41.03.B2, 41.03.C2 Error

The printer detected a different paper size than expected. Paper Size mismatch (0,A,B) or inter-page gap (C) error from Tray 2.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Check if paper is loaded correctly in the paper tray. Use paper that meets HP specifications for this printer. 3. Print a Configuration page to verify the size and type to which the trays are set. Make sure that the selected paper size and type meets the HP specifications for the printer. 240 Chapter 6 Numerical control panel messages

a. From the Home screen on the printer control panel, select Administration or the Reports button. NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the Reports menu, and then select Configuration/Status Pages. c. Select OK or Print to print the page. 4. Make sure to load the tray with the correct paper size and the paper guides are adjusted to the correct size for the paper. NOTE: Do not adjust the paper guides tightly against the paper stack. Adjust them to the indentations or markings in the tray. 5. Print internal pages from all trays to verify that this error only occurs when printing from the PC. 6. Verify that the error is not occurring as a result of an unexpected paper size trigger caused when multiple pages are picked up during paper feed. 7. Verify that the toner cartridge and the transfer roller are seated correctly. 8. Make sure that the rollers are installed correctly and show no damage or wear. Check if the rollers are worn out or coated with paper dust or other debris. ● If the rollers are not clean, use a damp, lint-free cloth to clean the rollers in the appropriate tray. ● If the rollers are worn or damaged and causing the issue, replace the roller kit. Table 6-77 Tray 2 roller kit part number

Part description Part number

Kit-Trays 2X Roller RM2-5752-000CN 9. If the error persists, contact HP customer support. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Print the configuration page to verify the size and type to which the trays are set. 3. Make sure that the tray is loaded with the correct paper size and that the sliding paper guides are correctly adjusted to the correct paper size. 4. Verify that the error is not occurring as a result of an unexpected paper size trigger caused by a multi-page feed. 5. Print internal pages from all trays to verify that this error only occurs when printing from the PC. If the error only occurs from the PC, check the print driver settings and ensure they are correct. 6. Verify that the toner cartridge and the transfer roller are seated correctly. Recommended action for call-center agents and onsite technicians 241

7. Check the rollers and make sure they are not worn smooth, or coated with paper dust or other debris. If the rollers are causing the issue, replace the roller kit. Part number: Roller kit - F2A68-67913 8. Use the Tray/Bin manual sensor test to verify that the cassette media switch is functioning correctly. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test 9. Check the paper path sensors for correct operation and ensure that they do not stick at all. If the issue persists, elevate the issue using the Standard Support Process for a possible printer replacement. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test 10. Remove and reconnect the connectors for the paper path sensors, intermediate-transfer belt, and the DC controller PCA. 11. Test the registration assembly motor and clutch. If they do not function correctly replace the registration assembly. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test Part Number (M501/M506/E50045/M527/E52545): RM2-5671-000CN Part Number (M507/E50145/M528/E52645): RM2-2577-000CN 12. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement.

41.03.02 with slow printing

Some instances of slow printing and 41.03.02 have been seen caused by timing issues with the correct size paper loaded.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Check if paper is loaded correctly in the paper tray. Use paper that meets HP specifications for this printer. 3. Print a Configuration page to verify the size and type to which the trays are set. Make sure that the selected paper size and type meets the HP specifications for the printer. a. From the Home screen on the printer control panel, select Administration or the Reports button. NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the Reports menu, and then select Configuration/Status Pages. 242 Chapter 6 Numerical control panel messages

c. Select OK or Print to print the page. 4. Make sure to load the tray with the correct paper size and the paper guides are adjusted to the correct size for the paper. NOTE: Do not adjust the paper guides tightly against the paper stack. Adjust them to the indentations or markings in the tray. 5. Print internal pages from all trays to verify that this error only occurs when printing from the PC. 6. Verify that the error is not occurring as a result of an unexpected paper size trigger caused when multiple pages are picked up during paper feed. 7. Verify that the toner cartridge and the transfer roller are seated correctly. 8. Make sure that the rollers are installed correctly and show no damage or wear. Check if the rollers are worn out or coated with paper dust or other debris. ● If the rollers are not clean, use a damp, lint-free cloth to clean the rollers in the appropriate tray. ● If the rollers are worn or damaged and causing the issue, replace the roller kit. Table 6-78 Tray 2 roller kit part number

Part description Part number

Kit-Trays 2X Roller RM2-5752-000CN 9. If the error persists, contact HP customer support.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Print a Configuration page to verify the size and type to which the trays are set. Make sure that the selected paper size and type meets the HP specifications for the printer. 3. Make sure that the tray is loaded with the correct paper size and the paper guides are adjusted to the correct size for the paper. NOTE: Do not adjust the paper guides tightly against the paper stack. Adjust them to the indentations or markings in the tray. 4. Verify that the error is not occurring as a result of an unexpected paper size trigger caused by a multi-page feed. 5. Print internal pages from all trays to verify that this error only occurs when printing from the PC. 6. Verify that the toner cartridge and the transfer roller are seated correctly. Recommended action for call-center agents 243

7. Check the rollers and make sure they are not worn smooth, or coated with paper dust or other debris. If the rollers are causing the issue, send the customer a roller kit. Table 6-79 Tray 2 roller kit part number

Part description Part number

Kit-Trays 2X Roller RM2-5752-000CN 8. Select the Tray/Bin Manual Sensor Test on the control panel to verify that the cassette paper switch is functioning correctly. a. From the Home screen on the printer control panel, scroll to and touch the Administration (FutureSmart 3), or Support Tools (FutureSmart 4). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following menus: Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test. c. Activate the desired sensor, and then check the control panel display to verify the sensor is in a active or inactive state. 9. Run a Paper Path Sensors test using the control panel to view the status of each paper path sensor. Ensure that the sensors are functioning correctly. a. From the Home screen on the printer control panel, scroll to and touch the Administration (FutureSmart 3), or Support Tools (FutureSmart 4). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following menus: Troubleshooting > Diagnostic Tests > Paper Path Sensors. c. Select Start to run the test. 10. If the error persists after performing the sensor tests, elevate the issue using the Standard Support Process for a possible printer replacement. 11. Test whether the registration assembly motor and clutch function correctly. a. From the Home screen on the printer control panel, scroll to and touch the Administration (FutureSmart 3), or Support Tools (FutureSmart 4). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following menus: Troubleshooting > Diagnostic Tests > Component Test. c. Select the component and desired options. 244 Chapter 6 Numerical control panel messages

12. If the registration assembly is not functioning correctly, replace the registration assembly. Table 6-80 Registration roller assembly part number

Product model Part description Part number

M501 M506 M527

E50045

E52545

Registration roller assembly RM2-5671-000CN M507 M528

E50145

E52645

Registration roller assembly RM2-2577-000CN

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Print a Configuration page to verify the size and type to which the trays are set. Make sure that the selected paper size and type meets the HP specifications for the printer. 3. Make sure that the tray is loaded with the correct paper size and the paper guides are adjusted to the correct size for the paper. NOTE: Do not adjust the paper guides tightly against the paper stack. Adjust them to the indentations or markings in the tray. 4. Verify that the error is not occurring as a result of an unexpected paper size trigger caused by a multi-page feed. 5. Print internal pages from all trays to verify that this error only occurs when printing from the PC. 6. Verify that the toner cartridge and the transfer roller are seated correctly. 7. Check the rollers and make sure they are not worn smooth, or coated with paper dust or other debris. If the rollers are causing the issue, send the customer a roller kit. Table 6-81 Tray 2 roller kit part number

Part description Part number

Kit-Trays 2X Roller RM2-5752-000CN 8. Select the Tray/Bin Manual Sensor Test on the control panel to verify that the cassette paper switch is functioning correctly. Recommended action for onsite technicians 245

a. From the Home screen on the printer control panel, scroll to and touch the Administration (FutureSmart 3), or Support Tools (FutureSmart 4). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following

menus: Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test. c. Activate the desired sensor, and then check the control panel display to verify the sensor is in a active or inactive state. 9. Check the paper path sensors to ensure the sensors are functioning correctly. a. From the Home screen on the printer control panel, scroll to and touch the Administration (FutureSmart 3), or Support Tools (FutureSmart 4). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following menus: Troubleshooting > Diagnostic Tests > Paper Path Sensors. c. Select Start to run the test. 10. If the error persists after performing the sensor tests, elevate the issue using the Standard Support Process for a possible printer replacement. 11. Test whether the registration assembly motor and clutch function correctly. a. From the Home screen on the printer control panel, scroll to and touch the Administration (FutureSmart 3), or Support Tools (FutureSmart 4). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following menus: Troubleshooting > Diagnostic Tests > Component Test. c. Select the component and desired options. 12. If the registration assembly is not functioning correctly, replace the registration assembly. Table 6-82 Registration roller assembly part number

Product model Part description Part number

M501 M506 M527

E50045

E52545

Registration roller assembly RM2-5671-000CN M507 M528

E50145

E52645

Registration roller assembly RM2-2577-000CN 246 Chapter 6 Numerical control panel messages

13. If the issue persists, perform an engine test with and without a formatter. To perform an engine test, follow these steps: a. Load paper in Tray 2. NOTE: The test page can only use Tray 2 as the paper source, so make sure that paper is loaded in Tray 2. b. Turn the printer on, and then use a small pointed object (like a paper clip) to depress the test-page switch located on the rear side of the printer (near the formatter). The test page should have a series of lines that are parallel to the short end of the page. Figure 6-82 Engine test-page switch c. Check if the engine test page prints or does not print. ● If the engine-test page does not print, try removing the formatter, and then performing the engine test again. ● If the engine test page prints without a formatter, the problem is with the formatter. 14. If the engine test page prints without a formatter, replace the formatter. Use the following table to order the correct part number for your printer. Table 6-83 Formatter PCA part numbers

Product models Part description Part number

M501dn Formatter PC board J8H61-67901 M501dn (China) Formatter PC board J8H61-67902 M501n Formatter PC board J8H60-67901 M501n (China) Formatter board assembly J8H60-67902 M506n/ M506dn E50045n/ E50045dn Formatter PC board assembly F2A68-67915 Recommended action for onsite technicians 247

Table 6-83 Formatter PCA part numbers (continued)

Product models Part description Part number

M506x E50045x Formatter PC board assembly F2A68-67916 M507

E50145

Formatter PC board 1PV87-60001 M527

E52545

Formatter PC board assembly F2A76-67910 M528

E52645

Formatter PC board 1PV64-60002 For instructions: See the Repair Service Manual for this product. 15. If replacing the formatter does not resolve the issue, replace the DC controller. Use the following table to order the correct part number for your printer. Table 6-84 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

For instructions: See the Repair Service Manual for this product.

41.03.03, 41.03.A3, 41.03.B3, 41.03.C3 Error

The printer detected a different paper size than expected. Paper Size mismatch (0,A,B) or inter-page gap (C) error from Tray 3.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 248 Chapter 6 Numerical control panel messages

1. Touch OK to use another tray. 2. Check if paper is loaded correctly in the paper tray. Use paper that meets HP specifications for this printer.
3. Print a Configuration page to verify the size and type to which the trays are set. Make sure that the selected paper size and type meets the HP specifications for the printer. a. From the Home screen on the printer control panel, select Administration or the Reports button. NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the Reports menu, and then select Configuration/Status Pages. c. Select OK or Print to print the page. 4. Make sure to load the tray with the correct paper size and the paper guides are adjusted to the correct size for the paper. NOTE: Do not adjust the paper guides tightly against the paper stack. Adjust them to the indentations or markings in the tray. 5. Print internal pages from all trays to verify that this error only occurs when printing from the PC. 6. Verify that the error is not occurring as a result of an unexpected paper size trigger caused when multiple pages are picked up during paper feed. 7. Verify that the toner cartridge and the transfer roller are seated correctly. 8. Make sure that the rollers are installed correctly and show no damage or wear. Check if the rollers are worn out or coated with paper dust or other debris. ● If the rollers are not clean, use a

damp, lint-free cloth to clean the rollers in the appropriate tray. ● If the rollers are worn or damaged and causing the issue, replace the roller kit. Table 6-85 Tray 2 roller kit part number

Part description Part number

Kit-Trays 2X Roller RM2-5752-000CN 9. If the error persists, contact HP customer support. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Print the configuration page to verify the size and type to which the trays are set. 3. Make sure that the tray is loaded with the correct paper size and that the sliding paper guides are correctly adjusted to the correct paper size. Recommended action for call-center agents and onsite technicians 249

4. Verify that the error is not occurring as a result of an unexpected paper size trigger caused by a multi-page feed. 5. Print internal pages from all trays to verify that this error only occurs when printing from the PC. If the error only occurs from the PC, check the print driver settings and ensure they are correct. 6. Verify that the toner cartridge and the transfer roller are seated correctly. 7. Check the rollers and make sure they are not worn smooth, or coated with paper dust or other debris. If the rollers are causing the issue, replace the roller kit. Part number: Roller kit - F2A68-67913 8. Use the Tray/Bin manual sensor test to verify that the cassette media switch is functioning correctly. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test 9. Check the paper path sensors for correct operation and ensure that they do not stick at all. If the issue persists, elevate the issue using the Standard Support Process for a possible printer replacement. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test 10. Remove and reconnect the connectors for the paper path sensors, intermediate-transfer belt, and the DC controller PCA. 11. Test the registration assembly motor and clutch. If they do not function correctly replace the registration assembly. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test Part Number (M501/M506/E50045/M527/E52545): RM2-5671-000CN Part Number (M507/E50145/M528/E52645): RM2-2577-000CN 12. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement.

41.03.04, 41.03.A4, 41.03.B4, 41.03.C4

The printer detected a different paper size than expected. Paper Size mismatch (0,A,B) or inter-page gap (C) error from Tray 4.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Check if paper is loaded correctly in the paper tray. Use paper that meets HP specifications for this printer. 250 Chapter 6 Numerical control panel messages

3. Print a Configuration page to verify the size and type to which the trays are set. Make sure that the selected paper size and type meets the HP specifications for the printer. a. From the Home screen on the printer control panel, select Administration or the Reports button. NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the Reports menu, and then select Configuration/Status Pages. c. Select OK or Print to print the page. 4. Make sure to load the tray with the correct paper size and the paper guides are adjusted to the correct size for the paper. NOTE: Do not adjust the paper guides tightly against the paper stack. Adjust them to the indentations or markings in the tray. 5. Print internal pages from all trays to verify that this error only occurs when printing from the PC. 6. Verify that the error is not occurring as a result of an unexpected paper size trigger caused when multiple pages are picked up during paper feed. 7. Verify that the toner cartridge and the transfer roller are seated correctly. 8. Make sure that the rollers are installed correctly and show no damage or wear. Check if the rollers are worn out or coated with paper dust or other debris. ● If the rollers are not clean, use a damp, lint-free cloth to clean the rollers in the appropriate tray. ● If the rollers are worn or damaged and causing the issue, replace the roller kit. Table 6-86 Tray 2 roller kit part number

Part description Part number

Kit-Trays 2X Roller RM2-5752-000CN 9. If the error persists, contact HP customer support. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Print the configuration page to verify the size and type to which the trays are set. 3. Make sure that the tray is loaded with the correct paper size and that the sliding paper guides are correctly adjusted to the correct paper size. 4. Verify that the error is not occurring as a result of an unexpected paper size trigger caused by a multi-page feed. 5. Print internal pages from all trays to verify that this error only occurs when printing from the PC. If the error only occurs from the PC, check the print driver settings and ensure they are correct. Recommended action for call-center agents and onsite technicians 251

6. Verify that the toner cartridge and the transfer roller are seated correctly. 7. Check the rollers and make sure they are not worn smooth, or coated with paper dust or other debris. If the rollers are causing the issue, replace the roller kit. Part number: Roller kit - F2A68-67913 8. Use the Tray/Bin manual sensor test to verify that the cassette media switch is functioning correctly. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test 9. Check the paper path sensors for correct operation and ensure that they do not stick at all. If the issue persists, elevate the issue using the Standard Support Process for a possible printer replacement. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test 10. Remove and reconnect the connectors for the paper path sensors, intermediate-transfer belt, and the DC controller PCA. 11. Test the registration assembly motor and clutch. If they do not function correctly replace the registration assembly. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test Part Number (M501/M506/E50045/M527/E52545): RM2-5671-000CN Part Number (M507/E50145/M528/E52645): RM2-2577-000CN 12. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement.

41.03.05, 41.03.A5, 41.03.B5, 41.03.C5

The printer detected a different paper size than expected. Paper Size mismatch (0,A,B) or inter-page gap (C) error from Tray 5.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Check if paper is loaded correctly in the paper tray. Use paper that meets HP specifications for this printer. 3. Print a Configuration page to verify the size and type to which the trays are set. Make sure that the selected paper size and type meets the HP specifications for the printer. 252 Chapter 6 Numerical control panel messages

a. From the Home screen on the printer control panel, select Administration or the Reports button. NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the Reports menu, and then select Configuration/Status Pages. c. Select OK or Print to print the page. 4. Make sure to load the tray with the correct paper size and the paper guides are adjusted to the correct size for the paper. NOTE: Do not adjust the paper guides tightly against the paper stack. Adjust them to the indentations or markings in the tray. 5. Print internal pages from all trays to verify that this error only occurs when printing from the PC. 6. Verify that the error is not occurring as a result of an unexpected paper size trigger caused when multiple pages are picked up during paper feed. 7. Verify that the toner cartridge and the transfer roller are seated correctly. 8. Make sure that the rollers are installed correctly and show no damage or wear. Check if the rollers are worn out or coated with paper dust or other debris. ● If the rollers are not clean, use a damp, lint-free cloth to clean the rollers in the appropriate tray. ● If the rollers are worn or damaged and causing the issue, replace the roller kit. Table 6-87 Tray 2 roller kit part number

Part description Part number

Kit-Trays 2X Roller RM2-5752-000CN 9. If the error persists, contact HP customer support. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Print the configuration page to verify the size and type to which the trays are set. 3. Make sure that the tray is loaded with the correct paper size and that the sliding paper guides are correctly adjusted to the correct paper size. 4. Verify that the error is not occurring as a result of an unexpected paper size trigger caused by a multi-page feed. 5. Print internal pages from all trays to verify that this error only occurs when printing from the PC. If the error only occurs from the PC, check the print driver settings and ensure they are correct. 6. Verify that the toner cartridge and the transfer roller are seated correctly. Recommended action for call-center agents and onsite technicians 253

7. Check the rollers and make sure they are not worn smooth, or coated with paper dust or other debris. If the rollers are causing the issue, replace the roller kit. Part number: Roller kit - F2A68-67913 8. Use the Tray/Bin manual sensor test to verify that the cassette media switch is functioning correctly. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test 9. Check the paper path sensors for correct operation and ensure that they do not stick at all. If the issue persists, elevate the issue using the Standard Support Process for a possible printer replacement. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test 10. Remove and reconnect the connectors for the paper path sensors, intermediate-transfer belt, and the DC controller PCA. 11. Test the registration assembly motor and clutch. If they do not function correctly replace the registration assembly. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test Part Number (M501/M506/E50045/M527/E52545): RM2-5671-000CN Part Number (M507/E50145/M528/E52645): RM2-2577-000CN 12. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement.

41.03.0D, 41.03.AD, 41.03.BD, 41.03.CD

The printer detected a different paper size than expected. Paper Size mismatch (0,A,B) or inter-page gap (C) error from duplexer.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Print the configuration page to verify the size and type to which the trays are set. 3. Make sure that the tray is loaded with the correct paper size and that the sliding paper guides are correctly adjusted to the correct paper size. 4. Print internal pages from all trays to verify that this error only occurs when printing from the PC. 5. Verify that the error is not occurring as a result of an unexpected paper size trigger caused by a multi-page feed. 6. Verify that the toner cartridge and the transfer roller are seated correctly. 7. If the error persists, please contact customer support. 254 Chapter 6 Numerical control panel messages

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Touch OK to use another tray. 2. Print the configuration page to verify the size and type to which the trays are set. 3. Make sure that the tray is loaded with the correct paper size and that the sliding paper guides are correctly adjusted to the correct paper size. 4. Verify that the error is not occurring as a result of an unexpected paper size trigger caused by a multi-page feed. 5. Print internal pages from all trays to verify that this error only occurs when printing from the PC. If the error only occurs from the PC, check the print driver settings and ensure they are correct. 6. Verify that the toner cartridge and the transfer roller are seated correctly. 7. Check the rollers and make sure they are not worn smooth, or coated with paper dust or other debris. If the rollers are causing the issue, replace the roller kit. Part number: Roller kit - F2A68-67913 8. Use the Tray/Bin manual sensor test to verify that the cassette media switch is functioning correctly. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test 9. Check the paper path sensors for correct operation and ensure that they do not stick at all. If the issue persists, elevate the issue using the Standard Support Process for a possible printer replacement. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test 10. Remove and reconnect the connectors for the paper path sensors, intermediate-transfer belt, and the DC controller PCA. 11. Test the

registration assembly motor and clutch. If they do not function correctly replace the registration assembly. Open the following menus to test sensor: Administration > Troubleshooting > Diagnostic Tests > Tray/Bin Manual Sensor Test Part Number (M501/M506/E50045/M527/E52545): RM2-5671-000CN Part Number (M507/E50145/M528/E52645): RM2-2577-000CN 12. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement.

41.03.FZ Unknown Misprint Error

This is a general misprint error. Either the paper is loaded off-center with the side guides in the tray or a paper width sensor failure occurred from an unknown tray. The error will be one of the following:

● 41.03.F0

Recommended action for call-center agents and onsite technicians 255

● 41.03.F1

● 41.03.F2

● 41.03.F3

● 41.03.F4

● 41.03.F5

● 41.03.FD

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Remove the paper from the tray and ensure that the paper tray size guides are set to the correct size for the paper loaded in the tray. 2. Try the print job again. Watch the paper tray feed mechanism to see if it is functioning correctly. If the linkage is broken, replace the paper tray. Table 6-88 Part numbers

Description Part number

Tray 2 cassette only RM2-5690-000CN 1x550 optional feeder cassette assembly 3. If the error persists, print a Configuration Page and note the paper size for the tray in question. ● If the size is not reported correctly, run the tray size sensor test in the Diagnostic menu. ● If the tray size sensors test as GOOD, replace the paper tray. ● If the tray size sensors test as BAD, check the cable connections between the tray size sensor and the DC Controller. If the cable connections are plugged in correctly and the cables are not damaged, elevate the issue using the Standard Support Process.

41.04.YZ Printer Error

An unknown misprint error occurred on the printer. Y = Type, Z = Tray ● Y = 0: Photo Media (1, 2, or 3) 256 Chapter 6 Numerical control panel messages

● Y = 1: Auto Sense (Normal) ● Y = 2: Normal (typed not from Auto Sense) ● Y = 3: Light media 1, 2, or 3 mode ● Y = 4: Heavy media 1 ● Y = 5: Heavy media 2 ● Y = 6: Heavy media 3 ● Y = 7: Glossy media 1 ● Y = 8: Glossy media 2 ● Y = 9: Glossy media 3 ● Y = A: Glossy film

● Y = B: OHT

● Y = C: Label ● Y = D: Envelope 1, 2, or 3 mode ● Y = E: Rough ● Y = F: Other mode ● Z = D Source is the duplexer. ● Z = 0 Source is the envelope feeder. ● Z = 1 Source is Tray 1. ● Z = 2 Source is Tray 2. ● Z = 3 Source is Tray 3. ● Z = 4 Source is Tray 4. ● Z = 5 Source is Tray 5.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Touch OK to clear the error. 2. If the error does not clear, turn the printer off, and then on. Recommended action for customers 257

3. If the error persists, visually inspect the toner cartridge, and then reinstall the toner cartridge. NOTE: Ensure that the toner cartridges are HP original cartridges and that the cartridges are seated correctly before replacing any other parts. a. Open the front door to remove the toner cartridge. b. Check the toner cartridge and ensure it is a genuine HP toner cartridge. c. Swap out the toner cartridge to test it. d. Install the toner cartridge until it is firmly seated, and then close the front door. 4. Disconnect and re-seat the flat-flexible cable (FFC) connections on the laser scanner and on the DC controller. Ensure that the cables are connected and seated correctly before replacing any part. 5. If the error persists, replace the laser/scanner assembly. Table 6-89 Laser scanner assembly part number

Part description Part number

Assembly- Laser scanner RM2-4860-000CN For instructions: See the Repair Service Manual for this product.

Recommended action for onsite service technicians

Follow these troubleshooting steps in the order presented. 1. Touch OK to clear the error. 2. If the error does not clear, turn the printer off, and then on. 3. If the error persists, visually inspect the toner cartridge, and then reinstall the toner cartridge. NOTE: Ensure that the toner cartridges are HP original cartridges and that the cartridges are seated correctly before replacing any other parts. a. Open the front door to remove the toner cartridge. b. Check the toner cartridge and ensure it is a genuine HP toner cartridge. c. Swap out the toner cartridge to test it. d. Install the toner cartridge until it is firmly seated, and then close the front door. 4. Disconnect and re-seat the flat-flexible cable (FFC) connections on the laser scanner and on the DC controller. NOTE: Ensure that the cables are connected and seated correctly before replacing any part. 258 Chapter 6 Numerical control panel messages

5. If the error persists, replace the laser/scanner assembly. Table 6-90 Laser scanner assembly part number

Part description Part number

Assembly- Laser scanner RM2-4860-000CN For instructions: See the Repair Service Manual for this product. 6. If the error persists after replacing the laser/scanner assembly, replace the DC controller. Table 6-91 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

For instructions: See the Repair Service Manual for this product.

41.05.YZ Unexpected type in tray <X>

Tray X is loaded with a paper type (transparencies, envelopes, etc.) that is different than what the tray is configured to use. The printer can detect the type of paper in the paper path, and it adjusts the print mode accordingly. Y = Expected type, Z = Detected type ● Y = 0: Photo Media (1, 2, or 3) ● Y = 1: Auto Sense (Normal) ● Y = 2: Normal (typed not from Auto Sense) ● Y = 3: Light media 1, 2, or 3 mode ● Y = 4: Heavy media 1 ● Y = 5: Heavy media 2

41.05.YZ Unexpected type in tray <X> 259

● Y = 6: Heavy media 3 ● Y = 7: Glossy media 1 ● Y = 8: Glossy media 2 ● Y = 9: Glossy media 3 ● Y = A: Glossy film

● Y = B: OHT

● Y = C: Label ● Y = D: Envelope 1, 2, or 3 mode ● Y = E: Rough ● Y = F: Other mode ● Z = 0: Photo Media (1, 2, or 3) ● Z = 1: Auto Sense (Normal) ● Z = 2: Normal (typed not from Auto Sense) ● Z = 3: Light media 1, 2, or 3 mode ● Z = 4: Heavy media 1 ● Z = 5: Heavy media 2 ● Z = 6: Heavy media 3 ● Z = 7: Glossy media 1 ● Z = 8: Glossy media 2 ● Z = 9: Glossy media 3 ● Z = A: Glossy film

● Z = B: OHT

● Z = C: Label ● Z = D: Envelope 1, 2, or 3 mode ● Z = E: Rough ● Z = F: Other mode

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. 260 Chapter 6 Numerical control panel messages

Recommended action

Follow these troubleshooting steps in the order presented. 1. Load the tray with the size and type of paper indicated, or use another tray if available. 2. If this message displays and the tray is loaded with the correct paper type, check the print driver settings to make sure they match the tray type settings. 3. Check all application and printer settings to make sure that the type setting is correct. 4. Clean the paper path sensors. 5. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement. 41.XX.YZ Error To continue, touch "OK" A printer error has occurred. Use this information to resolve general 41.XX.YY error messages. XX = error type Y = fuser mode Z = input tray ● XX = 02 Beam detect misprint ● XX = 09 Sub thermistor abnormally high ● XX = 10 Pickup failure. ● XX = 11 Illegal Duplex. ● XX = 18 Scan line inclination adjustment ● XX = 20 Image drum HV ● Y = 0: Photo Media (1, 2, or 3) ● Y = 1: Auto Sense (Normal) ● Y = 2: Normal (typed not from Auto Sense) ● Y = 3: Light media 1, 2, or 3 mode ● Y = 4: Heavy media 1 ● Y = 5: Heavy media 2 ● Y = 6: Heavy media 3 ● Y = 7: Glossy media 1 ● Y = 8: Glossy media 2 ● Y = 9: Glossy media 3 ● Y = A: Glossy film Recommended action 261

● Y = B: OHT

● Y = C: Label ● Y = D: Envelope 1, 2, or 3 mode ● Y = E: Rough ● Y = F: Other mode ● Z = 0 Envelope feeder ● Z = 1 Tray 1 ● Z = 2 Tray 2 ● Z = 3 Tray 3 ● Z = 4 Tray 4 ● Z = 5 Tray 5 ● Z = 6 Tray 6 ● D Duplexer

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. To clear the message, touch the OK button. 2. If the message displays again, turn the printer off, and then on. 3. If the error persists, replace the DC controller PCA. DC controller (M527) part number: RM2-8612-000CN DC controller simplex (M506) part number: RM2-8600-000CN DC controller duplex (M506) part number: RM2-8612-000CN DC controller simplex (M501) part number: RM2-8710-000CN DC controller duplex (M506) part number: RM2-7950-000CN For instructions: See the Repair Service Manual for this product. 262 Chapter 6 Numerical control panel messages

42.XX.YZ error messages

42.XX.YZ

Internal system failure.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. Retry the job. 2. If the error persists, clear the firmware image from the active partition by using the Partial Clean item in the Preboot menu. 42.B0.01 or 42.B0.02 Missing string in firmware error. 42.B0.01: UI or EWS requests a string ID that does not exist in the localization database. 42.B0.02: UI requests an image ID or media file that does not exist.

Recommended action for customers

Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, and then on. Retry the job. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents, and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. Retry the print job. 2. If the error persists, clear the firmware image from the active partition by using the Partial Clean item in the Preboot menu. NOTE: The Partial Clean option erases all data from the partitions, except for the firmware repository where a backup copy of the firmware file is stored. This allows the disk drive to be reformatted without having to download a firmware upgrade file to return the printer to a bootable state. Characteristics of a Partial Clean ● Customer-defined settings, third-party solutions, firmware files, and the operating system are deleted

42.XX.YZ 263

● Rebooting the printer restores the firmware files from the Repository location, but does not restore any customer-defined settings. ● For previous HP products, a Hard Disk Initialization is similar to executing the Partial Clean function for this printer CAUTION: HP recommends backing-up printer configuration data before executing a Partial Clean to retain customer-defined settings (if needed). See the Backup/Restore item in the Device Maintenance menu. 3. How to execute a Partial Clean from a touchscreen control panel. a. Touch in the middle of the control panel display when you see the 1/8 under the HP logo. Figure 6-83 Open the Pre-Boot menu b. Use the down arrow button to highlight the +3:Administrator item, and then touch the OK button. c. Use the down arrow button to highlight Partial Clean and then touch the OK button. d. Touch the OK button again. e. Touch the Home button to highlight Continue, and then touch the OK button. NOTE: The printer initializes. 44.XX.XX error messages - M527 only 44.* errors Errors in the 44.* family are related to the digital send functionality: fax, email, send to SharePoint, or save to folder.

Recommended action

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, contact your HP-authorized service or support provider, or contact HP support at www.hp.com/go/contactHP. 1. In many cases, the error will automatically clear, and you can try the job again. 2. Verify the digital send feature has been correctly configured at the control panel and with the HP Embedded Web Server (EWS). NOTE: To access the EWS, open a Web browser, and in the address line, enter the printer IP address. 264 Chapter 6 Numerical control panel messages

3. Turn the printer off, and then on. Retry the job. 4. For fax errors, verify the fax card is correctly installed on the formatter. 5. For SharePoint or save-to-folder errors, verify the permissions are set correctly for access to the SharePoint or network folder. 6. For email errors, verify connectivity to the network, and verify the SMTP gateway is configured correctly. Also verify if there is a size limit on email attachments. 7. If the error persists, reset the printer to factory settings, and then upgrade the firmware to the latest version. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions

44.01.xx Error Event log message

A digital send error has occurred.

Recommended action

Follow these troubleshooting steps in the order presented. 1. No action necessary. This error message should automatically clear. 2. Try to send the job again. 3. If the error does not clear or it returns: a. Use optimal resolution and image quality settings. b. Wait until all the digital send jobs have been processed. c. Turn the printer off, and then on. Retry the job. d. Verify if there is an attachment limit on the email. e. Verify network connectivity, SMTP gateways, access to folder share.

44.03.xx Error Event log message

A digital send error has occurred.

Recommended action for customers

Follow these troubleshooting steps in the order presented. ■ Try to send the job again.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Use optimal resolution and image quality settings. 2. Wait until all the digital send jobs have been processed. 3. Turn the printer off, and then on and retry the job. 4. Verify if there is an attachment limit on the email.

44.01.xx Error Event log message 265

5. Verify network connectivity, SMTP gateways, access to folder share.

44.10.xx Error Event log message (Multifunction product only.)

A send to email error has occurred.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Try to send the job again. 2. Check the digital send configuration. For more information, Go to: Or click here: [HP LaserJet Enterprise MFP - Set up Scan to Email](#).

44.34.xx Error Event log message

A fax error has occurred.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Try to send the job again. 2. Check the fax settings to make sure they are set to the proper settings for the environment. 3. If the issue persists, for additional fax troubleshooting information go to [HP LaserJet Enterprise MFP](#), [HP PageWide Enterprise MFP](#) - Checklist for solving fax problems.

44.34.03 Fax Modem Failure

Digital Send error. Fax result modem fail.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off. 2. Verify the fax card is correctly installed on the formatter, be sure the fax card is aligned with slot on the formatter chassis and is firmly seated against the formatter board. 3. Turn the printer on. 4. If the issue persists, replace the fax PCA. Part number: B5L53-67901 266 Chapter 6 Numerical control panel messages

44.34.E5 Fax Modem Failure

A fax error has occurred.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off. 2. Verify the fax card is correctly installed on the formatter, be sure the fax card is aligned with slot on the formatter chassis and is firmly seated against the formatter board. 3. If the issue persists, download and reinstall the firmware. 4. If the issue persists, perform a Partial Clean: a. Turn the printer off, and then on. b. The HP logo displays on the printer control panel. When a "1/8" with an underscore displays below the HP logo, touch the logo to open the Pre-boot menu. c. Use the arrow buttons on the touchscreen to navigate the pre-boot menu. d. Use the down arrow to highlight Partial Clean, and then touch the OK button. e. Touch the OK button again. f. Touch the Back button to highlight Continue, and then touch the OK button. The printer will continue to boot to Ready. 5. If the issue persists, replace the fax PCA. Part number: B5L53-67901

44.90.xx, 44.91.xx, 44.92.xx Error Event log message

A fax error has occurred.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Try to send the job again. 2. Check the fax settings to make sure they are set to the proper settings for the environment. 3. If the issue persists, for additional fax troubleshooting information go to HP LaserJet Enterprise MFP, HP PageWide Enterprise MFP - Checklist for solving fax problems.

44.34.E5 Fax Modem Failure 267

47.XX.XX error messages 47.* errors Errors in the 47.* family indicate an internal error has occurred.

Recommended action for customers

Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, and then on. 2. Resend the print job. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Turn the printer off, and then on. 2. Resend the print job. 3. If the error persists, perform a Format Disk procedure using the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - .

47.00.xx

Back channel internal error.

Recommended action for customers

Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, and then on. 2. Resend the print job. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Resend the print job. 268 Chapter 6 Numerical control panel messages

3. If the error persists, perform a Format Disk procedure using the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - .

47.01.xx

Image transformer internal error.

Recommended action for customers

Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, and then on. 2. Resend the print job. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Resend the print job. 3. If the error persists, clear the active partition by using the Format Disk item in the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - .

47.02.xx

Job parser internal error.

Recommended action for customers

Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, and then on. 2. Resend the print job. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Resend the print job.

47.01.xx 269

3. If the error persists, clear the active partition by using the Format Disk item in the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - .

47.03.xx

Print job internal error.

Recommended action for customers

Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, and then on. 2. Resend the print job. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Resend the print job. 3. If the error persists, clear the active partition by using the Format Disk item in the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - .

47.04.xx

Print spooler 9100 internal error.

Recommended action for customers

Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, and then on. 2. Resend the print job. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Resend the print job. 270 Chapter 6 Numerical control panel messages

3. If the error persists, clear the active partition by using the Format Disk item in the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - .

47.05.xx

Print spooler framework internal error.

Recommended action for customers

Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, and then on. 2. Resend the print job. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Resend the print job. 3. If the error persists, perform a Format Disk procedure using the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - .

47.06.xx

Print application internal error.

Recommended action for customers

Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, and then on. 2. Resend the print job. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Resend the print job.

47.05.xx 271

3. If the error persists, clear the active partition by using the Format Disk item in the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 48.XX.YY error messages 48.* errors Errors in the 48.* family indicate an internal error has occurred.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Upgrade the firmware. For the latest firmware versions, go to HP FutureSmart - Latest Firmware Versions 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. In most cases, no action is necessary. 2. If the error persists, upgrade the printer firmware. 3. If the error persists, continue troubleshooting with the flowcharts for either Intermittent or Persistent 48 error troubleshooting (whichever is appropriate) in document c03122817. Search for the following document on WISE: HP LaserJet FutureSmart Devices - 49 Error Troubleshooting (Persistent and Intermittent). NOTE: 48.wx.yz errors are similar to 49.wx.yz errors and use the same troubleshooting steps and procedures. 49.XX.YY error messages 49.XX.YY Error To continue turn off then on A firmware error occurred. Possible causes: ● Corrupted print jobs ● Software application issues 272 Chapter 6 Numerical control panel messages

● Non-product specific print drivers ● Poor quality USB or network cables ● Bad network connections or incorrect configurations ● Invalid firmware operations ● Unsupported accessories A 49 error might happen at any time for multiple reasons. Although some types of 49 errors can be caused by hardware failures, it is more common for 49 errors to be caused by printing a specific document or performing some task on the printer. 49 errors most often occur when a printer is asked to perform an action that the printer firmware is not capable of and might not have been designed to comply with, such as: ● Printing files with unsupported programming commands ● A unique combination of user environment and user interactions with the printer ● Interfacing with a third-party solution that was not designed to work with the printer ● Specific timing, network traffic, or concurrent processing of jobs

Recommended action for customers

Follow these troubleshooting steps in the order presented. NOTE: LaserJet formatter PCAs are rarely the root cause of 49 service errors. Please do not replace the formatter unless troubleshooting has identified the formatter as the root cause. 1. Turn the printer off, and then on. 2. If the error persists, check the following: ● The error might be caused by a network connectivity problem, such as a bad USB or network interface cable, a bad USB port, or an invalid network configuration setting. ● The error might be caused by the print job, due to an invalid print driver, a problem with the software application, or a problem with the file being printed. ● Upgrading the printer firmware might help resolve the error. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. NOTE: LaserJet formatter PCAs are rarely the root cause of 49 service errors. Please do not replace the formatter unless troubleshooting has identified the formatter as the root cause. 1. Turn the printer off, and then on. Recommended action for customers 273

2. If the error persists, check the following: ● The error might be caused by a network connectivity problem, such as a bad interface cable, a bad USB port, or an invalid network configuration setting. ● The error might be caused by the print job, due to an invalid print driver, a problem with the software application, or a problem with the file being printed. ● Upgrading the printer firmware might help resolve the error. 3. If the error persists, continue troubleshooting with the flowcharts for either Intermittent or Persistent 49 error troubleshooting (whichever is appropriate) in document c03122817. Search for the following document on WISE: HP LaserJet FutureSmart Devices - 49 Error Troubleshooting (Persistent and Intermittent). NOTE: 48 errors are similar to 49 errors.

49.2F.D8

Native video pipeline error in managed RC. This error has been seen after long idle periods.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Perform the following steps. 1. Turn the printer off, and then on to see if the error persists. 2. Ensure the printer is plugged into a stable power source. 3. If the error persists, replace the laser/scanner assembly. Part number: RM2-5528-000CN

Recommended action for on-site technicians

Perform the following steps as outlined. 1. Turn the printer off, and then on to see if the error persists. 2. Ensure the printer is plugged into a stable power source. 3. If the error persists, replace the laser/scanner assembly. Part number: RM2-5528-000CN for instructions: See the Repair Service Manual for this product. 274 Chapter 6 Numerical control panel messages

49.38.07

Generic error. This issue is caused by a formatter replacement that has not had the correct parameters set at the factory. This issue is tied to the factory installed Trusted Platform Module (TPM). NOTE: For additional information, go to WISE and search for this document: HP LaserJet Enterprise, HP LaserJet Managed - 49.38.07 error after replacing the formatter (Emerging Issue) (c06621339).

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, Upgrade the firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Ask the technician where the formatter came from and note the answer in the case notes. 2. Turn the printer off, and then on. 3. Confirm that the unit still boots to the same 49.38.07 error. 4. Elevate the case to ATS NOTE: Never replace the TPM on a unit that shipped with one. The TPM that can be ordered is only available for adding a level of security on a device that never had a TPM paired from the factory. A new TPM cannot be installed for security reasons.

49.38.0C

Unhandled printer error.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, Upgrade the firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

49.38.07 275

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the issue persists, replace the hard disk drive (HDD). NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-92 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the issue persists, replace the hard disk drive (HDD). NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-93 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

See NOTE above For instructions: See the Service Manual for this printer. 50.WX.YZ error messages 50. errors Errors in the 50.* family indicate a problem with the fuser. 276 Chapter 6 Numerical control panel messages

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Turn the printer off, and remove the fuser. Check the fuser for damage or obstructions. Reinstall or replace the fuser as needed. CAUTION: The fuser might be hot. 2. Check the connectors between the fuser and the DC controller and from the fuser to the printer. 3. Replace the fuser. If it has already been replaced, replace the fuser power supply. 50.1X.YZ Fuser Error Low fuser temperature. Y = previous printer sleep state, Z = next printer sleep state

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error returns, turn the printer off, unplug the device from any power-strips or uninterrupted power supplies, and plug printer directly in to a wall socket.

Electrical Specifications

110v input voltage: 100 to 127 VAC, 50/60 Hz, 7.5 A (+/- 10%) 220v input voltage: 220 to 240 VAC, 50/60 Hz, 4 A (+/- 10%) Table 6-94 Power consumption (avg. in watts)

Printing Ready Sleep Auto-Off Off

671 W 27.8 W 3.2 W 0.1 W 0.1 W

3. Turn the printer on. If the error returns, please contact your support provider. NOTE: The fuser was not designed to be end-user replaceable and requires authorized service personnel to replace. Should the error persist please contact HP Customer Support or authorized repair personnel. Recommended action for customers 277

Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off. 2. Remove the fuser. Check the connector (J290–291) between the fuser and the printer. If it is damaged, replace the fuser. Table 6-95 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 3. Reconnect the connectors (J132 and J152) on the DC Controller PCA. 4. If the error persists, replace the fuser power supply assembly. Table 6-96 Part numbers

Part Name Part Number

Fixing (fuser) power supply (FPS) 110V-127V RM2-7948-000CN Fixing (fuser) power supply (FPS) 220V-240V RM2-7949-000CN For instructions: See the Repair Service Manual for this product. 5. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement. 50.2X.YZ Fuser Error Fuser warm up failure. X = fuser mode, Y = previous printer sleep state, Z = next printer sleep state

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error returns, turn the printer off, unplug the device from any power-strips or uninterrupted power supplies, and plug printer directly in to a wall socket.

Electrical Specifications

110v input voltage: 100 to 127 VAC, 50/60 Hz, 7.5 A (+/- 10%) 278 Chapter 6 Numerical control panel messages

220v input voltage: 220 to 240 VAC, 50/60 Hz, 4 A (+/- 10%) Table 6-97 Power consumption (avg. in watts)

Printing Ready Sleep Auto-Off Off

671 W 27.8 W 3.2 W 0.1 W 0.1 W

3. Turn the printer on. If the error returns, please contact your support provider. NOTE: The fuser was not designed to be end-user replaceable and requires authorized service personnel to replace. Should the error persist please contact HP Customer Support or authorized repair personnel. Recommended action for call-center agents and onsite technician Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error returns, turn the printer off, unplug the device from any power-strips or uninterrupted power supplies, and plug printer directly in to a wall socket. 3. If error returns, turn the printer off. 4. Remove the fuser and check the fuser for damage or obstructions. Reinstall or replace the fuser as needed. Table 6-98 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 5. Check the connectors (J132 and J152) between the fuser and the DC controller PCA. J291 (TP1 cable) is a 2-pin wire harness visible when the connector cover is removed. If not connected and seated correctly, this can cause a 50.2x error. 6. If the error persists, replace the fuser and

then replace the fuser power supply assembly if needed or if the fuser has already been replaced. Table 6-99 Part numbers

Part Name Part Number

Fixing (fuser) power supply (FPS) 110V-127V RM2-7948-000CN Fixing (fuser) power supply (FPS) 220V-240V RM2-7949-000CN

Recommended action for call-center agents and onsite technician 279

For instructions: See the Repair Service Manual for this product. 7. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement. 50.2F.00 Fuser Error Fuser warm up failure.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error returns, turn the printer off, unplug the device from any power-strips or uninterrupted power supplies, and plug printer directly in to a wall socket.

Electrical Specifications

110v input voltage: 100 to 127 VAC, 50/60 Hz, 7.5 A (+/- 10%) 220v input voltage: 220 to 240 VAC, 50/60 Hz, 4 A (+/- 10%) Table 6-100

Power consumption (avg. in watts)

Printing Ready Sleep Auto-Off Off

671 W 27.8 W 3.2 W 0.1 W 0.1 W

3. Turn the printer on. If the error returns, please contact your support provider. NOTE: The fuser was not designed to be end-user replaceable and requires authorized service personnel to replace. Should the error persist please contact HP Customer Support or authorized repair personnel.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error returns, turn the printer off, unplug the device from any power-strips or uninterrupted power supplies, and plug printer directly in to a wall socket.

Electrical Specifications

110v input voltage: 100 to 127 VAC, 50/60 Hz, 7.5 A (+/- 10%) 220v input voltage: 220 to 240 VAC, 50/60 Hz, 4 A (+/- 10%) Table 6-101

Power consumption (avg. in watts)

Printing Ready Sleep Auto-Off Off

671 W 27.8 W 3.2 W 0.1 W 0.1 W

3. If error returns, turn the printer off. 280 Chapter 6 Numerical control panel messages

4. If the error persists, replace the fuser as needed. NOTE: The fuser was not designed to be end-user replaceable and requires authorized service personnel to replace. Should the error persist please contact HP Customer Support or authorized repair personnel. Table 6-102 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN

Recommended action for onsite technician

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error returns, turn the printer off, unplug the device from any power-strips or uninterrupted power supplies, and plug printer directly in to a wall socket.

Electrical Specifications

110v input voltage: 100 to 127 VAC, 50/60 Hz, 7.5 A (+/- 10%) 220v input voltage: 220 to 240 VAC, 50/60 Hz, 4 A (+/- 10%) Table 6-103
Power consumption (avg. in watts)

Printing Ready Sleep Auto-Off Off

671 W 27.8 W 3.2 W 0.1 W 0.1 W

3. Check the fuser TP1 for continuity. NOTE: TP1 (thermal switch) prevents an abnormal temperature rise in the fuser heater. TP1 continuity can be checked to identify if the switch is open. If the continuity measures open, the switch has been triggered and the fuser must be replaced.
a. Turn the printer off. b. Disconnect the power cable. c. Remove the rear door assembly. For instructions: See the Repair Service Manual for this product. NOTE: An MFP printer is shown in this section. However, the procedure is correct for all printer models. Recommended action for onsite technician 281

d. Remove the fuser connector cover on the inner right side. e. Verify that the wire harness is fully seated and connected correctly with the Fuser Power Supply PCA. J291 (TP1 cable) is a 2-pin wire harness visible when the connector cover is removed. If not connected and seated correctly, this can cause a 50.2F.00 error. f. If the wiring harness is seated properly unplug J291 from the Fuser Power Supply PCA as pictured (2-pin wire harness) g. Using a multimeter check for TP1 continuity ● If the switch is OPEN, replace the fuser. ● If the TP1 has continuity the switch is good. 282 Chapter 6 Numerical control panel messages

Table 6-104 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 4. If the error returns, turn the printer off and allow the fuser to cool for five minutes. Remove the fuser and check the fuser for visible damage. If damaged is identified, replace the fuser as needed. Table 6-105 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 5. Check the connectors (J132 and J152) between the fuser and the DC controller PCA. Recommended action for onsite technician 283

6. Check connector J216 at the Fuser power supply PCA, reseating as necessary. If after reseating the error continues, replace the fuser.

Table 6-106 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 7. If the error persists, elevate the issue using the Standard Support Process. 50.3X.YZ Fuser Error High fuser temperature. X = fuser mode, Y = previous printer sleep state, Z = next printer sleep state

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off. 2. Remove the fuser and check the fuser for damage or obstructions. Reinstall or replace the fuser as needed. Table 6-107 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 284 Chapter 6 Numerical control panel messages

3. Check the connector (J128) between the fuser and the printer. If it is damaged, replace the fuser. 4. Check the connectors (J132 and J152) on the DC controller PCA. 5. Replace the fuser. 6. If the error persists, replace the fuser power supply assembly. Table 6-108 Part numbers

Part Name Part Number

Fixing (fuser) power supply (FPS) 110V-127V RM2-7948-000CN Fixing (fuser) power supply (FPS) 220V-240V RM2-7949-000CN For instructions: See the Repair Service Manual for this product. 7. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement. 50.4X.YZ Fuser Error Drive circuit fault. X = fuser mode, Y = previous printer sleep state, Z = next printer sleep state

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error returns, turn the printer off, unplug the device from any power-strips or uninterrupted power supplies, and plug printer directly in to a wall socket.

Electrical Specifications

110v input voltage: 100 to 127 VAC, 50/60 Hz, 7.5 A (+/- 10%) 220v input voltage: 220 to 240 VAC, 50/60 Hz, 4 A (+/- 10%) Table 6-109
Power consumption (avg. in watts)

Printing Ready Sleep Auto-Off Off

671 W 27.8 W 3.2 W 0.1 W 0.1 W

3. Turn the printer on. If the error returns, please contact your support provider. NOTE: The fuser was not designed to be end-user replaceable and requires authorized service personnel to replace. Should the error persist please contact HP Customer Support or authorized repair personnel. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 50.4X.YZ Fuser Error 285

1. Check the power source. Make sure the power source meets printer requirements. NOTE: If the power source does not meet the power frequency requirement of 40 to 70Hz, the fuser temperature control does not work properly and causes this error. 2. Reconnect connectors (J132 and J152) on the DC controller PCA. 3. If the error persists, replace the fuser power supply assembly. Table 6-110 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 4. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement. 50.6X.YZ Fuser Error Fuser open error. X = fuser mode, Y = previous printer sleep state, Z = next printer sleep state

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Ensure the paper type and fuser mode are correctly set for the paper being used. 2. Turn the printer off. 3. Remove the fuser, and check the connector (J128) between the fuser and the printer. If it is damaged, replace the fuser. Table 6-111 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

286 Chapter 6 Numerical control panel messages

Table 6-111 Part numbers (continued)

Part Name Part Number

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 4. Reinstall the fuser and turn the printer on. 5. Reconnect connectors (J132 and J152) on the DC controller PCA. 6. Replace the fuser. 7. If the error persists, replace the power supply unit. Table 6-112 Part Numbers

Part Name

Low-voltage power supply (LVPS) 110V-127V (M527/E52545/

M528/E52645)

RM2-7951-000CN

Low-voltage power supply (LVPS) 220V-240V (M527/E52545/

M528/E52645)

RM2-7952-000CN

Low-voltage power supply (LVPS) 110V-127V (M506/E50045/

M507/E50145)

RM2-7941-000CN

Low-voltage power supply (LVPS) 220V-240V (M501/M506/

E50045/M507/E50145)

RM2-7942-000CN

For instructions: See the Repair Service Manual for this product. 50.7X.YZ Fuser Error Fuser pressure release failure. X = fuser mode, Y = previous printer sleep state, Z = next printer sleep state

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 50.7X.YZ Fuser Error 287

2. Resend the job. 3. If error returns, turn the printer off. 4. Remove the fuser and check the fuser for damage or obstructions. CAUTION: Be careful: the fuser is HOT. Allow it cool if you need to before removing to check the assembly. 5. Reinstall the fuser and turn the printer on. 6. If the error persists, replace the fuser assembly. Table 6-113 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 50.9X.YZ Fuser Error Low fuser temperature error. X = fuser mode, Y = previous printer sleep state, Z = next printer sleep state

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Ensure the power cord of the printer is plugged directly into a wall outlet and the outlet voltage matches the voltage specifications on the printer. NOTE: Unplug the power cord of the printer from any power-strip or uninterrupted power supply, and plug it directly into a wall socket. 3. Press the power button to turn on the printer. 4. Ensure the paper type and fuser mode are correct for the paper being used. 5. Open the Trays menu on the printer control panel. Verify that the tray is configured correctly for the paper type and size. 6. Ensure that the paper type set on the printer matches the paper type selection in the printer driver. Use only paper that meets HP specifications for this printer. 7. Retest the printer. 288 Chapter 6 Numerical control panel messages

8. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Ensure the power cord of the printer is plugged directly into a wall outlet and the outlet voltage matches the voltage specifications on the printer. NOTE: Unplug the power cord of the printer from any power-strip or uninterrupted power supply, and plug it directly into a wall socket. 3. Ensure the paper type and fuser mode are correctly set for the paper being used. 4. If the error reoccurs, turn off the printer, and then turn on the printer. 5. If the error persists, replace the fuser assembly. Use the table below and ensure the correct voltage fuser is installed in the printer. WARNING! The fuser is hot. Wait at least 30 minutes after turning the printer power off before removing the fuser. Table 6-114 Fuser assembly (For 110V and 220V) Part numbers

Printer models Part description Part number

M501 M506 M507 M527 M528

E50045

E50145

E52545

E52645

Fuser assembly - For 110 VAC Bonds toner to the paper with heat.

RM2-2585-000CN

M501 M506 M507 M527 M528

E50045

E50145

E52545

E52645

Fuser assembly - For 220 VAC Bonds toner to the paper with heat.

RM2-2586-000CN

Recommended action for call-center agents 289

For instructions: See the Repair Service Manual for this product.

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Ensure the paper type and fuser mode are correctly set for the paper being used. 3. Ensure the power cord of the printer is plugged directly into a wall outlet and the outlet voltage matches the voltage specifications on the printer. NOTE: Unplug the power cord of the printer from any power-strip or uninterrupted power supply, and plug it directly into a wall socket. 4. If the error returns, turn the printer off. 5. Remove the fuser and check the fuser for damage or obstructions. CAUTION: The fuser is hot. Wait at least 30 minutes after turning the printer power off before removing the fuser assembly. 6. Reinstall the fuser, ensure it is seated correctly, and then turn the printer on. 7. If the error persists, replace the fuser assembly. Table 6-115 Fuser assembly (For 110V and 220V) part numbers

Printer models Part description Part number

M501 M506 M507 M527 M528

E50045

E50145

E52545

E52645

Fuser assembly - For 110 VAC Bonds toner to the paper with heat.

RM2-2585-000CN

290 Chapter 6 Numerical control panel messages

Table 6-115 Fuser assembly (For 110V and 220V) part numbers (continued)

Printer models Part description Part number

M501 M506 M507 M527 M528

E50045

E50145

E52545

E52645

Fuser assembly - For 220 VAC Bonds toner to the paper with heat.

RM2-2586-000CN

For instructions: See the Repair Service Manual for this product. 8. If error persists, replace the power supply unit. Table 6-116 Low-voltage power supply (LVPS) part numbers

Printer models Part description Part number

M527 M528

E52545

E52645

Low-voltage power supply (LVPS) - For

110-127 VAC

RM2-7951-000CN

M527 M528

E52545

E52645

Low-voltage power supply (LVPS) - For

220-240 VAC

RM2-7952-000CN

M506 M507

E50045

E50145

Low-voltage power supply (LVPS) - For

110-127 VAC

RM2-7941-000CN

M501 M506 M507

E50045

E50145

Low-voltage power supply (LVPS) - For

220-240 VAC

RM2-7942-000CN

For instructions: See the Repair Service Manual for this product. Recommended action for onsite technicians 291

9. If the error persists, replace the DC controller PCA. Table 6-117 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

For instructions: See the Repair Service Manual for this product. 51.XX.YZ, 52.XX.YZ error messages 51.* errors Errors in the 51.* family are related to the laser scanner.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Upgrade the firmware. For the latest firmware versions, go to HP FutureSmart - Latest Firmware Versions 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Ensure the printer is running the most current version of firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 292 Chapter 6 Numerical control panel messages 2. Check all connections on the laser/scanner and from the laser/scanner to the DC controller, and reseal them if necessary. 3. If the error persists, replace the laser scanner.

51.00.10

Laser/scanner error. Laser/scanner beam detect error.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Reconnect connector (J811/J851) on the laser/scanner. 2. Reconnect connectors (J161) on the DC controller. 3. If the error persists, replace the laser/scanner. For instructions: See the Repair Service Manual for this product. Part number: RM2-5528-000CN 52.* errors Errors in the 52.* family are related to the laser scanner.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Upgrade the firmware. For the latest firmware versions, go to HP FutureSmart - Latest Firmware Versions 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process.

51.00.10 293

1. Ensure the printer is running the most current version of firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 2. Check all connections on the laser/scanner and from the laser/scanner to the DC controller, and reseal them if necessary. 3. If the error persists, replace the laser scanner.

52.XX.00

Laser/scanner error.

● XX = 00

laser/scanner motor startup error.

● XX = 20

Laser/scanner rotation error.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Upgrade the firmware. For the latest firmware versions, go to HP FutureSmart - Latest Firmware Versions 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Reconnect connector (J802) on the laser/scanner. 2. Reconnect connectors (J162) on the DC controller. 3. Use the scanner motor (M3) drive test in the Component Tests to verify that the scanner motor is functioning correctly. If it is not, replace the laser/scanner. NOTE: Listen for a high pitched whine from the motor. 4. If the error persists, replace the laser/scanner. For instructions: See the Repair Service Manual for this product. Part number: RM2-5528-000CN 53.WX.YZ Error Messages 53.B0.0z Tray "Z" feed roller nearing end of life. 294 Chapter 6 Numerical control panel messages

Prepare to replace tray pick rollers

NOTE: This is an event log only message, it will not show on the control panel. "Z" = Tray number. ● 53.B0.01: Tray 1 feed roller nearing end of life. ● 53.B0.02: Tray 2 feed roller nearing end of life. ● 53.B0.03: Tray 3 feed roller nearing end of life. ● 53.B0.04: Tray 4 feed roller nearing end of life. ● 53.B0.05: Tray 5 feed roller nearing end of life. ● 53.B0.06: Tray 6 feed roller nearing end of life.

Recommended action

Follow these troubleshooting steps in the order presented. ■ The paper tray rollers will need to be replaced soon. Be prepared to replace the tray rollers for the specified tray. NOTE: Check the event log for the following messages to determine which tray rollers need to be changed. ● 53.B0.01: Tray 1 feed roller nearing end of life. ● 53.B0.02: Tray 2 feed roller nearing end of life. ● 53.B0.03: Tray 3 feed roller nearing end of life. ● 53.B0.04: Tray 4 feed roller nearing end of life. ● 53.B0.05: Tray 5 feed roller nearing end of life. ● 53.B0.06: Tray 6 feed roller nearing end of life. 53.B1.0z Tray "Z" feed roller at end of life. NOTE: This is an event log only message, it will not show on the control panel. "Z" = Tray number. ● 53.B1.01: Tray 1 feed roller at end of life. ● 53.B1.02: Tray 2 feed roller at end of life. ● 53.B1.03: Tray 3 feed roller at end of life. ● 53.B1.04: Tray 4 feed roller at end of life. ● 53.B1.05: Tray 5 feed roller at end of life. ● 53.B1.06: Tray 6 feed roller at end of life. Recommended action 295

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. ■ Replace the feed and separation rollers for the specified tray. 53.B2.0z Tray "Z" feed roller brand new. NOTE: This is an event log only message, it will not show on the control panel. "Z" = Tray number. ● 53.B2.01: Tray 1 feed roller brand new. ● 53.B2.02: Tray 2 feed roller brand new. ● 53.B2.03: Tray 3 feed roller brand new. ● 53.B2.04: Tray 4 feed roller brand new. ● 53.B2.05: Tray 5 feed roller brand new. ● 53.B2.06: Tray 6 feed roller brand new.

Recommended action

No Action necessary. ■ This is an informational message; no action is necessary. 53.B3.0z Tray "Z" pick roller brand new (engine detected). The engine detected that new tray feed rollers have been installed. NOTE: This is an event log only message, it will not show on the control panel. "Z" = Tray number. ● 53.B3.01: Tray 1 feed roller brand new (engine detected). ● 53.B3.02: Tray 2 feed roller brand new (engine detected). ● 53.B3.03: Tray 3 feed roller brand new (engine detected). ● 53.B3.04: Tray 4 feed roller brand new (engine detected). ● 53.B3.05: Tray 5 feed roller brand new (engine detected). 296 Chapter 6 Numerical control panel messages
● 53.B3.06: Tray 6 feed roller brand new (engine detected).

Recommended action

No Action necessary. ■ This is an informational message; no action is necessary. 53.C1.0z Tray "Z" size mismatch. The specified tray contains a size that does not match the configured size. Complete screen message: The specified tray contains a size that does not match the configured size. The tray is configured to support the only size indicated Confirm guides are in correct position. This issue occurs when the managed print provider has locked the paper tray to either letter or A4 and the tray has a different size paper loaded. NOTE: This can occur if the tray was swapped out or the physical trays locks in the tray were removed and the guides changed. ● 53.C1.02: Tray 2 size mismatch. ● 53.C1.03: Tray 3 size mismatch. ● 53.C1.04: Tray 4 size mismatch. ● 53.C1.05: Tray 5 size mismatch. ● 53.C1.06: Tray 6 size mismatch.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Ensure that the paper size in the tray matches the tray size in the Trays menu. 2. Contact your managed print provider if you need to change the paper size from the one selected. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Ask the customer to check the media size loaded in the tray to see if it matches the size listed in the Trays menu or on the Configuration Page. 2. Instruct the customer to contact the managed print provider if the paper size needs to be changed from the one selected. Recommended action 297

54.XX.YZ error messages 54.* errors Errors in the 54.* family are related to the image-formation system. ● For HP LaserJet printers, they can indicate a problem with the toner cartridges or the transfer unit (color printers only), or they can indicate a problem with a sensor, such as with the laser/scanner. ● For HP PageWide printers, they can indicate a problem with the calibration process.

Recommended action for customers

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, and then on. 2. Make sure the printer is running the most current version of firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 3. Check the supplies status page using the Supplies menu on the control panel to verify that toner cartridges, toner collection unit (TCU), or the transfer belt kit are not past their useful life. Replace the supplies and maintenance parts as necessary. To print a Supplies Status Page: a. From the Home screen on the printer control panel, select Administration. b. Open the following menus: i. Reports ii. Configuration/Status Pages c. Scroll to and select Supplies Status Page. d. Select Print to print the page. To order parts, go to <https://www.hp.com/buy/parts>. 4. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Turn the printer off, and then on. 2. Check the supplies status page to verify that the toner cartridges, TCU, or the transfer belt kit are not past their useful life. Replace the supplies and maintenance parts as necessary. 298 Chapter 6 Numerical control panel messages

3. For color printers, inspect the transfer belt for damage. Replace the transfer belt if necessary or instruct the customer to replace it. 4. For color printers, if the error persists, replace the registration assembly. 5. Check the connections between the laser/scanner and the DC controller, and from the laser/ scanner to the printer. Reseat them if necessary. If the error persists, replace the laser scanner.

54.06.21 error

A sensor error has occurred. Primary laser/scanner beam detect abnormality.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the printer has had parts removed or replaced, check the connectors (J161 and J162) on the DC controller PCA. 3. If the error persists, replace the laser/scanner assembly. For

instructions: See the Repair Service Manual for this product. Part number: RM2-5528-000CN 55.XX.YZ, 56.XX.YZ error messages 55.* errors
Errors in the 55.* family often indicate a problem with the DC controller.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented.

54.06.21 error 299

Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Reset the printer: a. Turn the printer off using the power switch, and then wait at least 30 seconds. b. Turn the printer on and wait for it to initialize. 2. Make sure the printer is running the most current version of firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 3. If the error persists, replace the DC controller.

55.00.yy To continue turn off then on

DC controller PCA error. ● 55.00.01 (event code) DC controller memory error. ● 55.00.03 (event code DC controller no engine response. ● 55.00.04 (event code DC controller communications time-out.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Reset the printer. a. Press the power button to turn off the printer, and then wait at least 30 seconds. b. Press the power button to turn on the printer, and then wait for the printer to initialize. 2. If you are using a surge protector, turn off the printer, and then unplug the power cord from the surge protector. 3. Plug the power cord of the printer directly into the wall outlet, and then turn on the printer. 300 Chapter 6 Numerical control panel messages

4. If the error persists, test the power source with another power cord or a working power outlet. ● If the error persists, try a different power cord, if available. Plug the power cord to the printer and to the wall outlet. NOTE: Use a power cord with the same connector and power specifications as your printer power cord. ● If the error persists, try to plug the power cord to a working wall outlet. 5. If the issue persists, print an engine test page to verify the printer engine is functioning. a. Load paper in Tray 2. NOTE: The test page can only use Tray 2 as the paper source, so make sure that paper is loaded in Tray 2. b. Turn the printer on, and then use a small pointed object (like a paper clip) to depress the test-page switch located on the rear side of the printer (near the formatter). The test page should have a series of lines that are parallel to the short end of the page. Figure 6-84 Engine test-page switch For more information and instructions to perform an engine test, go to WISE and search for the following document: HP LaserJet Pro M501, M506, MFP M527, HP LaserJet Managed E50045, E52545 - Tools for troubleshooting: Engine diagnostics (c04794694). 6. If the engine test page does not print, replace the DC controller PCA. NOTE: Make sure to have a service technician check the connections at the DC controller PCA. Table 6-118 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN Recommended action for call-center agents 301

Table 6-118 DC Controller part numbers (continued)

Printer models Part description Part number

M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

For instructions: See the Repair Service Manual for this product.

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Reset the printer. a. Press the power button to turn off the printer, and then wait at least 30 seconds. b. Press the power button to turn on the printer, and then wait for the printer to initialize. 2. If you are using a surge protector, turn off the printer, and then unplug the power cord from the surge protector. 3. Plug the power cord of the printer directly into the wall outlet, and then turn on the printer. 4. If the error persists, test the power source with another power cord or a working power outlet. ● If the error persists, try a different power cord, if available. Plug the power cord to the printer and to the wall outlet. NOTE: Use a power cord with the same connector and power specifications as your printer power cord. ● If the error persists, try to plug the power cord to a working wall outlet. 5. If the issue persists, print an engine test page to verify the printer engine is functioning. a. Load paper in Tray 2. NOTE: The test page can only use Tray 2 as the paper source, so make sure that paper is loaded in Tray 2. 302 Chapter 6 Numerical control panel messages b. Turn the printer on, and then use a small pointed object (like a paper clip) to depress the test-page switch located on the rear side of the printer (near the formatter). The test page should have a series of lines that are parallel to the short end of the page. Figure 6-85 Engine test-page switch For more information and instructions to perform an engine test, go to WISE and search for the following document: HP LaserJet Pro M501, M506, MFP M527, HP LaserJet Managed E50045, E52545 - Tools for troubleshooting: Engine diagnostics (c04794694). 6. Check and reseat the connections in the DC Controller. IMPORTANT: Ensure all cable connections on the DC controller are securely and attached correctly before replacing any part. 7. If the engine test page does not print, replace the DC controller PCA. Table 6-119 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

Recommended action for onsite technicians 303

View the following video on how to replace the DCC controller for HP LaserJet Enterprise MFP M527, M528, Flow MFP M528, and Managed MFP E52645 How to replace the DCC controller for HP LaserJet Enterprise MFP M527, M528, Flow MFP M528, and Managed MFP E52645 For instructions: See the Repair Service Manual for this product. 55.0x.yy to.continue.off.on DC controller PCA error. ● 55.01.06 (event code) NVRAM memory data error warning. ● 55.02.06 (event code) NVRAM memory access error warning.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Reset the printer. a. Turn off the power by using the power switch, and then wait at least 30 seconds. b. Turn on the power and wait for the product to initialize. 2. If you are using a surge protector: a. Turn the printer power off. b. Remove the surge protector. c. Plug the printer directly into the wall socket and turn the printer power on. 3. If the error persists, try a different power cord if one is available. 4. If the error persists, try a different wall outlet. 5. If the error persists, replace the DC controller PCA. DC controller (M527) part number: RM2-8612-000CN DC controller simplex (M506) part number: RM2-8600-000CN DC controller duplex (M506) part number: RM2-8612-000CN DC controller simplex (M501) part number: RM2-8710-000CN 304 Chapter 6 Numerical control panel messages

DC controller duplex (M506) part number: RM2-7950-000CN For instructions: See the Repair Service Manual for this product. 56.* errors Errors in the 56.* family indicate a communication problem with an optional paper tray or other external accessory.

Recommended action

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, contact your HP-authorized service or support provider, or contact HP support at www.hp.com/go/contactHP. 1. Turn the printer off, and then on. 2. If any third-party hardware is installed, remove it and try printing again. 3. If an optional paper tray is installed, remove it. Check the connectors on the tray for damage. If the connector is damaged, replace the tray. 4. Reinstall the tray, and make sure it is correctly seated.

56.00.yy to.continue.off.on

Optional paper trays communication error.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, disconnect the power cable from the printer and wait 1-minute before reconnecting power and turning the printer on. 2. If the error persists, dispatch an Onsite CE to replace the 1x550-sheet paper feeder cassette assembly: Part Number: F2A72-67901

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, disconnect the power cable from the printer and wait 1-minute before reconnecting power and turning the printer on. 56.* errors 305

2. If the error persists, remove the optional paper trays (1x550-sheet paper feeder cassette assembly) and check the input connectors for damage. If the connector is damaged on the optional paper feeder tray, replace the optional paper feeder. Part Number: F2A72-67901 For instructions: Removal and replacement: Lifter drive assembly See the Repair Service Manual for this product. 3. If the connector is damaged on the printer side, replace the fuser power supply assembly (contains the connector to the paper tray assembly). Part numbers: Fixing (fuser) power supply (FPS) 110V-127V - RM2-7948-000CN Fixing (fuser) power supply (FPS) 220V-240V - RM2-7949-000CN For instructions: See the Repair Service Manual for this product. 306 Chapter 6 Numerical control panel messages

4. If the error persists, check, and RESEAT connector J622 on the 1x550-sheet paper feeder controller PC board assembly prior to replacing any parts. Part Number: F2A72A For instructions: Removal and replacement: Lifter drive assembly See the Repair Service Manual for this product. 5. If the issue persists after replacing the part, elevate the case using your Region's Elevation Process. 57.XX.YZ error messages 57.* errors Errors in the 57.* family indicate a problem with a fan. 57.* errors 307

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Press the Power button on the front of the printer to turn it off, and then wait 10 seconds. 2. Press the Power button again to turn on the printer. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Use the printer troubleshooting manual to identify the locations of each fan. Turn the printer off and then on, and listen for noise coming from the area of each fan. Replace any fan that is not making noise. 2. Update the firmware to the latest version. If the latest version firmware is already installed, reinstall it now. For more information, see: For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. Remove enough parts to access the DC controller or the power supply PCA. Check the connections from each fan to the DC controller or power supply PCA. Reseat them if necessary. 4. With the DC controller or power supply PCA exposed, turn the printer on. Immediately measure the voltage between the connectors for each fan and the DC controller. If the voltage changes from 0V to approximately 24V during the power-on cycle, replace the affected fan. If the voltage remains at 0V, replace the DC controller.

57.00.01 to.continue.off.on

Main fan (FM1) failure.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 308 Chapter 6 Numerical control panel messages

1. Turn the printer off, and then on. Listen for fan noise on the right side of the printer. If no noise is heard, replace the main fan (FM1). Part number: RK2-8068-000CN 2. If the fan has been removed or replaced, check the connectors (J372 and J341) on the high voltage PCA and (J133) on the DC controller PCA. 3. If the error persists, replace the printer.

57.00.02 to.continue.off.on

Sub fan (FM2) failure.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then back on. Listen for fan noise coming from the left side of the printer. The fan should turn on approximately 1.5 minutes after power on. 2. If no noise is heard, replace fan FM2. Part number: RK2-8068-000CN 3. If the fan has been removed or replaced, check connector J661 on the sub fan and J147 on the DC controller. 4. If the error persists, replace the high voltage power supply (HVPS). Table 6-120 Parts

Part number Description

RM2-7945-000CN Power supply, high-voltage (HVPS) (M501/M506/E50045/

M527/E52545)

RM3-7424-000CN Power supply, high-voltage (HVPS) (M507/E50145/M528/

E52645)

For instructions: See the Repair Service Manual for this product. 58.XX.YZ error messages 58.* errors Errors in the 58.* family indicate an electrical problem inside the printer.

57.00.02 to.continue.off.on 309

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Make sure the printer is connected to a dedicated power outlet and not to a surge protector or other type of extension cord. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Turn the printer off, and then on. 2. Make sure the printer is connected to a dedicated power outlet and not to a surge protector or other type of extension cord. 3. Check all connections on the DC Controller and the power supply. Trace the connections from the DC Controller and power supply to the sensors and other components and reseal them if necessary.

58.00.03 Error

DC controller CPU failure.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Check and reseal all the connectors on the DC controller PCA. IMPORTANT: Ensure that all the cable connections on the DC controller are secure and connected correctly before replacing any part. 3. If you are using a surge protector, turn off the printer, and then unplug the power cord from the surge protector. 4. Plug the power cord of the printer directly into the wall outlet, and then turn on the printer. 310 Chapter 6 Numerical control panel messages 5. If the error persists, test the power source with another power cord or a working power outlet. ● If the error persists, try a different power cord, if available. Plug the power cord to the printer and to the wall outlet. NOTE: Use a power cord with the same connector and power specifications as your printer power cord. ● If the error persists, try to plug the power cord to a working wall outlet. 6. If the issue persists, run an engine test on the printer. Print an engine test page to verify the printer engine is functioning. a. Load paper in Tray 2. NOTE: The test page can only use Tray 2 as the paper source, so make sure that paper is loaded in Tray 2. b. Turn the printer on, and then use a small pointed object (like a paper clip) to depress the test-page switch located on the rear side of the printer (near the formatter). The test page should have a series of lines that are parallel to the short end of the page. Figure 6-86 Engine test-page switch For more information and instructions to perform an engine test, go to WISE and search for the following document: HP LaserJet Pro M501, M506, MFP M527, HP LaserJet Managed E50045, E52545 - Tools for troubleshooting: Engine diagnostics (c04794694). 7. If the engine test page does not print, replace the DC controller PCA. NOTE: Make sure to have a service technician check the connections at the DC controller PCA. Table 6-121 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN Recommended action for call-center agents 311

Table 6-121 DC Controller part numbers (continued)

Printer models Part description Part number

M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

For instructions: See the Repair Service Manual for this product.

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Reset the printer. a. Press the power button to turn off the printer, and then wait at least 30 seconds. b. Press the power button to turn on the printer, and then wait for the printer to initialize. 2. If you are using a surge protector, turn off the printer, and then unplug the power cord from the surge protector. 3. Plug the power cord of the printer directly into the wall outlet, and then turn on the printer. 4. If the error persists, test the power source with another power cord or a working power outlet. ● If the error persists, try a different power cord, if available. Plug the power cord to the printer and to the wall outlet. NOTE: Use a power cord with the same connector and power specifications as your printer power cord. ● If the error persists, try to plug the power cord to a working wall outlet. 5. If the issue persists, run an engine test on the printer. Print an engine test page to verify the printer engine is functioning. a. Load paper in Tray 2. NOTE: The test page can only use Tray 2 as the paper source, so make sure that paper is loaded in Tray 2. 312 Chapter 6 Numerical control panel messages

b. Turn the printer on, and then use a small pointed object (like a paper clip) to depress the test-page switch located on the rear side of the printer (near the formatter). The test page should have a series of lines that are parallel to the short end of the page. Figure 6-87 Engine test-page switch For more information and instructions to perform an engine test, go to WISE and search for the following document: HP LaserJet Pro M501, M506, MFP M527, HP LaserJet Managed E50045, E52545 - Tools for troubleshooting: Engine diagnostics (c04794694). 6. Check and reseat all of the connectors on the DC controller PCA. IMPORTANT: Ensure all cable connections on the DC controller are securely and connected correctly before replacing any part. 7. If the engine test page does not print, replace the DC controller PCA. Table 6-122 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

Recommended action for onsite technicians 313

View the following video on how to replace the DCC controller for HP LaserJet Enterprise MFP M527, M528, Flow MFP M528, and Managed MFP E52645 How to replace the DCC controller for HP LaserJet Enterprise MFP M527, M528, Flow MFP M528, and Managed MFP E52645 For instructions: See the Repair Service Manual for this product.

58.00.04 Error

The printer experienced a low voltage power supply unit malfunction.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. NOTE: This error might be caused by source power related issues. Determine if the area where the printer is located has experienced brown outs or is subject to power quality issues. 2. Ensure the printer is connected to a dedicated power outlet. 3. If the error persists, replace the power supply unit. For instructions: See the Repair Service Manual for this product. Table 6-123 Parts

Description

Low-voltage power supply (LVPS) 110V-127V (M527) RM2-7951-000CN Low-voltage power supply (LVPS) 220V-240V (M527) RM2-7952-000CN Low-voltage power supply (LVPS) 110V-127V (M501/M506) RM2-7941-000CN Low-voltage power supply (LVPS) 220V-240V (M501/M506) RM2-7942-000CN

58.01.04 Error

During regular printing operation the 24V power supply experienced an error.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 314 Chapter 6 Numerical control panel messages

2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. NOTE: This error might be caused by source power related issues. Determine if the area where the printer is located has experienced brown outs or is subject to power quality issues. 2. Ensure the printer is connected to a dedicated power outlet. 3. If the error persists, replace the power supply unit. For instructions: See the Repair Service Manual for this product. Table 6-124 Parts

Description

Low-voltage power supply (LVPS) 110V-127V (M527) RM2-7951-000CN Low-voltage power supply (LVPS) 220V-240V (M527) RM2-7952-000CN Low-voltage power supply (LVPS) 110V-127V (M501/M506) RM2-7941-000CN Low-voltage power supply (LVPS) 220V-240V (M501/M506) RM2-7942-000CN

58.02.04 Error

During printer power on or when waking from sleep mode, the printer experienced an error with the 24V power supply. NOTE: Check the voltage of the unit on the regulatory sticker. This event is directly related to a 220V printer being plugged into a 110V outlet. Ensure that the voltage of the outlet matches the voltage of the printer.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. NOTE: This error might be caused by source power related issues. Determine if the area where the printer is located has experienced brown outs or is subject to power quality issues. Recommended action 315

2. Ensure the printer is connected to a dedicated power outlet. 3. If the error persists, replace the power supply unit. For instructions: See the Repair Service Manual for this product. Table 6-125 Parts

Description

Low-voltage power supply (LVPS) 110V-127V (M527) RM2-7951-000CN Low-voltage power supply (LVPS) 220V-240V (M527) RM2-7952-000CN Low-voltage power supply (LVPS) 110V-127V (M501/M506) RM2-7941-000CN Low-voltage power supply (LVPS) 220V-240V (M501/M506) RM2-7942-000CN 59.XX.YZ error messages 59.* errors Errors in the 59.* family indicate a problem with one of the motors or with the lifter drive assembly for one of the trays.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Turn the printer off, and then on. 2. Check all connections on the main control board of the printer, (DC controller, Engine control board ECB) each motor, and to the paper feeder drive PCA (for an optional paper feeder). Reseat them if necessary.

59.A2.02

Tray 2 lifter drive assembly failure.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. 316 Chapter 6 Numerical control panel messages

Recommended action

Follow these troubleshooting steps in the order presented. 1. Use the Tray/Bin manual sensor test to verify that the Tray 2 paper surface sensors are functioning correctly. 2. If any parts have been removed or replaced, check the connector (J144) on the on the DC controller PCA. 3. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement.

59.A2.0X

Tray 3 to 5 lifter drive assembly motor failure. NOTE: You can determine the tray number from the last digit in the error number. X = Tray number 59.A2.03 — Tray 3 59.A2.04 — Tray 4 59.A2.05 — Tray 5

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Open the failing tray and remove all paper from the tray. 2. Ensure that when reloading the paper the top of the stack is below the tray full indicator. 3. If Tray has paper loaded ABOVE the tray full indicator, remove enough paper to get stack BELOW the line. Close tray and test. Recommended action 317

4. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Open the failing tray and remove all paper from the tray. 2. Ensure that when reloading the paper the top of the stack is below the tray full indicator. 3. If the issue persists when the paper tray is properly loaded, swap the tray cassette with another from the printer that is the same size and check if the error follows the cassette. 4. If the error persists, dispatch an Onsite CE with a new Cassette Tray. Tray 2-6 Cassette Part Number: RM2-5758-000CN

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Open the failing tray and remove all paper from the tray. 318 Chapter 6 Numerical control panel messages

2. Ensure that when reloading the paper the top of the stack is below the tray full indicator. Recommended action for onsite technicians 319

3. If the error persists, check, and RESEAT connector J622 on the 1x550-sheet paper feeder controller PC board assembly prior to replacing any parts. 4. If the error goes away, swap the tray from another in the printer. If issue follows the cassette, replace the Tray Cassette: Part Number: RM2-5758-000CN For instructions: Removal and replacement: Cassette Tray See the Repair Service Manual for this product. 5. If the issue persists after swapping/replacing the Cassette Tray, replace the 1x550-sheet paper feeder cassette assembly: Part Number: F2A72-67901 For instructions: Removal and replacement: Cassette Tray See the Repair Service Manual for this product. 320 Chapter 6 Numerical control panel messages

6. If the issue persists after replacing the Tray Cassette, or the 1x550 Sheet Feeder Assembly, replace the 1x550-sheet paper feeder controller PC board assembly. Part Number: RM2-7944-000CN For instructions: Removal and replacement: Cassette Tray See the Repair Service Manual for this product. 7. If the issue persists after replacing the part, elevate the case using your Region's Elevation Process.

59.00.20 Error — To.continue.off.on

Feed motor (M2) failure.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Reconnect the connector (J711) on the feed motor and the connector (J171) on the DC controller PCA. 2. Use the feed motor (M2) drive test in the Component test to verify that the motor is functioning correctly. 3. If the feed motor is not functioning or the issue persists, replace the feed motor M2.

59.00.30 — To.continue.off.on

Fuser motor (M1) failure.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented.

59.00.20 Error — To.continue.off.on 321

1. Use the fuser motor (M1) drive test in the Component test to verify that the motor is functioning correctly. If test fails, replace the fuser. Table 6-126 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN See the Repair Service Manual for this product. 2. If the motor has been removed or replaced, check connector J712 on the fuser motor M1 and connector J146 on the DC controller. 3. If the error persists, replace the fuser motor M1. Part number: RM2-8684-000CN For instructions: See the Repair Service Manual for this product.

59.00.40 — To.continue.off.on

Fuser motor (M1) failure.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Use the fuser motor (M1) drive test in the Component test to verify that the motor is functioning correctly. If test fails, replace the fuser. Table 6-127 Part numbers

Part Name Part Number

Fuser assembly 110V-127V (M501/M506/E50045/M527/

E52545)

RM2-5679-000CN

Fuser assembly 110V-127V (M507/E50145/M528/E52645) RM2-2585-000CN Fuser assembly 220-240V (M501/M506/E50045/M527/

E52545)

RM2-5692-000CN

Fuser assembly 220-240V (M507/E50145/M528/E52645) RM2-2586-000CN 322 Chapter 6 Numerical control panel messages

See the Repair Service Manual for this product. 2. If the motor has been removed or replaced, check connector J712 on the fuser motor M1 and connector J146 on the DC controller. 3. If the error persists, replace the fuser motor M1. Part number: RM2-8684-000CN For instructions: See the Repair Service Manual for this product.

60.00.0Y, 62.00.00 error messages

60.00.0X Tray X lifting error

A tray lifting error has occurred.

60.00.02: Tray 2

60.00.03: Tray 3

60.00.04: Tray 4

60.00.05: Tray 5

NOTE: You can determine the tray number from the last digit in the error number. For example: ● 60.00.02 or 60.01.02 = Tray 2 ● 60.00.03 or 60.01.03 = Tray 3

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Open the failing tray and remove all paper from the tray.

60.00.0X Tray X lifting error 323

2. Ensure that when reloading the paper the top of the stack is below the tray full indicator. 3. If Tray has paper loaded ABOVE the tray full indicator, remove enough paper to get stack BELOW the line. Close tray and test. 4. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Open the failing tray and remove all paper from the tray. 2. Ensure that when reloading the paper the top of the stack is below the tray full indicator. 324 Chapter 6 Numerical control panel messages

3. If the issue persists when the paper tray is properly loaded, swap the tray cassette with another from the printer that is the same size and check if the error follows the cassette. 4. If the error persists, dispatch an Onsite CE with a new Cassette Tray. Tray 2-6 Cassette Part Number: RM2-5758-000CN

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Open the failing tray and remove all paper from the tray. 2. Ensure that when reloading the paper the top of the stack is below the tray full indicator. Recommended action for onsite technicians 325

3. If the error persists, check, and RESEAT connector J622 on the 1x550-sheet paper feeder controller PC board assembly prior to replacing any parts. 4. If the error goes away, swap the tray from another in the printer. If issue follows the cassette, replace the Tray Cassette: Part Number: RM2-5758-000CN For instructions: Removal and replacement: Cassette Tray See the Repair Service Manual for this product. 5. If the issue persists after swapping/replacing the Cassette Tray, replace the lifter drive assembly: Part Number: RM2-5715-000CN For instructions: Removal and replacement: See the Repair Service Manual for this product. 326 Chapter 6 Numerical control panel messages

6. If the issue is occurring on an Accessory Tray (Trays 3-6) and the Cassette Tray has been ruled out, replace the 1x550-sheet paper feeder cassette assembly – Part Number: F2A72-67901 For instructions: Removal and replacement: Cassette Tray See the Repair Service Manual for this product. 7. If the error persists after replacing the Lifter Drive Assembly, Tray Cassette, or the 1x550 Sheet Feeder Assembly, replace the 1x550-sheet paper feeder controller PC board assembly. Part Number: RM2-7944-000CN For instructions: Removal and replacement: See the Repair Service Manual for this product. 8. If the issue persists after replacing the part, elevate the case using your Region's Elevation Process.

60.01.0X Tray X lifting error

A tray lifting error has occurred.

60.01.02: Tray 2

60.01.03: Tray 3

60.01.04: Tray 4

60.01.05: Tray 5

NOTE: You can determine the tray number from the last digit in the error number. For example: ● 60.00.02 or 60.01.02 = Tray 2 ● 60.00.03 or 60.01.03 = Tray 3

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Open the failing tray and remove all paper from the tray.

60.01.0X Tray X lifting error 327

2. Ensure that when reloading the paper the top of the stack is below the tray full indicator. 3. If Tray has paper loaded ABOVE the tray full indicator, remove enough paper to get stack BELOW the line. Close tray and test. 4. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Open the failing tray and remove all paper from the tray. 2. Ensure that when reloading the paper the top of the stack is below the tray full indicator. 328 Chapter 6 Numerical control panel messages

3. If the issue persists when the paper tray is properly loaded, swap the tray cassette with another from the printer that is the same size and check if the error follows the cassette. 4. If the error persists, dispatch an Onsite CE with a new Cassette Tray. Tray 2-6 Cassette Part Number: RM2-5758-000CN

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Open the failing tray and remove all paper from the tray. 2. Ensure that when reloading the paper the top of the stack is below the tray full indicator. Recommended action for onsite technicians 329

3. If the error persists, check, and RESEAT connector J622 on the 1x550-sheet paper feeder controller PC board assembly prior to replacing any parts. 4. If the error goes away, swap the tray from another in the printer. If issue follows the cassette, replace the Tray Cassette: Part Number: RM2-5758-000CN For instructions: Removal and replacement: Cassette Tray See the Repair Service Manual for this product. 5. If the issue persists after swapping/replacing the Cassette Tray, replace the lifter drive assembly: Part Number: RM2-5715-000CN For instructions: Removal and replacement: See the Repair Service Manual for this product. 330 Chapter 6 Numerical control panel messages

6. If the issue is occurring on an Accessory Tray (Trays 3-6) and the Cassette Tray has been ruled out, replace the 1x550-sheet paper feeder cassette assembly – Part Number:F2A72-67901 For instructions: Removal and replacement: Cassette Tray See the Repair Service Manual for this product. 7. If the persists after replacing the Lifter Drive Assembly, Tray Cassette, or the 1x550 Sheet Feeder Assembly, 1x550 Sheet Feeder Assembly, replace the 1x550-sheet paper feeder controller PC board assembly. Part Number: RM2-7944-000CN For instructions: Removal and replacement: See the Repair Service Manual for this product. 8. If the issue persists after replacing the part, elevate the case using your Region's Elevation Process.

62.00.00 To continue turn off then on.

Internal system failure.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, reload the firmware. If the error still persists, perform a firmware upgrade. 3. If the firmware upgrade does not resolve the problem, replace the hard disk. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-128 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above

62.00.00 To continue turn off then on. 331

For instructions: See the Repair Service Manual for this product.. 65.X0.AZ error messages 65.* errors Errors in the 65.* family are related to output accessories.

Recommended action

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, contact your HP-authorized service or support provider, or contact HP support at www.hp.com/go/contactHP. 1. Turn the printer off, and then on. 2. Verify the output accessory is correctly connected to the printer. 3. If the error persists, replace the output accessory.

65.80.A0, 65.80.A1: Output accessory Failure

Output accessory disconnected. An external paper handling accessory connection has been interrupted.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off. 2. Make sure that the communication cable from the finisher to the engine is installed correctly. 3. Make sure that all packing materials have been removed from the paper handling accessory. 4. Check the paper path for obstructions, or jammed paper. 5. Turn the printer on. If the error persists, replace the stapler/stacker assembly. Part Number: B5L46-60102 332 Chapter 6 Numerical control panel messages

66.WX.YZ error messages 66.* errors Errors in the 66.* family are related to output accessories.

Recommended action

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, contact your HP-authorized service or support provider, or contact HP support at www.hp.com/go/contactHP. 1. Turn the printer off, and then on. 2. Verify the output accessory is correctly connected to the printer. 3. If the error persists, replace the output accessory.

66.00.20

This message is related to an output device failure. Over current error.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Make sure that the finisher is connected correctly. 3. If the error persists, replace the stapler/stacker assembly. Part Number: B5L46-60102

66.00.40

This is a finisher control board NVRAM error. The checksum for the finisher stacker controller PCA has an error when the power is turned on.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 66.* errors 333
2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Make sure that the finisher is connected correctly. 3. If the error persists, replace the stapler/stacker assembly. Part Number: B5L46-60102

66.00.50

This is a CAN-CPU sequence error.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Make sure that the finisher is connected correctly. 3. If the error persists, replace the stapler/stacker assembly. Part Number: B5L46-60102

66.00.77

This is a device communication error. The communication between the print engine and the finisher has been interrupted or lost.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 334 Chapter 6 Numerical control panel messages

1. Turn the printer off, and then on. 2. Make sure that the finisher is connected correctly. 3. If the error persists, replace the stapler/stacker assembly. Part Number: B5L46-60102

66.00.79

This is a JetLink communication error. The printer has lost JetLink communication with the output device.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn off the printer, and then disconnect the finisher. 2. Inspect and reconnect the JetLink cable (power and communication cable) from the finisher to the printer. 3. Reconnect the finisher to the printer. 4. Turn the printer on. 5. If the error persists, replace the stacker controller PCA or the stapler/stacker assembly. Stapler/stacker part number: B5L46-60102

66.80.YY Stapler/Stacker failure

An external paper handling accessory error has occurred. ● 66.80.01 (event code)

Y-align malfunction

● 66.80.02 (event code)

Jogger malfunction

● 66.80.03 (event code)

Stapler malfunction

● 66.80.21 (event code)

Lift up malfunction

66.00.79 335

● 66.80.22 (event code)

Lift down malfunction

● 66.80.23 (event code)

Lift sensor malfunction

● 66.80.33 (event code)

Output roller malfunction

● 66.80.35 (event code)

Self priming malfunction

● 66.80.51 (event code) System error (FW error) ● 66.80.55 (event code) System error 5 (FW error) ● 66.80.56 (event code) System error 6 (FW error) ● 66.80.57 (event code) System error 7 (FW error) ● 66.80.58 (event code) System error 8 (FW error) ● 66.80.59 (event code) System error 9 (FW error) ● 66.80.60 (event code) System error 10 (FW error) ● 66.80.61 (event code) System error 11 (FW error) ● 66.80.62 (event code) System error 12 (FW error) ● 66.80.63 (event code) System error 13 (FW error) ● 66.80.64 (event code) System error 14 (FW error) ● 66.80.65 (event code) 336 Chapter 6 Numerical control panel messages
System error 15 (FW error) ● 66.80.70 (event code)

Page-info in flush

● 66.80.71 (event code)

Flush request in PDLV

● 66.80.72 (event code)

Delivery notice error

● 66.80.73 (event code)

Flush request in checking paper path

● 66.80.74 (event code)

Checking paper path start in PDLV

● 66.80.75 (event code)

Flush request in flush

● 66.80.76 (event code)

Non-flush complete

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn off the printer, and then disconnect the finisher. 2. Inspect and reconnect the JetLink cable (power and communication cable) from the finisher to the printer. 3. Inspect the finisher for paper jams. 4. Reconnect the finisher to the printer. 5. Turn the printer on. 6. If the error persists, replace the stapler/stacker assembly. Part Number: B5L46-60102
Recommended action for customers 337

70.XX.YY error messages 70.* errors Messages in the 70.* family indicate a problem with the DC controller or Formatter (ECB) depending on your printer.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Turn the printer off, and then on. 2. Replace the DC controller or the Formatter as needed.

70.00.00 Error To continue turn off then on

DC controller failure.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, replace the DC controller. Table 6-129 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

338 Chapter 6 Numerical control panel messages

Table 6-129 DC Controller part numbers (continued)

Printer models Part description Part number

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

For instructions: See the Repair Service Manual for this product.

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Print an engine test page to verify the printer engine is functioning. a. Load paper in Tray 2. NOTE: The test page can only use Tray 2 as the paper source, so make sure that paper is loaded in Tray 2. b. Turn on the printer, and then use a small pointed object (like a paper clip) to depress the test-page switch located on the rear side of the printer (near the formatter). The test page should have a series of lines that are parallel to the short end of the page. Figure 6-88 Engine test-page switch Recommended action for onsite technicians 339

3. If the engine test page prints or does not print, verify that all the connections on the DCC are seated correctly. NOTE: Ensure all cable connections on the DC controller are secure and connected correctly before replacing any part. 4. If the error persists, replace the DC controller. Table 6-130 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

For instructions: See the Repair Service Manual for this product. 5. If the error persists after replacing the DC controller, elevate the case using the Standard Support Process. 80.XX.YY, 81.XX.YY, 82.XX.YY error messages 80.* errors Errors in the 80.* family indicate a problem with an external I/O device, such as a Jetdirect card, an EIO card, or an external hard disk. ● 80.00.00 error: Managed device lost connection to service provider. The product is under a service contract and has lost network connectivity for license validation. ● 80.01.01 error: HP Accessibility Assistant connection error. Managed device is unable to establish a connection with the HP Accessibility Assistant. ● 80.01.02 error: Managed Device Unknown HP Accessibility Assistant error. ● 80.01.03 error: HP Accessibility Assistant connection lost. The product lost communication with the HP Accessibility Assistant. ● 80.01.04 error: HP Accessibility Assistant disconnected. The HP Accessibility Assistant was disconnected from the product. 340 Chapter 6 Numerical control panel messages

● 80.01.05 error: HP Accessibility Assistant detected. Restart required. The HP Accessibility Assistant was connected to the product after turn on. The HP Accessibility Assistant is not a plug-and-play device.

Recommended action for customers

Customer actions for 80.* errors. Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, reconnect the network cable, and then turn the printer on. 2. Try another network cable. 3. Reload the printer firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 4. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call center agents

Call center agent actions for 80.* errors. 1. Turn the printer off, reconnect the network cable, and then turn the printer on. 2. Try another network cable. 3. If the error persists, perform a Partial Clean procedure using the Preboot menu. NOTE: For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . a. Turn the printer on. b. Press the HP logo that displays in the middle of the screen when you see the 1/8 under the logo. c. Press the down arrow button to highlight Administrator, and then press the OK button. d. Press the down arrow button to highlight Partial Clean, and then press the OK button. e. Press the OK button again. f. Press the back button once to highlight Continue, and then press the OK button. g. The printer automatically initializes and then returns to a Ready state. 4. If the error persists, perform a Format Disk procedure using the Preboot menu, and then upgrade the firmware to the latest version. NOTE: For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . a. Turn the printer on. Recommended action for customers 341

b. Press the HP logo that displays in the middle of the screen when you see the 1/8 under the logo. c. Press the down arrow button to highlight Administrator, and then press the OK button. d. Press the down arrow button to highlight Format Disk, and then press the OK button. e. Press the OK button again. f. Wait for the printer to automatically initialize. The message 99.09.67 appears on the control panel. g. Reload the firmware using a USB flash drive. See 99.09.67 error for more information. 5. If the error persists, dispatch an onsite technician (no replacement parts required).

Recommended action for call center agents

Call center agent actions for 80.* errors. 1. Turn the printer off, reconnect the network cable, and then turn the printer on. 2. Try another network cable. 3. If the error persists, perform a Partial Clean procedure using the Preboot menu. NOTE: For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . a. Turn the printer on. b. Press the HP logo that displays in the middle of the screen when you see the 1/8 under the logo. c. Press the down arrow button to highlight Administrator, and then press the OK button. d. Press the down arrow button to highlight Partial Clean, and then press the OK button. e. Press the OK button again. f. Press the back button once to highlight Continue, and then press the OK button. g. The printer automatically initializes and then returns to a Ready state. 4. If the error persists, perform a Format Disk procedure using the Preboot menu, and then upgrade the firmware to the latest version. NOTE: For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . a. Turn the printer on. b. Press the HP logo that displays in the middle of the

screen when you see the 1/8 under the logo. c. Press the down arrow button to highlight Administrator, and then press the OK button. d. Press the down arrow button to highlight Format Disk, and then press the OK button. 342 Chapter 6 Numerical control panel messages

e. Press the OK button again. f. Wait for the printer to automatically initialize. The message 99.09.67 appears on the control panel. g. Reload the firmware using a USB flash drive. See 99.09.67 error for more information. 80.0X.YY Embedded Jetdirect Error An Embedded HP JetDirect print server critical error has occurred. ● 80.01.80: (event log) No heartbeat ● 80.01.81: (event log) Reclaim timeout ● 80.01.82: (event log) Invalid data length ● 80.01.8B: (event log) Invalid max outstanding packet header field ● 80.01.8C: (event log) Invalid channel mapping response ● 80.03.01: (event log) No PGP buffers ● 80.03.02: (event log) Channel table full ● 80.03.03: (event log) Producer index not reset ● 80.03.04: (event log) Consumer index not reset ● 80.03.05: (event log) Queue position size too small ● 80.03.06: (event log) Transport overflow ● 80.03.07: (event log) No overflow packets ● 80.03.08: (event log) Invalid identify response ● 80.03.09: (event log) Invalid channel map return status ● 80.03.10: (event log) Invalid reclaim return status ● 80.03.12: (event log) Datagram invalid buffer ● 80.03.13: (event log) Max stream channels ● 80.03.14: (event log) Max datagram channels ● 80.03.15: (event log) Card reset failed ● 80.03.16: (event log) Self-test failure ● 80.03.17: (event log) Unknown PGP packet ● 80.03.18: (event log) Duplicate I/O channel

Recommended action for customers

Follow these troubleshooting steps in the order presented. 80.0X.YY Embedded Jetdirect Error 343

1. Press the power button to turn on the printer, and then press the power button to turn off the printer. 2. Disconnect the Ethernet cable from the Ethernet port on the printer and router. 3. If the error persists, turn off the printer, and then turn on the printer. 4. Reconnect the Ethernet cable to the Ethernet port on the printer and a port on the router. 5. If the error persists, try using a new Ethernet cable or a different Ethernet/LAN port on the router. Check the lights on the printer's Ethernet port to make sure the connection is successful. The green light should be steady and lit. 6. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Turn off the printer, and then turn on the printer. 3. Disconnect the Ethernet (RJ-45) cable from the Ethernet port on the printer and router. 4. If the error persists, turn off the printer, and then turn on the printer. 5. Reconnect the Ethernet (RJ-45) cable to the Ethernet port on the printer and a port on the router. 6. If the error persists, try using a new Ethernet (RJ-45) cable or a different Ethernet or LAN port on the router. Check the lights on the printer's Ethernet port to make sure the connection is successful. 7. If the error persists, update the firmware. For instructions, go to Update the printer firmware (ish_4158468-4158516-16). 8. If the error persists, dispatch a service technician to replace the formatter. Use the following table to order the correct part number for your printer. Table 6-131 Formatter PCA part numbers

Product models Part description Part number

M501dn Formatter PC board J8H61-67901 M501dn (China) Formatter PC board J8H61-67902 M501n Formatter PC board J8H60-67901 M501n (China) Formatter board assembly J8H60-67902 M506n/ M506dn E50045n/ E50045dn Formatter PC board assembly F2A68-67915 M506x E50045x Formatter PC board assembly F2A68-67916 344 Chapter 6 Numerical control panel messages

Table 6-131 Formatter PCA part numbers (continued)

Product models Part description Part number

M507

E50145

Formatter PC board 1PV87-60001 M527

E52545

Formatter PC board assembly F2A76-67910 M528

E52645

Formatter PC board 1PV64-60002 For instructions: See the Repair Service Manual for this product.

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Turn off the printer, and then turn on the printer. 3. Disconnect the Ethernet (RJ-45) cable from the Ethernet port on the printer and router. 4. If the error persists, turn off the printer, and then turn on the printer. 5. Reconnect the Ethernet (RJ-45) cable to the Ethernet port on the printer and a port on the router. 6. If the error persists, try using a new Ethernet (RJ-45) cable or a different Ethernet or LAN port on the router. Check the lights on the printer's Ethernet port to make sure the connection is successful. 7. If the error persists, update the firmware. For instructions, go to Update the printer firmware (ish_4158468-4158516-16). 8. If the error persists, replace the formatter. Use the following table to order the correct part number for your

printer. Table 6-132 Formatter PCA part numbers

Product models Part description Part number

M501dn Formatter PC board J8H61-67901 M501dn (China) Formatter PC board J8H61-67902 M501n Formatter PC board J8H60-67901 M501n (China) Formatter board assembly J8H60-67902 M506n/ M506dn E50045n/ E50045dn Formatter PC board assembly F2A68-67915 M506x E50045x Formatter PC board assembly F2A68-67916 Recommended action for onsite technicians 345

Table 6-132 Formatter PCA part numbers (continued)

Product models Part description Part number

M507

E50145

Formatter PC board 1PV87-60001 M527

E52545

Formatter PC board assembly F2A76-67910 M528

E52645

Formatter PC board 1PV64-60002 For instructions: See the Repair Service Manual for this product.

81.09.00 Error

Internal Jetdirect Inside Networking event.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technician Follow these troubleshooting steps in the order presented. 1. Verify that the issue occurs with the latest version of firmware. a. Obtain the latest public firmware version for the device from hp.com. b. Update the device firmware. c. The device will reboot during the firmware update process. d. If available (from HP Advance Technical Support), obtain the latest interim version of firmware to perform the same update test. e. If the issue persists, continue with the next troubleshooting step. 2. Verify that the issue occurs when the device has the latest firmware and is not connected to the network. a. Disconnect the network cable from the network I/O port on the device. b. Turn the printer off, and then on. c. If the error persists, continue with the next troubleshooting step. 3. Verify that the issue occurs when disconnected from the network and with default configuration. 346 Chapter 6 Numerical control panel messages

a. Run a partial clean. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid state drives" (ish_4502973-4502949-16) - . b. If the error persists, continue with the next troubleshooting step. 4. Call center agents: Dispatch an onsite technician to re-establish the trusted platform module state in the printer. IMPORTANT: Never replace the TPM on a unit that shipped with one. The TPM that can be ordered is only available for adding a level of security on a device that never had a TPM paired from the factory. A new TPM cannot be installed for security reasons. 82.* errors Errors in the 82.* family indicate a problem with an external I/O device, such as a Jetdirect card, an EIO card, or an external hard disk. ● 82.00.00 error: Memory Error. ● 82.73.45 error: Memory Error. Disk successfully cleaned. Event log only. ● 82.73.46 error: Memory Error. A hard disk or compact flash disk cleaning failed. Usually caused by a failure of the disk hardware. Event log only. ● 82.73.47 error: Memory Error. Some of sanitized disk did not correctly verify. Event log only.

Recommended action for customers

Customer actions for 80.* errors. Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, reconnect the network cable, and then turn the printer on. 2. Try another network cable. 3. Reload the printer firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 4. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call center agents

Call center agent actions for 80.* errors. 1. Turn the printer off, reconnect the network cable, and then turn the printer on. 2. Try another network cable. 82.* errors 347

3. If the error persists, perform a Partial Clean procedure using the Preboot menu. NOTE: For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . a. Turn the printer on. b. Press the HP logo that displays in the middle of the screen when you see the 1/8 under the logo. c. Press the down arrow button to highlight Administrator, and then press the OK button. d. Press the down arrow button to

highlight Partial Clean, and then press the OK button. e. Press the OK button again. f. Press the back button once to highlight Continue, and then press the OK button. g. The printer automatically initializes and then returns to a Ready state. 4. If the error persists, perform a Format Disk procedure using the Preboot menu, and then upgrade the firmware to the latest version. NOTE: For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . a. Turn the printer on. b. Press the HP logo that displays in the middle of the screen when you see the 1/8 under the logo. c. Press the down arrow button to highlight Administrator, and then press the OK button. d. Press the down arrow button to highlight Format Disk, and then press the OK button. e. Press the OK button again. f. Wait for the printer to automatically initialize. The message 99.09.67 appears on the control panel. g. Reload the firmware using a USB flash drive. See 99.09.67 error for more information. 5. If the error persists, dispatch an onsite technician (no replacement parts required).

Recommended action for call center agents

Call center agent actions for 80.* errors. 1. Turn the printer off, reconnect the network cable, and then turn the printer on. 2. Try another network cable. 3. If the error persists, perform a Partial Clean procedure using the Preboot menu. NOTE: For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 348 Chapter 6 Numerical control panel messages

a. Turn the printer on. b. Press the HP logo that displays in the middle of the screen when you see the 1/8 under the logo. c. Press the down arrow button to highlight Administrator, and then press the OK button. d. Press the down arrow button to highlight Partial Clean, and then press the OK button. e. Press the OK button again. f. Press the back button once to highlight Continue, and then press the OK button. g. The printer automatically initializes and then returns to a Ready state. 4. If the error persists, perform a Format Disk procedure using the Preboot menu, and then upgrade the firmware to the latest version. NOTE: For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . a. Turn the printer on. b. Press the HP logo that displays in the middle of the screen when you see the 1/8 under the logo. c. Press the down arrow button to highlight Administrator, and then press the OK button. d. Press the down arrow button to highlight Format Disk, and then press the OK button. e. Press the OK button again. f. Wait for the printer to automatically initialize. The message 99.09.67 appears on the control panel. g. Reload the firmware using a USB flash drive. See 99.09.67 error for more information.

82.73.46, 82.73.47

A hard disk or compact flash disk cleaning failed. This error is usually caused by a failure of the disk hardware.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the product off, and then on. 2. Reload the printer firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented.

82.73.46, 82.73.47 349

1. Turn the printer off, and then on. 2. Use the Format Disk item in the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 3. Reload the firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 98.0X.0Y error messages 98.* errors Errors in the 98.* family are related to data corruption in the firmware.

Recommended action for customers

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, and then on. 2. Download and install the latest firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Turn the printer off, and then on. 2. Download and install the most current version of the firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 3. Use the Format Disk item in the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 4. Reload the firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions

98.00.0C

Data corruption, fail to mount partition. 350 Chapter 6 Numerical control panel messages

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, Upgrade the firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, download and install the latest printer firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. Use the Format Disk item in the Preboot menu. CAUTION: Selecting Format Disk removes all data. The system is not bootable after this action and 99.09.67 displays on the control panel. A firmware download must be performed to return the system to a bootable state. Should any installed workflow solutions be present they will be deleted and require reloading and setup by the customer. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 4. Use the printer's Preboot menu and USB thumb drive, update the printer firmware: For more information, go to: HP LaserJet Enterprise, HP LaserJet Managed - Update the printer firmware | HP® Customer Support 5. If the issue persists, replace the hard disk drive (HDD). IMPORTANT: WARNING: Do not replace the printer formatter, it will not resolve this issue. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-133 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Recommended action for customers 351

Table 6-133 HDD part numbers (continued)

Description Part number

Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, download and install the latest printer firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. Use the Format Disk item in the Preboot menu. CAUTION: Selecting Format Disk removes all data. The system is not bootable after this action and 99.09.67 displays on the control panel. A firmware download must be performed to return the system to a bootable state. Should any installed workflow solutions be present they will be deleted and require reloading and setup by the customer. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 4. Use the printer's Preboot menu and USB thumb drive, update the printer firmware: For more information, go to: HP LaserJet Enterprise, HP LaserJet Managed - Update the printer firmware | HP® Customer Support 5. If the issue persists, replace the hard disk drive (HDD). IMPORTANT: WARNING: Do not replace the printer formatter, it will not resolve this issue. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-134 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above For instructions: See the Repair Service Manual for this product. 352 Chapter 6 Numerical control panel messages

98.00.00

An internal firmware error has occurred (corrupt data found in the Partition Manager).

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, Upgrade the firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, download and install the latest printer firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. Use the Format Disk item in the Preboot menu. CAUTION: Selecting Format Disk removes all data. The system is not bootable after this action and 99.09.67 displays on the control panel. A firmware download must be performed to return the

system to a bootable state. Should any installed workflow solutions be present they will be deleted and require reloading and setup by the customer. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 4. Use the printer's Preboot menu and USB thumb drive, update the printer firmware: For more information, go to: HP LaserJet Enterprise, HP LaserJet Managed - Update the printer firmware | HP® Customer Support 5. If the issue persists, replace the hard disk drive (HDD). IMPORTANT: WARNING: Do not replace the printer formatter, it will not resolve this issue. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory.

98.00.00 353

Table 6-135 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, download and install the latest printer firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. Use the Format Disk item in the Preboot menu. CAUTION: Selecting Format Disk removes all data. The system is not bootable after this action and 99.09.67 displays on the control panel. A firmware download must be performed to return the system to a bootable state. Should any installed workflow solutions be present they will be deleted and require reloading and setup by the customer. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 4. Use the printer's Preboot menu and USB thumb drive, update the printer firmware: For more information, go to: HP LaserJet Enterprise, HP LaserJet Managed - Update the printer firmware | HP® Customer Support 5. If the issue persists, replace the hard disk drive (HDD). IMPORTANT: WARNING: Do not replace the printer formatter, it will not resolve this issue. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-136 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above 354 Chapter 6 Numerical control panel messages

For instructions: See the Repair Service Manual for this product.

98.00.01 or 98.01.00 Corrupt data in firmware volume

Data corruption has occurred in the firmware volume.

Recommended action for customers

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, and then on. 2. Download and install the latest firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Use the Format Disk item in the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 3. Reload the firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions

98.00.02 Corrupt data in the solutions volume

Data corruption has occurred in the solutions volume.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, Upgrade the firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware.

3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on.

98.00.01 or 98.01.00 Corrupt data in firmware volume 355

2. If the error persists, download and install the latest printer firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. Use the Format Disk item in the Preboot menu. CAUTION: Selecting Format Disk removes all data. The system is not bootable after this action and 99.09.67 displays on the control panel. A firmware download must be performed to return the system to a bootable state. Should any installed workflow solutions be present they will be deleted and require reloading and setup by the customer. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 4. Use the printer's Preboot menu and USB thumb drive, update the printer firmware: For more information, go to: HP LaserJet Enterprise, HP LaserJet Managed - Update the printer firmware | HP® Customer Support 5. If the issue persists, replace the hard disk drive (HDD). IMPORTANT: WARNING: Do not replace the printer formatter, it will not resolve this issue. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-137 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, download and install the latest printer firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. Use the Format Disk item in the Preboot menu. CAUTION: Selecting Format Disk removes all data. The system is not bootable after this action and 99.09.67 displays on the control panel. A firmware download must be performed to return the 356 Chapter 6 Numerical control panel messages

system to a bootable state. Should any installed workflow solutions be present they will be deleted and require reloading and setup by the customer. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 4. Use the printer's Preboot menu and USB thumb drive, update the printer firmware: For more information, go to: HP LaserJet Enterprise, HP LaserJet Managed - Update the printer firmware | HP® Customer Support 5. If the issue persists, replace the hard disk drive (HDD). IMPORTANT: WARNING: Do not replace the printer formatter, it will not resolve this issue. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-138 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above For instructions: See the Repair Service Manual for this product.

98.00.03 Corrupt data in the configuration volume

Data corruption has occurred in the configuration volume.

Recommended action for customers

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. 1. Turn the printer off, and then on. 2. Download and install the latest firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on.

98.00.03 Corrupt data in the configuration volume 357

2. Download the firmware again, and then attempt the upgrade again. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 3. Use the Format Disk item in the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 4. Reload the firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions

98.00.04 Corrupt data in the job data volume

Data corruption has occurred in the job data volume.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Make sure the printer is running the most current version of firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 3. Rerun the file erase function. 4. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. 99.XX.YY error messages 99.* errors Errors in the 99.* family are related to the firmware upgrade process.

Recommended action for customers

Follow these troubleshooting steps in the order presented. Use the following general troubleshooting steps to try to resolve the problem. 1. Make sure the connection to the network is good, and then try the firmware upgrade again. 2. If the error persists, try using the USB upgrade method. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents and onsite technicians Follow these troubleshooting steps in the order presented. 358 Chapter 6 Numerical control panel messages Use the following general troubleshooting steps to try to resolve the problem. If the error persists, elevate the case using the Standard Support Process. 1. Make sure the connection to the network is good, and then try the upgrade again. 2. Try using the USB upgrade method. 3. If the error persists, run the Format Disk process from the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 4. If the error persists, replace the hard disk drive. NOTE: Do NOT replace the formatter board, it will not resolve the issue.

99.00.01 Upgrade not performed file is corrupt

A remote firmware upgrade (RFU) was not performed. This is a CRC error in the firmware image (bad image).

Recommended action

Follow these troubleshooting steps in the order presented. ■ Download the firmware upgrade file, and then attempt the upgrade again. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware.

99.00.02 Upgrade not performed timeout during receive

A remote firmware upgrade (RFU) was not performed. The issue is an I/O timeout when reading the header number and size. It indicates a problem with the network environment, not the product.

Recommended action

Follow these troubleshooting steps in the order presented. The most common cause is an issue with the network environment. 1. Make sure that there is a good network connection to the product, and then attempt the firmware upgrade again. NOTE: If the upgrade is being performed over the network, check the link light on the ethernet connection on the printer formatter. Make sure that one light is solid and the other is blinking, which signals that data is passing over the ethernet connection. This is an indication of a good physical connection. 2. If the error persists, use the USB upgrade method. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware.

99.00.01 Upgrade not performed file is corrupt 359

99.00.03 Upgrade not performed error writing to disk

A remote firmware upgrade (RFU) was not performed. This is a disk error. It might indicate a problem or a hard disk failure. It might be necessary to check the connection to the hard disk or replace the hard disk.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, Upgrade the firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Download the RFU file, and then attempt the upgrade again. 2. If the error persists, run the Clean Disk process from the Preboot menu. You will need to download the firmware from the Preboot menu. 3. If the error persists, replace the hard disk drive. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information

Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-139 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above For instructions: See the Repair Service Manual for this product..

99.00.04 Upgrade not performed timeout during receive

A remote firmware upgrade (RFU) was not performed. The issue is an I/O timeout when reading the header. 360 Chapter 6 Numerical control panel messages

The most common cause is an issue with the network environment.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Make sure that there is a good network connection to the product, and then attempt the firmware upgrade again. NOTE: If the upgrade is being performed over the network, check the link light on the ethernet connection on the printer formatter. Make sure that one light is solid and the other is blinking, which signals that data is passing over the ethernet connection. This is an indication of a good physical connection. 2. If the error persists, use the USB upgrade method. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware.

99.00.05 Upgrade not performed timeout during receive

A remote firmware upgrade (RFU) was not performed. The issue is an I/O timeout when reading image data. The most common cause is an issue with the network environment.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Make sure that there is a good network connection to the product, and then attempt the firmware upgrade again. NOTE: If the upgrade is being performed over the network, check the link light on the ethernet connection on the printer formatter. Make sure that one light is solid and the other is blinking, which signals that data is passing over the ethernet connection. This is an indication of a good physical connection. 2. If the error persists, use the USB upgrade method. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware.

99.00.06 Upgrade not performed error reading upgrade

A remote firmware upgrade (RFU) was not performed. The issue is an unexpected read error when reading the header number and size.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, Upgrade the firmware. Go to HP FutureSmart - Latest Firmware Versions. Recommended action 361

For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Download the RFU file, and then attempt the upgrade again. 2. If the error persists, replace the hard disk drive. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-140 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above For instructions: See the Repair Service Manual for this product..

99.00.07 Upgrade not performed error reading upgrade

A remote firmware upgrade (RFU) was not performed. The issue is an unexpected read error when reading the rest of the header.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, Upgrade the firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Download the RFU file, and then attempt the upgrade again. 362 Chapter 6 Numerical control panel messages

2. If the error persists, replace the hard disk drive. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-141 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above For instructions: See the Repair Service Manual for this product..

99.00.08 Upgrade not performed error reading upgrade

A remote firmware upgrade (RFU) was not performed. The issue is an unexpected read error when reading image data.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. If the error persists, Upgrade the firmware. Go to HP FutureSmart - Latest Firmware Versions. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Download the RFU file, and then attempt the upgrade again. 2. If the error persists, replace the hard disk drive. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory.

99.00.08 Upgrade not performed error reading upgrade 363

Table 6-142 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above For instructions: See the Repair Service Manual for this product..

99.00.09 Upgrade canceled by user

A remote firmware upgrade (RFU) was not performed. The RFU was canceled.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Resend the remote firmware upgrade (RFU).

99.00.10 Upgrade canceled by user

A remote firmware upgrade (RFU) was not performed. The RFU was canceled when reading the header number and size.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Resend the remote firmware upgrade (RFU).

99.00.11 Upgrade canceled by user

A remote firmware upgrade (RFU) was not performed. The RFU was canceled when reading the rest of the header, after reading the header number and size.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Resend the remote firmware upgrade (RFU).

99.00.12 Upgrade not performed the file is invalid

A remote firmware upgrade (RFU) was not performed. The header number is 1, but the header size does not match version 1 size.

Recommended action

Follow these troubleshooting steps in the order presented. 364 Chapter 6 Numerical control panel messages

1. Download the remote firmware upgrade (RFU) file again. Make sure that you download the file for the correct printer model. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 2. Resend the RFU.

99.00.13 Upgrade not performed the file is invalid

A remote firmware upgrade (RFU) was not performed. The header number is 2, but the header size does not match version 2 size.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Download the remote firmware upgrade (RFU) file again. Make sure that you download the file for the correct printer model. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 2. Resend the RFU.

99.00.14 Upgrade not performed the file is invalid

A remote firmware upgrade (RFU) was not performed. The file is invalid.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Download the remote firmware upgrade (RFU) file again. Make sure that you download the file for the correct printer model. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions 2. Resend the RFU.

99.00.2x

There is a compatibility issue with the firmware. The specific message varies depending on the cause, but the solution for each message is the same. ● 99.00.20 (event log) The bundle is not for this product. ● 99.00.21 (event log) The bundle is not signed with the correct signature, or the signature is invalid. ● 99.00.22 (event log) The bundle header version is not supported by this firmware.

99.00.13 Upgrade not performed the file is invalid 365

● 99.00.23 (event log) The package header version is not supported by this firmware. ● 99.00.24 (event log) The format of the bundle is invalid. ● 99.00.25 (event log) The format of the package is invalid. ● 99.00.26 (event log) A CRC32 check did not pass. ● 99.00.27 (event log) An I/O error occurred while downloading the bundle.

Recommended action

Follow these troubleshooting steps in the order presented. 1. 99.00.27 only: Turn the product off, and then on. 2. Download the correct firmware file, and then resend the firmware upgrade. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. If the error persists, try installing the upgrade by another method (USB or Embedded Web Server). For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware.

99.01.xx

A firmware install error has occurred. The specific message varies depending on the cause, but the solution for each message is the same. ● 99.01.00 ● 99.01.10 ● 99.01.20 ● 99.01.21

Recommended action

Follow these troubleshooting steps in the order presented. ■ Reload the firmware. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions Firmware update steps, For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 366 Chapter 6 Numerical control panel messages

99.02.01

Firmware installation was successful.

Recommended action

See recommended action. ■ No action necessary.

99.02.09

Firmware upgrade cancelled by user.

Recommended action

See recommended action. ■ No action necessary.

99.07.22 Firmware install error

This error indicates that the firmware installation failed. It displays on the printer control panel when the fax modem installer fails to download the installed firmware to the modem.

Recommended action for customers

Use the following general troubleshooting steps to try to resolve the problem. 1. Make sure that the network connection is stable and good, and then attempt to update the firmware again. 2. If the error persists, try to update the firmware at the control panel using a USB flash drive. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Use the following general troubleshooting steps to try to resolve the problem. 1. Make sure that the network connection is stable and good, and then attempt to update the firmware again. 2. If the error persists, try to update the firmware at the control panel using a USB flash drive. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. Use the Format Disk item in the Preboot menu. CAUTION: Selecting Format Disk removes all data. The system is not bootable after this action and 99.09.67 displays on the control panel. A firmware download must be performed to return the system to a bootable state. Should any installed workflow solutions be present they will be deleted and require reloading and setup by the customer.

99.02.01 367

For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 4. If the issue persists, identify which storage solution is utilized, a hard disk drive (HDD) or embedded multi-media card (eMMC). a. Print or view the device configuration page. b. Reference section Installed Personalities and Options. c. Reference Internal Disk: Hard Disk: Enabled d. Reference Hard Disk Encryption Status, "Disk cannot be encrypted" denotes an eMMC storage device. 5. Depending on the storage solution installed, replace either the hard disk drive (HDD) or embedded multi-media card (eMMC). IMPORTANT: WARNING: Do not replace the printer formatter, it will not resolve this issue. NOTE: Device is unusable until a new boot device is installed. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-143 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above Module 16GB embedded Multimedia Card (eMMC) kit 5851-6587

Recommended action for onsite technicians

Use the following general troubleshooting steps to try to resolve the problem. 1. Make sure that the network connection is stable and good, and then attempt to update the firmware again. 2. If the error persists, try to update the firmware at the control panel using a USB flash drive. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. Use the Format Disk item in the Preboot menu. CAUTION: Selecting Format Disk removes all data. The system is not bootable after this action and 99.09.67 displays on the control panel. A firmware download must be performed to return the system to a bootable state. Should any installed workflow solutions be present they will be deleted and require reloading and setup by the customer. 368 Chapter 6 Numerical control panel messages

For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 4. If the issue persists, identify which storage solution is utilized, a hard disk drive (HDD) or embedded multi-media card (eMMC). a. Print or view the device configuration page. b. Reference section Installed Personalities and Options. c. Reference Internal Disk: Hard Disk: Enabled d. Reference Hard Disk Encryption Status, "Disk cannot be encrypted" denotes an eMMC storage device. 5. Depending on the storage solution installed, replace either the hard disk drive (HDD) or embedded multi-media card (eMMC). IMPORTANT: WARNING: Do not replace the printer formatter, it will not resolve this issue. NOTE: Device is unusable until a new boot device is installed. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-144 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above Module 16GB embedded Multimedia Card (eMMC) kit 5851-6587 6. If the issue persists, elevate using your region's support process.

99.09.60 Unsupported disk

The hard disk currently installed is not recognized or supported by the product. This is a Preboot menu error.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Install the correct hard disk drive for this printer.

99.09.61 Unsupported disk

The hard disk drive installed is not support in this printer. The hard disk drive (HDD) is not encrypted and the printer is configured for an encrypted HDD.

99.09.60 Unsupported disk 369

Recommended action

Follow these troubleshooting steps in the order presented. NOTE: Do NOT replace the formatter board, it will not resolve this error. ■ Access the Preboot menu, and then select Lock Disk to lock the disk. a. Access the Preboot menu b. Turn the product on. c. Touch the HP logo that displays in the center of the touchscreen until the Preboot menu item opens. d. Use the arrow buttons on the touchscreen to navigate the Preboot menu. e. Touch the OK button to select a menu item.

99.09.62 Unknown disk

This error indicates that there is an encryption mismatch between the HDD and the formatter. This typically happens because an HDD was swapped into a device from another device.

Recommended action for customers

Follow these troubleshooting steps in the order presented. NOTE: You will need a USB drive containing the printer firmware to complete this process. Get the latest printer firmware from support.hp.com Use the Preboot menu to unlock the disk. 1. Access the Preboot menu. a. Turn the product on. b. Touch the HP logo that displays in the center of the touchscreen until the Preboot menu item opens. Figure 6-89 The Preboot menu 2. Erase/unlock the disk. a. While still in the Preboot menu, use the arrow buttons on the touchscreen to scroll down to Administrator menu. 370 Chapter 6 Numerical control panel messages

b. Touch the OK button to select Administrator. c. Use the arrow buttons on the touchscreen to scroll down to Manage Disks menu. d. Touch the OK button to select Manage Disks. e. Use the arrow buttons on the touchscreen to scroll down to Boot Device menu. f. Touch the OK button to select Boot Device. g. Use the arrow buttons on the touchscreen to scroll down to Erase / Unlock menu. h. Touch the OK button to select Erase / Unlock. This will completely erase the disk removing the firmware (printer operating system). You will need to reinstall the printer firmware after performing the Erase/Unlock procedure. 3. Reinstall printer firmware using a USB thumb drive. View this video for more information: How to Load Firmware on HP PageWide and LaserJet Enterprise Printers When a 99.09.63 or 99.09.67 Error Displays. a. Use the Back button on the control panel to navigate back to Administrator in the Preboot menu. b. Use the OK button to select Administrator. c. Use the OK button to select Download. Figure 6-90 Navigate to Download d. Insert the USB drive containing the printer firmware into the front/side USB port on the device. Recommended action for customers 371

e. Use the down arrow to navigate to USB Thumbdrive. Figure 6-91 Navigate to USB Thumbdrive f. Use the OK button to select USB Thumbdrive. g. Use the arrow buttons and the OK button to navigate to and select the BDL file stored on the USB drive. Figure 6-92 Navigate to the BDL file h. After selecting OK, the printer will begin copying the BDL firmware file to the device. This can take up to 10 minutes. Figure 6-93 Copying the BDL file 372 Chapter 6 Numerical control panel messages

i. When the firmware copy is complete, turn the printer off and then on again. The printer will continue with the firmware installation. 4. If the previous steps did not resolve the issue, replace the hard disk drive. Part Number: 5851-6712

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. NOTE: Do NOT replace the formatter board, it will not resolve this error. Use the Preboot menu to unlock the disk. 1. Access the Preboot menu. a. Turn the product on. b. Touch the HP logo that displays in the center of the touchscreen until the Preboot menu item opens. Figure 6-94 The Preboot menu 2. Erase/unlock the disk. a. While still in the Preboot menu, use the arrow buttons on the touchscreen to scroll down to Administrator menu. b. Touch the OK button to select Administrator. c. Use the arrow buttons on the touchscreen to scroll down to Manage Disks menu. d. Touch the OK button to select Manage Disks. e. Use the arrow buttons on the touchscreen to scroll down to Boot Device menu. f. Touch the OK button to select Boot Device. g. Use the arrow buttons on the touchscreen to scroll down to Erase / Unlock menu. h. Touch the OK button to select Erase / Unlock. This will completely erase the disk removing the firmware (printer operating system). You will need to reinstall the printer firmware after performing the Erase/Unlock procedure. Recommended action for call-center agents 373

3. Reinstall printer firmware using a USB thumb drive. View this video for more information: How to Load Firmware on HP PageWide and LaserJet Enterprise Printers When a 99.09.63 or 99.09.67 Error Displays. a. Use the Back button on the control panel to navigate back to

Administrator in the Preboot menu. b. Use the OK button to select Administrator. c. Use the OK button to select Download. Figure 6-95 Navigate to Download d. Insert the USB drive containing the printer firmware into the front/side USB port on the device. e. Use the down arrow to navigate to USB Thumbdrive. Figure 6-96 Navigate to USB Thumbdrive f. Use the OK button to select USB Thumbdrive. 374 Chapter 6 Numerical control panel messages

g. Use the arrow buttons and the OK button to navigate to and select the BDL file stored on the USB drive. Figure 6-97 Navigate to the BDL file h. After selecting OK, the printer will begin copying the BDL firmware file to the device. This can take up to 10 minutes. Figure 6-98 Copying the BDL file i. When the firmware copy is complete, turn the printer off and then on again. The printer will continue with the firmware installation. 4. If the previous steps did not resolve the issue, replace the hard disk drive. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-145 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above Recommended action for call-center agents 375

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. NOTE: Do NOT replace the formatter board, it will not resolve this error. 1. Access the Preboot menu to unlock the disk. 2. Select Administrator menu. 3. Select Manage Disks menu. 4. Select Boot Device menu. 5. Select Erase / Unlock. This will completely erase the disk removing the firmware (printer operating system). You will need to reinstall the printer firmware after performing the Erase/Unlock procedure. 6. Reinstall printer firmware using a USB thumb drive. View this video for more information: How to Load Firmware on HP PageWide and LaserJet Enterprise Printers When a 99.09.63 or 99.09.67 Error Displays. a. While still in the Preboot menu, use the Back button on the control panel to navigate back to Administrator. b. Use the OK button to select Administrator. c. Use the OK button to select Download. d. Insert the USB drive containing the printer firmware into the front/side USB port on the device. e. Use the down arrow to navigate to USB Thumbdrive. f. Use the OK button to select USB Thumbdrive. g. Use the arrow buttons and the OK button to navigate to and select the BDL file stored on the USB drive. h. After selecting OK, the printer will begin copying the BDL firmware file to the device. This can take up to 10 minutes. i. When the firmware copy is complete, turn the printer off and then on again. The printer will continue with the firmware installation. 7. If the previous steps did not resolve the issue, replace the hard disk drive. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-146 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above 376 Chapter 6 Numerical control panel messages

99.09.63 Incorrect disk

This error indicates that the expected encrypted HDD is not present. This is expected behavior when installing a new HDD in a device where the previous HDD was encrypted.

Recommended action for Customers

Use the following general troubleshooting steps to try to resolve the problem. 1. If installing a new hard disk drive (HDD), follow the instructions which came with the replacement drive or reference the following support document, Removal and replacement: Hard-disk drive

(HDD).

2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for onsite technicians

Use the following general troubleshooting steps to try to resolve the problem. 1. If installing a new hard disk drive (HDD), follow the instructions which came with the replacement drive or reference the following support document, Removal and replacement: Hard-disk drive

(HDD).

2. If the error persists, try to update the firmware at the control panel using a USB flash drive. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. Turn the printer off and then on to access the printer's Preboot menu to erase / unlock the new HDD, reference support document, HP LaserJet Managed MFP – Preboot menu options. a. From the Preboot menu, select Administrator. b. Select Manage Disk. c. Select Boot Device. d. Select Erase / Unlock. e. Select OK. f. Turn the printer off, and then on. Printer will display a 99.09.67 error message. 4. Insert the USB thumb drive with the previously extracted firmware file into the walkup USB port. 5. Use the printer's Preboot menu to update the printer firmware For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. IMPORTANT: For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware.

Recommended action for onsite technicians

Use the following general troubleshooting steps to try to resolve the problem.

99.09.63 Incorrect disk 377

1. If installing a new hard disk drive (HDD), follow the instructions which came with the replacement drive or reference the following support document, Removal and replacement: Hard-disk drive

(HDD).

2. If the error persists, try to update the firmware at the control panel using a USB flash drive. For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 3. Turn the printer off and then on to access the printer's Preboot menu to erase / unlock the new HDD, reference support document, HP LaserJet Managed MFP – Preboot menu options. a. From the Preboot menu, select Administrator. b. Select Manage Disk. c. Select Boot Device. d. Select Erase / Unlock. e. Select OK. f. Turn the printer off, and then on. Printer will display a 99.09.67 error message. 4. Insert the USB thumb drive with the previously extracted firmware file into the walkup USB port. 5. Use the printer's Preboot menu to update the printer firmware For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. IMPORTANT: For the more information, go to: HP Enterprise, HP Managed - Update the printer firmware. 6. If the issue persists, elevate the case using your regions process.

99.09.64 Disk malfunction

A fatal hard disk failure has occurred.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Determine if the hard disk drive needs to be replaced. 2. Ask if the customer is using eMMC as a temporary mass storage solution (eMMC must be present). 3. Instruct the customer to enable eMMC from the preboot menus. 4. Turn the printer off. 5. Inform the customer that the broken hard disk drive must be removed to continue. 6. Turn the printer on. The boot sequence is expected to stop at 99.39.67 eMMC Not Bootable. 7. Provide instructions to download firmware (This will automatically download to eMMC). 8. During the download to eMMC, the firmware will clear the data migration bit. 378 Chapter 6 Numerical control panel messages

9. Ship a new hard disk drive. Do NOT replace the formatter board, it will not resolve this.

99.09.65 Disk data error

Disk data corruption has occurred.

Recommended action

Follow these troubleshooting steps in the order presented. NOTE: Do NOT replace the formatter board, it will not resolve this error. ■ Use the Format Disk procedure from the Preboot menu, and then resend the remote firmware upgrade (RFU). For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - .

99.09.66 No boot device.

A hard disk drive is not installed in the printer.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Determine the customer's intended boot device (hard disk drive or eMMC). 2. Install a compatible hard disk drive or eMMC. 3. If a compatible hard disk drive or eMMC is installed, reseal the hard disk drive or eMMC to make sure that it is connected correctly. Additionally reseal all cables on the formatter, except the Flat Flexible cable (FFC). 4. If the error persists, replace the hard disk drive or eMMC. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 6-147 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above

99.09.65 Disk data error 379

For instructions: See the Repair Service Manual for this product.. NOTE: Do NOT replace the formatter board, it will not resolve this. NOTE: Device is unusable until a new boot device is installed.

99.09.67 Disk is not bootable please download firmware

This is an error indicating that there is no firmware installed on the disk. This is usually the result of installing a new disk or performing a Clean Disk operation from the Preboot menu. NOTE: When installing a new hard drive or eMMC, the disk should be formatted through the Preboot menu, BEFORE loading firmware.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Press any button to continue to the main Preboot menu. 2. Press the Help button to see the help text for the error. 3. Select the Administration menu. NOTE: If there is a password assigned to the Administrator, a prompt to enter the printer displays. Enter the password to proceed. 4. Select the Format disk option, select OK. 5. Select the Download item, and then download the latest firmware. The user can now download a new firmware bundle to the printer. 6. If the download fails to the hard disk drive, complete the following: a. Determine if the hard disk drive needs to be replaced. b. Ask if the customer is using eMMC as a temporary mass storage solution (eMMC must be present). c. Instruct the customer to enable eMMC from the preboot menus. d. Turn the printer off. e. Inform the customer that the broken hard disk drive must be removed to continue. f. Turn the printer on. The boot sequence is expected to stop at 99.39.67 eMMC Not Bootable. g. Provide instructions to download firmware (This will automatically download to eMMC). h. During the download to eMMC, the firmware will clear the data migration bit. i. Ship a new hard disk drive. Do NOT replace the formatter board, it will not resolve this. 380 Chapter 6 Numerical control panel messages

99.39.64 eMMC Nonfunctional

The eMMC is not functioning.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Replace the eMMC. Table 6-148 Part numbers

Description Part number

Kit-eMMC Replacement 16gb (M527) 5851-6587 Module 16B embedded MultiMedia Card (eMMC) kit 5851-6436 NOTE: The device is unusable until a new eMMC is installed.

99.39.67 eMMC Not Bootable

Data on the eMMC cannot be secured or encrypted. When the hard disk drive is installed all data on the eMMC is automatically migrated to the hard disk drive and erased from the eMMC. As long as the hard disk drive is installed the eMMC is non-functional. The customer passed the data migration and put the eMMC back in.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Download firmware to the eMMC. 2. If the download fails to eMMC, Replace the eMMC. Table 6-149 Part numbers

Description Part number

Kit-eMMC Replacement 16gb (M527) 5851-6587 Module 16B embedded MultiMedia Card (eMMC) kit 5851-6436 NOTE: The device is unusable until a new eMMC is installed.

99.XX.YY

A message of this form indicates a firmware installation error.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Reload the firmware.

99.39.64 eMMC Nonfunctional 381

7 Alphabetical control panel messages

Use the following alphabetical message to see further information on the message.

Alphabetical messages

Accept bad signature

The product is performing a remote firmware upgrade and the code signature is invalid.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Download the correct firmware upgrade file for the product, and then reinstall the upgrade. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions

Bad optional tray connection

The optional tray is not connected, not connected correctly, or a connection is not working correctly.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off. 2. Remove and then reinstall the optional tray. 3. Reconnect the connectors for the tray. 4. If the problem continues, replace the connector for the tray. <binname> full Remove all paper from bin The specified output bin is full.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Empty the bin to continue printing.

Canceling

The printer is canceling the current job.

Recommended action

See recommended action. ■ No action necessary. 382 Chapter 7 Alphabetical control panel messages

Canceling...<jobname> The printer is canceling the current job <jobname>.

Recommended action

See recommended action. ■ No action necessary.

Cartridge Low

This message appears even though the toner cartridge is new.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Remove, and then reinstall the toner cartridge. 2. Make sure a genuine HP supply is used. 3. If the error persists, replace the toner cartridge.

Cartridge memory abnormal

This message appears even though the toner cartridge is new.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Remove, and then reinstall the toner cartridge. 2. Make sure a genuine HP supply is being used. 3. Reconnect connector (J376) on the high voltage power supply PCA. 4. If the error persists, replace the toner cartridge.

Cartridge out

This message appears even though the toner cartridge is new.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Remove, and then reinstall the toner cartridge. 2. Make sure a genuine HP supply is being used. 3. If the error persists, replace the toner cartridge.

Checking engine

The printer is conducting an internal test. Canceling...<jobname> 383

Recommended action

See recommended action. ■ No action necessary.

Checking paper path

The printer is checking for possible paper jams.

Recommended action

See recommended action. ■ No action necessary. Chosen personality not available To continue touch "OK" A print job requested a printer language (personality) that is not available for this printer. The job will not print and will be cleared from memory.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Print the job by using a print driver for a different printer language, or add the requested language to the printer (if possible). To see a list of available personalities, print a configuration page. a. From the Home screen on the printer control panel, go to the following menus: Reports > Configuration/Status Pages b. Select Configuration Page, then select the Print button to print the pages. Cleaning The printer is performing an automatic cleaning cycle. Printing will continue after the cleaning is complete.

Recommended action

See recommended action. ■ No action necessary.

Cleaning do not grab paper

The printer is performing an automatic cleaning cycle. Printing will continue after the cleaning is complete.

Recommended action

See recommended action. ■ No action necessary.

Clearing event log

This message is displayed while the event log is cleared. The printer exits the menus when the event log has been cleared. 384 Chapter 7 Alphabetical control panel messages

Recommended action

See recommended action. ■ No action necessary.

Clearing paper path

The printer is attempting to eject jammed paper.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Check the progress at the bottom of the display.

Close top cover

This message appears even though the top cover is closed.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Verify that the switch (SW2) is functioning correctly (open and close the top cover). If the switch fails the test, replace the switch. 2. Make sure that the switch flag at the right-side of the top cover assembly, behind the control-panel display is not damaged or missing. If the flag is damaged or missing, replace the top cover assembly. Table 7-1 Part numbers

Description Part number

Top cover assembly (duplex MF models only) RM2-5686-000CN Top cover assembly (simplex models only) RM2-5687-010CN 3. If the problem persists, replace the top cover switch.

Cooling device

The printer is cooling.

Recommended action

See recommended action. ■ No action necessary. Creating cleaning page... A cleaning page is being generated.

Recommended action

See recommended action. ■ No action necessary. Recommended action 385

Data received To print last page press "OK" The printer is waiting for the command to print the last page.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the "OK" button on the control panel to print the last page of the job.

Event log is empty

No printer events are in the log.

Recommended action

See recommended action. ■ No action necessary.

Expected drive missing

The printer cannot find the encrypted hard drive.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Install the encrypted hard disk drive.

External device initializing

An external device is initializing.

Recommended action

See recommended action. ■ No action necessary.

Face Down Tray Full

This message is displaying even though the tray is not full.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 386 Chapter 7 Alphabetical control panel messages

1. Make sure that the output bin sensor flag is not damaged and can move freely. Try to manually lift the output bin actuator up and see if the actuator goes down (or is lowered). Figure 7-1 Lift up the output bin full actuator 2. If the output bin sensor flag is damaged, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents (Remote support) Follow these troubleshooting steps in the order presented. Use the following procedure to access the Manual Sensor Test from the printer control panel to verify the output bin sensor flag is functioning correctly. 1. From the Home screen on the printer control panel, scroll to and touch the Administration (FutureSmart 3), or Support Tools (FutureSmart 4). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. 2. Open the following menus: Troubleshooting > Diagnostic Tests > Manual Sensor Test. Recommended action for call-center agents (Remote support) 387

3. Select the SR4 Output Bin Full Sensor. Figure 7-2 SR4 Output Bin Full Sensor 4. Lift the output bin full actuator up and verify the toggle counter under the sensor name is incremented from "0" to "1" on the control panel. ● If the toggle counter under the sensor name toggles from "0" to "1", the output sensor flag is functioning correctly and the diagnostic test is successful. ● If the toggle counter under the sensor name does not toggle, the output sensor flag is not functioning correctly and the diagnostic test fails. 388 Chapter 7 Alphabetical control panel messages

Figure 7-3 Lift up the output bin full actuator 5. If the diagnostic test fails and the sensor does not toggle, the printer needs to be replaced. 6. If the diagnostic test is successful and the issue persists, send a service technician to diagnose the issue.

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Make sure that the output bin sensor flag is not damaged and can move freely. 2. Access the Manual Sensor Test from the printer control panel to verify the output bin sensor flag is functioning correctly. a. From the Home screen on the printer control panel, scroll to and touch the Administration (FutureSmart 3), or Support Tools (FutureSmart 4). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following menus: Troubleshooting > Diagnostic Tests > Manual Sensor Test. Recommended action for onsite technicians 389

c. Select the SR4 Output Bin Full Sensor. Figure 7-4 SR4 Output Bin Full Sensor d. Lift the output bin full actuator up and verify the toggle counter under the sensor name is incremented from "0" to "1" on the control panel. ● If the toggle counter under the sensor name toggles

from "0" to "1", the output sensor flag is functioning correctly and the diagnostic test is successful. ● If the toggle counter under the sensor name does not toggle, the output sensor flag is not functioning correctly and the diagnostic test fails. 390 Chapter 7 Alphabetical control panel messages

Figure 7-5 Lift up the output bin full actuator 3. If the diagnostic test fails and the sensor does not toggle, the printer needs to be replaced. 4. If the diagnostic test is successful and the issue persists, check if the fuser output sensor flag is functioning correctly. a. From the Home screen on the printer control panel, scroll to and touch the Administration (FutureSmart 3), or Support Tools (FutureSmart 4). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following menus: Troubleshooting > Diagnostic Tests > Manual Sensor Test. c. Select the SR13 Fuser Output Sensor. Figure 7-6 SR13 Fuser Output Sensor Recommended action for onsite technicians 391

d. Manually toggle the sensor and verify that the toggle counter under the sensor name increments accordingly. 5. If the sensor does not toggle and the sensor flag fails to function correctly, replace the fuser assembly. Table 7-2 Fuser assembly (For 110V and 220V) part numbers

Part description Part number

Fuser assembly - For 110 VAC Bonds toner to the paper with heat.

RM2-2585-000CN

Fuser assembly - For 220 VAC Bonds toner to the paper with heat.

RM2-2586-000CN

For instructions: See the Repair Service Manual for this product. 6. If the error persists, replace the DC controller. Table 7-3 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

392 Chapter 7 Alphabetical control panel messages

Table 7-3 DC Controller part numbers (continued)

Printer models Part description Part number

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

For instructions: See the Repair Service Manual for this product. 7. If issue persists, elevate the issue using the Standard Support Process for a possible printer replacement. FIM Load Error Send full FIM on <X> port The printer displays this message before the firmware is loaded at startup if an error has occurred during a firmware upgrade.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Re-send the firmware upgrade.

Fuser Kit low

The printer indicates when a supply is low.

10.23.60 (event code)

Recommended action

Follow these troubleshooting steps in the order presented. ■ Replace the fuser. For instructions: See the Repair Service Manual for this product. Fuser assembly 110V-127V: RM2-5679-000CN Fuser assembly 220-240V: RM2-5692-000CN Fuser Kit very low To continue, touch "OK" The printer indicates when a supply is very low.

10.23.70 (event code)

Recommended action

Follow these troubleshooting steps in the order presented. FIM Load Error Send full FIM on <X> port 393

■ If print quality is no longer acceptable, the customer must order and pay for a replacement fuser assembly (fuser kit). For instructions: See the Repair Service Manual for this product. Fuser assembly 110V-127V: RM2-5679-000CN Fuser assembly 220-240V: RM2-5692-000CN

Genuine HP cartridge installed

A new genuine HP toner cartridge has been installed. The message appears for about 6 seconds before the printer returns to the READY state.

Recommended action

See recommended action. ■ No action necessary.

Genuine HP supply installed

A new genuine HP supply has been installed.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the Hide button to remove this message.

HP Secure hard drive disabled

The hard disk drive has been encrypted for another printer.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Remove the hard disk drive or use the Embedded Web Server for more information. Incompatible <supply> The indicated supply <supply> is not compatible with this printer. ● 10.00.35 (event code)

Black toner cartridge

- Fuser kit

10.23.35 (event code)

Recommended action

Follow these troubleshooting steps in the order presented. ■ Replace the supply with one that is designed for this printer. 394 Chapter 7 Alphabetical control panel messages

Incompatible supplies

The toner cartridge or other supply items are installed that were not designed for this printer. The printer cannot print with these supplies installed. Event codes are supply specific.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Touch the OK button to identify the incompatible supplies. 2. Replace the supplies with those that are designed for this printer. Initializing... The printer is starting.

Recommended action

See recommended action. ■ No action necessary.

Install Black Cartridge

A supply item is either not installed or installed incorrectly. ● Black cartridge

10.00.15 (event code)

Recommended action

Follow these troubleshooting steps in the order presented. ■ Install the supply item or make sure that the installed supply item is correctly installed and fully seated.

Install Fuser

The fuser has been removed or installed incorrectly.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then wait for the fuser to cool. 2. Remove the output bin or stapler/stacker. 3. Remove the fuser entrance guide. 4. Remove the fuser. CAUTION: Be careful: the fuser is HOT. Allow it cool if you need to before removing to check the assembly. Incompatible supplies 395

5. Reinstall the fuser correctly. 6. If issue persists, replace the fuser. For instructions: See the Repair Service Manual for this product. Fuser assembly 110V-127V: RM2-5679-000CN Fuser assembly 220-240V: RM2-5692-000CN

Install supplies

More than one supply is missing or is installed incorrectly.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Touch the OK button to identify the supplies that need to be replaced. 2. Touch the OK button a second time for more information about the specific supply. 3. Install the supply or make sure it is correctly installed and fully seated. Internal disk device failure To clear touch "OK" The internal disk failed. 82.0X.YY (event code)

Recommended action

Follow these troubleshooting steps in the order presented. 1. Touch the OK button to clear the error. 2. If the error persists, turn off the product, and then remove and reinstall the hard drive. 3. Turn on the product. 4. If the error persists, replace the internal hard drive.

Internal disk file operation failed

A P.J.L system command attempted to perform an illogical operation, such as downloading a file to a nonexistent directory.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error.

Internal disk file system is full

A PJL system command attempted to write data to the internal hard disk drive but was unsuccessful because the hard disk drive is full. 396
Chapter 7 Alphabetical control panel messages

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error.

Internal disk is write protected

The internal hard disk drive is write protected and no new files can be written to it.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error.

Internal disk not found

The internal hard disk drive was not found at start up.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Turn the printer off, and then on.

Internal disk not functional

The internal hard disk drive is not functioning correctly. 82.0X.YY (event code)

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, remove and then reinstall the hard disk drive. 2. If the error persists, replace the internal hard disk drive. NOTE: Most customers have the Self-Encrypting Drive, SED, and should not have a Federal Information Processing Standards, FIPS Drive. Only send the FIPS drive for federal government printers, customers that require FIPS per HP agreement, or customers that have bought the FIPS drive as an accessory. Table 7-4 HDD part numbers

Description Part number

Self-Encrypting Drive, SED (HDD) L41606-011 Federal Information Processing Standards Drive, FIPS (HDD) *See NOTE above

L42243-021

*See NOTE above For instructions: See the Repair Service Manual for this product.. Recommended action 397

Internal disk not initialized

The internal hard disk drive file system must be initialized before it can be used.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Initialize the internal hard disk drive file system. For information on performing various actions on the hard disk drive, go to: HP LaserJet, OfficeJet, PageWide, ScanJet - HP FutureSmart Firmware Device Hard Disk, SSD, and eMMC Security (white paper)

Internal disk spinning up

The internal hard disk drive device is spinning up its platter. Jobs that require hard disk drive access must wait.

Recommended action

See recommended action. ■ No action necessary.

Job not stapled due to mixed sizes

This message is displayed when the job to be stapled has more than one paper size (paper width).

Recommended action

Follow these troubleshooting steps in the order presented. ■ Paper with different widths cannot be stapled. Use the same width paper for the entire print job. Load Tray <X>: [Type], [Size] Load paper in Tray X as specified.

Recommended action for customers

Follow these troubleshooting steps in the order presented. ■ Load paper in specified tray. If this message appears even though there is paper loaded in the tray, perform the following. Follow these troubleshooting steps in the order presented. 1. Use the sensor tests to verify that the tray sensors are functioning correctly. 2. Make sure that the sensor flag on the paper presence sensor is not damaged and moves freely. 3. Reconnect the corresponding connector for the paper tray having the issue. 398 Chapter 7 Alphabetical control panel messages

Load Tray <X>: [Type], [Size] To use another tray, press "OK" This message appears when the indicated tray is selected but is not loaded, and other paper trays are available for use. It also appears when the tray is configured for a different paper type or size than the print job requires.

Recommended action

Use the following steps to resolve the error. 1. Load the correct paper in the tray. 2. If prompted, confirm the size and type of the paper loaded. 3. Otherwise, press the OK button to select another tray. Loading program <XX> Do not power off Programs and fonts can be stored on the printer's file system and are loaded into RAM when the printer is turned on. The number <XX> specifies a sequence number indicating the current program being loaded.

Recommended action

See recommended action. ■ No action necessary. Manually feed: <Type><Size> This message appears when manual feed is selected, Tray 1 is not loaded, and other trays are empty.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Load the tray with requested paper. 2. If the paper is already in the tray, press the Help button to exit the message and then press the OK button to print. 3. To use another tray, clear paper from Tray 1, press the Help button to exit the message and then press the OK button. Manually feed: <Type><Size> To use another tray, press "OK" This message appears when manual feed is selected, Tray 1 is loaded, and other trays are available.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Load the tray with requested paper. 2. If the paper is already in the tray, press the Help button to exit the message and then press the OK button to print. 3. To use another tray, clear paper from Tray 1, press the Help button to exit the message and then press the OK button. Load Tray <X>: [Type], [Size] To use another tray, press "OK" 399

Manually feed output stack Then touch "OK" to print second side The printer has printed the first side of a manual duplex job and is waiting for you (or the applicable user) to insert the output stack to print the second side.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Maintaining the same orientation, remove the pages from the output bin. 2. Flip the document printed side up. 3. Load the document in Tray 1. 4. Touch the OK button to print the second side of the job.

Moving solenoid

The solenoid is moving as part of a component test.

Recommended action

Follow these troubleshooting steps in the order presented. ■ To exit press X.

Moving solenoid and motor

The solenoid and a motor are moving as part of a component test.

Recommended action

Follow these troubleshooting steps in the order presented. ■ To exit press X.

No job to cancel

You have pressed the stop button but the printer is not actively processing any jobs.

Recommended action

See recommended action. ■ No action necessary.

NON HP Supply Installed

This message is displayed for about 6 seconds when a new non-HP supply is installed.

10.99.31 (event code)

Recommended action

Follow these troubleshooting steps in the order presented. 1. Use a genuine HP supply for the printer. 2. If you believe a genuine HP supply is being used, go to www.hp.com/go/anticoncounterfeit. 400 Chapter 7 Alphabetical control panel messages

Output Bin Full

This message appears even though the output bin is not full.

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Make sure that the output bin sensor flag is not damaged and can move freely. Try to manually lift the output bin actuator up and see if the actuator goes down (or is lowered). Figure 7-7 Lift up the output bin full actuator 2. If the output bin sensor flag is damaged, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. Recommended action for call-center agents (Remote support) Follow these troubleshooting steps in the order presented. Use the following procedure to access the Manual Sensor Test from the printer control panel to verify the output bin sensor flag is functioning correctly. 1. From the Home screen on the printer control panel, scroll to and touch the Administration (FutureSmart 3), or Support Tools (FutureSmart 4). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. 2. Open the following menus: Troubleshooting > Diagnostic Tests > Manual Sensor Test. Output Bin Full 401

3. Select the SR4 Output Bin Full Sensor. Figure 7-8 SR4 Output Bin Full Sensor 4. Lift the output bin full actuator up and verify the toggle counter under the sensor name is incremented from "0" to "1" on the control panel. ● If the toggle counter under the sensor name toggles from "0" to "1", the output sensor flag is functioning correctly and the diagnostic test is successful. ● If the toggle counter under the sensor name does not toggle, the output sensor flag is not functioning correctly and the diagnostic test fails. 402 Chapter 7 Alphabetical control panel messages

Figure 7-9 Lift up the output bin full actuator 5. If the diagnostic test fails and the sensor does not toggle, the printer needs to be replaced. 6. If the diagnostic test is successful and the issue persists, send a service technician to diagnose the issue.

Recommended action for onsite technicians

Follow these troubleshooting steps in the order presented. 1. Make sure that the output bin sensor flag is not damaged and can move freely. 2. Access the Manual Sensor Test from the printer control panel to verify the output bin sensor flag is functioning correctly. a. From the Home screen on the printer control panel, scroll to and touch the Administration (FutureSmart 3), or Support Tools (FutureSmart 4). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following menus: Troubleshooting > Diagnostic Tests > Manual Sensor Test. Recommended action for onsite technicians 403

c. Select the SR4 Output Bin Full Sensor. Figure 7-10 SR4 Output Bin Full Sensor d. Lift the output bin full actuator up and verify the toggle counter under the sensor name is incremented from "0" to "1" on the control panel. ● If the toggle counter under the sensor name toggles from "0" to "1", the output sensor flag is functioning correctly and the diagnostic test is successful. ● If the toggle counter under the sensor name does not toggle, the output sensor flag is not functioning correctly and the diagnostic test fails. 404 Chapter 7 Alphabetical control panel messages

Figure 7-11 Lift up the output bin full actuator 3. If the diagnostic test fails and the sensor does not toggle, the printer needs to be replaced. 4. If the diagnostic test is successful and the issue persists, check if the fuser output sensor flag is functioning correctly. a. From the Home screen on the printer control panel, scroll to and touch the Administration (FutureSmart 3), or Support Tools (FutureSmart 4). NOTE: The control panel menu options might vary depending on the printer model and firmware version installed. b. Open the following menus: Troubleshooting > Diagnostic Tests > Manual Sensor Test. c. Select the SR13 Fuser Output Sensor. Figure 7-12 SR13 Fuser Output Sensor Recommended action for onsite technicians 405

d. Manually toggle the sensor and verify that the toggle counter under the sensor name increments accordingly. 5. If the sensor does not toggle and the sensor flag fails to function correctly, replace the fuser assembly. Table 7-5 Fuser assembly (For 110V and 220V) part numbers

Part description Part number

Fuser assembly - For 110 VAC Bonds toner to the paper with heat.

RM2-2585-000CN

Fuser assembly - For 220 VAC Bonds toner to the paper with heat.

RM2-2586-000CN

For instructions: See the Repair Service Manual for this product. 6. If the error persists, replace the DC controller. Table 7-6 DC Controller part numbers

Printer models Part description Part number

M501dn/ M501n DC controller PCA RM2-8711-030CN M506 M527

E52545

For duplex models - DC controller PC board

assembly (PCA)

RM2-8612-000CN

406 Chapter 7 Alphabetical control panel messages

Table 7-6 DC Controller part numbers (continued)

Printer models Part description Part number

M506

E50045

For simplex models - DC controller PC board

(PCA)

RM2-8614-000CN

M507 M528

E52645

For duplex models - DC controller PC board

assembly (PCA)

RM3-7475-010CN

M507

E50145

For simplex models - DC controller PC board

assembly (PCA)

RM3-7476-000CN

For instructions: See the Repair Service Manual for this product. 7. If issue persists, elevate the issue using the Standard Support Process for a possible printer replacement. Paused... The printer is paused, and there are no error messages pending at the display. The I/O continues receiving data until the memory is full.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Press the Stop button.

Performing Paper Path Test

A paper path test is being performed.

Recommended action

See recommended action. ■ No action necessary. Please Wait... The printer is in the process of clearing data.

Recommended action

See recommended action. ■ No action necessary. Printing Cleaning Page... The printer is printing the cleaning page. Paused... 407

Recommended action

See recommended action. ■ No action necessary. Printing Configuration... The printer is printing the Configuration page.

Recommended action

See recommended action. ■ No action necessary. Printing engine test... The printer is printing an engine test page.

Recommended action

See recommended action. ■ No action necessary. Printing Event Log... The printer is printing the Event Log page.

Recommended action

See recommended action. ■ No action necessary. Printing File Directory... The printer is printing the File Directory pages.

Recommended action

See recommended action. ■ No action necessary. Printing Font List... The printer is printing the Font List pages.

Recommended action

See recommended action. ■ No action necessary. Printing Help Page... The printer is printing the Help page. 408 Chapter 7 Alphabetical control panel messages

Recommended action

See recommended action. ■ No action necessary. Printing Menu Map... The printer is printing the Menu Map pages.

Recommended action

See recommended action. ■ No action necessary.

Printing Registration Page

The printer is printing the Registration pages.

Recommended action

See recommended action. ■ No action necessary. Printing stopped... Time has expired on the Print/Stop test.

Recommended action

See recommended action. ■ No action necessary. Printing Supplies Status Page... The printer is printing the Supplies Status page.

Recommended action

See recommended action. ■ No action necessary. Printing Usage Page... The printer is printing the Usage page.

Recommended action

See recommended action. ■ No action necessary. Recommended action 409

Processing... The printer is currently processing a job but is not yet picking pages. When paper motion begins, this message is replaced by a message that indicates the tray the job is using.

Recommended action

See recommended action. ■ No action necessary. Processing... copy <x> of <y> The printer is currently processing or printing collated copies. The message indicates that copy number <x> of total copies <y> is currently being processed.

Recommended action

See recommended action. ■ No action necessary. Processing duplex job Do not grab paper until job completes Paper temporarily comes into the output bin while printing a duplex job.

Recommended action

See recommended action. ■ No action necessary. Processing job from tray <x>... Do not grab paper until job completes The printer is actively processing a job from the designated tray.

Recommended action

See recommended action. ■ No action necessary. Ready The printer is online and ready for data. No status or printer attendance messages are pending at the display.

Recommended action

See recommended action. ■ No action necessary. RAM disk device failure To clear press "OK" The specified device failed. 410 Chapter 7 Alphabetical control panel messages

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error. RAM disk file operation failed To clear press "OK" A PJJ command was received that attempted to perform an illegal operation, such as downloading a file to a nonexistent directory.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error. RAM disk file system is full To clear press "OK" The RAM disk is full.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error. RAM disk is write protected To clear press "OK" The device is protected and no new files can be written to it.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error.

RAM disk not initialized

The RAM disk file system must be initialized before it can be used.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Initialize the RAM disk file system. Ready <IP Address> The printer is online and ready for data. No status or printer attendance messages are pending at the display. The printer IP address displays.

Recommended action

See recommended action. ■ No action necessary. Recommended action 411

Receiving Upgrade

The printer is receiving a firmware upgrade.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Do not turn the printer off until it reaches the Ready state.

Remove USB accessory

This message displays when an unsupported USB device is inserted into a host USB port on the printer.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Remove the unsupported USB device. Replace <supply> This alert appears only if the printer is configured to stop when a supply reaches the very low threshold. The printer indicates when a supply level is at its estimated end of life. The actual life remaining might be different than estimated. The supply does not need to be replaced now unless the print quality is no longer acceptable. NOTE: HP recommends having replacement supplies available to install when the print quality is no longer acceptable. The printer can be configured to stop when the supply level is very low. The supply might still be able to produce acceptable print quality. ● 10.00.70 (event code)

Black toner cartridge

● 10.23.70 (event code)

Fuser Kit

Recommended action

Follow these troubleshooting steps in the order presented. 1. Replace the specified supply. 2. Or, configure the printer to continue printing by using the Manage Supplies menu.

Replace supplies

This alert appears only if the printer is configured to stop when a supply reaches the very low threshold. The printer indicates when a supply level is at its estimated end of life. The actual life remaining might be different than estimated. The supply does not need to be replaced now unless the print quality is no longer acceptable. 412 Chapter 7 Alphabetical control panel messages

HP recommends that the customer have a replacement supply available to install when print quality is no longer acceptable. Recorded event codes depend on which supplies are at the end of life. ● 10.00.70 (event code)

Black toner cartridge

● 10.23.70 (event code)

Fuser Kit

Recommended action

Follow these troubleshooting steps in the order presented. 1. Touch the OK button to find out which supplies need to be replaced. 2. Or, configure the printer to continue printing by using the Manage Supplies menu.

Resend external accessory firmware

An external accessory requires a firmware upgrade. Printing can continue, but jams might occur if the job uses the external accessory.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Perform a firmware upgrade. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions

Resend Upgrade

A firmware upgrade did not complete successfully.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Upgrade the firmware again. For the latest firmware versions, go to: HP FutureSmart - Latest Firmware Versions

Restore Factory Settings

The printer is restoring factory settings.

Recommended action

See recommended action. ■ No action necessary. ROM disk device failed To clear press "OK" The specified device failed. Recommended action 413

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error. ROM disk file operation failed To clear press "OK" A PjL command was received that attempted to perform an illegal operation, such as downloading a file to a nonexistent directory.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error. ROM disk file system is full To clear press "OK" The specified device is full.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error. ROM disk is write protected To clear press "OK" The device is protected and no new files can be written to it.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error. ROM disk not initialized To clear press "OK" The ROM disk file system must be initialized before it can be used.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Initialize the ROM disk file system.

Rotating Motor

The printer is executing a component test and the component selected is a motor.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Press the STOP button when ready to stop this test. 2. To exit, press X. 414
Chapter 7 Alphabetical control panel messages

Size Mismatch

This message appears even though the correct size paper is loaded in the correct paper tray.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Use the Tray 2 size switch test in the Tray/Bin manual sensor test to test the switch. 2. If sensor test does not respond, reconnect the connector on the Tray 2 paper size switch, and then reconnect connector on the DC controller. 3. If the error persists, elevate the issue using the Standard Support Process for a possible printer replacement. Size mismatch in Tray <x> The paper in the listed tray does not match the size specified for that tray.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Load the correct paper. 2. Make sure that the paper is positioned correctly. 3. Close the tray, and then make sure that the control panel lists the correct size and type for the specified tray. 4. If necessary, use the control panel menus to reconfigure the size and type settings for the specified tray. 5. If error persists, use the tray/bin manual sensor test to test the switch.

Sleep mode on

The printer is in sleep mode. Pressing a control-panel button, receiving a print job, or occurrence of an error condition clears this message.

Recommended action

See recommended action. ■ No action necessary.

Supplies low

Multiple supplies on the printer have reached the low threshold.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Replace the supply when print quality is no longer acceptable. Size Mismatch
415

Supply memory warning

The printer cannot read or write to the e-label or the e-label is missing.

Recommended action

See recommended action. ■ No action necessary.

Supply low

The printer indicates when a supply level, or more than one supply, is low. Actual toner cartridge life might vary. You do not need to replace the toner cartridge at this time unless print quality is no longer acceptable. When multiple supplies are low, more than one event code is recorded. ● 10.00.60 (event code)

Black toner cartridge

● 10.23.60 (event code)

Fuser Kit

Recommended action

Follow these troubleshooting steps in the order presented. ■ If print quality is no longer acceptable, replace the supply. HP recommends that the customer have a replacement supply available to install when print quality is no longer acceptable. NOTE: When an HP supply has

reached its approximated end of life, the HP Premium Protection Warranty ends.

Supply very low OR Supplies very low

The printer indicates when a supply level, or more than one supply, is very low. Actual toner cartridge life might vary. You do not need to replace the toner cartridge at this time unless print quality is no longer acceptable. When multiple supplies are low, more than one event code is recorded. ● 10.00.70 (event code)

Black toner cartridge

● 10.23.70 (event code)

Fuser Kit

Recommended action

Follow these troubleshooting steps in the order presented. 416 Chapter 7 Alphabetical control panel messages

■ If print quality is no longer acceptable, the customer must purchase and replace the supply. HP recommends that the customer have a replacement supply available to install when print quality is no longer acceptable. NOTE: When an HP supply has reached its approximated end of life, the HP Premium Protection Warranty ends.

The unit has corrupt data

Data corruption has occurred in the firmware volume. ● 98.00.01 : Corrupt data in the firmware volume ● 98.00.02 : Corrupt data in the solutions volume ● 98.00.03 : Corrupt data in the configuration volume ● 98.00.04 : Corrupt data in the job data volume Recommended action for 98.00.01, 98.00.02, and 98.00.03 Follow these troubleshooting steps in the order presented. For 98.00.01 , 98.00.02 , and 98.00.03 , perform the following steps: 1. Turn the printer off, and then on. 2. Use the Format Disk item in the Preboot menu. For the steps to perform a Clean or Format Disk procedure, search for "HP LaserJet Enterprise, HP LaserJet Managed - Various methods to clean the hard disk drives or solid-state drives" (ish_4502973-4502949-16) - . 3. Reload the firmware. Recommended action for 98.00.04 Follow these troubleshooting steps in the order presented. For 98.00.04 , perform the following steps: 1. Turn the printer off, and then on. 2. Run the file erase function. For the steps to perform this procedure, go to WISE and search for the following document: HP LaserJet Enterprise Printers - Performing a Partial Clean or Format Disk Procedure (c03398779). Tray <X> empty: [Type], [Size] The specified tray is empty and the current job does not need this tray to print.

● X = 1

Tray 1

● X = 2

The unit has corrupt data 417

Tray 2

● X = 3

Tray 3

● X = 4

Tray 4

● X = 5

Tray 5

Recommended action for customers

Follow these troubleshooting steps in the order presented. 1. Refill the tray at a convenient time. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP.

Recommended action for call-center agents

Follow these troubleshooting steps in the order presented. 1. Identify which Tray the error is occurring on. This will help focus subsequent troubleshooting. 2. Once the Tray has been identified, refill the tray at a convenient time. 3. If the message continues when the paper tray is properly loaded, swap the tray cassette with another from the printer that is the same size and check if the error follows the cassette. Replace the cassette tray as needed. NOTE: NOTE: If the error is occurring with the Multipurpose Tray (also known as the MP Tray or Tray 1), the ability to swap cassette trays is not applicable. Continue to next Troubleshooting steps of testing the appropriate Tray Paper Presence sensor. Tray actuating the tray paper present sensor flag (See the Troubleshooting manual – pg. 164) and check for any damage of the part. If it is damaged, replace the listed part for the targeted Tray. ● The Tray 1 media-out sensor (PS205) detects whether paper is present in Tray 1. If Tray 1 media-out sensor (PS205) is damaged, dispatch an Onsite Technician with the Cartridge door assembly: PS205 Tray 1 paper sensor Part Number: F2A68-67914 ● The Tray 2 media-out sensor (PS3) detects the presence of paper in Tray 2. If Tray 2 media-out sensor (PS3) is damaged, dispatch an Onsite Technician with the Paper Cassette Tray: Paper cassette tray (cassette tray only, no feeder) - Part Number: RM2-5758-000CN ● The accessory Trays (3-6) media-out sensor (PS451) detects the presence of paper in accessory Trays 418 Chapter 7 Alphabetical control panel messages

If accessory Tray media-out sensor (PS451) is damaged, dispatch an Onsite Technician with 1x550 Sheet Feeder Assembly: Part Number: F2A72-67901

Recommended action for onsite technician

Follow these troubleshooting steps in the order presented. 1. Identify which Tray the error is occurring on. This will help focus subsequent troubleshooting. 2. Once the Tray has been identified, refill the tray at a convenient time. 3. If the message continues when the paper tray is properly loaded, swap the tray cassette with another from the printer that is the same size and check if the error follows the cassette. Replace the cassette tray as needed. NOTE: NOTE: If the error is occurring with the Multipurpose Tray (also known as the MP Tray or Tray 1), the ability to swap cassette trays is not applicable. Continue to next Troubleshooting steps of testing the appropriate Tray Paper Presence sensor. Tray actuating the tray paper present sensor flag (See the Troubleshooting manual – pg. 164) and check for any damage of the part. If it is damaged, replace the listed part for the targeted Tray. ● The Tray 1 media-out sensor (PS205) detects whether paper is present in Tray 1. If Tray 1 media-out sensor (PS205) is damaged, dispatch an Onsite Technician with the Cartridge door assembly: PS205 Tray 1 paper sensor Part Number: F2A68-67914 For instructions: Removal and replacement: Cassette Tray See the Repair Service Manual for this product. ● The Tray 2 media-out sensor (PS3) detects the presence of paper in Tray 2. If Tray 2 media-out sensor (PS3) is damaged, dispatch an Onsite Technician with the Paper Cassette Tray: Paper cassette tray (cassette tray only, no feeder) - Part Number: RM2-5758-000CN For instructions: Removal and replacement: Cassette Tray See the Repair Service Manual for this product. NOTE: The paper presence (media-out) Sensor for Tray 2 is not an orderable part. If the cassette does not resolve the issue, elevate the case using your Region's Elevation Process. ● The accessory Trays (3-6) media-out sensor (PS451) detects the presence of paper in accessory Trays If accessory Tray media-out sensor (PS451) is damaged, dispatch an Onsite Technician with 1x550 Sheet Feeder Assembly: Part Number: F2A72-67901 For instructions: Removal and replacement: Cassette Tray See the Repair Service Manual for this product. Recommended action for onsite technician 419

4. If the issue persists after replacing the part, elevate the case using your Region's Elevation Process. Tray <X> lifting The printer is in the process of lifting paper in the indicated tray.

● X = 2

Tray 2

● X = 3

Tray 3

● X = 4

Tray 4

● X = 5

Tray 5

Recommended action

See recommended action. ■ No action necessary. Tray <X> open The specified tray is open or not closed completely.

● X = 2

Tray 2

● X = 3

Tray 3

● X = 4

Tray 4

● X = 5

Tray 5

Recommended action

Follow these troubleshooting steps in the order presented. ■ Close the tray. NOTE: If this message appears after the lifter drive assembly was removed or replaced, make sure that the connector on the assembly is correctly connected and fully seated. If the error persists, use the paper size switches test in the Tray/Bin manual sensor test to test the switches. If they do not respond, replace the associated lifter drive assembly. 420 Chapter 7 Alphabetical control panel messages

Tray <X> overfilled The tray is filled above the stack-height mark.

● X = 2

Tray 2

● X = 3

Tray 3

● X = 4

Tray 4

● X = 5

Tray 5

Recommended action

Follow these troubleshooting steps in the order presented. ■ Remove enough paper so that the paper stack does not exceed the limit for the tray. NOTE: If this message appears after the lifter drive assembly was removed or replaced, make sure that the connector on the assembly is correctly connected and fully seated. Type mismatch Tray <x> The specified tray contains a paper type that does not match the configured type.

Recommended action

Follow these troubleshooting steps in the order presented. The specified tray will not be used until this condition is addressed. Printing can continue from other trays. 1. Load the correct paper in the specified tray. 2. On the printer control panel, make sure the paper type loaded in the tray matches the specified setting for the tray. Unsupported drive installed To continue, touch "OK" A non-supported hard disk drive has been installed. The hard disk drive is unusable by this printer.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off. 2. Remove the hard drive. 3. Turn the printer on. Tray <X> overfilled 421

Unsupported supply in use OR Unsupported supply installed To continue, touch "OK" A non-supported supply has been installed, or the toner cartridge is for a different HP printer.

● XX = 00

Black toner cartridge

Recommended action

Follow these troubleshooting steps in the order presented. ■ Install the correct supplies for this printer. See the parts chapter in the service manual for supply part numbers.

Unsupported tray configuration

The printer has too many optional trays installed.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Turn the printer off, remove the unsupported trays, and then turn the printer on. Unsupported USB accessory detected Remove USB accessory A non-supported USB accessory has been installed.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Turn the printer off, remove the USB accessory, and then turn the printer on.

Upgrade Error

Scanner Control Board (SCB) upgrade error.

30.01.36 (event code)

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, and then on. 2. Re-send the upgrade. 3. If the error persists, replace the SCB. For instructions: See the Repair Service Manual for this product. Part number: B5L47-67903

USB accessory not functional

A parameter in the USB accessory is not correctly functioning. 422 Chapter 7 Alphabetical control panel messages

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off. 2. Remove the USB accessory. 3. Insert a replacement USB accessory. 4. Turn the printer on. USB hubs are not fully supported Some operations may not work properly Some USB hubs require more power than the printer has available.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Remove the USB hub. USB is write protected To clear press "OK" The device is protected and no new files can be written to it.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error. USB needs too much power Remove USB and then turn off and on A USB accessory is drawing too much electrical current. Printing cannot continue.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Turn the printer off, remove the USB accessory, and then turn the printer on. 2. Use a USB accessory that uses less power or that contains its own power supply.

USB not initialized

The USB device file system must be initialized before it can be used.

Recommended action

Follow these troubleshooting steps in the order presented. 1. Enable the USB port using the following steps: ● FutureSmart 3: a. From the Home screen on the printer control panel, open the following menus: i. Administration Recommended action 423 ii. General Settings b. Select Enable Device USB. c. Select Enabled, and then select Save. d. Touch the Back button to return to the General Settings menu. ● FutureSmart 4: a. From the Home screen on the printer control panel, select Settings. b. Select Copy/Print. c. Select Enable Device USB, and then select Enabled. d. Touch the Back button to return to the Settings menu. 2. If the error persists, contact your HP-authorized service or support provider, or contact customer support at www.hp.com/go/contactHP. USB storage accessory removed Clearing any associated data This message displays for about 6 seconds after a USB device is removed.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to remove this message. USB storage device failure To clear press "OK" The specified device failed.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error. USB storage file operation failed To clear press "OK" A PjL file system command was received that attempted to perform an illegal operation, such as downloading a file to a nonexistent directory.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Touch the OK button to clear the error. USB storage file system is full To clear press "OK" The file system on the installed USB device is full.

Recommended action

Follow these troubleshooting steps in the order presented. 424 Chapter 7 Alphabetical control panel messages

■ Touch the OK button to clear the error. Used supply installed To continue, touch "OK" OR Used supply in use The toner cartridge has been previously used.

● XX = 00

Black toner cartridge

Recommended action

Follow these troubleshooting steps in the order presented. ■ If you believe a genuine HP supply is being used, go to www.hp.com/go/anticoncounterfeit. Waiting for tray <x> to lift The specified tray is in the process of lifting paper to the top of the tray (so it can correctly feed).

Recommended action

See recommended action. ■ No action necessary.

Windows Login Required to Use this Feature

Windows login required.

Recommended action

Follow these troubleshooting steps in the order presented. ■ Enter your windows login. Used supply installed To continue, touch "OK" OR Used supply in use 425

Index Symbols/Numerics

76.00.24 5

B backup error 32.WX.YZ error 4 reset error 4 restore error 4 C connector error 65.WX.YZ error 5 D

DC controller communication error

55.WX.YZ error 4

DC controller firmware error

70.WX.YZ error 5 digital sending error (firmware) 44.WX.YZ error 4 document feeder error 31.WX.YZ error 4 duplexer error 69.WX.YZ error 5 E

Embedded Jetdirect error

80.WX.YZ error 5 engine error (LaserJet) 46.WX.YZ error 4 63.WX.YZ error 5 engine error (PageWide) 61.WX.YZ error 4 event log error (firmware) 42.WX.YZ error 4 F fan error 58.WX.YZ error 4 firmware communication error 49.WX.YZ error 4 firmware install error 99.WX.YZ error 5 hard disk error 5 remote firmware upgrade error 5 fuser error 41.WX.YZ error 4 laser scanner error 4 paper path error 4 fuser error (LaserJet) 50.WX.YZ error 4 H hard disk partition error 98.WX.YZ error 5 I input accessory error 67.WX.YZ error 5 input/output error 40.WX.YZ error 4 internal diagnostics error 90.WX.YZ error 5 video display error 5 J jam error (LaserJet) 13.WX.YZ error 3 jam error (PageWide) 13.WX.YZ error 4 job accounting error (firmware) 48.WX.YZ error 4 job management error (firmware) 4 job pipeline error (firmware) 4 job parser error (firmware) 47.WX.YZ error 4 printer calibration error 4 L laser scanner error (LaserJet) 51.WX.YZ error 4 52.WX.YZ error 4 last update 1 M memory error 82.WX.YZ error 5 EMMC error 5 hard disk error 5 motor error (LaserJet) 59.WX.YZ error 4 N

Near Field Communication error

81.WX.YZ error 5 Bluetooth error 5 external I/O card error 5 internal EIO error 5 wireless error 5 O output accessory error 66.WX.YZ error 5 OXPd/Web kit error 45.WX.YZ error 4 P page error 21.WX.YZ error 4 paper handling error (LaserJet) 56.WX.YZ error 4 print bar error (PageWide) 62.WX.YZ error 5 printer memory error 20.WX.YZ error 4 R real-time clock error 11.WX.YZ error 3 S scanner error 30.WX.YZ error 4 security error 33.WX.YZ error 4 sensor error 54.WX.YZ error 4 58.WX.YZ error 4 supplies error (LaserJet) 10.WX.YZ error 3 supplies error (PageWide) 17.WX.YZ error 4 system error (LaserJet) 62.WX.YZ error 5 426 Index
T tray motor error (LaserJet) 60.WX.YZ error 4 Index 427