

Chandra X-ray Observatory

HRC Anomaly on 24 August 2020

Plan of action following the anomaly re-occurrence

Chandra Community Briefing

28 August 2020

HRC Operations Team

D. Patnaude, R. Kraft, P. Nulsen, G. Tremblay, T. Gauron, A. Kenter, K. Gage, B. Bissell, G. Austin, J. Chappell


CENTER FOR **ASTROPHYSICS**
HARVARD & SMITHSONIAN


The re-appearance of the HRC anomaly

- In response to the initial HRC anomaly that began on Monday morning, the HRC Team recommended that we **attempt a reset of the Side A power supply bus.**
 - A summary of this initial anomaly and first response plan can be found in our two prior community briefings, found [here](#) and [here](#).
- On Wednesday night, **we executed CAP 1541 to reset the power supply bus** during the 8:05pm EDT pass.
- **The CAP execution was *technically successful***, and returned the HRC bus voltages to their nominal states. Those nominal states were persistent and stable for 11h 13 min, including through the 6am comm pass yesterday morning.
- **At the start of the 5:20 pm (BOT, EDT) comm pass yesterday evening, the HRC Team noted that the +/-15 V voltages had returned to the same off-nominal values encountered during the first anomaly.**

Timeline of the reappearance

- The anomaly returned yesterday at 11:53:19 UTC (7:53:19 EDT), i.e. 53 min, 19 seconds after the end of yesterday's 6am comm pass.
- The return of the anomaly was noted immediately at BOT of the 5:20pm comm pass last night. We successfully shut down the instrument via SCS 41 at 5:37pm local time.





Hypotheses


- The rapid reoccurrence of the anomaly **now disfavors a single event upset (SEU) scenario.**
- Timescales argue that **the thermal environment is one potential driver of whatever is causing the anomaly.**

Plan of action


- **The HRC Team now recommends that we swap to redundant Side B electronics**
 - The HRC Team has been reviewing, analyzing, and discussing the commanding and procedures necessary to make this change.
 - This includes shift reports from orbital activation, early logs and notes, etc.
- While prioritizing operational activities, the HRC team is actively investigating potential causes of the anomaly.

EXTRA SLIDES

Top level diagram to switch from Side A on the Prime Bus to Side B on the Redundant Bus




HRC Power Switching



Post-power up HRC

turn on PMT#2
turn on HRC-I/S HV
ramp up HRC-I/S HV - point at blank sky

Swap to side B on redundant bus is represented by power configuration PCFG08



Hypotheses from 8/26 tagup

- The anomaly is due to a problem **with the +/- 15 V power supply bus on Side A**
 - **A problem in the +15 V bus would also take out the -15 V power supply due to DC-to-DC design**
 - A problem in the -15 V bus would not cause issues with the +15 V bus
 - **There could be a fault in the electronics on this bus**
 - A load fault that is transient in nature (e.g. an SEL). This should clear with a power cycle.
- ... or ...
- A failed component that is dragging down the +15V bus. This would not clear with a power cycle and would require an A/B swap.
- ... or ...
- A latched-up component downstream of DC-DC converter may clear with power cycle. Otherwise an A / B swap is indicated.


Decision tree during CAP execution

- Following CAP Step 2 (205VAON with telemetry verifier **2PS5A0N=ON**):
 - **Success:** We expect to see the +5 V bus return to a nominal value (i.e. around +5 V and stable for several frames).
 - **Failure:** The +5 V bus does *not* return to a nominal value, or only stays there for a very short period of time before returning to an off-nominal value.
 - If this step is **successful**, we will proceed to the next step. If it is **not successful**, we will execute contingency steps 6 and 7 in the CAP to safely shutdown the instrument. The CAP will end there.
- Assuming the above step is **successful**, following CAP Step 5 (215PCA0N with telemetry verifier **215PCAST=ON**):
 - **Success:** We expect to see the +15 V and -15 V bus monitors return to nominal values (i.e., *roughly* -14.5 V to -15 V for the -15 V monitor, and +14.5 V to +15 V monitor. Note that these thresholds are *not* exact. **Important note:** it is *possible* that we will see some secondary ~~science~~ corruption in the telemetry. This is not surprising and will not necessarily constitute a failure. The HRC Team will decide if the exact returned values can be considered “nominal”.
 - **Failure:** One or both of the +15 V and -15 V monitors do *not* return to their expected values.
 - If this step is **successful**, we will proceed to the next step. If it is **not successful**, we will execute contingency steps 6 and 7 in the CAP to safely shutdown the instrument. The CAP will end there.
- Assuming the above step is **successful**, following CAP Step 8 (224PCA0N with telemetry verifier **225PCAST=ON**):
 - **Success:** We expect to see the +24 V return to a nominal value of *roughly* +24 V. The HRC Team will decide if the exact returned values can be considered “nominal”. Again, some SSC might be present, and this does not necessarily mean failure.
 - **Failure:** The +24 V monitor does *not* return to its expected values.
 - If this step is **successful**, we will proceed to the next step. If it is **not successful**, we will execute contingency steps 6 and 7 in the CAP to safely shutdown the instrument. The CAP will end there.

Chandra X-ray Observatory

HRC anomaly on day 2020:237


Plots by G. Tremblay & the HRC Team: grant.tremblay@cfa.harvard.edu



Chandra X-ray Observatory

HRC anomaly on day 2020:237


Plots by G. Tremblay & the HRC Team, grant.tremblay@cfa.harvard.edu



Chandra X-ray Observatory

HRC anomaly on day 2020:237


Plots by G. Tremblay & the HRC Team: grant.tremblay@cfa.harvard.edu



Chandra X-ray Observatory

HRC anomaly on day 2020:237


Plots by G. Tremblay & the HRC Team; grant.tremblay@cfa.harvard.edu




Chandra X-ray Observatory

HRC anomaly on day 2020:237

Plots by G. Tremblay & the HRC Team; grant.tremblay@cfa.harvard.edu




Forecasted HRC Thermistor Temperatures if Current Slopes Hold



Explanation of trigger noise

(T. Gauron)



Top Level Trigger from MCP output:




T/HRES! Routes to SEC_SCI_CTR pin 29 on backplane

CE	SLOT 11	SEC SCI CTR A
5209		
CEJ11	0 1	CE+15A
46	0 2	CEGND
47	0 3	CE-15A
48	0 4	CEGND
49	0 5	CE+5A
50	0 6	CE+5A
51	0 7	
52	0 8	
53	0 9	
54	0 10	
55	0 11	
56	0 12	
57	0 13	
58	0 14	
59	0 15	
60	0 16	
61	0 17	
62	0 18	
63	0 19	
64	0 20	
65	0 21	
66	0 22	
67	0 23	
68	0 24	
69	0 25	
70	0 26	
71	0 27	
72	0 28	
73	0 29	T/HRES! A
74	0 30	SECTIC! A
75	0 31	1.024MHZ2A
76	0 32	


It's called TLEV on the SEC_SCI PWA



GSI is synced with S/C clock and becomes T/HRES! in SEQUENCER



...and gets counted for TOTAL EVENTS




Why is a Side A reset preferred?

- Resetting Side A offers *lower risk* than swapping to Side B.
 - The HRC team ***cannot find any plausible scenario*** in which turning on the 5 and 15 V would cause any damage to the single stream components (e.g., MCPs, crossed grid array, etc.)
 - This is a **straightforward procedure** derived from an SCS
 - This addresses the possible “single event latchup” hypothesis
- **Swapping to Side B is more complicated and risky.**
 - It requires switching of latching relays which we haven’t activated in 20 years.
 - It requires shutting the 28 V bus power to the HRC off.
 - B-side electronics have not been used in 20 years
 - It entails significant alteration of all HRC commanding, including protected SCSs, ATSs, and support software
 - It would require a complete calibration of the detectors

Explanation of trigger noise

(T. Gauron)



Top Level Trigger from MCP output:




T/HRES! Routes to SEC_SCI_CTR pin 29 on backplane

CE	SLOT 11	SEC SCI CTR A
5209		
CEJ11	0 1	CE+15A
47	0 2	CEGND
48	0 3	CE-15A
49	0 4	CEGND
50	0 5	CE+5A
51	0 6	CE-5A
52	0 7	
53	0 8	
54	0 9	
55	0 10	
56	0 11	
57	0 12	
58	0 13	
59	0 14	
60	0 15	
61	0 16	
62	0 17	
63	0 18	
64	0 19	SFDAT7A
65	0 20	SFDAT6A
66	0 21	SFDAT5A
67	0 22	SFDAT4A
68	0 23	SFDAT3A
69	0 24	SFDAT2A
70	0 25	SFDAT1A
71	0 26	SFDAT0A
72	0 27	
73	0 28	VEVA
74	0 29	T/HRES! A
75	0 30	SECTIC! A
76	0 31	1.024MHZ2A
	0 32	


It's called TLEV on the SEC_SCI PWA



GSI is synced with S/C clock and becomes T/HRES! in SEQUENCER



...and gets counted for TOTAL EVENTS



Prime and redundant side wiring

(T. Gauron)

