



LEMBAR PENGESAHAN

LAPORAN BULANAN TRANSMISI JAWA BAGIAN BARAT

LAPORAN DOKUMENTASI KEGAGALAN INFRASTRUKTUR MANAJEMEN ASET DAN REALIBILITAS INFRASTRUKTUR OPERASI (MARIO)

APRIL 2020

Diperiksa, Pj. O&M Jawa Bagian Barat Disetujui, Pj. MARIO Jawa Bagian Barat

Yusron Firmansyah

Nurdiansyah

Mengetahui, PT.PGN - GTM OMM Zona Jawa Bagian Barat

Sony Achmad





LAPORAN DOKUMENTASI KEGAGALAN INFRASTUKTUR BULAN APRIL TAHUN 2020

bearing the second									The State of the S						
Record No**	Asset Name	Tag No**	Commissioning Date***	Failure Date**	Failure Mode**	Failure impact on equipment function *(a) **	Failure Cause	Subunit failed	Component/ Maintainable item(s) failed	Maintenance Section	Operating condition at failure *(b)	Repair Time (Hours)	Running Hours at Failure	Documentation	
STASIUN MBK	2	3	4	3		7			10	11	12	13	14	15	16
057/FAILURE/MBK	STATE OF THE PARTY OF	F. 4 401													
058/FAILURE/MBK	Fire System Panel Dewpoint Transmitter	81-DT-2340		01/21/2020 03/24/2020		Critical Failure Incipient Failure	Sensor smoke rusak Kerusakan pada modul	DM 005	modul	penggantian modul	running	12	24		Closed 1/21/7020
				0.02 21000		Incipiens Familie	Kerusakan pana monui		modul	penggantian modul	running	-	_		open
059/FAILURE/MBK	Display Controller diesel pompa hydrant A			03/24/2020		Incipient Failure	Kerusakan pada modul		modul	penggantian modul	rutining				open
OGO/FAILURE/MBK	CCTV PLN & RMJ		13/03/2015	17/05/2019		Critical Failure	Video lost	DVR?NVR		Penggantian DVR, camera	running				open
036/FAILURE/OFFSHORE	NAVIGATIONAL BUOY	BUOY 2		7-3an-20	Kerusakan Pada Radar Ring Guad		Indikasi kerusakan dikarenakan tertabrak oleh kapal			Dilakukan Penggantian Ring Guad					Closed 1/21/2020
037/FAILURE/OFFSHORE	NAVIGATIONAL BUDY	BUOY 8		18-Jan-20	Kerusakan Pada Radar Ring Guad		Indikasi kerusakan dikarenakan tertabrak oleh kapal							4	0000
038/FAILURE/OFFSHORE	NAVIGATIONAL BUOY	BUOY 3		17-Jan-20	Buoy Hilang		Indikasi kerusakan Body Buoy bocor dan mengalibatkan tenggelam			akan dilakukan pengadaan dan pergantian Bouy 3					DDDD
D39/FAILURE/OFFSHORE	NAVIGATIONAL BUOY	BUOY 1		18- tan- 20	Buoy Terendam		Indikasi kerusakan Body Buoy bocor dan mengakibatkan buoy I terendam			dilakukan pemasangan pelampung derigen Bouy 1				À	0000
040/FAILURE/OFFSHORE	NAVIGATIONAL BUOY	BUOY 8		11-Feb-20	Kerusakan Pada Radar Ring Guad		Indikasi kerusakan dikarenakan tertabrak oleh kapal			Dilakukan Penggantian Ring Guad					
D41/FAILURE/OFFSHORE	NAVIGATIONAL BUOY	BUOY8		6-Mar-20	Kerusakan Pada Radar Ring Guard dan Cross Tep Mark		Indikasi kerusakan dikarenakan tertabrak oleh kapal			Belum dilakukan penggantian Ring Guad karena faktor cuaca buruk dan akan dilakukan perbaikan di patroli yg akan datang					
D42/FAILURE/OFFSHORE	NAVIGATIONAL BUOY	BUOY7		16-Mar-20	Kerusakan Pada Marine Lantern dan Cross Top Mark		Indikasi kerusakan dikarenakan tertabrak oleh kapal			Belum dilakukan penggantian Ring Guad karena faktor cuaca buruk dan akan dilakukan perbaikan di patroli yg akan datang				Self Acet Harby	
D43/YAILURE/OFFSHORE	NAVIGATIONAL BUOY	BUOY 7		6/04/2020	Kerusakan Pada Lantern guard dan Cross Top Mark tambahan kerusakan Radar reflektor		Indikasi kerusakan dikarenakan tertabrak oleh kapal			Sudah dilakukan penggantian Ring Guad,Radar Reflektor,dan Marine Lantern					
D44/FAILURE/OFFSHORE	NAVIGATIONAL BUOY	BUOY 9		16/04/2020	Kerusakan Pada Marine Lantern dan Cross Top Mark		Indikasi kerusakan dikarenakan tertabrak oleh kapal			Sudah dilakukan penggantian Marine Lantern dan Cross Top Mark					
STASIUN BOJONEGARA			March Control										III.		
THE STATE OF THE S	The second second		SUBSCIENCES CO.		CANADA SERVICE AND	STATISTICS TO SERVICE	The second second	delin delin del	CONTRACTOR OF THE PARTY OF THE	Charles of the later of the lat	CHARLES AND			the state of the s	10 - 4 - 11 - 11 - 11 - 11 - 11 - 11 - 1
007A/FAILURE/BIN	GAS CHROMATOGRAPH UNIT A	52-AT-1347A	24 Agustus 2017	30-Oct-18	GC Failure	Critical Failure	Kerusakan Electrical Komponen	Controller Board	Controller Board	Dilakukan penggantian fuse & realignment PCT	ldle	2	3504		Closed (6 Mei 2019)
008/FAILURE/BIN	POWER SUPPLY LAMBDA METERING CABINET	52-P5U-A1	12 Agustus 2010	13 Juli 2018	Power Supply Trip	Critical Failure	Lifetime Power Supply	Power Supply	Power Supply	Dilakukan penggantian power supply lambda	adle	0.15	0.15		Closed (13 Juli 2018)
009/FAILURE/BIN	Lighting Street	Area DEG Fasilitas	1 Juli 2007	29 Juli 2018	Loss Power	Degraded Failure	Power cable is broken	power cable	power cable	dilakukan penarikan jalur kabel listrik yang baru	idle	2	2		Oosed (29 Juli 2018)
010/FAILURE/BIN	Pompa Hydrant Unit A	52 P-4120A	18 Januari 2018	20 Juli 2018	Muncul Alarm battery drop	Critical Failure	Battery rusak	battery	battery	dilakukan penggantian battery	idle	1	231		Closed (29 Agustus 2018)

	* 5													
011/FAILURE/BIN	Panel Smoke & Heat Detector	Area Control Building	1.3uli 2007	27 Juli 2018	Muncul alarm ground fault dan tampilan display pada panel board error	Critical Failure	panel board, power supply dan jalur kabel ground mengalami kerusakan	panel board, power supply dan jalur kabel ground	panel board, power supply dan jalur kabel ground	dilakukan penggantian panel board, power supply dan jalur kabel ground	running	1	2160	Closed (20 September 2018)
017/FAILURE/BIN	Thermowell 52-TT-13108	52-TT-1310B	17 Agustus 2010	15 Juli 2018	Kebocoran pada thermowell	Critical Failure	korosi / crack pada thermowell	thermowell	thermowell	dilakukan penggantian thermowell	funning	1	384	Closed
013/FARURE/BIN	PLC	PLC Metering	12 Agustus 2010	10-Nov-18	Data Stuck	Critical Failure	Logic Failure	Logic	Software	Dilakukan reset PLC dan setting ulang waktu PLC	idle	1	5	Closed (10 November 2018)
014/FAILURE/BIN	Solenoid Valve DEG Fasilitas		12 Agustus 2010	14-Nov-18	Splenoid Always Open Position	Critical Failure	Kerusakan Solenoid dan Sensor Level Daily Tank	Solenoid dan Sensor Level Solar	Solenoid dan Sensor Level Solar fail	Penggantian sensor level daily tank DEG fasilitas dan setting ulang upper level	idle	1	36	Closed (15 November 2018)
015/FAILURE/BJN	Limit Switch 52-BV-1344		12 Agustus 2010	13-Nov-18	Blinking Indication	Critical Failuce	Kerusakan Limit Switch	3ensor	Sensor	Penggantian Limit Swit Switch 52-BV-1344	adle	1	30	Closed (14 November 2018)
016/FAILURE/BIN	Panel FM 200	UPS Room	1 Juli 2007	4-Dec-18	Alaem PSU	Critical Failure	Battery Fail	Battery	Battery 12 V, 12 Ah	Penggantian Battery 12 V, 12 Ah	idle	2	2	Closed (4 Desember 2018)
017/FAILURE/BIN	Panel FM 200	IT Room	1 Juli 2007	4-Dec-18	Alacm PSU	Critical Failure	Battery Fail	Battery	Battery 12 V, 12 Ah	Penggantian Battery 12 V, 12 Ah	idle	2	2	Clased (4 Desember 2018)
018/FAILURE/BIN	Panel Pompa DEG	DEG Facility	1 Juli 2007	10-Dec-18	Alarm Pump Fail & Sensor Fail	Critical Failure	Sensor upper dan lower mengalami kerusakan dan ada kontaktor pada panel pompa yang harus diganti	Sensor, Termination Cable	Sesor Level	Penggantian Sensor daily tank, penggantian terminasi kabel dan pemasangan PSU yang baru untu LT	Standby	5	5	Closed (10 Desember 2018)
019/FAILURE/BIN	Decoder CCTV	MCS Building	12 Agustus 2010	3 Desember 2018	Terdapat beberapa CCTV yang tidak terbaca dan tidak dapat masuk kedalam decoder eksisting	Critical Failure	Decoder eksisting hanya ada 8 channel	Decoder DVR	Decoder DVR	Penggantian decoder 16 channel	Standby	2	7	Closed (3 Desember 2018)
020/FAILURE/BIN	Limit Switch 52-HCV-1303	52-HCV-1303	12 Agustus 2010	10-Dec-18	Blinking Indication	Critical Failure	Kerusakan Limit Switch	Sensor	Sensor	Penggantian Limit Swit Switch 52-HCV-1303	idle	2	2	Closed (10 Desember 2018)
021/FAILURE/BIN	Limit Switch 52-HCV-1302	52-HCV-1302	12 Agustus 2010	10-Dec-18	Blinking Indication	Critical Failure	Kerusakan Limit Switch	Sensor	Sensor	Penggantian Limit Swit Switch 52-HCV-1302	idle	2	2	Closed (10 Desember 2018)
022/FAILURE/BIN	Jet Pump	Hydrant (Water Pond)	18 Januari 2018	2-Dec-18	Air pengisi water pond tidak keluar	Critical Failure	Kerusakan jet pump	check valve	check valve & suction pipe	Penggantian check valve & suction pipe	ldle	8	8	Closed (2 Desember 2018)
023/FARURE/BIN	Temperature Transmitter	52-TT-1307	1 Juli 2007	31 Desember 2018	Alarm Er-02	Critical Failure	Kerusakan RTD PT 100	RTD	PT 100	dilakukan penggantian sensor RTD PT 100	idle	2	2	Closed (31 Desember 2018)
024/FAILURE/BIN	Temperature Gauge	52-TI-1301 A	1 Juli 2007	31 Desember 2018	Kerusakan indikator	Critical Failure	kerusakan unit indikator	RTD	PT 100	dilakukan penggantian unit temperature indikator	idle	2	2	Closed (31 Desember 2018)
025/FAILURE/BIN	Limit Switch 52-HCV-1303	52-HCV-1303	12 Agustus 2010	10-Dec-18	Blinking Indication	Critical Failure	Kerusakan Limit Switch	Sensor	Sensor	Penggantian Limit Swit Switch 52-HCV-1303	idle	2	2	Closed (10 Desember 2018)
026/FAILURE/BIN	Limit Switch 52-HCV-1302	52-HCV-1302	12 Agustus 2010	10-Dec - 18	Blinking Indication	Critical Failure	Kerusakan Limit Switch	Sensor	Sensor	Penggantian Limit Swit Switch 52 HCV-1302	idle	2	2	Closed (10 Desember 2018)
027/FAILURE/BIN	Jet Pump	Hydrant (Water Pond)	18 Januari 2018	2-Dec-18	Air pengisi water pond tidak keluar	Critical Failure	Kerusakan jet pump	check valve	check valve & suction pipe	Penggantian check valve & suction pipe	idle	8	8	Closed (2 Desember 2018)
028/FAILURE/BIN	Temperature Transmitter	52-TT-1307	1 Juli 2007	31 Desember 2018	Alarm Er-02	Critical Failure	Kerusakan RTD PT 100	RTD	PT 100	dilakukan penggantian sensor RTD PT 100	ktle	2	2	Closed (31 Desember 2018)
029/FAILURE/BIN	Temperature Gauge	52-TI-1301 A	1 Juli 2007	31 Desember 2018	Kerusakan indikator	Critical Failure	kerusakan unit indikator	RTD	PT 100	dilakukan penggantian unit temperature indikator	idle	2	2	Closed (31 Desember 2018)
030/FAILURE/BIN	Temperature Gauge	52-TI-1303 A	1 Juli 2007	31 Desember 2018	Kerusakan indikator	- Critical Failure	kerusakan unit indikator	RTD	PT 100	dilakukan penggantian unit temperature indikator	ldle	2	7	Closed (31 Desember 2018)
031/FAILURE/BIN	Water Utility	52-TI-1303 A	1 Juli 2007	14 Januari 2019	Tidak tercapanya level high dan low air pada torrent	Critical Failure	kerusakan sensor	Sensor Level Ornron	Ormon ps-3s-ap	dilakukan penggantian sensor Jewel	ktie	1	1.	Closed (14 Junuari 2019)
032/FAILURE/BIN	H2S Analyzer Unit B	52-AT-13498	1 Juli 2007	16 Januari 2019	Nilai Hunting dan Alarm pembacaan H25 yang tidak valid	Critical Failure	kerusakan sensor lampu Cd dan Cu	Cu dan Cd Lamp	Cu dan Cd Lamp	dilakukan penggantian part Cu dan Cd Lamp	idle	3	3	Closed (16 Januari 2019)
033/FAILURE/BIN	Limit Switch 52-BV-1377B	52-8V-13778	1 Juli 2007	25 Februari 2019	Blinking Indication	Incipient Failure	Kerusakan Limit Switch	Sensor	Sensor	Penggantian Limit Swit Switch 52-BV-1377 B	idle	2	30	Closed (25 Februari 2019)
034/FAILURE/BIN	Flow Computer	52 FC 1330 B	1 Juli 2007	2 Maret 2019	No Differential Pressure Appear, No Flow Counting	Critical Failure	Cable Data dari Signal Conditioning Lepas	Cable Data DPT	Cable Data DPT	Pernasangan Cable Data DPT	idle	2	2	Closed (2 Maret 2019)
035/FAILURE/BIN	Proximity Switch	52-55V-2120	1 Juli 2007	4 Maret 2019	Blinking Indication	Critical Failure	Kerusakan Proximity Switch	Sensor	Sensor	Penggantian Proximity Switch 52-SSV-2120	idle	2	3	Closed (4 Maret 2019)
036/FAILURE/BIN	Odorizer	52-V-2501	L luli 2007	15 Maret 2019	Ex tank low and high, pump failure, slow fill, no fill	Critical Failure	Kerusakan seal pompa, Mter bulk odorant, filter verometer dan expansion tank terni odorant	seal pompa, filter bulk odorant, filter verometer dan expansion tank terisi odorant	seal pompa, filter bulk odorant, filter verometer dan expansion tank terisi odorant	Penggantian seal pompa, filter bulk odorant, filter verometer dan expansion tank terisi odorant	idle	2	120	Closed (20 Maret 2019)
037/FAILURE/BIN	Pressure Trasnmitter	52-PT-1002 A	1 Juli 2007	26-Mar-19	Nilai Pembacaan Pressure di SCADA Stuck	Critical Failure	Kerusakan Limit Switch	Transmitter	Instrument	Simulation	ldle	1	7416	CLOSED
038/FAILURE/BIN	Pressure Trasnmitter	52-PT-1302 C	1 Juli 2007	26 Mar-19	Nilai Pembacaan Pressure di SCADA Stock	Critical Failure	Kerusakan Limit Switch	Transmitter	Instrument.	Simulation	ldle	1	7416	CFO2ED
039/FAILURE/BIN	Thermowell Upstream	52-71-1301	1 July 2007	8-Apr-19	Kebocoran terjadi di thermowell Temperatur Indikator 52-TI-1301 di area PCV 1301	Incipient Failure	Crack atau Korosi	thermowell	thermowell	Diberikan plug pada thermowell dan pemberian LOTO	Idle	1	5568	CLOSED
040/FAILURE/BIN	AC Training Room	AC NO 40	1 July 2007	9 Apr-19	Kompresor tidak dingin	Incipient Failure	Kerusakan kompresor	kompresor	kompresor	nonaktifan AC	idle	1	6288	CLOSED
													11	

										Vince				
041/FAILURE/BIN	AC Training Room	AC NO 41	1 Juli 2007	9-Apr-19	Kompresor tidak dingin	Incipient Failure	Kerusakan kompresor	kompresor	kompresor	nonaktifan AC	tdle	1	6312	CLOSED
042/FAILURE/BIN	Odorizer	52-02-2501	1 Juli 2007	11-Apr-19	Kebocoran pada pneumatic relay	Incipient Failure	Relay longgar	relay	seal relay	Pengencangan relay	ldle	2	2	CLOSED
043/FAILURE/BIN	Flame Detector	52-FD-2130	I auni 2008	12-Apr:19	Muncul alarm	Critical Failure	Sensor selalu tertriger	Sensor	Instrument	Cleaning Sensor	ldle	1	-1045608	OPEN
044/FAILURE/BIN	Flame Detector	52-FD-1311	1 gani 2008	12-Apr-19	Muncul alarm	Critical Failure	Sensor selalu tertriger	Sensor	Instrument	Cleaning Sensor	klie	E	8352	OPEN
045/FAILURE/BIN	Flame Detector	52-FD-1330	1 juni 2008	17-Apr-19	Muncul alarm	Critical Failure	Seesor selalu tertriger	Sensor	Instrument	Cleaning Sensor	klle	1	8352	OPEN
046/FAILURE/BIN	Gas Detector	52-60-2132	1 pani 2008.	17-Jan-19	Muncul alarm	Critical Failure	Sensor solalu tertriger	Sensor & Transmitter	Instrument	Cleaning Sensor	ktle	1	8352	OPEN
047/FAILURE/BIN	Loss Power	52-PT-1002 A	1 Juli 2007	15 Apr-19	Kondisi pembacaan pressure pada SCADA stuck	Critical Failure	Fuse yang putus	Fuse	Fuse RTU	Pengantian Fuse	idle	1 -	1	CFORED
048/FAILURE/BIN	Panel pompa solar DEG	52-DEG-5020	1 Juli 2007	11-Apr-19	Pada bagsan level control, thermal overload relay dan push button sehingga pengisian solar dari storage Lank menuju daliy tank serganggu	Critical Failure	Level Control Roller	Automatic Pump	Automatic Pump	Penggantan Level Control	running	ı	144	CLOSED
049/FAILURE/BIN	Wind Shock	Area pig launcher dan slug catcher	1 Juli 2007	12 Jun-19	Life time pasang sudah 6 bulan	Critical Failure	Kerusakan Wind Sock	Wind Sock	Wind Sock	Penggantian Wind Sock	ldle	1	I	CLOSED [17 Juni 2019]
OSO/FAILURE/BIN	Monture Generator pada Monture Analyzer B	52-AT-12488	1. Juli 2007	14-Jun-19	Di alubatkan alarm replace moisture generator pada saat dilakukan performance test moisture analyzer	Critical Failure	Kerusakan Moisture Generator pada Moisture Analyzer B	Moisture Analyzer B	Moisture Analyzer B	Penggantian Moisture Generator	idie	ı	1	CLOSED [14 Juni 2019]
051/FAILURE/BJN	Lampu di Platform	Area Redzone	1 Juli 2007	17-Jun-19	Lampu di Platform	Critical Failure	Kerusakan Lampu di Platform	Lampu di Platform	Lampu di Platform	Penggantian Lampu di Platform	ldle	1	1	CLOSED [17 Juni 2019]
052/FAILURE/BIN	Pressure Gauge	52-PF-1303A	1 Juli 2007	17-Jun-19	nılai pressure didalam chamber PCV 1301 – A tidak dapat diketahui menggunakan pressure gauge	Critical Failure	Kerusakan Pressure Gauge 52-PF-1303A	Pressure Gauge	Pressure Gauge	Penggantian Pressure Gauge	hille	1	1	CLOSED (17 Juni 2019)
05:3/FAILURE/BIN	QCM	52 AT-1348 A	1 Juli 2007	10-Jul-19	Alarm calibration error	Critical Failure	Kerusakan QCM pada H2O analyzer A	Sensor frekuensi	Sensor frekuensi	Penggantian QCM pada H2O Analyter A	idle	ı	1	CLOSED (10 Juli 2019)
054/FAILURE/BIN	Solenoid valve LCV	52-4VC-7102	1 Juli 2007	26 Jul 19	Lambatnya respon pembukaan solenoid valve saat mendapatkan perintah open dari SCADA	Critical Failure	Kerusakan pada solenoid valve eksisting	Solenoid valve	Solenoid valve	Penggantian solenoid valve	Me	1	1	EFO2ED (56 YM 501a)
055/FAILURE/BIN	Moisture Generator pada Moisture Analyzer A	52-AT-1348A	2 Juli 2007	28-Jul-19	Alarm calibration error dan replace dryer pada saat dilakukan performance test moisture analyzer	Critical Failure	Kerusakan Moisture Generator pada Moisture Analyzer A	Moisture Analyzer A	Moisture Analyzer A	Penggantian dryer dan calibrasi ulang	idle	1	1	£1.05£0 (28 Juli 2019)
056/FAILURE/BJN	H25 Analyzer AMETEK 933 A	52-AT-13498	1 Juli 2007	28-Jul-19	Alarm error ALC dan kerusakan pada Iampu Cadmium dan Cooper	Critical Failure	Kerusakan sensor lampu Cadmium dan Cooper	lampu Cadmium dan Cooper	lampu Cadmium dan Cooper	Penggantian part lampu Cadmium dan Cooper serta Auto Zero	ldle	1	1	CLOSED (28 Juli 2019)
057/FAILURE/BIN	MCCB incoming DEG di pagel pdb fasilitas	Panel Distribution Bord Fasilitas BIN	1 Juli 2007	5-Aug-19	Switch Motor tidak bekerja dan pada Breaker yang menempel dimotor penggerak terdapat bau hangus	Critical Failure	Kerusakan Switch Motor	Switch Motor	Switch Motor	Penggantian Breaker 4 pool	ldle	7	2	CLOSED (5 Agustus 2019)
058/FAILURE/BIN	MCCB incoming PLN di panel pdb fasilitas	Panel Distribution Bord Fasilitas BIN	Duli 2007	21 Aug-19	Adanya kabel fasa yang tidak kencang	Critical Failure	Kendornya kabel fasa	MCCB	MCCB	Pengencangan kabel fasa dan coating ulang	idle	4	4	CLOSED [21 Agustus 2019]
059/FAILURE/BIN	Timer dan Perbaikan Kabel Fasa yang meleleh pada Incoming PLN di panel PDB	Panel Distribution Bord Fasilitas BIN	1 Juli 2007	22 Agustus 2019	Timer Relay tidak beskerja dan adanya kabel fase yang leleh	Critical Failure	Kerusakan Timer Relay dan kendornya kabel fasa	Timer Relay	Timer Relay	Penggantian Timer Relat dan pengencangan kabel fasa	ldle	3	3	C1 OSED { 72 Agustus 2019}
060/FAILURE/BIN	Batery UPS MCS	Batery UPS MCS Stasium BJN	1 Juli 2007	24 Agustus 2017	Milai impedansi battery lebih dari J mili ohm (mO)	Critical Failure	Kerusakan Batery UPS	Left Time	Left Time	Batery UPS	ldle	3	3	CLOSED (24 Agustus 2019)
061/FAILURE/BIN	AC	PDB Room	1Juli 2007	27 Agustus 2019	Kompresor tidak dingin	Critical Failure	Kerusakan kompresor	kompresor	kompresor	Perbaikan Outdoor AC	idle	1	1	CLOSED (27 Agustus 2019)
062/FAILURE/BIN	USM 1310 A	52-GM-1310A	1 Juli 2007	6-Sep-19	Nilai gas velocity	Critical Failure	Kerusakan Nilai gas velocity pada USM tidak terbaca	nilai gas velocity dan velocity of sound	nilai gas velocity dan velocity of sound	Perbaikan USM 1310 A	ldle	1	ı	CLOSED (6 September 2019)
063/FAILURE/BIN	Lampu TL dan LED	Control Room dan Akomodasi	13uli 2007	19-Sep-19	Lampu terputus	Critical Failure	Kerusakan Lampu	Lampu	Lampu	Pengantian Lampu	idle	1	1	CLOSED (19 September 2019)
064/FAILURE/BIN	Regulator Labung Hellium Gas Chromatograph 52-GC 13478	52-GC-1347B	1Juli 2007	27-Oct-19	Kebocoran pada regulator tabung Hellium gas Chromatograph 52 GC 13478	Incipient Failure	Kerusakan regulator tabuny hellium	Volume Helium dalam tabung cepat berkurang	Volume Helium dalam tabung cepat berkurang	Perbaikan regulator tabung hellium	tdle	1	1	CLOSED (27 Oktober 2019)
065/FAILURE/BJN	Jalur air pompa submersible	MDB Room	13uli 2007	5- Nov-19	Kebocoran di sambungan jahar pipa 1% outlet meter air	Incipient Failure	Kerusakan disambungan jalur pipa 1%	Jalur pipa 1%"	Jalur pipa 1%"	Perbaikan jakir pipa air yang mengalami kebocoran	Nile	1	1	CLOSED (5 November 2019)

066/FAILURE/BIN	Gas Chromatograph B	33-AT-1352B	13uli 2007	14-Nov-19	Terdapat aktif alarm dengan nilai GVH lebih dani 2000 btu/scf	Critical Failure	Kerusakan Gas Chromatograph B	Investigasi dengan melaliukan leak test dan pengecekan parameter pressure	Leak test dan pengecekan parameter pressure	Penggantian Selenoid Valve Ten Port	ldle	1	288	CLOSED (7 Desember 2019)
067/YAJLURE/BIN	Odorizer	52-V-2501	13uli 2007	20 Nov-19	Kebocoran pada Regulator actusation supply gas pada panel NJEX	Incipient Failure	Munculnya Alarm Pump Failure	Supply actuation pressure	Supply actuation pressure	Perbaikan Odoriver 52-V-2501	idle	1	840	CLOSED
068/FAILURE/BIN	Limit Switch 52-BV-1336	52-8V-1336	13uh 2007	21-Nov-19	Blinking Indication	Critical Failure	Kerusakan Limit Switch	Sensor	Sensor	Penggantian Limit Swit Switch 52-HCV-1336	idle	2	2	CLOSED (21 November 2019)
069/FAILURE/BIN	Limit Switch 52-8V-1344	52-8V-1344	13uli 2007	21 Nov-19	Blinking Indication	Critical Failure	Kerusakan Limit Switch	Sensor	Sensor	Penggantian Limit Swit Switch 52-HCV-1344	idle	2	2	CLOSED (21 November 2019)
070/FAILURE/BJN	Regulator tabung Hellium	52-GC-13478	13ub 2007	2 Dec-19	Kebocoran pada regulator tabung Heliam gas Chromatograph	Incipient Failure	Munculnya alarm dengan nilai GVH tinggi	nilai GVH tinggi	Volume Helium dalam tabung cepat berkurang	Perbaikan regulator tabung hellium	idle	1	1	CLOSED (02 Desember 2019)
071/FAILURE/BJN	PCV	1301A	13uli 2007	24 Dec-19	Muncul alarm low pressure pada positioner	Critical Failure	Tidak bisa dilakukan verifikasi dan quick calibration	verifikasi dan quick calibration	verifikasi dan quick calibration	Penggantian Spoot Valve positioner PCV 1301A	idle	1	1	CLOSED (24 Desember 2019)
072/FAILURE/BIN	Odorizer	52-7 5021	1 juni 2008	31 Desember 2019	Overflow	Critical Failure	Tekanan Actuation berlebih	Regulator	Mechanical	Cleaning & Normalization	idle	1	24	CTORED
073/FABURE/BIN	Gas Chromatograph	52-AT-1347 A	1 juni 2008	26 Januari 2020	Total Unnormalize	Critical Failure	Tekanan Carrier Gas	Inhibit Setting	Peak Area	Time event setting	Incipient Failure	1	96	CLOSED
074/FAILURE/BIN	UPSAEG	52-UPS-5010 A	1 juni 2008	27 Januari 2020	Inverter Fault	Critical Failure	Live Time	Inverter	Instrument	Check QI, Fuse & Incoming	Incipient Failure	1	2136	OPEN
075/FAILURE/BIN	H2S Analyzer Unit A	52 AT-1349A	1 juni 2008	15 Februari 2020	Terdapat beberapa anomali (alarm) pada H2S analyzer A	Critical Failure	Umer lampu	Penggantian lampu Cd & Cu	Instrument	Dilakukan Performance Check	Running	1	1680	OPEN
076/FAILURE/BIN	Moisture Generator pada Moisture Analyzer A	52-AT-1348A	1 juni 2008	15 Februari 2020	Terdapat alarm moisture analyzer A	Critical Failure	Umar Dryer, Umar Moisture Generator	Penggantian Dryer, Penggantian Moisture Generator	Instrument	Dilakukan Performance Check	Running	1	1680	OPEN
077/FAILURE/BIN	Mosture Generator pada Mosture Analyzer B	52 AT-13488	1 juni 2008	15 Februari 2020	Terdapat alarm moisture analyzer B	Critical Failure	Umus Dryer, Umur Moisture Generator	Penggantian Dryer, Penggantian Moisture Generator	instrument	Dilahukan Performance Check	Running	1	1680	OPEN
078/FAILURE/BIN	Tanki Storage DEG	52-XA-5020	1 juni 2008	16 Februari 2020	Penurunan pipa 2" outlet tangki solar	Critical Failure	Support pipa solar mengalami penurunan	Perbaikan support atau pemasangan fleksible pipa	Mechanical	Sudah dilakukan pencopotan clamp pada support agar pipa tidak ikut tertarik	Running	1	1656	OPEN
079/FAILURE/BIN	Instalasi Hydrant	Pump Shelter	1 juni 2008	21 Februari 2020	Kebocoran impeller pompa & sensor eror	Critical Failure	Pompa deepwell 01 yang tidak mengeluarkan air	Sensor	Sensor	Dilakukan perbaikan peralatan yang termasuk pada sistem hydrant	Running	1	1536	OPEN
080/FAILURE/BIN	Pressure Transmitter	52-PT-1304 A	1 juni 2008	6 Maret 2020	Nilai Pembacaan Pressure di SCADA Stuck	Critical Failure	Kerusakan Limit Switch	Transmitter	Instrument	Simulation	Running	1	1200	OPEN
081/FAILURE/IUN	Pressure Transmitter	52-PT-1304 B	1 juni 2008	6 Maret 2020	Nilai Pembacaan Pressure di SCADA Stuck	Critical Failure	Kerusakan Limit Switch	Transmitter	Instrument	Simulation	Running	1	1200	OPEN
082/FAILURE/BIN	Panel FM 200	UPS Room	1 juni 2008	22 Maret 2020	Tidak aktifnya heat & smoke detector	Critical Failure	Tidak terdapet power 24 VDC	Heat & smoke detector	Heat & smoke detector	Penggantian Printed Circuit Board (PCB) Fenwalnet 6000	ldle	1	24	CLOSED
083/FAILURE/BIN	Panel FM 200	UPS Room	1 juni 2008	24 Maret 2020	Tidak aktifnya heat & smoke detector	Critical Failure	Tidak terdapet power 24 VDC	Heat & smoke detector	Heat & smoke detector	Penggantian Printed Circuit Board (PCB) Fenwalnet 6000	Running	1	768	CLOSED
084/FAILURE/BIN	Gas Detector	52-F0-1321	I puni 2008	10 April 2020	Muncul alarm	Critical Failure	Sensor yelalu tertriger	Sensor & Transmitter	Instrument	Cleaning Sensor	Idle	1	360	OPEN
OBS/FAILURE/BIN	H25 Analyser A	52 AT-1349 A	1 juni 2008	20 April 2020	Muncul alarm Warning ALC, Warning Auto Setup, Warning Outpuit Range, Warning Zero Drift dan Warning Terrp, Bench sehingga nilai pembacaan H25 Analyzer A hunting	Critical Failure	Pembacaan H25 Hunting	Cu dan Cd Lamp	Cu dan Cd Lamp	Dilakukan penggantian part Cu dan Cd Lamp, 3. Bearing for Cooper Wheel, 4. O ring Motor Cooper Wheel	ldle	1	4	CLOSED
DBG/FAILURE/BJN	H25 Analyzer B	52-AT-1349 B	1 juni 2008	20 April 2020	Muncul alarm Warning ALC, Fault Lamp, Warning Output Range sehingga nilai pembacaan H2S Analyzer B hunting	Critical Failure	Pembacaan H25 Hunting	Cu dan Cd Lamp	Cu dan Cd Lamp	Dilakukan penggantian part Cu dan Cd Lamp	kdle	1	2	ctosep