8574 expander is not working, as it will set the output high initially, which switches on the relay.

ULN2803 accepts Z state as well.
9534 could be a good solution as its initial state is Z
74HC595 is also good, but OE should be connected and pulled up

