

## AD-4326/7 C Settings

- 1. With indicator OFF, press and hold CAL and TARE and press ON, the display will show 0.
- 2. Press 14 and then ENTER, display will show C1.
  Continue entering C settings if you do not need to change the model type.
- 3. To change the model type, Press ENTER, then 14 and then ENTER.
- 4. The display will show C0, set the model type and continue with C settings.
- 5. Turn OFF at any time to store the settings.

C Function	Setting	Description
C0	0	AD 4326A
Model Setting	1	AD 4326B
Prode Setting	2	AD 4327A
	3	AD 4327B
C1	0	Universal
Country Type	1	OIML
Country Type	2	Canada/USA
C2	0	OFF
Imperial lb	1	ON
C3	0	Turn on in both Gross and Net
CZ in Gross Zero	1	Turn on in only Gross
C4	0	Turn on in only Net mode, (except if C6=1)
CZ in Net Zero	<u>0</u> 1	Will not turn on
C5	0	0
Zero suppress	1	00
C6	0	Internal Count
TARE	1	Display count
C7	0	Impossible in Net mode
Push Zero with Tare	1	Enabled in both Net and Gross
C8	0	Enunciator on when Stable
Stable/Motion detect	1	Enunciator on when Motion Detect
C9	0	Enable
Unit Display	1	Disable