HVW-G CF FUNCTION SETTINGS

	Туре	HV 15	HV 60	HV 200	HW 10	HW 60	HW 100	HW 200
CF 2	Triple	1	1	1	0	0	0	0
CF 3	Capacity	0	1	2	0	1	2	3

CF 1	1	
CF 4	0	1 (lbs, oz)
CF 5	0	1 (lbs, oz, lbs & oz)
CF 6	1	
CF 7	1	
CF 8	1	
CF 9	1	
CF 10	0	
CF 11	0	
CF 12	1	
CF 13	1	
CF14	1	0 for HV NSC
CF15	0	

With the display turned off.

Press & Hold <Cal> & <Zero> Keys

Press <On/Off> Key F1 – will be displayed

Press three times <F> Key CF – will be displayed

Press <Mode > Key CF1 – will be displayed

Press <Mode> key to move from CF1 to CF15

Press < Sample> key to change CF value

Press <Mode> key until "END" is displayed.

Press <On/Off> key twice to return to weighing mode.