Entering Check mode

Step 1. Turn off the display.

Step 2. Press and hold the ZERO key and MODE keys and press the ON/OFF key.

Release the MODE and ON/OFF keys while still holding the ZERO key.

Press the MODE key twice.

When the process is made within 2 seconds, the check mode is started.

Step 3. The balance will display the ROM version, product name and all segements.

Exiting Check mode.

Step 1. Press the ON/OFF key when the check mode menu is displayed.

Principle key functions

ON/OFF key Turning on or off the display.

SAMPLE key Selecting a item or changing a target digit (a figure).

ZERO key Changing the parameter.

PRINT key Entering the parameter and proceeding next step.

MODE key Cancel key.

Lnr-2
Ī
\checkmark
Press print key
Lnr 0
Put nothing on the pan.
\downarrow
Press print key
Lnr 1
Put weight A on pan.
Lnr 2
$\overline{\downarrow}$
Put weight B on the pan.
Lnr 3
$\overline{\downarrow}$
Put weight A and B n pan.
End
Remove weight A and B.
Cal out