DEALER DIAGNOSTIC AND EVIDENCE-RECORDING PROCEDURE

BSA LWR Case Welding Area Investigation

VEHICLE	OSe EV
SYSTEM	HV Battery (BSA)

01 INITIAL DIAGNOSIS

CUSTOMER COMPLAINT
Relevant symptoms

→ **READ & RECORD**
BMS DTCs + conditions

→ **SUSPECTED**
BSA water ingress

→ **BSA leak tester available?**

YES → DEDICATED BSA LEAK TESTER PATH

NO → ALTERNATIVE OPEN-BSA / AIR-GUN PATH

02 LEAK LOCALIZATION

YES — DEDICATED BSA LEAK TESTER PATH

1. Apply soapy water to the LWR weld area
2. Perform BSA leak test with dedicated service tool

OBSERVE
Observe the LWR welding area: do air bubbles form?

NO — ALTERNATIVE OPEN-BSA / AIR-GUN PATH

1. Open BSA
2. Inspect for moisture, corrosion, mold, contamination or staining
3. Apply soapy water to the LWR weld area
4. Apply compressed air around the BSA perimeter and observe weld

OBSERVE
Do air bubbles form at the LWR welding area?

03 RESULT & DOCUMENTATION

COMMON RESULT Was leakage localized at the LWR welding area by bubble formation?

YES — LEAKAGE AREA CONFIRMED
Proceed with standard warranty repair

NO — LEAKAGE AREA NOT CONFIRMED
Continue diagnosis per standard warranty procedure

RECORD FOR BOTH OUTCOMES

- ☐ DTCs
- ☐ Complaint conditions
- ☐ Method used
- ☐ Exact location
- ☐ Photos / video