BSA LWR Case Welding Area Investigation

Dealer diagnostic and evidence-recording procedure

VEHICLE
OSe EV

SYSTEM
HV Battery (BSA)

Start / end · Action · Decision · Observation · Record

CUSTOMER COMPLAINT
Relevant symptoms

→ **READ & RECORD**
BMS DTCs + conditions

→ **SUSPECTED**
BSA water ingress

BSA leak tester available?

YES → **DEDICATED BSA LEAK TESTER PATH**

1. Apply soapy water to the LWR weld area
2. Perform BSA leak test with dedicated service tool

Observe the LWR welding area: do air bubbles form?

NO → **ALTERNATIVE OPEN-BSA / AIR-GUN PATH**

1. Open BSA
2. Inspect for moisture, corrosion, mold, contamination or staining
3. Apply soapy water to the LWR weld area
4. Apply compressed air around the BSA perimeter and observe weld

Do air bubbles form at the LWR welding area?

COMMON RESULT
Was leakage localized at the LWR welding area by bubble formation?

YES → **LEAKAGE AREA CONFIRMED**
Proceed with standard warranty repair

NO → **LEAKAGE AREA NOT CONFIRMED**
Continue diagnosis per standard warranty procedure

RECORD FOR BOTH OUTCOMES

☐ DTCs ☐ Complaint conditions ☐ Method used ☐ Exact location ☐ Photos / video