BSA LWR Case Welding Area Investigation

Dealer diagnostic and evidence-recording procedure

VEHICLE **OSe EV** · SYSTEM **HV Battery (BSA)**

INITIAL DIAGNOSIS

CUSTOMER COMPLAINT
Relevant symptoms

READ & RECORD
BMS DTCs + conditions

SUSPECTED
BSA water ingress

BSA leak tester available?

LEAK LOCALIZATION

YES — DEDICATED BSA LEAK TESTER PATH

1. Apply soapy water to the LWR weld area
2. Perform BSA leak test with dedicated service tool

Observe the LWR welding area: do air bubbles form?

NO — ALTERNATIVE OPEN-BSA / AIR-GUN PATH

1. Open BSA
2. Inspect for moisture, corrosion, mold, contamination or staining
3. Apply soapy water to the LWR weld area
4. Apply compressed air around the BSA perimeter and observe weld

Do air bubbles form at the LWR welding area?

RESULT

YES
LEAKAGE AREA CONFIRMED
Proceed with standard warranty repair

COMMON RESULT
Was leakage localized at the LWR welding area by bubble formation?

NO
LEAKAGE AREA NOT CONFIRMED
Continue diagnosis per standard warranty procedure

RECORD FOR BOTH OUTCOMES

- ✓ DTCs
- ✓ Complaint conditions
- ✓ Method used
- ✓ Exact location
- ✓ Photos / video