



Republic of the Philippines
Department of Education
Region VII, Central Visayas
SCHOOLS DIVISION OF TOLEDO CITY

SCHOOL RISK ASSESSMENT REPORT SY 2025-2026

School Name: **Landahan Elementary School**
School ID: **120746**
Address: Landahan, Toledo City
Date of Assessment: April 17, 2026
Prepared by: Hannah P. Abasa
Designation: Administrative Officer

SCHOOL PROFILE

Total Land Area 4488 square meters

No. of Buildings 4

No. of Classrooms 9 FUNCTIONAL
(7 used for learners' classroom,
1 converted to principal office / faculty room)
1 converted to school library / IT room)

0 NON FUNCTIONAL

Enrollment 109 Male
107 Female
216 Learners: SY 2025 - 2026

Personnel 8 Teaching
2 Non-Teaching

SPED Learners None


SUMMARY OF HAZARDS IDENTIFIED

Quick Guide

	LOW - SAFE / NOT urgent
	MEDIUM - Needs Attention
	HIGH - Act immediately




Republic of the Philippines
Department of Education
 Region VII, Central Visayas
SCHOOLS DIVISION OF TOLEDO CITY

AREA / LOCATION	TYPE OF HAZARD	DESCRIPTION OF HAZARD	RISK LEVEL	POSSIBLE IMPACT	EXISTING MEASURES	RECOMMENDED ACTION	TIME LINE
Marcos Pre Fab Building	Structural Hazard / Condemnable Building Hazard	The Marcos Pre-Fab Building was constructed in 1970 and has significantly deteriorated due to its age and prolonged use. The building has already been identified and subjected for demolition because of its weakened structural condition; however, it is still currently being utilized by the school due to lack of available classrooms and limited school facilities. Visible signs of deterioration such as weakened walls, roofing issues, corroded materials, and structural instability may already be present	 Yellow	Possible impacts include structural collapse, falling debris, injuries to learners and school personnel, disruption of classes, damage to school property, and increased vulnerability during earthquakes, strong winds, and heavy rains. The continued use of the building may pose serious safety risks to occupants.	The school continuously monitors the condition of the building and implements precautionary measures to minimize risks to learners and personnel. Temporary repairs and regular inspections are conducted whenever necessary while awaiting further action from concerned authorities.	It is strongly recommended that the Marcos Pre-Fab Building be immediately assessed by the Schools Division Engineer and other concerned authorities for possible demolition, rehabilitation, or replacement. Alternative learning spaces or temporary classrooms should also be identified to ensure the safety of learners and personnel. Coordination with the Local Government Unit (LGU), Division Office, and other government agencies for funding and infrastructure support is likewise recommended.	To Be Determined implementation of demolition, rehabilitation, or replacement measures remains subject to technical assessment, approval, and availability of funds from concerned agencies.




Republic of the Philippines
Department of Education
 Region VII, Central Visayas
SCHOOLS DIVISION OF TOLEDO CITY

Librinica Building	Structural Hazard / Building Safety Hazard	The Librinica Building is an old wooden structure currently being utilized by the school for ICT and Library. Portions of the building already show signs of deterioration due to prolonged use and exposure to weather conditions. The ceiling requires immediate repair as some areas are already damaged and weakened, posing potential safety risks to learners and school personnel. Being primarily constructed from wood, the building is also vulnerable to decay, termite infestation, and structural weakening over time.	 Yellow	Possible impacts include falling ceiling materials, injuries to learners and personnel, disruption of classes, deterioration of the building structure, and increased vulnerability during strong winds, heavy rains, and earthquakes. Continued use without repair may further compromise the safety and stability of the building.	The school continuously monitors the condition of the building and conducts minor repairs and maintenance whenever possible. Teachers and school personnel also ensure that learners avoid unsafe portions of the classroom while awaiting necessary repairs and assistance from concerned offices.	It is recommended that the damaged ceiling and other weakened portions of the Librinica Building be immediately repaired to ensure the safety of learners and school personnel. Regular structural assessment and maintenance should also be conducted, particularly on wooden components vulnerable to deterioration and termite infestation. Coordination with the Schools Division Engineer, Local Government Unit (LGU), and other concerned agencies for possible rehabilitation or upgrading of the building is likewise recommended.	To Be Determined Determined. Repair and rehabilitation measures remain subject to technical assessment, approval, and availability of funds from the School MOOE.
Non Operational Classroom	Structural Hazard / Construction Hazard	The unfinished room/building structure within the school premises remains incomplete and		Possible impacts include minor to moderate injuries caused by	The school continuously reminds learners to avoid the unfinished area and	It is recommended that the unfinished room/building be secured through installation of temporary barriers,	To Be Determined.



Republic of the Philippines
Department of Education
 Region VII, Central Visayas
SCHOOLS DIVISION OF TOLEDO CITY

		lacks essential structural components and safety features. Exposed construction materials, unfinished walls, uneven surfaces, and open areas may pose potential hazards to learners and school personnel, especially when the area is accessible during school activities.	Yellow	accidental slips, trips, falls, contact with exposed materials, and unauthorized entry into the unfinished area. The unfinished structure may also become unsafe during heavy rains and strong winds	conducts regular monitoring to ensure safety within the school premises. Temporary safety precautions and restricted access measures are also implemented whenever necessary.	warning signs, and restricted access measures to prevent accidents. Immediate completion, repair, or rehabilitation of the structure should also be prioritized through coordination with the Schools Division Office, LGU, and other concerned agencies. Regular monitoring and maintenance should be conducted while the structure remains unfinished.	Completion and rehabilitation measures remain subject to technical assessment, approval, and availability of funds from concerned agencies.
Old Stage	Safety Hazard	The old stage within the school premises is currently being used as a storage and dumping area for old chairs, damaged furniture, unused equipment, and other materials. Due to the deteriorating condition of the structure and the improper stacking and storage of heavy objects, the area poses serious	 Red	Possible impacts include serious injuries caused by falling or collapsing materials, accidents involving learners entering the area, damage to school property, obstruction during emergencies, and increased risks	The school continuously reminds learners to stay away from the old stage area and conducts regular monitoring of the structure and stored materials. Temporary precautionary measures and restricted access are	It is strongly recommended that the old stage be immediately cleared of unused chairs, damaged furniture, and other unnecessary materials to minimize safety risks. The structure should also undergo immediate assessment by the Schools Division Engineer for possible repair, rehabilitation, or demolition if deemed	Immediate clearing and securing of the area is recommended, while repair, rehabilitation, or demolition measures remain subject to technical



Republic of the Philippines
Department of Education
Region VII, Central Visayas
SCHOOLS DIVISION OF TOLEDO CITY

		safety hazards to learners and school personnel. The unstable condition of the old stage and accumulated materials may potentially collapse or fall, especially during strong winds, heavy rains, or accidental contact by learners.		during severe weather conditions and earthquakes.	also implemented whenever possible.	unsafe. Installation of warning signs, safety barriers, and designation of a proper storage facility for school equipment are likewise recommended to ensure the safety of learners and school personnel.	assessment, approval, and availability of funds from concerned agencies.
--	--	--	--	---	-------------------------------------	---	--

Prepared by:

HANNAH P. ABASA

School DRRM Coordinator

Reviewed and Checked by:

NARCISO M. MORALES JR.

School Head



Republic of the Philippines
Department of Education
 Region VII, Central Visayas
SCHOOLS DIVISION OF TOLEDO CITY

SCHOOL WATCHING CHECKLIST

	Broken window	✓	Broken/dilapidated ceiling
✓	Slippery pathway	✓	Open/incomplete perimeter fence
	Blocked corridor	✓	Presence of stray animals inside the school campus
	Heavy objects mounted on top of cabinets/shelves		Presence of electrical post/transformer near or within the school perimeter
	Flooded area		No system of release to parents during emergencies
✓	Busted plugs/light bulbs/electrical facilities		No posted emergency hotlines around the school
	Exposed electrical wires	✓	Garbage Area (Segregation of Biodegradable and Non-Biodegradable)
✓	Protruding nails in chairs and tables		Detached or peeled off GI sheet
✓	Broken door knobs	✓	Broken toilet bowl and/or sinks
	Warning sign: Slippery pathways/corridors	✓	Broken chairs/desks/tables
	Plants mounted on the building railings		Blocked/no emergency exits
	Flooding	✓	Unmounted cabinets/shelves
	Exposed chemicals and liquids		Medical kits in every classroom
✓	Lack/absence of storage for equipment		Bells / alarms
	Unlabeled chemicals	✓	Condemnable building (i.e. very old structure, collapsing building and/or prominent cracks on classroom walls)
✓	Dripping ceiling		Open/Clogged canals
	Open pit	✓	No ramps for elevated school buildings or other facilities
	Stagnant water		Swing-in doors
	Unpruned trees/bushes/shrubs		