EIGHTY-AID
Markus Dellinger
Leistenstr. 3
97082 Würzburg/Germany

Fon: +49 931 783250
Fax: +49 931 783225
email: help@eighty-aid.com(bevorzugt)
http://www.eighty-aid.com

USt-ID: DE 168254679
Rechnungsdatum ist Lieferdatum

EIGHTY AID | Leistenstr. 3 | D-97082 Würzburg
customer #16913 | fork .# 30244 LEFTY OCHO Carbon 100, Ticketno. 20032...

Tobias BjörkgrenAB
Körlingevägen 51
18691 Vallentuna
Sweden

Date	15.05.2025
Customer-No.	16913
Your VAT	SE559295649301
Fork #	30244
Fork-Model	LEFTY OCHO Carbon 100, Ticketno. 200323319
color	black
Radgröße	29"

Invoice 87364

	Article	unit price	units	Eur
01	200h Service hybrid spätestens nach 2 Jahren(Teleskope zerlegen, reinigen, Neuaufbau- Luftdichtungen erneuern), Telescope disassemble, clean, complete rebuild- damper air chamber service	200,00 €	1	200,00 €
02	Innerleg Ocho 29"- Gabelfuß /Standrohr-100m, 55mm Offset/Versatz	0,00 €	1	0,00 €
03	Lefty Ocho Bushing assembly and wiper seal	0,00 €	1	0,00 €
04	Versand und Verpackung	0,00 €	2	0,00 €

amount **200,00 €**

form of Payment **Moneytransfer/cash in advance**

Total **200,00 €**

The 200h hybrid Service or latest after two years (whichever comes first) -
The damper was tested for function- we changed the oil and the air seals. We disassembled the telescope, cleaned all parts, rebuilt fully(use new needle bearing and races) , greased it and made a reset. The telescope tolerance was optimized for a smoother performance.
We also changed the lower collar including glide bushing and wiper seal+ Innerleg (has elox fatigue) under warranty.
Attension: Please don´t use the RSP hybrid Set - you don´t need it after our change from oil to grease of the telescope.
If you don´t use the full travel of the fork- there will be No autoreseting of the telescope.
(look for o-ring! on spindle)- just a short info- we mounted two o-Ring the lower reflects the maximum of travel and the one on top reflects the actual use of the travel. We always recommend to positon the one on top on the hightest point before your ride- so you can check the travel after every ride!
Please make latest every 50h the reset of the telescope or as needed!

After use, an oil/grease film may appear on the surface of the Innerleg /Stanchion. This oil film is necessary for lubricating the lip seal of the dust cap - this must cover the entire range of outside temperatures - this lubricating film can become more pronounced due to warm outside conditions.
The excess oil film should be removed after driving for the first few weeks after the service. If this is not removed regularly, the impression of a leak may arise.(also to avoid brake contamination)

siehe nächste Seite ...

Date	15.05.2025
Invoice #	87364

Wir wünschen

viele HAPPY TRAILS 2025!

mit freundlichen Grüßen,

Ihr Eighty-Aid Team

Markus & Harald