EIGHTY-AID
Markus Dellinger
Leistenstr. 3
97082 Würzburg/Germany

Fon: +49 931 783250
Fax: +49 931 783225
email: help@eighty-aid.com(bevorzugt)
http://www.eighty-aid.com

USt-ID: DE 168254679
Rechnungsdatum ist Lieferdatum

EIGHTY AID | Leistenstr. 3 | D-97082 Würzburg
customer #18214 | fork .# 32615 LEFTY OCHO Carbon 120, Ticketno. 20035...

Meija Kristaps
Zeltinu street 59
LV-2167 Marupe
Latvia

Datum	19.08.2026
Kunden-Nr.	18214
Ihre USt ID	
Gabel-Nr.	32615
Gabel	LEFTY OCHO Carbon 120, Ticketno. 2...
Farbe	carbon
Radgröße	29"

Rechnung 88106 Kopie

	Artikel	Einzelpreis	Menge	USt	Eur
01	Systemdiagnose	17,64 €	1	19%	17,64 €
02	200h Service hybrid spätestens nach 2 Jahren(Teleskope zerlegen, reinigen, Neuaufbau- Luftdichtungen erneuern), Telescope disassemble, clean, complete rebuild- damper air chamber service	200,00 €	1	19%	200,00 €
03	Innerleg Ocho 29"- Gabelfuß/Standrohr -110/ 120mm- 50mm Offset/Versatz	0,00 €	1	19%	0,00 €
04	Versand und Verpackung	0,00 €	1	19%	0,00 €

Gesamt	**217,64 €**
19% USt	**41,35 €**
Gesamtbetrag	**258,99 €**

Zahlungsweise per: **Moneytransfer/cash in advance**

The 200h hybrid Service or latest after two years (whichever comes first) -
The damper was tested for function- we changed the oil and the air seals. We disassembled the telescope, cleaned all parts, rebuilt fully(use new needle bearing and races) , greased it and made a reset. The telescope tolerance was optimized for a smoother performance.
We also changed the lower collar including glide bushing and wiper seal.+ Innerleg pos3. (goodwill).
-> we also reduced the air chamber for more progression- please make a new setup!
Attension: Please don´t use the RSP hybrid Set - you don´t need it after our change from oil to grease of the telescope.
If you don´t use the full travel of the fork- there will be No autoreseting of the telescope.
(look for o-ring! on spindle)- We always recommend to positon the one on top on the hightest point before your ride- so you can check the travel after every ride!
Please make latest every 50h the reset of the telescope or as needed!

After use, an oil/grease film may appear on the surface of the Innerleg /Stanchion. This oil film is necessary for lubricating the lip seal of the dust cap - this must cover the entire range of outside temperatures - this lubricating film can become more pronounced due to warm outside conditions.
The excess oil film should be removed after driving for the first few weeks after the service. If this is not removed regularly, the impression of a leak may arise.(also to avoid brake contamination)

siehe nächste Seite ...

Datum	19.08.2026
Rechnung #	88106 Kopie

We wish HAPPY TRAILS .

mit freundlichen Grüßen,

Ihr Eighty-Aid Team

Markus & Harald