

Northstar Edge Controller - Product Support Manual

Document ID: NS-EDGE-SUP-4.2

DOCUMENT OVERVIEW

Controlled troubleshooting guidance for Northstar Edge Controller hardware, sensor links, motor feedback, and display behavior.

TRAINING DATA NOTICE

This fictional document was created for the Advanced Retrieval Methodologies lesson. It contains overlapping concepts, exact identifiers, and detailed procedures so different retrieval methods can be compared.

SECTION 1 - NX-417 SENSOR LINK LOSS

NX-417 means the controller stopped receiving a valid heartbeat from the primary position sensor for more than 1.5 seconds.

Recognizing the fault

The operator panel shows NX-417 and places the affected axis in a safe hold. The event log may also record intermittent sensor voltage or a missing heartbeat. Do not confuse NX-417 with NX-471, which indicates a motor feedback disagreement after motion begins.

Common causes include a loose M12 sensor connector, moisture inside the harness, or a sensor that was reconnected before stored charge left the input circuit.

Recovery procedure

Stop the line and apply the approved lockout procedure. Inspect the sensor body and cable before touching the connector. Disconnect the primary position sensor at port J7. Wait 90 seconds before reconnecting the sensor harness. The delay allows the input circuit to discharge and prevents an immediate false heartbeat failure.

- Reconnect the J7 harness until the locking ring clicks.
- Restore power and open Diagnostics > Sensors > Primary Position.
- Confirm that heartbeat status remains Stable for 30 seconds.
- Clear NX-417 and run the axis verification cycle at reduced speed.

Escalate the incident if NX-417 returns twice during the same shift or if sensor voltage remains below 22.8 V.

SECTION 2 - NX-471 MOTOR FEEDBACK MISMATCH

NX-471 indicates that commanded motor movement and encoder feedback differ beyond the allowed tolerance.

Difference from NX-417

NX-471 occurs after a motion command and normally points to the motor encoder, coupling, or mechanical load. NX-417 occurs before safe motion can continue because the position sensor heartbeat has disappeared. The recovery steps are not interchangeable.

Inspection sequence

Record the commanded position and measured encoder position from the event log. Check the flexible coupling for movement, then inspect the encoder cable at port J9. If the mismatch exceeds 2.0 degrees after the coupling is secured, replace the encoder and repeat calibration.

- Do not reset calibration values before exporting the diagnostic bundle.
- Do not apply the 90-second J7 discharge step to an NX-471 event.
- Escalate repeated mismatch events to Motion Systems Engineering.

Verification

A successful repair produces three reduced-speed cycles with less than 0.5 degrees of position difference. Attach the verification log to the service record.

SECTION 3 - DISPLAY AND POWER BEHAVIOR

Normal display sleep, firmware-related dark-screen behavior, and full controller power loss require different checks.

Normal display sleep

The operator display dims after five minutes without input and turns off after fifteen minutes when no alarm is active. Touching the screen or pressing the wake key should restore the interface within two seconds. This behavior does not stop the controller process.

Unexpected dark screen

If the display remains dark while the status ring stays cyan, the controller is still running. Check the installed firmware version before replacing hardware. Firmware 4.8.0 has a known display sleep regression documented in the Firmware Release Notes. Firmware 4.8.2 corrects that issue.

A cyan status ring with a dark screen points to the display software path. No status ring points to power or controller hardware.

Evidence to capture

Record the firmware version, status-ring color, time since the last operator input, and whether remote monitoring remains available. These details separate a display-only problem from a controller outage.