

Northstar Edge Controller - Firmware Release Notes

Document ID: NS-EDGE-FW-4.8

DOCUMENT OVERVIEW

Release history and known issues for firmware versions 4.8.0 through 4.8.3 on the Northstar Edge Controller.

TRAINING DATA NOTICE

This fictional document was created for the Advanced Retrieval Methodologies lesson. It contains overlapping concepts, exact identifiers, and detailed procedures so different retrieval methods can be compared.

SECTION 1 - VERSION 4.8.0 KNOWN ISSUE UI-204

Version 4.8.0 can leave the operator screen dark after automatic display sleep even though the controller remains online.

Observed behavior

Some displays do not process the first wake event after fifteen minutes of inactivity. Operators describe the symptom as a screen that keeps going dark after the update. The cyan status ring remains illuminated, remote monitoring continues, and production logic is unaffected.

The issue is tracked as UI-204: display wake event lost after idle transition. It affects firmware 4.8.0 on display hardware revisions C2 and C3.

Temporary workaround

Press and hold the wake key for three seconds. If the screen does not return, use remote monitoring to confirm that the controller remains healthy, then restart only the display module from the service menu. Do not cycle the entire production controller for UI-204.

Install firmware 4.8.2 or later for the permanent correction. Hardware replacement does not resolve UI-204.

Identification

UI-204 does not create NX-417 or NX-471. If either code is present, follow the matching hardware procedure in the Product Support Manual.

SECTION 2 - VERSION 4.8.2 DISPLAY FIX

Version 4.8.2 restores reliable display wake behavior and preserves the normal fifteen-minute sleep policy.

Correction

The display service now queues a second wake event when the panel leaves its lowest-power state. Internal testing completed 1,200 sleep and wake cycles across display revisions C2 and C3 without reproducing UI-204.

Update procedure

Export the current configuration, confirm at least 40 percent backup power, and install the signed 4.8.2 package. The update restarts the display module and communication service but preserves controller configuration and calibration values.

- Allow approximately six minutes for installation.
- Confirm that the displayed version reads 4.8.2 after restart.
- Test one manual sleep and wake cycle before returning the station to service.

Post-update check

If the screen stays dark after 4.8.2, capture the display revision and diagnostic bundle. Treat the event as a separate hardware or power issue rather than UI-204.

SECTION 3 - VERSION 4.8.3 SENSOR TELEMETRY

Version 4.8.3 adds clearer sensor-heartbeat telemetry without changing the NX-417 recovery procedure.

Telemetry changes

The diagnostics page now shows heartbeat age, input voltage, and the last five connection transitions for ports J7 and J9. These fields help technicians separate intermittent cabling from a failed sensor.

No procedural change

Firmware 4.8.3 improves evidence collection but does not change the controlled NX-417 recovery sequence. Technicians must still disconnect J7, wait 90 seconds, reconnect the harness, and verify a stable heartbeat before clearing the code.

Do not shorten the discharge interval because the new telemetry page updates faster.

Compatibility

The release supports controller revisions B through D and display revisions C2 through C4. Older display hardware continues to use the standard service interface.