

STANDARD OPERATING PROCEDURE

SOP-Pump-Maintenance-2025: High Vibration Overhaul Protocol

Document Ref: SOP-PLANT-2025-V4 | **Effective Date:** Jan 15, 2025

Section 4.2 Emergency Overhaul Thresholds

Whenever measured vibration on high pressure feedwater pumps exceeds **7.0 mm/s RMS**, maintenance engineers must immediately trigger a Category 2 Emergency Shutdown.

Required Overhaul Steps:

1. Obtain formal Maintenance Approval Note signed by Maintenance Lead.
2. Verify LOTO isolation on high pressure feedwater valves HV-104 and pump power unit.
3. Clean and backflush Suction Strainer ST-01.
4. Inspect sleeve bearing B-102-BRG for tolerance wear and replace sleeve if clearance > 0.15mm.