Structure No. 00-000-0000-00-001 Facility Carried: Sample Road over Example Creek
Inspection Type: Routine Inspector: Inspector A (synthetic)

ROUTINE BRIDGE INSPECTION REPORT

Inspection Date: 06/12/2025 Year Built: 1978 Spans: 3

Condition Ratings

Deck:	6
Superstructure:	6
Substructure:	5
Channel:	6
Culvert:	N

Special Inspection Needed: No
Load Posting: Not required

Structure No. 00-000-0000-00-001 Facility Carried: Sample Road over Example Creek
Inspection Type: Routine Inspector: Inspector A (synthetic)

Element Condition Summary

Element / Component	Rating	Comment
Deck - Concrete	6	Longitudinal cracking with efflorescence near Bent 2.
Beams - Prestressed	6	Hairline crack at midspan of Beam 3.
Bent Caps - Concrete	5	Spall with exposed rebar at Bent 2 cap, about 2 sq ft.
Bearings - Elastomeric	7	Slight bulging at Bent 2.
Channel - Riprap	6	Riprap partially displaced at Abutment 1.

Notes: Ratings reflect the worst condition observed for each component.

Structure No. 00-000-0000-00-001 Facility Carried: Sample Road over Example Creek
Inspection Type: Routine Inspector: Inspector A (synthetic)

Recommended Maintenance

Item	Location	Priority	Action
1	Bent 2 cap	High	Patch spall; clean and coat exposed rebar
2	Deck	Medium	Seal longitudinal cracks
3	Abutment 1	Medium	Replace displaced riprap