---
doc_id: pdf-sb-2025-11
title: Service Bulletin SB-2025-11 (PDF)
model: X100
doc_type: service_bulletin
version: 1.0
section: E-204 Fan Connector Batch Issue
page: 2

Affected X100 units built between January 2024 and September 2024 may develop high contact resistance at fan connector XF3 in hot and humid sites.

Recommended action:

1. Inspect XF3 for oxidation, pushed-back pins, or burning.
2. Replace the harness with improved part HARN-XF3-02 when affected.
3. If F3 is open, check fan motor current before replacing the fuse.
4. Record the connector batch number in the work order.