---
doc_id: pdf-x100-manual-7-3
title: X100 Service Manual (PDF)
model: X100
doc_type: manual
version: v3.2
section: 7.3 Cooling Fan and Overheat Protection
page: 84
---

## 7.3 Cooling Fan and Overheat Protection

The X100 compressor trips E-204 when outlet water temperature exceeds 95 C and the cooling fan feedback is below 50 rpm while the command is above 90 percent.

Check the following items in order:

1. Lock out and tag out (LOTO) the main power.
2. Inspect fan connector XF3 for loose or burnt pins.
3. Measure F3 fuse continuity; replace with a 5 A slow-blow fuse if open.
4. Manually rotate the fan; replace fan assembly FAN-12038 if seized.

Never hot-plug the fan connector. Confirm the fan has stopped before service.