

Preventive Maintenance Schedule - Line 2

Preventive maintenance (PM) keeps equipment reliable and prevents the breakdowns that cause unplanned downtime. Follow this schedule; record completion in the maintenance log.

VMX-500 CNC Mill

- Daily: check coolant level, air pressure 6 bar, run 8-min warm-up.
- Weekly: check way-oil reservoir, coolant concentration 6-8%, clean chip tray and filter.
- Every 500 hours: grease X/Y/Z ballscrew bearings (NLGI 2), replace coolant filter.
- Every 3 months: replace coolant, inspect spindle drive belt tension.

BX-200 Conveyor

- Daily: check belt tracking, listen for abnormal noise, confirm guards.
- Weekly: inspect rollers, check take-up tension, clear debris.
- Monthly: gearmotor oil level, belt wear, bolt torque.
- Every 1,000 hours: replace worn idlers, inspect drive lagging.

Rules

- Apply lockout/tagout (LOTO-01) before any task inside a guard.
- Use only calibrated tools and OEM spare parts.
- Log every PM with date, technician, and downtime.

Escalation

Overdue PM or a fault found during PM: raise a work order to the maintenance supervisor (ext. 4500).