

CMM-Inspection — Calibration & Operating Procedure

CMM-Inspection — Calibration & Operating Procedure

1. Purpose
2. Normal operating envelope
3. Idle reasons
4. Faults & corrective actions
5. Preventive maintenance schedule
6. References

CMM-Inspection — Calibration & Operating Procedure

Audience: Maintenance Tech · Quality Worker · Line Manager
Applies to: Line-A, station 5, CMM-Inspection (Coordinate Measuring Machine)

1. Purpose

CMM-Inspection is the final station of Line-A and the quality gate for the entire precision machining cell. It verifies dimensional tolerances on every part before release. Because its ideal cycle time (60 s) is the longest on the line, it is the **bottleneck** — any extra delay here directly caps line throughput and pushes blocked state back through stations 1–4.

2. Normal operating envelope

- Ideal cycle time: **60 s** (bottleneck)
- Max acceptable cycle time: **72 s**
- Expected reject rate: **≤ 5 %**
- Fault probability per cycle: **0.4 %**
- Input buffer capacity: **5 parts**

3. Idle reasons

idle_reason	Meaning here	First check
Starved	Deburring-Station (station 4) is not feeding parts.	Verify deburring state.
Blocked	Final part-out conveyor is full.	Verify the line discharge.

4. Faults & corrective actions

4.1 Probe-Calibration

- **Symptoms in telemetry:** fault_type = "Probe-Calibration". Rejects often jump just before the fault as the probe drifts.

- **Likely root cause:** probe stylus is bent, cross-axis ruby has worn, or thermal drift has shifted the touch trigger force.
- **Corrective action:**
 1. Run the **probe qualification cycle** against the master sphere.
 2. If qualification error > 2 µm, replace the stylus and re-qualify.
 3. Reset the part coordinate frame using the alignment datum holes.
- **Restart criteria:** master sphere qualification error ≤ 2 µm.

4.2 Air-Supply

- **Symptoms in telemetry:** fault_type = "Air-Supply". CMM bearings are air-bearing — without supply the machine cannot home.
- **Likely root cause:** compressed air pressure dropped below 80 psi at the CMM inlet, or air dryer failure produced moisture trip.
- **Corrective action:**
 1. Confirm shop-air pressure at the CMM regulator; target 90 psi.
 2. Check the inlet filter / dryer; drain condensate trap.
 3. If the dryer tripped, allow recovery before re-energizing.
- **Restart criteria:** stable 90 ± 5 psi for 5 minutes with no moisture alarm.

4.3 Sensor-Fail

- **Symptoms in telemetry:** fault_type = "Sensor-Fail". CMM may home short, drop axes, or report touch-misses on a known-good part.
- **Likely root cause:** scale read-head failure or probe interface cable intermittent.
- **Corrective action:**
 1. Cycle CMM power; check error log for axis fault codes.
 2. Inspect read-head cables for damage; reseal at controller.
 3. Replace the failed read-head; recalibrate that axis.
- **Restart criteria:** axis accuracy check passes within 2 µm.

5. Preventive maintenance schedule

- **Daily:** thermal soak (CMM must run for 30 minutes before inspection starts on a cold morning).
- **Weekly:** clean granite table; check air filter; run probe qualification.
- **Monthly:** full ball-bar test; replace air dryer desiccant.
- **Annually:** ISO 10360 volumetric accuracy certification by an external calibration lab.

6. References

- Maintenance_Workflow_Overview.pdf
- Quality_Reject_Disposition_Policy.pdf
- Line-A_04_Deburring-Station_SOP.pdf
- Production_Lines_Reference.pdf