

Trimming-Station — Standard Operating Procedure

Trimming-Station — Standard Operating Procedure

- 1. Purpose
- 2. Normal operating envelope
- 3. Idle reasons
- 4. Faults & corrective actions
- 5. Preventive maintenance schedule
- 6. References

Trimming-Station — Standard Operating Procedure

Audience: Maintenance Tech · Line Manager · Quality Worker
Applies to: Line-B, station 3, Trimming-Station

1. Purpose

The Trimming-Station removes excess flash and flange material left after the Hydraulic-Press deep-draw, leaving a clean periphery for the final Quality-Inspection check.

2. Normal operating envelope

- Ideal cycle time: **10 s**
- Max acceptable cycle time: **14 s**
- Expected reject rate: **≤ 2 %**
- Fault probability per cycle: **0.4 %**
- Input buffer capacity: **5 parts**

3. Idle reasons

idle_reason	Meaning here	First check
Starved	Hydraulic-Press (station 2) is not feeding parts.	Verify Hydraulic-Press state — most common cause of Starved on Line-B.
Blocked	Quality-Inspection (station 4) cannot accept the trimmed part.	Verify Quality-Inspection state.

4. Faults & corrective actions

4.1 Blade-Dull

- **Symptoms in telemetry:** `fault_type = "Blade-Dull"`. Quality-Inspection flags edge-finish defects in the cycles leading up to the fault.

- **Likely root cause:** trimming blade has reached the end of resharpening service life.
- **Corrective action:**
 1. LOTO. Remove and inspect each blade segment.
 2. Send for resharpening or install a fresh blade set.
 3. Re-set cut depth against the master gauge.
- **Restart criteria:** burr height ≤ 0.05 mm on three test parts.

4.2 Guard-Trip

- **Symptoms in telemetry:** fault_type = "Guard-Trip". Safety door or light-curtain interrupted mid-cycle.
- **Likely root cause:** light-curtain misalignment, door latch wear, or an operator reach-in during cycle.
- **Corrective action:**
 1. Reset the safety controller and acknowledge the fault per local EHS procedure.
 2. Verify the trigger source from the safety log (door, curtain, e-stop).
 3. If recurring on the same channel, inspect the sensor wiring.
- **Restart criteria:** safety system passes the daily verification cycle.

4.3 Alignment-Shift

- **Symptoms in telemetry:** fault_type = "Alignment-Shift". Uneven trim geometry; sudden jump in reject rate.
- **Likely root cause:** part-locating fixture has shifted; clamp pressure drift.
- **Corrective action:**
 1. LOTO. Verify fixture pin location.
 2. Re-torque the fixture base bolts to spec.
 3. Validate trim contour against a CMM-checked master.
- **Restart criteria:** trim contour passes the master comparison check.

5. Preventive maintenance schedule

- **Daily:** blade visual check; clear scrap chute.
- **Weekly:** clamp-pressure verification; fixture pin gauge.
- **Monthly:** blade replacement / resharpening cycle.
- **Quarterly:** safety system function test.

6. References

- Maintenance_Workflow_Overview.pdf
- Safety_Lockout_Tagout_Procedure.pdf
- Line-B_02_Hydraulic-Press_Maintenance_SOP.pdf
- Line-B_04_Quality-Inspection_SOP.pdf