

Component-Loader — Standard Operating Procedure

Component-Loader — Standard Operating Procedure

- 1. Purpose
- 2. Normal operating envelope
- 3. Idle reasons
- 4. Faults & corrective actions
- 5. Preventive maintenance schedule
- 6. References

Component-Loader — Standard Operating Procedure

Audience: Maintenance Tech · Line Manager **Applies to:** Line-C, station 1, Component-Loader

1. Purpose

The Component-Loader is the entry point of Line-C (Welding & Assembly). It feeds raw components from a vibratory bowl / hopper onto the line for the Welding-Robot. As station 1, every downstream station starves when this loader stops.

2. Normal operating envelope

- Ideal cycle time: **10 s**
- Max acceptable cycle time: **13 s**
- Expected reject rate: **0 %**
- Fault probability per cycle: **0.1 %**
- Input buffer capacity: **5 parts**

3. Idle reasons

idle_reason	Meaning here	First check
Starved	Hopper is empty or operator has not staged components.	Refill component magazine; check Production Schedule.
Blocked	Welding-Robot (station 2) output buffer is full.	Verify Welding-Robot state.

4. Faults & corrective actions

4.1 Feed-Jam

- **Symptoms in telemetry:** fault_type = "Feed-Jam". Loader stops feeding; downstream Welding-Robot reports Starved.
- **Likely root cause:** component bridged in the feeder track, or a misshapen part lodged at the pickoff.

- **Corrective action:**
 1. LOTO. Clear the jammed component from the track.
 2. Inspect the track for wear; smooth any galled surfaces.
 3. Verify bowl amplitude per recipe.
- **Restart criteria:** 20 cleanly delivered components.

4.2 Sensor-Block

- **Symptoms in telemetry:** `fault_type = "Sensor-Block"`. The pick-position detector is reporting "part present" continuously even when empty.
- **Likely root cause:** photo-eye is fouled with dust or has misaligned.
- **Corrective action:**
 1. Clean the sensor face.
 2. Realign the sensor against the reflector / target.
 3. Verify trigger margin in the diagnostic.
- **Restart criteria:** sensor reads clean transitions on 10 cycles.

4.3 Hopper-Empty

- **Symptoms in telemetry:** `fault_type = "Hopper-Empty"`. The bowl level switch tripped; this is operationally distinct from `idle_reason = Starved` only because the simulator raised it as a fault.
- **Likely root cause:** kit shortage; missed material request; bulk run longer than planned.
- **Corrective action:**
 1. Refill the hopper to the upper level mark.
 2. Confirm operator has the component lot number captured for traceability.
 3. Reset the level fault.
- **Restart criteria:** continuous feed for 5 cycles.

5. Preventive maintenance schedule

- **Daily:** clean photo-eye lenses; check hopper level.
- **Weekly:** lubricate feeder track guides.
- **Monthly:** replace track liner if grooved.
- **Quarterly:** vibratory bowl spring set inspection.

6. References

- Maintenance_Workflow_Overview.pdf
- Line-C_02_Welding-Robot_SOP.pdf
- Production_Lines_Reference.pdf