

Weld-Inspection — NDT Procedure

Weld-Inspection — Non-Destructive Testing (NDT) Procedure

- 1. Purpose
- 2. Normal operating envelope
- 3. Idle reasons
- 4. Faults & corrective actions
- 5. Preventive maintenance schedule
- 6. References

Weld-Inspection — Non-Destructive Testing (NDT) Procedure

Audience: Quality Worker (primary) · Maintenance Tech · Line Manager
Applies to: Line-C, station 3, Weld-Inspection

1. Purpose

Weld-Inspection performs non-destructive testing (X-ray and ultrasonic) on every welded subassembly leaving station 2. This station has the most varied reject codes on Line-C and gates parts before Fastening at station 4. Reject disposition follows `Quality_Reject_Disposition_Policy.pdf`.

2. Normal operating envelope

- Ideal cycle time: **30 s**
- Max acceptable cycle time: **38 s**
- Expected reject rate: **≤ 4 %**
- Fault probability per cycle: **0.5 %**
- Input buffer capacity: **5 parts**

3. Idle reasons

idle_reason	Meaning here	First check
Starved	Welding-Robot (station 2) is not feeding parts.	Verify Welding-Robot state.
Blocked	Fastening-Station (station 4) cannot accept the inspected part.	Verify Fastening state.

4. Faults & corrective actions

4.1 X-Ray-Tube-Fault

- **Symptoms in telemetry:** `fault_type` = "X-Ray-Tube-Fault". Image quality drops or imaging stops; reject rate may swing wildly.

- **Likely root cause:** X-ray tube reached end of life, or high-voltage arc-over.
- **Corrective action:**
 1. Lock out the X-ray cabinet per radiation safety.
 2. Verify HV power supply readings; replace the tube if filament is open.
 3. Run image quality indicator (IQI) test pieces.
- **Restart criteria:** IQI sensitivity meets the spec written on the recipe.

4.2 Calibration

- **Symptoms in telemetry:** `fault_type = "Calibration"`. Inspection reports either no defects ever or every part rejected.
- **Likely root cause:** automatic defect classifier drift; recipe parameters out of range.
- **Corrective action:**
 1. Run the calibration set (known-defect + known-good parts).
 2. Tune sensitivity until both pass and reject thresholds are met.
 3. Sign off recipe revision in the QMS.
- **Restart criteria:** 100 % accuracy on the calibration set.

4.3 Film-Jam

- **Symptoms in telemetry:** `fault_type = "Film-Jam"`. Inspection cycle cannot complete.
- **Likely root cause:** legacy radiographic media handler jammed (where applicable), or detector-panel transport stuck.
- **Corrective action:**
 1. LOTO. Clear the jam.
 2. Inspect transport rollers; replace worn ones.
 3. Verify panel positioning against the master target.
- **Restart criteria:** transport cycles 10 times with no slip.

5. Preventive maintenance schedule

- **Daily:** IQI verification at shift start.
- **Weekly:** detector clean; transport rollers inspected.
- **Monthly:** radiation safety integrity test.
- **Quarterly:** classifier retraining against the latest accepted defects.

6. References

- [Quality_Reject_Disposition_Policy.pdf](#)
- [Maintenance_Workflow_Overview.pdf](#)
- [Line-C_02_Welding-Robot_SOP.pdf](#)
- [Line-C_04_Fastening-Station_SOP.pdf](#)