

Paint-Booth — Standard Operating Procedure

Paint-Booth — Standard Operating Procedure

- 1. Purpose
- 2. Normal operating envelope
- 3. Idle reasons
- 4. Faults & corrective actions
- 5. Preventive maintenance schedule
- 6. References

Paint-Booth — Standard Operating Procedure

Audience: Maintenance Tech · Line Manager · Quality Worker
Applies to: Line-D, station 4, Paint-Booth

1. Purpose

The Paint-Booth applies the finish topcoat via electrostatic or robotic spray. It feeds the Curing-Oven (Line-D’s bottleneck), so a paint outage quickly back-fills the booth-side buffer and blocks Primer-Application.

2. Normal operating envelope

- Ideal cycle time: **40 s**
- Max acceptable cycle time: **52 s**
- Expected reject rate: **≤ 4 %**
- Fault probability per cycle: **0.8 %**
- Input buffer capacity: **5 parts**

3. Idle reasons

idle_reason	Meaning here	First check
Starved	Primer-Application (station 3) is not feeding parts.	Verify Primer-Application state.
Blocked	Curing-Oven (station 5) cannot accept the painted part.	Verify Curing-Oven state — this is the line bottleneck.

4. Faults & corrective actions

4.1 Nozzle-Clog

- **Symptoms in telemetry:** fault_type = "Nozzle-Clog". Pattern asymmetric; coating thickness rejects rise.
- **Likely root cause:** dried paint in the gun tip; supply contamination.

- **Corrective action:**
 1. Purge gun with solvent; clean tip.
 2. Inspect supply filter; replace if loaded.
- **Restart criteria:** pattern matches reference card.

4.2 Air-Filter-Saturated

- **Symptoms in telemetry:** fault_type = "Air-Filter-Saturated".
Booth airflow drops; overspray accumulates on parts.
- **Likely root cause:** intake or exhaust filter loaded with paint solids past service interval.
- **Corrective action:**
 1. LOTO. Replace saturated filters.
 2. Verify booth pressure differential.
- **Restart criteria:** airflow within spec.

4.3 Paint-Viscosity-Drift

- **Symptoms in telemetry:** fault_type = "Paint-Viscosity-Drift".
Coating thickness variable; orange peel appearance.
- **Likely root cause:** solvent evaporation in the supply pot, or batch out of spec.
- **Corrective action:**
 1. Sample paint; measure viscosity.
 2. Adjust thinner to recipe.
 3. Re-validate against the test card.
- **Restart criteria:** viscosity within recipe range.

5. Preventive maintenance schedule

- **Daily:** gun purge; viscosity check.
- **Weekly:** filter inspection; booth pressure check.
- **Monthly:** filter changeout.
- **Quarterly:** full atomization-system service.

6. References

- Maintenance_Workflow_Overview.pdf
- Safety_Lockout_Tagout_Procedure.pdf
- Line-D_03_Primer-Application_SOP.pdf
- Line-D_05_Curing-Oven_SOP.pdf
- Line-D_06_Coating-Inspection_SOP.pdf