

Safety — Lockout / Tagout (LOTO) Procedure

Safety — Lockout / Tagout (LOTO) Procedure

1. Purpose
2. When LOTO is required
3. The 7-step LOTO sequence
4. Station-specific notes
5. Group lockout
6. Removing LOTO
7. References

Safety — Lockout / Tagout (LOTO) Procedure

Audience: Every technician, operator, and engineer who opens an enclosure, exposes hazardous energy, or services any of the 30 stations. **Applies to:** All 5 lines, all 30 stations.

1. Purpose

This procedure prevents injury from unexpected energization, start-up, or release of stored energy during service, maintenance, or troubleshooting of factory equipment. Every per-station SOP cross-references this document under “Corrective action” steps that open an enclosure.

LOTO covers all hazardous energy sources present at this site:

- **Electrical** — line voltage at all CNC, robotic, and material-handling stations.
- **Hydraulic** — Line-B Hydraulic-Press, Line-D paint pumps.
- **Pneumatic** — every station with air-actuated clamps or gates.
- **Thermal** — Line-D Curing-Oven, Line-E Reflow-Oven, Line-E Wave-Solder pot. Thermal residue can remain hours after shutdown.
- **Chemical** — Line-D Chemical-Wash bath, paint solvents.
- **UV** — Line-E Conformal-Coat UV cure lamps.
- **Stored mechanical** — press rams (Line-B), spring-loaded clamps.

2. When LOTO is required

Apply LOTO before performing any of the following on any station:

1. Opening an enclosure to service a motor, drive, sensor, or control panel.
2. Replacing tools, blades, dies, nozzles, or other consumables.
3. Clearing a jam where a hand or tool will pass a guarded boundary.
4. Touching parts of the equipment that could become energized.
5. Performing PM tasks listed in section 5 of any station SOP.

LOTO is **not** required for purely external visual checks (e.g., reading a machine status display from the operator side).

3. The 7-step LOTO sequence

The standard sequence every technician must follow:

1. **Prepare:** identify all energy sources on the machine. Use the station-specific energy chart posted at the machine.
2. **Notify:** tell affected operators that the machine is going out of service. Capture the work order ID.
3. **Shut down:** bring the machine to a normal stop via the operator controls.
4. **Isolate:** turn off the disconnect for every energy source. Close manual valves on air, hydraulic, and chemical lines.
5. **Lockout / tagout:** apply your personal padlock and tag to each disconnect. Tag must show technician ID, date, time, and work order ID.
6. **Release stored energy:** bleed residual pressure (hydraulic, pneumatic), wait for thermal cooldown, ground any capacitive circuits.
7. **Verify:** attempt to start the machine using the normal start controls. The machine must remain de-energized.

4. Station-specific notes

- **Line-B Hydraulic-Press** — main accumulator can hold ~3,000 psi after electrical disconnect. **Always bleed before opening the ram enclosure.** See Line-B_02_Hydraulic-Press_Maintenance_SOP.pdf section 4.2.
- **Line-D Curing-Oven** — surfaces stay > 60 °C for at least 60 minutes after power-off. Wait for the cool-down indicator before opening any panel. See Line-D_05_Curing-Oven_SOP.pdf.
- **Line-E Wave-Solder** — solder pot stays molten for ~3 hours after power-off. Replace UV lamps on the Conformal-Coat station only when the driver disconnect is locked out (UV radiation hazard even at off-cycle start). See Line-E_06_Wave-Solder_Troubleshooting.pdf.
- **Robotic cells (Welding-Robot, Assembly-Robot)** — robot teach-pendant enable is *not* a substitute for LOTO. Always isolate at the drive cabinet before entering the cell envelope.

5. Group lockout

When more than one technician services the same machine:

- Each technician applies their own padlock to a multi-lock hasp.
- The machine cannot be returned to service until **every** padlock is removed by the technician who applied it.

6. Removing LOTO

- Only the technician who applied the lock may remove it (except in documented emergency-override situations approved by EHS).
- Sequence: verify work is complete → remove tools and personnel from machine → re-install all guards → notify operators → remove locks in reverse order of application → restore energy → run a verification cycle.

7. References

- Maintenance_Workflow_Overview.pdf
- Every per-station SOP under section 4 (Faults & corrective actions).

- Local EHS site procedure (binder at the supervisor station).