FLEET TEAM DIGEST

737MAX-FTD-20-17001

Issue Title : C-Wrap Side Entry Wire Insulation Repair

Airplane Model	ATA	Minor Model(s)
737MAX	2010-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
767, 757, 717, 737NG, 737, 787, 707, 777, MD-80, MD-10, MD-11, 727, MD-90	9E991

Originated Date	Last Revised Date	Created On
03/28/2017	03/28/2017	03/02/2017

Estimated Completion Date	Next Update Date

Description

BACS13DP SLEEVE, WIRE INSULATION REPAIR - SIDE ENTRY (C-Wrap)

When damage occurs to wire insulation during production, the preferred approach is to remove and replace the wire and correct the condition that caused the damage to prevent recurrence. However, there are some circumstances when wire removal and replacement might incur risk of additional damage to adjacent wire bundles. In these circumstances, and within specific constraints, there are some instances where a controlled repair is appropriate and authorized.

Currently, tape wrap repair is a common repair method in production and in service. C-Wrap (BACS13DP) is a new wire insulation repair method designed to provide an alternative to tape wrap.

The BACS13DP is a two piece shrinkable wire insulation sleeve for repair of damage (minor tear, scuff, or scrape) to the insulation of primary wires. It provides an environmentally resistant repair to damaged primary wire insulation, and it is an alternative to the tape wrap wire insulation repair. The two pieces of the BACS13DP consist of an inner adhesive sleeve and an outer protective sleeve, both slit axially allowing installation on a wire mid-bundle. The process to install is similar to solder sleeve or other shrinkable sleeves. No new specialty tools are required.

There are strict guidelines for usage and application. For production, use must be authorized by Engineering as defined within the guidelines of the D6-36911 and D6-83525-767. For use in service, the process detailing the use of this new repair will be included in the next revision of the D6-54446 scheduled for release June 1, 2015 (see Ch 20-10-13).

There are 4 sizes to cover wire insulation generally 22AWG -14AWG. Each size is color coded. For BACS13DP product dimensions, see attached illustration.

Status

The BACS13DP is now authorized for use.

Interim Action

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

None

Final Action

None

Part Information

D6-54446 is the engineering authority not this digest note.

BACS13DP repair sleeve application notes (not all inclusive):

See D6-54446 (beginning rev 60) Section 20-10-13 for the applicable conditions for the repair of wire, and for the damage and repair conditions for the wire that must have a repair

• Can be used only on the insulation of a wire, and that wire must already be installed in the airplane or installed in an airplane panel

• Only one BASC13DP repair sleeve can be used for each repair

• Have a maximum operating temperature of 150C

• Can be used on a wire in a wire harness that has a maximum temperature grade of B (135C)

• Cannot be used on a wire that has damage where the conductor can be seen

• Cannot be used on a fuel system wire

• Cannot be used on a flight control wire

• Cannot be used on a wire that is manufactured with a single extruded insulation

BACS13DP repair sleeve process summary (not all inclusive):

• Select the BACS13DP based on the outer diameter of the wire insulation to be repaired

• Clean and lightly abrade the insulation surface

• Push the adhesive sleeve and insulation sleeve onto the wire insulation, aligning the sleeve slits and opposite the damage on the wire insulation, and centered over the damage on the wire insulation

• Shrink the sleeves into position with a hot air gun (with reflector), until adhesive sleeve is melted and the insulation sleeve is shrunk

• While sleeve is still hot, lightly compress with a contact insertion tool for 20 seconds

• Remove insertion tool and check that insulation sleeve is fully shrunk on the wire and the melted adhesive sleeve does not have a void and wire insulation is not visible

• IF installation is unsatisfactory, reheat the sleeve and remove, clean the wire insulation and repeat the installation processes

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability

Attachments:

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

a) Product Dimensions

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991