FLEET TEAM DIGEST

737MAX-FTD-20-22001

Issue Title : Flight Deck Door Header Wire Riding

Airplane Model	ATA	Minor Model(s)
737MAX	2010-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
01/31/2023	02/29/2024	02/27/2024
Estimated Completion Date	**Next Update Date**	

Revision Description

Updated Description: Minor, wording

Updated Status: Minor, wording, removed flight deck door alteration

Updated Final Action: Minor, wording, removed flight deck door alteration

Updated Milestones: removed dates related to flight deck door alteration and added a completion date for SB release.

Description

Multiple operators reported various adverse flight deck effects occurring intermittently at cruise altitudes. Subsequent operator investigations found chafing on wire bundles above the flight deck door header. Reported flight deck effects include intermittent illumination of Standby Rudder Light and ELT (Emergency Locator Transmitter) Light. Root cause was found to be wire bundle interference with the flight deck door header because of reduced clearance at cruise altitude. Reduced clearance is caused by fuselage deflection from pressurization loads at cruise altitudes. Additional potential contributing factors include:

1. Incorrect installation of wire bundle clamps above the flight deck door header during production
2. Operator-installed Supplemental Type Certificate (STC) modification of wire bundles in the flight deck door header area

Status

Boeing completed a flight test to observe and quantify the reduction in clearance above the flight deck door header. The flight test confirmed that the flight deck door frame moves more than originally anticipated, causing clearance to be reduced more than anticipated at altitude.

Boeing completed its safety evaluation process and determined that the impact of wire chafing of one or more wires is Not Safety.

Boeing initiated an SRP (Service Related Problem) on 09-SEPT-2022. Rework instructions are provided in Service Bulletin

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

737-33-1179.

Interim Action

Operators are encouraged to exercise caution when implementing any Supplemental Type Certificate (STC) modifications of wire bundles in the flight deck door header area. The existing design has enough clearance through all phases of flight but has limited margin to accommodate modifications to wire runs or clamp configurations.

Final Action

Design solutions incorporated on line number 8885:

- A note was added to the 288A4101 wire installation drawing to communicate the increased clearance requirement
- Drawings have been updated to support adding Teflon sleeving to wire bundles and a caterpillar grommet on the surface of the flight deck door header

Boeing issued a Service Bulletin to:

- Ensure correct clamp installation
- Provide instructions to inspect for insufficient clearance conditions
- Provide necessary rework instructions for:
  - Incorrect clamp configuration
  - Insufficient clearance conditions

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: October 2022
Solution Selected: October 2022
Change Committed for Addition of Sleeving and Grommet: May 2023
Service Bulletin Available: 20-DEC-2023 (Complete)

Parts Available: January 2024 (Complete)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Related Problem (SRP)	737MAX-SRP-33-0075		
Service Bulletin (SB)	737-33-1179		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Flight Deck Door Header	B224350-501	Safran	

Related Categories

- SRPs - Economic : Service Related Problems in work by Boeing that have an economic impact

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991