FLEET TEAM DIGEST

737MAX-FTD-21-18001

Issue Title : 737MAX PACK Light Illumination After Engine Start

Airplane Model	ATA	Minor Model(s)
737MAX	2161-25	-7, -8, -8200, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
03/19/2018	06/06/2018	05/29/2018
Estimated Completion Date	**Next Update Date**	

Revision Description

Background was updated with minor edits and statements on closing this issue.

Status was updated with teardown and testing information, and statements on closing this issue.

Interim and Final Action were updated with final recommendations if this issue occurs.

Milestones were updated with teardown and testing information and a closing statement.

This FTD article has been closed.

Applicability

737MAX Airplanes

Description

Operators have reported the PACK light being illuminated while on the ground just after engine start.

Background

Boeing received seven (7) reports of the PACK light illuminating on the ground on 737MAX airplanes. This issue occurs after engine start, when the PACK switches are set to AUTO.
A PACK light is illuminated due to the air conditioning pack's Electronic Flow Control Valve (eFCV) not opening when commanded, thus triggering Maintenance Message 21-55030 or 21-55031 ("LEFT/RIGHT AIR CONDITIONING PACK FCV SIGNAL IS OUT OF RANGE OR VALVE IS NOT IN COMMANDED POSITION").

Electronic Data Recorder (EDR) data, downloaded from two airplanes that exhibited either of these faults, showed that the system commands to the pack valve were correct, and fault detection was operating properly. The data indicates that the eFCV did not respond properly. However, this issue appears to be intermittent, with at least one event being cleared without replacement of the valve.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

An investigation was conducted by Boeing and Honeywell.

No root cause for this issue was found.

Status

Boeing and Honeywell gathered all available data as part of the joint root cause investigation.

Three eFCVs were returned to Honeywell and evaluated after these events.

- Units were inspected (including CT Scan), tested and torn down with Boeing participation

- Two valves tested NFF

- One valve had some findings that may have indicated increased friction or binding in the valve.

Aircraft simulation test completed on returned valve with Boeing provided ducts

- Completed 15,000 cycles at ambient, 15,000 cycles at elevated temp

- No findings

Solenoid cycle testing completed on returned valve with Boeing provided ducts.

- Completed 14,000 cycles at ambient, 11,000 cycles at elevated temp

- No findings

Extra loads were applied to the couplings, and the ducting was adjusted to out-of-tolerance angles to determine if installation factors could cause this issue.

Valve failure to open could not be replicated.

Boeing/Honeywell investigation developed fault tree.

- 7 major branches, 18 sub-branches,

- All branches closed with no viable root cause candidate identified.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

From these investigations, some discrepancies in how the eFCV units' sub-components were assembled were observed. As a result, this has driven multiple improvements into the manufacturing process for the eFCV units. Boeing and Honeywell believe that these improvements will help to reduce future fault occurrences.

After multiple valve teardowns and tests, the team believes that mechanical binding could have been a contributing factor, but was unable to determine it as the root cause.

No other faults could be found with any of the returned valves.

With no further reports from the fleet, Boeing and Honeywell have agreed to close this issue.

Service Related Problem (SRP) 737MAXSRP21-0258 has been closed.

If the issue is reported again in the future it will be investigated at that time.

Interim Action

None at this time

Final Action

If this issue occurs, Boeing recommends troubleshooting per the Interactive Fault Isolation Manual (IFIM) section 21-51-00-810-807/808.

Previous operator experiences show that replacing the eFCV, P/N 63396754-2, will likely resolve the issue.

A root cause for this issue could not be determined.

There is no planned corrective action at this time.

If this issue occurs, please notify Boeing.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Issue Identified: October 2017

Initial Valve Investigations: November & December 2017 (complete)

Valve Assembly Improvements: January 2018 (complete)

3rd Valve Investigation: March 2018 (complete)

Aircraft Simulation Testing: April 2018 (complete)

Installation Load Testing: May 2018 (complete)

Root Cause Established: N/A (root cause could not be established)

Corrective Action: N/A (no root cause established)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

This issue has been closed with no further reports from the fleet.

Supplier Information

Honeywell Aerospace

1300 W Warner Rd

Tempe, AZ

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fault Isolation Manual (FIM)	IFIM 21-51-00-810-807/808		
Service Related Problem (SRP)	737MAXSRP21-0258		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Electronic Flow Control Valve		Honeywell	63396754-2

Related Categories

- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations
- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message
- SRPs - Economic : Service Related Problems in work by Boeing that have an economic impact

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991