FLEET TEAM DIGEST

737MAX-FTD-21-26001

Issue Title : 737 MAX Erroneous Electrical Ground Signal Resulting in Hot Cabin and Flight Deck

Airplane Model	ATA	Minor Model(s)
737MAX	2151-21	-8, -8200, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
01/29/2026	10/05/2026	09/25/2026
Estimated Completion Date	**Next Update Date**	
12/23/2027	01/24/2027	

Revision Description

Provide updates on Service Bulletin (SB) and training video release, production fix release and upcoming updates to Interim Action #1 Non Normal Checklist (NNC)/Flight Crew Operations Manual (FCOM) Bulletin.

Applicability

All 737-8, -8200, -9 aircraft delivered prior to Line Number 9825.
All future 737-7 and 737-10 will be delivered with the wiring fix discussed in this Fleet Team Digest (FTD) article.

Description

The FTD article is to provide 737 MAX operators with background information as well as project updates regarding excessive flight deck and cabin temperatures due to an erroneous ground signal received by the Smart Ram Air Door Actuator (SRADA) when Standby Power Control Unit (SPCU) BAT BUS SECT 2 C3062 Circuit Breaker (CB) and Air Conditioning Pack Control Valve C262 or C263 CB trips. **This condition is deemed Airplane-Level Safety.**

Background

Boeing received a report in June 2025 of an in-flight technical issue where the MASTER CAUTION lights along with amber STANDBY POWER OFF, RIGHT REVERSER LIMITED, LEFT PACK, RIGHT PACK, CONT CAB ZONE, FWD ZONE, and AFT ZONE lights illuminated. Additionally, air to the flight deck and passenger cabin became increasingly warm. The flight crew noticed that circuit breaker CB C3062 BAT BUS SECT 2 on SPCU tripped and reset it prior to descending. During descent, it was reported that the cabin altitude was climbing and subsequent CABIN ALTITUDE warning light illuminated along with manual deployment of passenger oxygen masks. The flight crew reported inability to control the Outflow Valve (OFV) via MANUAL cabin pressure selector setting.

When CB C3062 BAT BUS SECT 2 trips, downstream power to various systems are lost including power to the following ATA 21 related breakers:

- CB C262 AIR CONDITIONING PACK CONT VALVES LEFT Results in loss of left Flow Control Valve (FCV) open/close solenoid power

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

- CB C263 AIR CONDITIONING PACK CONT VALVES RIGHT Results in loss of right FCV open/close solenoid power
- CB C1176 AIR CONDITIONING PACK/ENGINE BLEED AIR OVHT LEFT Results in loss of left pack overheat protection
- CB C1177 AIR CONDITIONING PACK/ENGINE BLEED AIR OVHT RIGHT Results in loss of right pack overheat protection
- CB C1269 PRESSURIZATION CONTROL MANUAL Results in loss of OFV manual mode control (auto channel 1 and 2 remain active)

The unanticipated effect of the CB C3062 tripping is an erroneous ground through the Air Conditioning Accessory Unit (ACAU) K10 PACK AIR/GND relay which ties into the Proximity Switch Electronics Unit (PSEU) AIR/GND SYS 1_2 Weight on Wheels (WOW) and Left/Right SRADA. The loss of power allowed for the ground to be recognized by the SRADA and resulted in the SRADA fully retracting to ground mode, which deploys the deflector door. With the deflector doors deployed in flight, ram air was deflected around the ram air inlet which prevented the heat exchangers from conditioning the bleed air throughout the air cycle system. This along with the inability to shut down the packs via the automatic Pack Overheat Protection and P5 Panel Pack switches resulted in the inability to mitigate unconditioned hot air from entering the flight deck and cabin. **Boeing has determined the inability to mitigate unconditioned hot air from entering the flight deck and cabin during this condition using existing Non-Normal Checklist (NNCs) to be an Airplane-Level Safety issue.**

Boeing also received one additional report in November 2025 which did not result in cabin depressurization or deployment of passenger oxygen masks. However, the same flight deck and system effects were observed.

In both events, the pilots were able to reset C3062, which restored system functionality, and performed an uneventful safe landing.

Additional review and aircraft testing of downstream circuit breakers C262 (P6-4 C6) AIR CONDITIONING PACK CONT VALVES LEFT and C263 (P6-4 C5) AIR CONDITIONING PACK CONT VALVES RIGHT confirms that the associated Left/Right SRADA will receive the erroneous ground signal resulting in deflector door deployment and excessive pack outlet temperatures for the affected pack. While C262 or C263 have never been reported to have tripped in the 737 MAX fleet history, it is considered a single failure mode which can impact the continued safe flight and landing of the aircraft.

In January 2026, Boeing determined via circuit analysis and aircraft testing on both 737NG eFlow (line number 5684, 5759 and subsequent) and 737NG non-eFlow aircraft (prior to line number 5759, with the exception of 5684), that 737 Classic and 737NG are not affected due to differences in the ACAU and external electrical inputs to the ACAU.

Status

To address the Airplane Level Safety issue, Boeing has completed the following actions:

- Interim Action #1 (C3062 CB trips): Released Flight Crew FCOM Bulletin and NNC to provide flight crews with information regarding the issue along with steps for flight crew action if the issue arises. See MOM-MOM-26-0048-01B.
  - Boeing performed an additional aircraft test and determined additional aircraft system effects when SPCU C3062 CB trips and does not reset.
  - Boeing evaluated these additional findings as part of Boeing's in-service safety process and no further action has been deemed to be required to maintain the safety of the fleet.
  - The findings resulted in three (3) changes being made to the Cabin Temperature Hot BAT BUS SECT 2 Circuit Breaker Trips flight crew guidance that are not anticipated to be mandated via FAA Airworthiness Directive (AD).
  - The changes will be available via standard FCOM release cycle 30-Nov-2026.
- Interim Action #2 (C262 or C263 CB trips): Released Flight Crew FCOM Bulletin and NNC to provide flight crews with information regarding the issue along with steps for flight crew action if the issue arises. (complete)
- Final Action:
  - Wiring changes (production and retrofit) to isolate the SRADA and PSEU WoW signal from the Air Conditioning Accessory Unit (ACAU) to prevent erroneous ground signal during power loss condition of C3062, C262, and C263. (complete)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

For additional information on Interim Action #1, #2 and above additional findings, please reference the attached Out-of-Sequence (OoS) call “27-JAN-2026_Interim Action #1_Out-of-Sequence Call” and “24-FEB-2026_Interim Action #2_Out-of-Sequence Call” and "Erroneous Ground Signal_OoS Call_ 28-Sep-2026".

For more information on the 737 MAX Flight Crew Training Simulation Software SimBinary 3.27.2 Software Release, reference MOM-MOM-26-0412-02B, -03B and Simulator Data Bulletin SDB-737-026.

Interim Action

Operators are encouraged to:

1. Comply with AD 2026-14-11, which supersedes AD 2026-13-05 and AD 2026-04-05.
   a. Reference MOM-MOM-26-0048-01B, -02B, -03B, -04B, -05B, -06B, -07B and Global Alternative Method of Compliance (GAMOC) #523-26-00150. This GAMOC provides higher resolution copies of the Appendices referenced in AD 2026-14-11.

If the event occurs:

1. Follow standard practices to troubleshoot the tripped circuit breaker and any active Flight Deck Effects (FDEs) and/or maintenance messages upon landing. This would include checking wiring downstream of the tripped circuit breaker, and upstream of each individual breaker that feeds from the tripped circuit breaker. If there are other conditional effects, such as cabin pressure loss (Cabin Altitude Warning), or smell of smoke/odor in the cabin, follow the AMM ATA 05 Conditional Inspections, as needed.

For Additional Information:

1. Review the attached Frequently Asked Questions (FAQ) page which includes additional information and responses to questions asked during 27-JAN-2026 and 24-FEB-2026 OoS calls. Boeing will continue to update the FAQ page as additional questions come in.
2. Review the attached 15_16-July-2026 Fleet Team Call Presentation which includes information regarding the recent ADs and industrialization/parts plan.

Final Action

For all 737 MAX Prior to Line Number 9825:

Incorporate the retrofit SB 737-21A1278 wiring change to isolate the PSEU 1/2 WoW signal and L/R SRADA from the ACAU. Boeing recommended compliance time is within twelve (12) months after SB release. Operators are encouraged to report incorporation of the bulletin via SB Center. Operators that have not placed Purchase Orders (POs) for kits are advised to do so.

Operators are encouraged to refer to the training video VIDEO-MXE-02-00109 titled "Air Conditioning Pack Flow Control and Pack Cooling System Air Conditioning Accessory Unit Wiring Change" available on MyBoeingFleet New Maintenance Performance Toolbox. See access instructions below:

1. Log into MyBoeingFleet
2. Open the Application "New Maintenance Performance Toolbox"
3. At bottom right of screen, click tab "Media Library"
4. On top left, Filter by "Media Type" - Video

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

For those that do not have access to New Maintenance Performance Toolbox, please send a Boeing Communication System (BCS) Case using the product details below in order to receive the training video directly.

- Service Category: Fleet Wide Inquiry
- Product Type: Airplane
- Product Line: 737
- Product: 737-8/-9/-8200
- ATA Code: 2100 Environmental control

For 737 MAX Line Number 9825 an ON:

- Utilize Global Alternative Method of Compliance (GAMOC) #523-26-00193 to revert back to original Cabin Temperature Procedure in the AFM.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

- Event #1: JUN-2025
- Event #2: NOV-2025
- 737 MAX Aircraft Testing: DEC-2025 (complete)
- Airplane Safety Determination (C3062): 7-JAN-2026 (complete)
- Safety SRP Kick-Off: 9-JAN-2026 (complete)
- 737NG eFlow and SRADA non-eFlow Aircraft Testing: 17-JAN-2026 (complete)
- Fleet Communication Interim Action #1 (Out of Sequence Call): 27-JAN-2026 (complete)
- Flight Crew FCOM Bulletin and NNC Release Date: 2-FEB-2026 (complete) | MOM-MOM-26-0048-01B
- Airplane Safety Determination (C262 & C263): 4-FEB-2026 (complete)
- Customer Specific Flight Crew FCOM Bulletin and NNCs (Interim Action #1) Release Date: 11-FEB-2026 (complete)
- Interim Action# 1 Airworthiness Directive (AD) 2026-04-05: 24-FEB-2026 (complete)
- Fleet Communication Interim Action #2 (Out of Sequence Call): 24-FEB-2026 (complete)
- Flight Crew FCOM Bulletin and NNC Release Date: 6-MAR-2026 (complete)
- Customer Specific Flight Crew FCOM Bulletin and NNCs (Interim Action #2) Release Date: 6-MAR-2026 (complete)
- Service Bulletin 737-21A1278 Survey: 6-JUL-2026 (complete)
- Interim Action# 1 & 2 Airworthiness Directive (AD) 2026-14-11: 13-JUL-2026 (complete)
- Interim Action# 1 & 2 Airworthiness Directive (AD) 2026-13-05: 16-JUL-2026 (complete)
- Industrialization Plan Fleet Team Call: 15 and 16-JUL-2026 (complete)
- Global Alternative Method of Compliance (GAMOC) #523-26-00150: 28-JUL-2026 (complete)
- Final Action Wiring Change - Production: Line Number 9825: SEP-2026 (complete)
- Global Alternative Method of Compliance (GAMOC) #523-26-00193: 24-SEP-2026 (complete)
- Final Action Wiring Change - Retrofit Service Bulletin 737-21A1278: 1-OCT-2026 (complete)

Part Information

For further information regarding industrialization plan to supply parts in effort to support the Final Action Wiring Change via Service Bulletin, please reference the attached "Erroneous Ground Signal_OoS Call_28-Sep-2026" or "Erroneous Ground Signal WTT 19-Aug-2026".

Boeing is expediting kit production and aims to achieve 100% availability by November 2026. For operators who wish to fabricate wire kits in-house, please refer to the associated drawings for each aircraft group in SB 737-21A1278. The drawings are available on REDARS for review.

Reference Categories

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Type	Reference Number	Revision Number	Reference Date
Other	VIDEO-MXE-02-00109		
Airworthiness Directive (AD)	2026-14-11		07/13/2026
Other	Global Alternative Method of Compliance #523-26-00150		07/28/2026
Airworthiness Directive (AD)	2026-13-05		07/16/2026
Airworthiness Directive (AD)	2026-04-05		02/24/2026
Service Related Problem (SRP)	737MAX-SRP-21-0296		
Service Bulletin (SB)	737-21A1278		10/01/2026

Related Categories

- Flight Operations : Flight Operations
- Significant Technical Flight Interruptions : Issues that cause in-flight events such as rejected takeoffs, air turnbacks, diversions, emergency landings, in-flight shutdowns, and abnormal stops
- SRPs - Safety : Service Related Problems in work by Boeing that have an airplane or personal safety impact

Attachments:

a) Erroneous Ground Signal_OoS Call_ 28-Sep-2026

b) Erroneous Ground Signal WTT 19-Aug-2026

c) 24-FEB-2026_Interim Action #2_Out-of-Sequence Call

d) 27-JAN-2026_Interim Action #1_Out-of-Sequence Call

e) Frequently Asked Question (FAQ)_Rev2

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991