# FLEET TEAM DIGEST

## 737MAX-FTD-22-21001

**Issue Title :** 737 MAX Overshoot when Using Lateral Navigation Mode (LNAV) to Intercept the Localizer

| Airplane Model | ATA | Minor Model(s) |
|---|---|---|
| 737MAX | 2200-00 | -7, -8, -8200, -9, -BBJ |

| Other Model(s) | ECCN |
|---|---|
| | 9E991 |

| Originated Date | Last Revised Date | Created On |
|---|---|---|
| 06/16/2021 | 02/24/2026 | 02/24/2026 |

| Estimated Completion Date | Next Update Date |
|---|---|
| 12/31/2026 | 09/30/2026 |

## Revision Description

No updates required for this FTD article.

## Applicability

All fielded 737 MAX airplanes currently operating with Collins Flight Control Computer (FCC) software version P12.1.2.

## Description

737NG operators have reported that the Autopilot/Flight Director System (AFDS) did not provide proper guidance to capture the Instrument Landing System (ILS) localizer when intercepting from Lateral Navigation mode (LNAV) transitions. The issue could also occur on a 737 MAX airplane because the airplane shares a common Collins AFDS system with the 737NG airplane. To-date, no reports have been received from 737 MAX airplane operators.

The reported events have occurred during Lateral Navigation to Localizer (LNAV-LOC) approach transitions with large intercept angles (60 degrees or more), resulting in overshoots. Flight data have confirmed that during these overshoot events, the AFDS initially banks up to 30 degrees but then reduces bank angle during the localizer capture and then continues through the final approach course, even when VOR/LOC is the engaged roll mode as shown by the Flight Mode Annunciation (FMA). AFDS correction back to the localizer course may not occur within the distance available to establish a stabilized final approach. Most overshoot events have been reported on Instrument Landing Systems (ILS) approaches with transition segments which intercept the localizer at 90-degree angles. However, some overshoots have also occurred with intercept angles less than 90 degrees. In these events, LNAV is the engaged roll mode prior to engagement of localizer mode (VOR/LOC) during localizer capture. In all reported overshoot events, deviation from the localizer was accurately shown by the localizer pointer and scale on the primary flight display (PFD) and the navigation display (ND), and by the airplane symbol on the ND.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

Attached for reference are several approach charts reported by operators that are susceptible to this condition.

## Background

Functional changes that were implemented into the AFDS LNAV-LOC transition control laws were expected to provide better flight path tracking and faster airplane convergence to the centerline. Boeing has determined that these functional changes have caused unanticipated airplane lateral overshoots, as described in the description section.

## Status

Findings from the referenced Service Related Problem (SRP) are being used to update the 737 MAX AFDS LNAV-LOC functionality per the forthcoming P13.0 FCC OPS, which is under development in conjunction with the 737-10 certification program.

## Interim Action

Operators should review the referenced 737 MAX Flight Crew Operations Manual (FCOM) Bulletin, entitled "Localizer Overshoot When Using LNAV to Intercept the Localizer" to help mitigate this condition from occurring, until corrected in a future AFDS update.

## Final Action

All fielded 737 MAX Operators will be encouraged to update the AFDS (FCC) software to P13.0 per the referenced Alert Service Bulletin when it becomes available as discussed in the milestones..

## Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: 14-Jan-2021 (complete)

Solution Selected: 14-Jan-2021 (complete)
P13.0 Alert Service Bulletin 737-22A1382 Available: Will follow post 737-10 ammended type certification activity completion

## Operator Action

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

Please review the interim and final action sections.

## Reference Categories

| Reference Type | Reference Number | Revision Number | Reference Date |
|---|---|---|---|
| Flight Crew Operations Manual Bulletin (FCOMB) | TBC-25 | | 05/21/2021 |
| Service Bulletin (SB) | 737-22A1382 | | |
| Service Related Problem (SRP) | 7x7-SRP-22-0054 | | |

## Related Categories

- Flight Operations : Flight Operations
- SRPs - Safety : Service Related Problems in work by Boeing that have an airplane or personal safety impact

## Attachments:

a) Approach Charts

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991