FLEET TEAM DIGEST

737MAX-FTD-22-21004

Issue Title : Nuisance NO AUTOLAND Message Latched During Takeoff Caused by the HUD System Commanding the ILS Antenna Switching Relay to the Forward Position

Airplane Model	ATA	Minor Model(s)
737MAX	2200-00	-10, -7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
12/21/2021	10/22/2026	10/12/2026
Estimated Completion Date	**Next Update Date**	
06/30/2027	02/28/2027	

Revision Description

Adding 737-10 into the aircraft model, updated milestones.

Applicability

Applicable to 737MAX airplanes that operate an HGS-6000 series Heads-up Display (HUD) system with a Category (CAT) IIIB/Fail-Operational Autopilot/Flight Director system.

Description

A nuisance condition has been identified wherein the Heads-up Guidance System (HGS) will command the Instrument Landing System (ILS) antenna source switching relay to the forward position during takeoff roll and latches a fault at Take Off/Go Around (TOGA) mode engagement.

Prior to initiating the takeoff roll, if the Navigation (NAV) radio configuration is such that one NAV radio is tuned to an ILS frequency, and the other NAV radio is NOT tuned to an ILS frequency (or is tuned to a VOR frequency), the HGS can command the ILS antenna source switching relay to the forward position once the aircraft ground speed exceeds 40 knots. This command is the result of a HGS software implementation issue. The effect of this issue causes the Autopilot/Flight Director System (AFDS) to believe that the antenna has erroneously been switched to the forward position and will latch a NO AUTOLAND advisory message at TOGA mode engagement. The NO AUTOLAND advisory message will be then observed by the crew after landing on the engine page, and when the airplane decelerates below 40 knots of ground speed or recall activity is performed. When the DFCS BITE fault history is reviewed, the NO AUTOLAND fault is found, with correlated maintenance messages 22-11108 and/or 22-11109 shown. While troubleshooting these maintenance messages, the operator can be misled to think that there is a problem with the Integrated Flight Systems Accessory Unit (IFSAU) because the IFSAU provides information to the AFDS for what antenna source (front/rear) has been selected, resulting in an unscheduled removal of the IFSAU and subequent no fault found shop finding.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Background

The HGS can provide low visibility takeoff guidance capability via head-up display guidance, provided that all of the following conditions are satisfied:

- Aircraft is on the ground.
- HGS Primary mode is selected.
- Both NAV receivers are tuned to the departing runway ILS frequency or both Multi-mode Receivers (MMR) are tuned to the departing runway station ID (OPC Option).
- Combiner is not stowed.

During takeoff, the navigation data provided by the rear antenna sources are used by the Autopilot/Flight Director System (AFDS). During approach, the navigation data provided by the forward antenna sources are used by the AFDS.

Status

Collins Aerospace is developing corrective actions to the HGS software in order to mitigate this nuisance condition. Collins has published the referenced Service Information Letter (SIL), advising operators of the nuisance condition and will status operators of long term corrective action. The updated HUD software is scheduled for certification as a post-project for the other in-service minor models (-7, -8, -8200, -9, -BBJ) after the MAX-10 airplane type certification occurs, which will require an additional amount of time before retrofit capability becomes available to the in-service fleets. Please refer to the Milestones section for more information pertaining to schedule.

Interim Action

Operators are encouraged to discuss the following information with their flight crews, to inform them and in order to operationally mitigate the nuisance event.

Until a final action is implemented, flight crews should consider adhering to the following operations, which will help prevent the nuisance from occurring:

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

1. Prior to takeoff roll initiation, ensure that either:

- Both NAV receivers are tuned to an ILS frequency, OR
- Both NAV receivers are tuned to a VOR frequency.

2. Once airborne and above 50 feet, tune the NAV receivers, as desired or if necessary.

Final Action

Operators affected by the nuisance condition described in this Fleet Team Digest Article should incorporate the Collins Phase 2.2 HGS update when it becomes available.

Milestones

Collins HGS Service Information Letter Available: Nov-2021 (Complete)

Current Collins Phase 2.2 HGS Software Retrofit Availability Date: April 2027

More information for Collins Phase 2.2 HGS can be found in the enhanced AOA Fleet Team Digest Article 737MAX-FTD-27-23003

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Information Letter (SIL)	Collins SIL HGS-6000-21-2		11/10/2021

Related Categories

- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations
- Flight Operations : Flight Operations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991