FLEET TEAM DIGEST

737MAX-FTD-22-24001

Issue Title : 737MAX Nuisance MACH TRIM Failures During Preflight Recall Activities

Airplane Model	ATA	Minor Model(s)
737MAX	2211-24	-10, -7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
04/18/2024	10/22/2026	09/21/2026

Estimated Completion Date	Next Update Date
02/29/2028	06/30/2027

Revision Description

Update the Estimated Completion Date

Description

Boeing has been made aware of several in-service events that prompted the illumination of the MACH TRIM FAIL light during recall on various 737MAX model aircraft.

These faults are known as "single-channel" trips and will only be evident when the flight crew performs a Master Caution (MC) recall (usually initiated at the flight crew's top-of-descent checklist and preflight activities), which will cause the MACH TRIM FAIL light to illuminate thereafter. Maintenance personnel typically performs the Digital Flight Control System (DFCS) Built-In Test Equipment (BITE) checks per Aircraft Maintenance Manual (AMM) Pageblock 22-11-00/501 and finds one or more of these maintenance messages logged: 22-1196, 22-11205, 22-11199 or 22-11334. The DFCS BITE Mach Trim library test (60.33) is performed during troubleshooting with no fault found and the MACH TRIM FAIL light extinguishes. The airplane is returned to service afterward with Mach Trim operating normally.

A comprehensive in-service data review has determined that the above condition occurs during break power transfer activities involving the Ground Power Unit (GPU), Auxiliary Power Unit (APU), and Integrated Drive Generator (IDG) resulting in a "single-channel" trip of the Mach Trim voltage monitors in the FCC.

At this time, Boeing considers these reports to be “nuisance” events with no detrimental airplane effects expected.

Status

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Findings from the in-service data are being investigated to identify and update all applicable Interactive Fault Isolation Manual (IFIM) tasks and identify root causes.

These actions are expected to mitigate the nuisance condition once fielded.

Interim Action

Perform the Interactive Fault Isolation Manual (IFIM) tasks, as applicable to the observed Mach Trim Faults below to diagnose and clear the nuisance condition:

MACH TRIM FAIL light: light on (fault code: 221 622 00)

IFIM Task 22-11-00-810-D74

Boeing also recommends that operators experiencing this nuisance issue provide the following data to Boeing through BCS for further analysis.

If the master caution is activated and the Mach trim light is on, then do the following:

During daily flight operations:

- Check if both Mach trim circuit breakers are OPEN or CLOSED.
- Check whether the flaps are UP or DOWN.
- Was the Master Caution activated when the pilots set the flaps down?
- Open C/B C1044 for 7 seconds, then reset.
- Open C/B C1047 for 7 seconds, then reset.
- Run library test 60.33. If the test passes, the aircraft is cleared for operation. If the test fails and the screen shows "TEST DATA, please select this option and provide a picture of the test data.

If there isn't enough time to download the data, please download the following data to us later:

- Download the autopilot fault history for both FCCs.
- Download ADR-ALL data.
- Please provide the outside temperature when the event happened.

Summary of all the data provided to Boeing in the BCS:

- Mach trim C/B status – Open or Closed?
- Flap position – Up or Down?
- Did the master caution activate when the pilot set the flaps to DOWN – Yes or No?
- Library Test 33 Pass status – Pass or Fail. If FAIL, please provide a screenshot of the "TEST DATA."
- FCC A and B autopilot inflight fault history
- ADR-ALL data Outside temperature
- Date, Time, and Airport of the events.
- Aircraft Tail Number

Final Action

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

No final action has been identified at this time.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.
Interactive Fault Isolation Manual tasks (IFIM) update estimated on May-31-2024

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fault Isolation Manual (FIM)	IFIM Task 22-11-00-810-D74		
Fleet Team Economic (FTE)	ISO-22-18-21770		
Fleet Team Economic (FTE)	ISO-22-24-45636		

Related Categories

- AOGs : Events that cause a significant Airplane On Ground (AOG) condition
- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations
- Fleet Team IdeaXchange : Topic of discussion on the Fleet Team IdeaXchange bulletin board
- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message
- Significant Event Report : List of significant in-service or maintenance events reported to Boeing that result in
  Air turnbacks, ground turnbacks, diversions, rejected takeoffs, in-flight shutdowns, or Significant AOGs.
  High failure rate of costly/critical systems

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991