FLEET TEAM DIGEST

737MAX-FTD-23-17001

Issue Title : Datalink Issue with CMU-900 Installation

Airplane Model	ATA	Minor Model(s)
737MAX	2327-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
747, 737NG, 767	9E991

Originated Date	Last Revised Date	Created On
03/15/2017	04/10/2019	03/13/2019

Estimated Completion Date	Next Update Date

Revision Description

Collins has received STC approval.

Applicability

737 MAX airplanes equipped with Collins CMU-900 (822-1239-151) and all versions of AOA (ACARS over Aviation VHF Link Control (AVLC)) & ATN (Aeronautical Telecommunications Network) PM-CPDLC (Protected Mode-Controller Pilot Data Link Communications) software.

Description

The symptom of the "Ack-N-Toss" problem is that an uplink message can be received by the Communication Management Unit (CMU) and acknowledged to the ground, but then "tossed" (not delivered to the application or peripheral as it should be).

Status

The root cause of the Ack-N-Toss issue has been determined. It only occurs with uplinks sent over SATCOM or HFDL (High Frequency DataLink) but not VHFDL (Very High Frequency DataLink). It also only occurs when an uplink having the same label, sublabel, and UBI (unsorted block image) character as the last block in a previous multi-block uplink is received over that sub network (SATCOM or HFDL) since the last time the CMU was powered up. Rockwell Collins has prototyped a solution and confirmed the prototype resolves the issue.

Interim Action

Occurrences are generally rare and possibly non-existent for some aircraft/operators because of the conditions necessary for it to occur (see current status above). If the aircraft avionics (i.e. CMU) are powered down regularly, that would reduce the possibility for this scenario to occur.

Final Action

A Collins Aerospace Supplemental Type Certificate (STC) Service Bulletin CMUS-900-23-115 provides a software change to the CMU-900 to correct this issue.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Root Cause Established: October 2016

Solution Selected: January 2017

Collins Aerospace Supplemental Type Certificate (STC) available: March 2019

Operator Action

Since this issue only occurs via SATCOM or HFDL when a multi-block uplink having the same information as the previous multi-block uplink is received, occurrences are generally rare and possibly non-existent for most 737MAX aircraft/operators and therefore no action is required. If operators expect to utilize multi-block datalink over SATCOM or HFDL in their specific airline operations, they can consider cycling the CMU C/B on the ground prior to these flights to reduce the possibility of this fault occurring.

Contact Collins Aerospace for details on how to incorporate STC Service Bulletin CMUS-900-23-115.

Supplier Information

Collins Aerospace

Data Link Applications

Air Transport Systems

400 Collins Road NE

Cedar Rapids, IA 52498-0001

Phone: +1 (319) 295-5000

Email: customersupport@rockwellcollins.com

Web: www.rockwellcollins.com

CAGE: 4V792

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	CMUS-900-23-115	-	

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
CMU-900		Rockwell Collins	822-1239-151

Related Categories

- Fleet Team IdeaXchange : Topic of discussion on the Fleet Team IdeaXchange bulletin board

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991