FLEET TEAM DIGEST

737MAX-FTD-23-19004

Issue Title : Collins Aerospace SATCOM Handover Disabled due to IRS not available at Startup

Airplane Model	ATA	Minor Model(s)
737MAX	2315-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
737NG, 747, 777	9E991	

Originated Date	Last Revised Date	Created On
09/03/2019	09/03/2019	03/18/2019
Estimated Completion Date	**Next Update Date**	

Applicability

737 airplanes with Collins Aerospace SATCOM Satellite Data Unit (SDU) model 2200 [Part Number (P/N) 822-2556-102].

Description

When the Satellite Data Unit (SDU) P/N 822-2556-102, with Operational Program Software COL42-0060-0003 or prior, is powered up before completion of the Inertial Reference System (IRS) alignment, the SDU's automatic handover (transition to a new satellite) will be disabled until the SDU is reinitialized.

The Satellite Data Unit (SDU) prevents communication (blacklist) to the I-4 satellites when encountering a P-Channel loss and may move to a non-Swift Broadband (SBB) I-3 satellite, causing a 20 minute loss of SBB service.

Background

Operators have reported issues of SATCOM logging off from the satellite in flight, resulting in loss of SATCOM data and voice functions.

Status

Boeing has published Service Letter 737-SL-23-060 to indicate to operators that Collins Aerospace has released Service Bulletin SDU-2200-23-7 which is available in the Technical Publications section of their website <https://www.rockwellcollins.com/>.

The SDU software update Collins Aerospace Service Bulletin (SB) SDU-2200-23-7 for P/N 822-2556-102 with MOD plate marked with 4, 5 and 7 will update the following:

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

1. The SDU will no longer prevent communication (blacklist) to the satellite from which the P-Channel loss was encountered.
2. The Automatic Satellite Handover (transition to a new satellite) will no longer be disabled when powered up without Inertial Reference System (IRS) alignment.

Interim Action

Boeing published a Maintenance TIP (737 MT 23-007) for applicable 737 airplanes equipped with Collins Aerospace Satellite Data Unit (SDU) Model 2200.

Final Action

Boeing has published Service Letter 737-SL-23-060 to indicate that Collins Aerospace has released Service Bulletin SDU-2200-23-7 which is available in the Technical Publications section of their website <https://www.rockwellcollins.com/>.

This SB provides a software upgrade to address the following:

1. The SDU will no longer prevent communication (blacklist) to the satellite from which the P-Channel loss was encountered.
2. The Automatic Satellite Handover (transition to a new satellite) will no longer be disabled when powered up without Inertial Reference System (IRS) alignment.

Cost, supplier warranty considerations, and time to complete are included in the Service Bulletin document.

Operator Action

As stated in SB SDU-2200-23-07, Operators can coordinate with Collins Aerospace regarding return of units for software upgrade.

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Letter (SL)	Collins Aerospace SDU-2002-2 SIL 15-1		06/01/2016
Maintenance Tip (MT)	737 MT 23-007		09/28/2018
Service Letter (SL)	737-SL-23-060	Initial	07/17/2019
Service Bulletin (SB)	SDU-2200-23-7	Initial	07/08/2019

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Satellite Data Unit			822-2556-102

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

Attachments:

a) SB SDU-2200-23-7

b) 737-SL-23-060

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991