FLEET TEAM DIGEST

737MAX-FTD-23-20002

Issue Title : Cabin Interphone Handsets - Reliability Improvement

Airplane Model	ATA	Minor Model(s)
737MAX	2342-01	-7, -8, -8200, -9

Other Model(s)	ECCN
777, 767, 737NG	9E991

Originated Date	Last Revised Date	Created On
08/12/2020	08/28/2020	08/24/2020

Estimated Completion Date	Next Update Date

Revision Description

Updated Status, Final Action, and Milestones sections to reflect the release of the Boeing Service Letter.

Applicability

This FTD is applicable to 737MAX airplanes equipped with BAE Systems Flight Deck and Cabin Handset having either P/N 285W0024-1M or 285W0024-5M.

Description

Improvements for the Flight Deck Handset/Cabin Attendant Handset (AEF or ACEF) P/N 285W0024-XX have been identified:

In 2020, to further address operator handset removals, BAE Systems modified the handset to address obsolescence and manufacturability of the internal Printed Wiring Assembly (PWA), in addition to general improvements with the Push To Talk (PTT) button circuitry.

Background

Boeing and BAE Systems have been working together to continuously improve the reliability of the Cabin Attendant / Flight Deck Handsets P/N 285W0024-XX due to removals from different aircraft models.Many reliability improvements as well as obsolescence had been addressed to the handset.

In 2020, BAE Systems also determined the additional following improvements, as shown in BAE Systems SL-CE-071:

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

- A new modification level of the handset (P/N 285W0024-XX) AEF or ACEF have been introduced to address obsolescence, improve manufacturability, and generally improve reliability (NOTE: modification level depends on the handset dash number).
- Addressed the Tone/Pulse Dialer (DTMF) Integrated Circuit used on the handset's PWA.
- Improved the receiver used on the cable assembly for obsolescence that has no direct replacements.
- A change to address the erosion of the gold plating on the switch contacts of the PTT button.
- An updated connector between the handset and the cord with thicker gold plating to address any inadequate connections.

Status

BAE Systems published SL-CE-071 in Jun-2020.

Boeing released Service Letter 737-SL-23-064 in Aug-2020 to cover BAE Systems SL-CE-071.

Interim Action

1. Boeing recommends that operators use the Boeing approved cleaners as published in the CMM 23-42-01 or in the SOPM 20-11-04 to clean the handsets.
2. Boeing recommends that operators review their operating procedures to minimize the incidence of over-stretched cords, handset shells stressed due to improper insertion into the handset cradle, and the use of hand lotions/sanitizers which may contribute to the wearing of the nomenclature on the handset keypad.
3. Boeing recommends that operators review the cabin handset while troubleshooting other Cabin Services components to prevent faulty handsets that are unlikely to be noticed by the cabin crews prior to departure.
4. Boeing recommends that operators perform a test of the Attendants PA for all handsets periodically to prevent the degradation of the communication quality due to intermittent cords. Boeing recommends utilizing the AMM task 23-42-00-710-801 titled "Cabin Interphone System - Operational Test" as an accepted procedure.
5. Boeing recommends that operators replace the handsets and its cord as an assembly to prevent NFF removals due to a potential faulty cord. Please reference the CMM 23-42-01 to perform this check and associated required maintenance.

Final Action

To receive handset improvements, operators can replace their existing handsets on their airplanes with improved handsets, as given in BAE Systems SL-CE-071.

Boeing released Service Letter 737-SL-23-064 to cover BAE Systems SL-CE-071.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Milestones

BAE Systems SL-CE-071: 30-JUN-2020 (complete)

Boeing 737-SL-23-064: 21-AUG-2020 (complete)

Supplier Information

BAE Systems Service Center Addresses:

BAE Systems Dallas Service Center

3131 Story Road West

Irving, TX USA 75038 - 3514

Phone: +1 972-659-4140

Fax: +1 972-659-2504

BAE Systems London Service Centre

21 Sutton Park Ave.

Reading, RG6 1LA, UK

Phone: +44 1189-664554

Fax: +44 1189-267790

BAE Systems Asia Pacific Service Centre

18 Loyang Lane

Singapore, 508918, Singapore

Phone: + 65 9638-4977

Fax: +65 6542-0994

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Component Maintenance Manual (CMM)	23-42-01		
Service Letter (SL)	BAE Systems SL-CE-071		
Service Letter (SL)	737-SL-23-064		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Flight Deck and Cabin Attendant Handset	285W0024-5M	BAE Systems	
Flight Deck and Cabin Attendant Handset	285W0024-1M	BAE Systems	

Related Categories

- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991