FLEET TEAM DIGEST

737MAX-FTD-23-21001

Issue Title : Reset or Lockup Issue with Communication Management Unit (CMU) P/N 822-1239-151

Airplane Model	ATA	Minor Model(s)
737MAX	2327-00	-7, -8, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
04/18/2021	06/17/2021	06/08/2021
Estimated Completion Date	**Next Update Date**	

Revision Description

Updated Status, Final Action and Milestones to indicate Service Bulletin (SB) release.This FTD is closed

Description

Applicability:

Airplanes equipped with Collins CMU P/N 822-1239-151

Multiple reports have been received from various operators indicating that there exists an intermittent communication loss on aircrafts equipped with CMU P/N 822-1239-151. The issue can be identified as either CMU lockup or CMU reset. CMU lockup happens when the oscillator reaches a threshold and can't obtain a frequency. CMU reset happens when the oscillator tries to reboot but can't maintain the oscillator.

Status

Collins Aerospace has advised Boeing that numerous CMU P/N: 822-1239-151 returns are due to a CMU reset or CMU lockup, but have concluded these with "No Fault Found" (NFF). Many of these NFF findings have been narrowed down to the operation/ function of the ARINC 429 I/O Circuit Card (A3). Both CMU reset and CMU lockup issues can be resolved by improving the A3U101 signal waveform of the A3 card within the CMU. This change has been approved by Boeing and is being implemented into Collins Aerospace production line. Collins Aerospace will issue a Service Bulletin (SB) to inform operators about this update.

Interim Action

Request operators to reset the CMU circuit breaker when the airplane is on ground. If the issue is not resolved, replace the CMU

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

with a new CMU and send the faulty CMU to Collins Aerospace for an upgrade of the A3 card.

Final Action

Collins Aerospace has released SB 523-0832418 (April 2021).

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established:

Solution Selected 2/5/2021

Change Committed: N/A

Production Incorporation: 1/29/2021

Service Bulletin Available: 4/15/2021

Parts Available: TBD

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
822-1239-151		Rockwell Collins	

Related Categories

- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations
- Significant Event Report : List of significant in-service or maintenance events reported to Boeing that result in Air turnbacks, ground turnbacks, diversions, rejected takeoffs, in-flight shutdowns, or Significant AOGs. High failure rate of costly/critical systems

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991