FLEET TEAM DIGEST

737MAX-FTD-23-21004

Issue Title : 737MAX Cockpit Voice Recorder Non-Compliance

Airplane Model	ATA	Minor Model(s)
737MAX	2371-00	-8
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
01/04/2022	08/22/2023	08/09/2023
Estimated Completion Date	**Next Update Date**	

Revision Description

No Changes. FTD is closed

Description

The recently certified Honeywell 25 hour Cockpit Voice Recorder (CVR) Part Number (P/N) 69004751-001 installed on the 737-8 airplanes was discovered to have a condition where the recorded audio is erased when the CVR push to test button is pressed for more than two seconds. Another condition discovered resulting in the CVR recorded audio erasure, is when the maintenance interface cable is attached to the CVR without first ensuring that the ARINC-757 adapter plug is installed.

Boeing has assessed that this CVR audio erase condition has no airplane or system level impact. The audio can still be downloaded from the CVR by the manufacturer or accident investigation agency in support of any incident or accident investigations, even when the CVR audio is erased.

Status

The root cause and a fix have been established and a new Honeywell CVR P/N 69004751-002, has been tested and certified. The new part will eliminate the potential for an un-intended erasure of the recorded audio. Honeywell released a Service Bulletin, 69004751-23-0001 Document Number D202203002318. Which provides instruction on how to upgrade the CVR P/N 69004751-001 to P/N 69004751-002.

Interim Action

Boeing has updated the AMM 23-71-00 to include temporary revision (TR) with a note advising operators not to press the CVR test button for more than two seconds and a note that explains the potential for erasing of data if the maintenance cable COM-20206 is installed before the ARINC-757 rack adapter is installed.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Additionally, an Operation Manual Bulletin (OMB) has been issued to communicate the potential for erasure of data if the test button is pressed for more then two seconds.

Final Action

The new Honeywell CVR P/N 69004751-002 is certified and approved for use. Boeing has obtained approval for one way interchangeability for the new CVR and recommends. Operators will need to remove the current CVR P/N 69004751-001 and replace it with the new part. For instruction on how to upgrade the CVR P/N 69004751-001 to the new CVR P/N 69004751-002, reference Honeywell Service Bulletin 69004751-23-0001 document number D202203002318.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: December 2021 (Complete)

Solution Selected: December 2021 (Complete)

Change Committed: December 2021 (Complete)

Production Incorporation: April 2022 (Complete)

AMM Temporary Revision: January 2022 (Complete)

OMB Issued: January 2022 (Complete)

Parts Available: August 2022 (Complete)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Aircraft Maintenance Manual (AMM)	23-71-00		
Service Bulletin (SB)	69004751-23-0001	0	05/01/2022

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- Flight Operations : Flight Operations
- New Equipment : Information on new parts available now or soon to be introduced

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991