FLEET TEAM DIGEST

737MAX-FTD-24-22004

Issue Title : 737MAX Integrated Drive Generator SEC Filter

Airplane Model	ATA	Minor Model(s)
737MAX	2411-11	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
11/14/2022	11/22/2023	12/14/2022

Estimated Completion Date	Next Update Date

Revision Description

Boeing Investigation results updated in FTD Status and Milestones section

Description

There have been operator reports of non-SEC (Service Extender Concentrate) filters on 737 MAX IDG 1725616. Use of non-SEC filters on 737 MAX Integrated Drive Generator (IDG) 1725616 can compromise IDG reliability. Utilize AIPC or CMM for filter to IDG part number effectivity. See attachment for Filter part number and IDG part number interchangeability summary (reference only).

Collins SIL781 R1 documents benefits of the SEC Filter.

Each IDG has 2 filters (1 scavenge filter + 1 charge filter) with the same part number.

Each IDG has 4 packing/o-rings: each filter having a large packing/o-ring (with cap) and small packing/o-ring (with filter). See attachment.

IDG 761574B: Early 737 MAX airplanes were delivered with IDG 761574B. For improved reliability, SEC filters are recommended for use on IDG 761574B on MAX.

IDG 1725616: The improved IDG 1725616 was added to production aircraft in Dec 2020. SEC Filter 5910422 is the only approved filter for 737MAX IDG 1725616.

Status

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Filter Kit P/N 65-90305-94 has been added to Aircraft Illustrated Parts Catalog (AIPC) Front Matter/Filter Maintenance Kit Listing section.

Regarding reports of non-SEC filters on IDG 1725616:

Collins Aerospace completed inspections of build records of IDG deliveries to Boeing and current inventory, and found no discrepancies.

Boeing completed an investigation.

- RECORDS REVIEWS: production records review yielded no history of the reported condition, and no related nonconformances or flight squawks for the datum airplane

- ENGINEERING/PLANNING REVIEWS: All related engineering drawings, associated functional tests, and installation plans were reviewed and found to be in accord and without errors.

Interim Action

Ensure use of SEC filter 5910422 on 737 MAX IDG 1725616.

For improved reliability, SEC filters are recommended for use on IDG 761574B on MAX.

Final Action

- When preparing for MPD tasks 24-040-01 and 24-040-02, ensure P/N 5910422 is in stock for filter replacement. The small and large packing/o-ring should be replaced with each filter replacement.

- If P/N 5901422 is not in stock, place a PO with Boeing or Collins Aerospace.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Milestones

Boeing Investigation status completed December 2022.

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

Attachments:

a) Attachment for 737MAX-24-22004

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991