FLEET TEAM DIGEST

737MAX-FTD-24-24001

Issue Title : Integrated Drive Generator (IDG) Feeder Harness Electrical Plug D30038 to Fan Cowl Support Beam Receptacle D30238 or D30438 Arcing

Airplane Model	ATA	Minor Model(s)
737MAX	2421-00	-8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
12/19/2024	10/12/2026	08/19/2026
Estimated Completion Date	**Next Update Date**	
12/31/2027	12/31/2026	

Revision Description

Revision 5 is released to informs operators that Boeing is conducting inspections on connectors early wear pattern and plating quality assessment of the removed connectors.

Description

Several operators have reported a repetitive arcing condition on power feeder connectors, D30038/D30238 or D30038/D30438. The issue is observed on several airplanes during engine replacement or during electrical power system failure troubleshooting. Boeing notes that in most of the reported cases, the incidents occurred on airplanes with engines previously replaced by operators.

The affected power feeder wire harnesses discussed in this FTD are as follows:

1. Left-Hand (LH) engine, IDG Feeder Harness W1062 Plug D30038, secured to Engine Strut Feeder Harness W1162 through Receptacle D30238
2. Right-Hand (RH) engine, IDG Feeder Harness W1062 Plug D30038, secured to Engine Strut Feeder Harness W1262 through Receptacle D30438

To determine the Root Cause and Corrective Action (RCCA), Boeing initiated an investigation including design and maintenance document review and performing Equipment Quality Analysis (EQA) on damaged feeders returned from operators. For system installation illustration, refer to Attachment I.

Status

Boeing and affected Suppliers (Safran, Spirit and ITT Cannon) have participated in initial investigations. During the investigation, the following were accomplished:

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

a. Boeing performed four EQAs and EQA1, EQA2, EQA3 and EQA4 reports have been released. For summary of the reports, refer to Attachment II.

b. The harness feeder connection procedure was missing from Power Plant Installation, AMM 71-00-02-400-801-G00, in comparison to the engineering drawing number 332A6200 and Power Plant Buildup (PPBU) Manual 71-00-02:

1. The distance from the top of the IDG Feeder Harness Plug D30038 to the upper end of the upper clamp required adjustment from 18.7 inches to 19.2 inches. Note: Maintaining the proper distance between the top of the Plug and the Clamp ensures proper engagement of the plug to the receptacle, thereby preventing relative movement between pin and socket due to engine vibration.

c. Safran, the supplier responsible for assembling the wire bundles (Part Numbers: 286A1062, 286A1162, and 286A1262), confirmed that no deviations from the specifications were used during wire harness manufacturing.

d. Spirit, the supplier responsible for assembling the Engine Strut Feeder to the Strut, recognizes that the W1162/W1262 bundles are rigid and could be a contributing factor leading to preload conditions on the connectors.

e. On three engines, at the Boeing Engine Buildup (EBU) shop, Boeing conducted inspections per Drawing 332A6200 for correct IDG harness W1062 installation and routing.

1. On one engine, the master keyway (notch) on IDG harness W1062 plug D30038 was found at the 5/6 o'clock position.
2. On the second engine, the IDG harness W1062 plug D30038 master keyway was found rotated to the 4 o'clock position.
3. On the third engine, the master keyway was observed at the 12 o'clock position.

Misalignment between the master keyway on the plug and keyway on the receptacle could cause preload on harness W1062 during installation, which is one of the potential factors for connectors arcing. When connector D30038 does not match the keyway position of the mating receptacle, D30038 needs to be twisted in order to mate properly, adding additional load to the connection point. Drawing 332A6200 did not previously provide specific instructions on the position of the master keyway on D30038. To help prevent preloading while securing the plug D30038 to receptacle D30238 (W1162) or D30438 (W1262), the master keyway alignment must be at the 12 o'clock position.

f. To characterize early wear patterns on connector contacts (pins and sockets), Boeing is visually inspecting a 737 MAX airplane with aproximately1000 flight hours.

g. On previously received connectors for EQA, Boeing is conducting inspections of pins and sockets to assess plating quality and develop a damage scale to differentiate between events.

Interim Action

AMM 71-00-02-000-801-G00 and AMM 71-00-02-400-801-G00 were revised on 15 January 2025 to provide procedures and figure to make sure that the distance from the top of the IDG Feeder Harness Plug D30038 to the upper end of the upper clamp is between 18.7 inches to 19.2 inches.

Boeing revised Power Feeder Installation Drawing 332A6200 with the following changes:

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

1. Revised Sheet 3 to Rev G to include view 1H10 for harness W1062 master keyway (notch) position clarification and to add Flag Note 19.
2. Revised the Picture Sheet Data List (PSDL) to Rev L to include Flag Note 19, which reads as follows:

   VERIFY THE WIRE BUNDLE MASTER KEYWAY (NOTCH) IS IN THE UPRIGHT POSITION (12 O'CLOCK POSITION) +/-10 DEGREES AFTER WIRE HARNESS IS INSTALLED ON ENGINE.

   To reflect Drawing 332A6200 Sheet 3 Rev G and PSDL Rev L into maintenance documents, Boeing released:

   1. 737MAX AMM 71-00-02-000-801-G00 and 71-00-02-400-801-G00 revision on 15 September 2025. If engine replacement or troubleshooting is performed in this area, operators are encouraged to follow the detailed instruction in the AMM to make sure the position of the master keyway on D30038 is at the upright position (12 o'clock position) +/-10 degrees after the wire harness is installed on engine.

   2. 737MAX PPBU manual 71-00-02 revision on 15 September 2025. During power plant buildup, Maintenance Repair and Overhaul (MRO) and Operators are encouraged to follow the instruction in PPBU manual to make sure the position of the master keyway on D30038 is at the upright position (12 o'clock position) +/-10 degrees after the wire harness is installed on engine.

   Boeing seeks partnership from the 737 MAX fleet operators and requests to gather all necessary data/information for any issues or incidents related to IDG Feeder Harness (W1062) and Engine Strut Feeder Harness, W1162/W1262. Boeing requested operators to submit any noted conditions or findings through the Boeing Communication System (BCS). This topic is posted on Fleet IdeaXchange (FIX) under ISO-24-25-48997. According to the FIX, five operators have reported encountering the issue, with four having already previously submitted reports via BCS. Additionally, one new operator has reported four incidents in response to the FIX request.

Final Action

Boeing is continuing to investigate root cause and has not yet determined a final solution. Final solution is pending RCCA investigation.

Milestones

• Fleet Data Monitoring through BCS and Fleet IdeaXchange - Through 30 September 2025 - Completed

• AMM 71-00-02-000-801-G00 and 71-00-02-400-801-G00 revised 15 January 2025 to include the 18.7-19.2 inches requirement.

• AMM 71-00-02-000-801-G00 and 71-00-02-400-801-G00 revised 15 September 2025 to indicate the master keyway alignment must be at 12 o'clock position.

• PPBU Manual 71-00-02 revised 15 September 2025 to indicate the master keyway alignment must be at 12 o'clock position

• EQA1, EQA2, EQA3 and EQA4 - Completed

• Early wear patterns and plating quality evaluation on connector contacts - Completion: Fourth quarter of 2026

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Drawing	332A6200 SH3	G	04/24/2025
Drawing	332A6200 PSDL	L	04/28/2025
Power Plant Buildup Manual (PPBU)	71-00-02		01/26/2026
Aircraft Maintenance Manual (AMM)	71-00-02-000-801-G00 and 71-00-02-400-801-G00		01/15/2026
Fleet Team Economic (FTE)	ISO-24-25-48997		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
IDG Feeder Harness	286A1062-()	Safran	
Engine Strut Feeder Harness	286A1162-()	Safran	
Engine Strut Feeder Harness	286A1262-()	Safran	
Plug	D30038	ITTC	CA66287-50
Receptacle	D30238/D30438	ITTC	CA66286-45

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations

Attachments:

a) IDG Power Feeder to Strut Power Feeder Instl

b) EQA Summary

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/04/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991