FLEET TEAM DIGEST

737MAX-FTD-34-18006

Issue Title : Honeywell RDR-4000 Weather Radar System Troubleshooting Guide

Airplane Model	ATA	Minor Model(s)
737MAX	3441-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
767, 737NG, 777	9E991

Originated Date	Last Revised Date	Created On
04/11/2018	04/02/2019	03/13/2019

Estimated Completion Date	Next Update Date

Revision Description

IFIM updates completed per Milestones and Final Action sections.

Applicability

737 MAX airplanes equipped with the Honeywell RDR-4000 Weather Radar System.

Description

Honeywell has issued a Service Information Letter (SIL) and have updated the RDR-4000 Line Maintenance Manual to improve fault isolation and troubleshooting guidance, and to help in reducing component removals.

Background

Some operators have experienced multiple component removals when troubleshooting failures of the Honeywell RDR-4000 Weather Radar System.

Status

The referenced Honeywell service information letter offers fault isolation and troubleshooting guidance to help in reducing No Fault Founds (NFF) when replacing RDR4000 system components such as the WxR Processor, Transmitter Receiver (T/R), or Antenna Drive Assembly. The SIL mentions fault codes displayed on the processor front panel Liquid Crystal Display (LCD) that can mistakenly lead to the removal of two WxR components from the airplane when only one is faulted (i.e., where one component is actually faulted and one is not leading to a NFF removal).

This Troubleshooting Guide is Honeywell Publication Number D201712000040 and has recently been update to Revision 1 dated 17 July 2018. It is available directly from Honeywell at the following location: My Aerospace Portal - https://myaerospace.honeywell.com/account/login (or contact Honeywell Technical Support at: aerotechsupport@honeywell.com).

The Troubleshooting Guide supplements the recently revised RDR-4000 Weather Radar System Line Maintenance Manual (LMM) 34-41-67 (Publication Number 012-0745-001, Revision 7) dated 19 July 2018 which includes information on all of the possible fault indicators that can be logged by the WxR Processor and possible flight deck effects. This publication is also available directly from Honeywell at the address listed above.

Interim Action

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Review the Honeywell SIL and LMM for guidance when troubleshooting the RDR-4000 Weather Radar System.

Final Action

Boeing incorporated RDR-4000 troubleshooting guidance/information into the airplane Interactive Fault Isolation Manual (IFIM).

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Release of IFIM updates: Complete March 2019

Operator Action

Review the Honeywell SIL and LMM for applicable troubleshooting guidance.

Part Information

Radar Processor (RP) - 930-1000-001, -002, -003

Transmitter Receiver (TR) - 930-200-001, -010

Antenna Drive Assemblies (DA) - 930-3000-001

Supplier Information

Honeywell

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Other	Line Maintenance Manual 34-41-67 (012-0745-001)	Rev 7	07/19/2018
Service Information Letter (SIL)	D201712000040	1	07/17/2018

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Radar Processor (RP)		Honeywell	930-1000-001, -002, -003
Transmitter Receiver (TR)		Honeywell	930-2000-001, -010
Antenna Drive Assembly (DA)		Honeywell	930-3000-001

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Best Practices / Operational Efficiency : Operational / Maintenance-focused best practices, techniques, health checks or recommendations for preserving aircraft efficiency.
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991