FLEET TEAM DIGEST

737MAX-FTD-34-18010

Issue Title : Display of TCAS FAIL in TA/RA Mode

Airplane Model	ATA	Minor Model(s)
737MAX	3445-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
12/17/2018	05/15/2020	05/08/2020

Estimated Completion Date	Next Update Date

Revision Description

Updated Applicability and Parts List.

Applicability

All 737MAX airplanes with Honeywell TCAS computer P/N 940-0351-001 installed.

Description

A TCAS FAIL message can get latched to a fail condition on Boeing 737MAX aircraft as a result of an external system interface issue, where the required inputs are not available. A TCAS Fail message can be displayed on the navigation display (ND) if TCAS self-test was initiated in any mode other than TA/RA, and is then changed via the air traffic control ATC Control Panel to TA/RA.

Background

After data analysis, Honeywell has confirmed the following two TCAS FAIL latching conditions described below:

1) If self-test is run in any mode prior to completion of air data inertial reference unit (ADIRU) alignment, the result will be an aural “TCAS Self-Test Fail” and a “TCAS Fail” annunciation on the ND. As a result of the ADIRU being in alignment, the display system will set the RA display discretes to the TCAS in the open state, causing TCAS to latch the resolution advisory (RA) display discrete faults. If the TCAS is not in the traffic advisory/resolution advisory (TA/RA) mode, after the ADIRU successfully completes alignment, the ADIRU will provide the needed data to TCAS to clear the fault on ND. However, the latched RA display discrete failure in TCAS will remain and will only be evident when in TA/RA mode.

2) The resolution advisory discrete from the display computers were not able to toggle from valid (grounded) to invalid (open) and back to valid during TCAS self-test. This was due to some issue with those units, or because the TCAS self-test was re-started prior to completion. Failure will be evident when in TA/RA Mode.

Status

Honeywell Service Bulletin to correct the latching fail condition was release on November 1, 2019.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Interim Action

It is recommended that operators follow the guidance provided in the referenced Boeing Maintenance Tip and Honeywell Service Information Letter.

Final Action

Boeing suggest operators to implemented Honeywell Service Bulletin 940-0351-34-0009 at the next available opportunity.

Milestones

S/W MOD Release - November 1, 2019.

Boeing Service Letter Release - March 19, 2020.

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Information Letter (SIL)	D201212000028	1	11/28/2018
Service Bulletin (SB)	940-0351-34-0009	0	11/01/2019
Maintenance Tip (MT)	737 MT 34-056	R3	08/24/2018
Service Letter (SL)	737-SL-34-257	Initial	03/19/2020

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
940-0351-001		Honeywell	

Related Categories

- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991