FLEET TEAM DIGEST

737MAX-FTD-34-20001

Issue Title : Honeywell IMMR Part No. 69002600-0101 Software Issues causing Reset or Loss of GPS Output Data in Flight if Unit is Continuously Powered for 7 Days

Airplane Model	ATA	Minor Model(s)
737MAX	3458-00	-8, -9
Other Model(s)	**ECCN**	
777, 737NG	9E991	

Originated Date	Last Revised Date	Created On
02/11/2020	01/18/2021	01/15/2021
Estimated Completion Date	**Next Update Date**	

Revision Description

Added service bulletin release information and closed FTD

Applicability

This applies to 737-8 / -9 airplanes delivered, or models that have been modified by Boeing Service Bulletin, with the Honeywell IMMR receiver installed.

Description

This FTD provides information regarding airplanes equipped with the Honeywell IMMR, PN: 69002600-0101, experiencing software issues that may cause reset or stoppage of GPS data output in flight if the unit is continuously powered for 7 days.

Background

Honeywell recently identified two separate software issues that may cause the IMMR to reset or stop GPS data output in flight:

1. A failure due to an internal communication error between the IMMR host software and the GNSS module when the IMMR is continuously powered for 7 days. If aircraft power is applied to all IMMRs simultaneously, the failure would occur at the same time on all IMMRs, leaving the aircraft with no GPS capability unless power to the IMMRs is cycled.

2. A failure that occurs as a result of an IMMR host software monitor that incorrectly compares test results to a similar test that is run on the GNSS module. This issue occurs infrequently and randomly, so usually this is isolated to a single IMMR.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

The affected software part numbers are:

MMR OPS SWM69003225-505 (MSP) / HNR55-2601-0501 (LSP)

MMR OPS SWM69003225-506 (MSP) / HNR56-2601-0601 (LSP)

MMR OPS SWM69003225-508 (MSP) / HNR58-2601-0801 (LSP)

Status

Honeywell has released a Service Information Letter (SIL), Publication number D202001000400, to inform and provide details of these issues to operators. The two issues do not invalidate TSO/MOPS compliance and do not represent flight safety issues. The faults are annunciated and an alternate form of navigation is available.

Depending on aircraft configuration, the IMMR may or may not recover automatically from this failure.

Honeywell, the manufacturer of the unit, has determined both issues will recover automatically if the installation has GLS or LPV functionality enabled, and the aircraft is not actively using ILS, GLS or LPV (guidance not valid).

Boeing and Honeywell have become aware of a new IMMR OPS software issue, which is also affecting the availability of the GPS systems and is detailed in 737MAX-FTD-34-20003. Boeing is currently in discussions with Honeywell to determine if the 7-day continuous power on issue detailed in this FTD and the new issue can be resolved in the same software release.

Interim Action

As an interim action to avoid the GPS data stoppage in flight, Boeing recommends cycling the CBs of the MMR units while on the ground prior to 7 days of the MMR being continuously powered. Operators should reference AMM 34-58 Global Positioning System tasks for approved IMMR deactivation, activation, and operational test procedures.

If a MMR unit experiences a GPS data stoppage in flight with maintenance messages 34-53011 (IMMR-L) or 34-53013 (IMMR-R),

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Boeing recommends following the FIM that addresses these maintenance messages. According to FIM 34-31 tasks 846 and 848 the initial evaluation includes AMM tasks to reset the MMRs and perform a GPS operational test. If PASSES shows adjacent to the TEST CONDITION on the MAT, then no further action is necessary, and replacement of the units is not required if the operational test is passed.

Final Action

Boeing has released Service Bulletin 737-34-3684 that updates the IMMR software to resolve this GPS stoppage issue. The dual GPS dropout issue described in 737MAX-FTD-34-20003 is also resolved by Service Bulletin 737-34-3684.

Milestones

Root Cause: 15-JAN-2020

Production Incorporation: Line Number 8035 and on, 7960

Parts Available: Jan 2021

Service Bulletin Available: Jan 2021

Supplier Information

Honeywell International

Airline and Avionics Products

15001 NE 36th Street

Redmond WA 98073-9701 USA

Phone: 1-425-885-8367

Fax: 1-425-885-8722

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	737-34-3684	NEW	
Fleet Team Digest Article (FTD)	737MAX-FTD-34-20003		

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Service Information Letter (SIL)	D202001000400	0	01/15/2020

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Integrated Multi-Mode Receiver (IMMR)	69002600-0101	Honeywell	

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991