FLEET TEAM DIGEST

737MAX-FTD-34-20002

Issue Title : Flight Management Computer System (FMCS) - Update 14.1 FMC Operational Software (OPS)

Airplane Model	ATA	Minor Model(s)
737MAX	3461-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
04/27/2020	03/27/2026	01/16/2026
Estimated Completion Date	**Next Update Date**	
09/30/2026	09/30/2026	

Revision Description

Updated the following section(s):

- Interim Action
- Final Action
- Milestones.

Description

The U14.1 FMC OPS includes a change to address a Collins Aerospace Head-Up Guidance System Model 6000 (HGS-6000) issue introduced in the Update 14 (U14) FMC OPS. The U14.1 FMC OPS adds an additional label on its ARINC output to the HGS-6000 system. The new label will include the reference glide slope (REF G/S) angle for the selected approach. U14.1 and an update to the HGS system software will allow the HGS to display the REF G/S angle, similar to what the HGS system displayed prior to the U14 FMC OPS software. This condition is discussed in further detail in Fleet Team Digest (FTD) article 737MAX-FTD-34-19010.

The U14.1 FMC OPS will also address the following issues reported during testing or on in-service aircraft:

1. Incorrect Engine Out Standard Instrument Departure (EO SID) inserted when selecting EO SID on DEP page with no regular SIDS
2. Incorrect Thrust Setting during Climb
3. Last SID Overfly waypoint converted to Non-Overfly when a waypoint is added/ or route disconnect closed after it
4. FMC DISAGREE message displayed during Cruise Climb or Cruise Descent
5. Unexpected Vertical Deviation Jump during Descent
6. Dual FMC Reset due to VECTOR/DISCONTINUITY
7. Dual FMC Reset on Approach when Entering Airway/Airway in an Inactive Route

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

8. FMC Selects Incorrect De-Rate for Second Flight
9. FMC Terminates CPDLC Session while Pending Uplink Exists

The attachment to this FTD provides details related to the aforementioned issues.

NOTE: For additional details pertaining to the changes introduced by the U14 FMC OPS, please refer to 737MAX-FTD-34-18005 and 737-SL-34-251.

Boeing issued an Information Notice (IN), reference (d). The IN informs operators who have upgraded to Flight Management Computer (FMC) Operational Program Software (OPS) Update 14.1 (U14.1), the original service bulletin SB 737-34-3656 does not cover the Required Navigational Performance/Authorization Required (RNP/AR) Airplane Flight Manual (AFM) Limitation restriction, applicable when FMCs Model 2907C1 (Boeing Part Number 10-62225-004; GE Aviation Part Number 176200-01-01) are installed on the airplane.

However, if the operator upgrades to FMCs Model 2907C2 (Boeing Part Number 10-62225-005; GE Aviation Part Number 176200-02-01), the AFM Limitation no longer applies. Certification of the FMC Model 2907C2 is on-going and its progress is tracked in 737MAX-FTD-34-18008.

NOTE: For IN details, please refer to 737-34-3656 IN 03.

Status

The U14.1 FMC OPS will be incorporated into all 737 MAX production airplanes per Production Revision Record (PRR) 3M0259. The airplane line number incorporation point was set for Airplane Line Position 8179 which started being delivered in 2022.

Retrofit of U14.1 FMC OPS into the 737 MAX airplane will be per Boeing Service Bulletin 737-34-3656.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Interim Action

Collins Aerospace has advised operators to not use the HGS-6000 on the 737 MAX airplanes equipped with the U14 FMC OPS. Collins released a Service Information Letter for the HGS6000 systems impacted by this issue. Furthermore, Boeing is working with both Collins Aerospace and GE Aviation to expedite certification of the U14.1 FMC OPS and HGS system software to address this issue.

As an interim solution, Boeing plans to deliver the U13 FMC OPS on non 737-7 MAX aircraft equipped with HGS-6000 systems until the U14.1 FMC OPS and HGS software updates are available. Note: The 737-7 airplane will be delivered with FMC OPS U14 or later, the U13 FMC OPS is not certified on the 737-7 airplane. The 737-10 airplane will be delivered with FMC OPS U14.1 and later. The FMC OPS U14.1 will not be listed on the Collins Sensor Interchangeability Specification (doc #: 946-6849-001) until after the STC has been updated to include the next HGS software release for the Model 6000 HGS Computer.

Final Action

Boeing issued U14.1 FMC OPS Service Bulletin, 737-34-3656, to allow retrofit of the U14.1 FMC OPS. Collins Aerospace has released Service Information Letters for HGS-6000 operation with U14/U14.1 FMC OPS. U14 FMC OPS with HGS-6000 (Phase 2.1 OPS) require the operator to manually enter the glideslope value on the MCDU. Furthermore, U14.1 FMC OPS with HGS-6000 (Phase 2.1 OPS) reintroduces the reference glideslope auto-set feature.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

1. 737 MAX - FMC OPS U14.1 - Certification Date | 19-November-2021 (Complete)
2. 737 MAX - FAA AFM Limitation Release | Apr-2022 (Complete)
3. 737 MAX - EASA & TCCA AFM Limitation Release | May-2022 (Complete)
4. 737 MAX - FMC OPS U14.1 - Boeing Service Bulletin Release | 28-May-2022 (Complete)
5. 737 MAX - Collins HGS-6000 & U14/U14.1 Software Certification | 21-Jul-2022 (Complete)
6. 737 MAX - FMC OPS U14/U14.1 - CPDLC function with FANS enabled OMB Release | 12-Sep-2022 (Complete)
7. 737 MAX - Collins HGS-6000 & C2 HW Availability | Q3-2026 (Target)
8. 737 MAX - HGS-6000 HUD + C2 FMC Hardware Production Incorporation | Q3-2026 (Target)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Information Notice (IN)	737-34-3656 IN 03		
Fleet Team Digest Article (FTD)	737MAX-FTD-34-18008		
Fleet Team Digest Article (FTD)	737MAX-FTD-34-18005		
Fleet Team Digest Article (FTD)	737MAX-FTD-34-19010		
Service Bulletin (SB)	737-34-3656		

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
U14.1 OPS	Disk P/N 10-62225-1026	GE Aviation	650630-004

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- Flight Operations : Flight Operations
- Significant Event Report : List of significant in-service or maintenance events reported to Boeing that result in Air turnbacks, ground turnbacks, diversions, rejected takeoffs, in-flight shutdowns, or Significant AOGs. High failure rate of costly/critical systems

Attachments:

a) FMC OPS U14.1 - Summary

b) U14.1 Fixes

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991