FLEET TEAM DIGEST

737MAX-FTD-34-21003

Issue Title : Honeywell IMMR Intermittent ILS Related Fault messages

Airplane Model	ATA	Minor Model(s)
737MAX	3431-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
07/15/2021	07/15/2021	07/15/2021
Estimated Completion Date	**Next Update Date**	

Applicability

737MAX airplanes equipped with the IMMR Part Number, PN: 69002600-0101, without Hardware MOD 2 installed.

NOTE: This is not applicable to Honeywell IMMR units shipped with serial number IMMR-03000 or higher, which already have MOD 2 installed.

Description

This FTD provides information regarding maintenance message and flight deck effects that may intermittently appear indicating the MMR unit has an internal fault and degraded functionality.

Background

Boeing has received reports from operators indicating the presences of various intermittent IMMR maintenance messages related to an internal fault of the unit. The maintenance messages include, but are not limited to the following:

34-31001 / MMR-1 HAS AN INTERNAL FAULT

34-61323 / MMR-1 LOCALIZER DEVIATION SIGNAL IS INVALID (FMC 1)

34-61324 / MMR-1 LOCALIZER DEVIATION SIGNAL IS INVALID (FMC 2)

34-31002 / MMR-2 HAS AN INTERNAL FAULT

34-62323 / MMR-2 LOCALIZER DEVIATION SIGNAL IS INVALID (FMC 1)

34-62324 / MMR-2 LOCALIZER DEVIATION SIGNAL IS INVALID (FMC 2)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

During an event, these messages will intermittently appear along with fail flags for the Localizer and/or Glideslope systems.

Status

Per the supplier, Honeywell, these events can be caused by an ILS DDM miscomparison being performed in the IMMR hardware of units that do not have MOD 2 installed. Honeywell has released SB 69002600-34-0055 (Honeywell Publication Number: D201911000169) which installs MOD 2 and will alleviate these events.

Interim Action

No Interim Action Required.

Final Action

Operators are recommended contact Honeywell to arrange installation of SB 69002600-34-0055 Rev 0, Dated: 12-FEB-2020.

Milestones

Honeywell SB Available: 12-FEB-2020 (Complete)

Supplier Information

HONEYWELL INTERNATIONAL INC.

15001 NE 36TH ST

REDMOND, WA 98052-5317

Telephone: 800-601-3099 (Toll Free U.S.A./Canada)

Telephone: 602-365-3099 (International Direct)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	Honeywell 69002600-34-0055 (Pub#: D201911000169)	0	02/12/2020

Parts List

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Integrated Multi-Mode Receiver	69002600-0101	Honeywell International, Inc.	

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991