FLEET TEAM DIGEST

737MAX-FTD-34-21005

Issue Title : High-Cycle Pitot-static Probe Reliability Improvement

Airplane Model	ATA	Minor Model(s)
737MAX	3411-01	-8, -8200, -9, -BBJ

Other Model(s)	ECCN
767, 737NG, 777	9E991

Originated Date	Last Revised Date	Created On
10/23/2021	12/19/2025	09/02/2025

Estimated Completion Date	Next Update Date
02/25/2026	02/25/2026

Revision Description

Updated Status, Final Action, and Milestones.

Applicability

All 737 MAX airplanes.

Description

High cycle operators are experiencing high removal rates of Pitot-Static probes due to suspected heater failure. The Pitot-Static probe failures have caused operational impact, resulting in delays and occasional Ground or Air Turn Backs.

Background

The 737 MAX has two probes on the vertical stabilizer to provide impact pressure inputs to the Elevator Load Feel System (ATA 27) and three probes providing impact pressure inputs to the Captain's, First Officer's, and Standby Air Data Systems (ATA 34).

Boeing initiated a Service Related Problem (SRP), 737NG-SRP-34-0137 to investigate the high removal issue and has determined the root cause as follows:

- The material used for the pitot probe heater sheath material is susceptible to corrosion. This corrosion can lead to a breach in the heater sheath, allowing ingress of moisture and contaminants, which subsequently degrades the insulation of the heater wire. This degradation ultimately results in heater wire failure, manifesting as either a short or an open circuit. Contributing factors to this failure include exposure to corrosive environmental contaminants, elevated operating temperatures, and a high number of operating cycles.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Based on the above root cause, the SRP determined the proposed solution:

- A revision to create an Enhanced / Alternate Pitot Probe: Collins has implemented modifications to the manufacturing process to ensure comprehensive high-temperature braze coverage over the heater sheath in all critical areas utilizing the existing braze material. This current braze material, which is used to join the heater to the probe shell, is known to have superior corrosion resistance compared to the bare nickel heater sheath. The revised pitot probe will have a new part number (P/N): 0851HT-2.

Status

The new pitot probe, P/N 0851HT-2, is now available for purchase and Boeing has issued Service Letter (SL) 737-SL-34-273 to inform operators on the availability of the new part.

The Federal Aviation Administration (FAA) has certified and the European Union Aviation Safety Agency (EASA) has validated the design and installation of pitot probe P/N 0851HT-2. Pitot probe 0851HT-2 is two way interchangeable with 0851HT-1.

The first FAA Boeing Production aircraft equipped with the improved pitot probe P/N 0851HT-2 was Line Position 9176, delivered in June, 2025.

The first EASA Boeing Production aircraft equipped with the improved pitot probe P/N 0851HT-2 is expected to be Line Position 9451, with expected delivery in January, 2026.

For other International Type Validation status of pitot probe P/N 0851HT-2, operators should contact their local regulatory authority.

The next scheduled 737 NG/MAX Aircraft Illustrated Parts Catalogue (IPC) update will include the incorporation of the new pitot probe model 0851HT-2 for use in all five positions on all in-service 737 NG/MAX model airplanes as applicable.

These updates will be published in the 737 MAX IPC ECD January 15, 2026 and in the 737 NG IPC ECD February 15, 2026.

Interim Action

As a mitigating action, some operators have implemented a “fixed removal time” probe replacement program, reportedly ranging from 7,000 to 20,000 flight hours, to minimize flight schedule disruptions caused by probe failures. Additionally, operating cycles may also influence probe lifespan; therefore, high-cycle operators may consider establishing a proactive removal schedule based on the number of cycles.

Final Action

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Boeing has completed work with the FAA to certify and EASA to validate the redesigned pitot probe, P/N 0851HT-2, for incorporation into production and for use in the in-service 737 fleet.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

SRP Issue Accepted: 30-July-2014

Root Cause Established: 30-June-2015 (complete)

Solution Selected: September-2020 (complete)

Supplier Service Information Letter: July-2023 (complete)

Part Availability: July-2023 (complete)

Boeing Service Letter Available: January-2024 (complete)

Production Incorporation FAA: May-2025 (complete)

Production Incorporation EASA: December-2025 (complete)

Operator Action

Both Boeing and Collins are actively collecting data on the fleet performance of the P/N 0851HT-2 pitot probe. Any instances of early life failure of the P/N 0851HT-2 pitot probe should be sent to Collins for investigation at the address provided in the Supplier Information section.

Part Information

Collins Aerospace, previously UTC, Pitot-Static Probe, P/N 0851HT-1 and P/N 0851HT-2

Affected Documents

Supplier CMM: 34-11-08

Boeing IPC 34-11-01-01/-02

Supplier Information

COLLINS AEROSPACE

14300 Judicial Road

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Burnsville, MN 55306-4898 U.S.A.

Tel: +1 952 892 4783

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Letter (SL)	737-SL-34-273		
Service Related Problem (SRP)	737NG-SRP-34-0137		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Pitot Probe		Collins	0851HT-1
Pitot Probe		Collins	0851HT-2

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991