FLEET TEAM DIGEST

737MAX-FTD-34-22001

Issue Title : Inertial Reference System (IRS) 2025 Magnetic Variation (MagVar) Update

Airplane Model	ATA	Minor Model(s)
737MAX	3421-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
777, 737NG, 787, 757, 767, 747	9E991

Originated Date	Last Revised Date	Created On
03/11/2022	02/27/2026	01/19/2026

Estimated Completion Date	Next Update Date

Revision Description

This is the final revision for the 737 MAX IRS 2025 MagVar update effort. Updated the References, Description, Background, Status, Milestones, and Operator Action sections. D6-85262 Rev. C released so attachment removed.

Applicability

All 737 MAX airplanes equipped with Honeywell HG2050BC04 Air Data Inertial Reference Units (ADIRUs).

Description

MagVar tables within the ADIRU are used to convert true heading and true track to magnetic heading and magnetic track respectively. The accuracy of magnetic heading and magnetic track must be maintained for critical systems, including flight displays and autoflight. To ensure accuracy, MagVar tables require periodic updates to account for constant changes in the Earth's magnetic field and the location of magnetic north.

Boeing opened a Service Related Problem (SRP) project and worked with Honeywell to certify a new 2025 IRS MagVar table for the 737 MAX fleet. According to the latest assessment of prior certified IRS 2015 MagVar table, some outlying airports are beginning to exceed the 3 degree error limit, applicable to 737 MAX with the Fail-Operational autopilot, and as of May 2025 one airport has exceeded the 5 degree error limit.

IRS MagVar tables on the 737 MAX fleet* are not on-board data loadable and units must be removed and upgraded at Honeywell. The airplane program pin wiring will also change. The component SB for ADIRU upgrade is provided by Honeywell. Boeing Installation SB is available for activating the IRS 2025 MagVar update on the airplane. The Illustrated Parts Catalog (IPC) allows the new part number to be interchanged and intermixed on airplanes still configured with IRS 2015 MagVar table activated to facilitate unit rotations. To complete the incorporation of the Boeing IRS 2025 SB on an airplane, all ADIRUs must be the upgraded part number.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Boeing re-assessed the 737 MAX ADIRU MagVar table (i.e. 2015) against the newly released National Oceanic and Atmospheric Administration (NOAA) 2025 World Magnetic Model (WMM) and revised D6-85262 guidance and instructions to Rev. C to cover the 2025-2030 year period. Differences between the 2020 and 2025 WMMs drove changes to the Boeing MagVar (BMV) table error maps, airport lists and projected exceedance dates. Guidance was also enhanced so the Airplane Flight Manual (AFM) operational limitations for airplane IRS MagVar error could be better determined.

Operators with routes impacted by the Airplane Flight Manual (AFM) limitations may want to prioritize upgrading units. It can take time to cycle units off-wing and through the supplier workshop. A ship-set is required before the IRS 2025 MagVar SB can be incorporated.

*NOTE: Boeing emphasizes there may be value in holding off on upgrading MAX airplanes to the new IRS 2025 MagVar table via ADIRU PN HG2050BC06 (reference Boeing SB 737-34-4248) if the operational limits for IRS MagVar table errors do not yet impact your routes. ADIRU PN HG2050BC04 will be upgradable to HG2050BD02 via a Honeywell component Service Bulletin. The BD02 part will be certified with IRS 2025 MagVar tables and will be required for 737 MAX operators following -10 certification in association with eAOA (reference Boeing FTD 737MAX-FTD-27-23003). If able to wait to incorporate SB 737-34-4248, then the box can be upgraded and new tables put on in one removal process. This makes for less scheduled disturbances for the operator.

Background

In order to maintain Boeing airplane capabilities per the type design requirements (continued airworthiness) and raise operator awareness to ensure their aircraft are in a state for safe flight and operations per Code of Federal Regulations (CFR) 121 requirements, "Guidance for Airplane Flight Operations Using Inertial Reference Systems with Magnetic Variation Tables", D6-85262, document was updated to Revision C to cover the 2025-2030 year period.

D6-85262, Revision C is posted and available on:

MyBoeingFleet - Flight Operations portal under 'FMC Document' ->'General Airplane Information' -> 'Magnetic Variation Documents'

Every five-year NOAA WMM publishing cycle, Boeing reassesses the IRS equipment with MagVar tables installed in 737 MAX airplanes and revises D6-85262 accordingly. The need for a new IRS MagVar table is based on the results, typically occurring every ten years. The next planned reassessment and revision of D6-85262 is in 2030 when NOAA publishes a new WMM.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Boeing Service Letters (SLs) 737-SL-34-222 and 737-SL-34-231 provide more information on this topic.

Information on magnetic declination and changes in the Earth's magnetic field may be found at the following NOAA website:

http://www.ngdc.noaa.gov/geomag/declination.shtml

Status

- 737 MAX SRP project opened September 29, 2021.
- Honeywell issued the ADIRU 2025 MagVar Component SBs and is supporting part upgrades.
- Boeing issued SL for ADIRU 2025 MagVar update.
- Boeing issued 737 MAX SB for ADIRU 2025 MagVar update.
- 737 MAX model SRP project closed April 2025.
- Multi-Model Multi-Operator Message (MOM) released to advise fleets of D6-85262 Rev. B to C update and impacts due to the to new NOAA WMM 2025.
- Reference MOM-MOM-25-0211-04B for latest information.
- All operator meeting was held on October 14 and 15 to notify operators of updated guidance for assessing the 3 degree error limit to be published in D6-85262 Rev. C.
- MOM-MOM-25-0461-01B released advising fleets of D6-85262 Rev. C posting, November 14, 2025.
- Released and posted **D6-85262 Rev. C** on MyBoeingFleet Flight Operations portal and removed Rev. B as no longer applicable, **November 17, 2025**.

Interim Action

None. SRP actions complete. See Operator Action.

Final Action

a) Honeywell Parts Available and Service Bulletin (SB) for 737 MAX ADIRU part updates update. **Completed July 2024**

New ADIRU 2025 MagVar part number is HG2050BC06.

Refer to Honeywell Component SB HG2050BC-34-3595.

b) Boeing IRS 2025 MagVar SB issued for 737-7, -8, -9, -8200, -BBJ ADIRU equipped airplanes. **Completed March 2025.**

Refer to SB 737-34-4248.

c) Boeing IRS 2025 MagVar SL issued for 737 MAX ADIRU equipped airplanes. **Completed February 2025.**

Refer to SL 737-SL-34-278-A.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Milestones

Note: Target dates and milestones are based upon currently available status and have risk of future revision.

1) Root Cause Established: complete

2) Solution Selected: complete

3) Open 737 MAX SRP: complete

4) Production Incorporation: June 2025 (complete)

5) Honeywell Part Available and SB for BC Series ADIRU part updates released: January 2025 (complete)

6) Boeing IRS 2025 MagVar SB released for 737-7, -8, -9, -8200, -BBJ: March 2025 (complete)

7) Boeing IRS 2025 MagVar SL released for 737 MAX ADIRU equipped airplanes: November 2024 (complete)

8) Release D6-85262 Revision C: November 17, 2025 (complete)

1. MOM-MOM-25-0461-01B announcement of D6-85262 Rev. C posting on MyBoeingFleet, Flight Operations Portal: (complete)
2. MOM-MOM-25-0211-04B closeout message (complete)

Operator Action

All 737 MAX operators should review the IRS equipment installed in their airplanes, D6-85262 Rev. C document, and comply with the AFM limitations/normal procedures for the applicable IRS Boeing MagVar (BMV) table based on Autopilot design (fail active or fail operational) or incorporate the IRS 2025 MagVar table update SB* to avoid operational limitations.

*Verification of compatibility with any installed Supplemental Type Certificates (STCs) (e.g. Heads Up Display (HUD) Installation) is required.

Contact Honeywell regarding ADIRU part upgrades.

Operators with further questions on this topic may submit a Boeing Communication System (BCS) message.

Supplier Information

- Honeywell Inc. Commercial Flight Systems, 8840 Evergreen Blvd. Minneapolis, MN 55433, Phone: 612-957-4408, https://myaerospace.honeywell.com/wps/portal/ , Cage Code: V65507

Reference Categories

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Digest Article (FTD)	737MAX-FTD-27-23003		
Service Letter (SL)	737-SL-34-278-A		
Multi-Operator Message (MOM)	MOM-MOM-25-0211-04B		11/24/2025
Service Related Problem (SRP)	737MAX-SRP-34-0185		09/29/2021
Other	D6-85262	C	10/24/2025
Service Letter (SL)	737-SL-34-231-A		
Service Letter (SL)	737-SL-34-222		
Service Bulletin (SB)	HG2050BC-34-3595		07/17/2024
Service Bulletin (SB)	737-34-4248		03/06/2025
Multi-Operator Message (MOM)	MOM-MOM-25-0461-01B		11/14/2025

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Air Data Inertial Reference Unit (ADIRU)	N/A	Honeywell	HG2050BC04/BC06

Related Categories

- Flight Operations : Flight Operations
- New Equipment : Information on new parts available now or soon to be introduced
- Obsolescence : Information on parts that are obsolete, becoming obsolete, or have excessive lead times
- SRPs - Economic : Service Related Problems in work by Boeing that have an economic impact

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991