# FLEET TEAM DIGEST

## 737MAX-FTD-34-22004

**Issue Title :** Enhanced Global Positioning System (GPS) Antenna - AT575-343B

| Airplane Model | ATA | Minor Model(s) |
|---|---|---|
| 737MAX | 3458-02 | -8, -8200, -9, -BBJ |

| Other Model(s) | ECCN |
|---|---|
| 737NG | 9E991 |

| Originated Date | Last Revised Date | Created On |
|---|---|---|
| 05/06/2022 | 08/03/2022 | 07/13/2022 |

| Estimated Completion Date | Next Update Date |
|---|---|

## Revision Description

Updated Final Action and Milestones section. Work complete, closing FTD.

## Description

A new improved GPS antenna, part number AT575-343B, is available.

## Background

The GPS antenna was originally certified on the 737NG and carried over to the 737MAX. The Satellite Communication (SATCOM) Iridium antenna was subsequently installed close to each other resulting in insufficient signal isolation margins between the antennas as defined in RTCA/DO-262. Insufficient isolation could lead to SATCOM interfering with GPS Radio Frequency (RF) band which would result in loss of both GPS systems. The GPS antenna supplier, AeroAntenna Technology, has performed minor changes to the existing antenna which resolves the insufficient isolation issue. The revised GPS antenna will bring the current antenna location installations into compliance.

## Status

Although there have been no in-service reports of interference issue for the existing GPS antenna part number AT575-343W, analysis was performed and showed a potential for non-compliance. The new antenna P/N AT575-343B changes the nominal values of three (3) capacitors on the Low Noise Amplifier board inside the antenna housing to improve rejection and filtering of SATCOM signals. This update has no impacts to form and fit, of the GPS antenna.

## Interim Action

The new GPS Antenna P/N AT575-343B is one-way forward interchangeable with the old antenna P/N AT575-343W for all applicable NG and MAX models. The new part number is recommended for all applicable NG and MAX models with the Iridium

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

SATCOM installed. The old GPS Antenna is two-way interchangeable with the new antenna for all applicable NG and MAX airplanes that do not have the Iridium SATCOM option installed. Production Revision Record (PRR) 3M0292 incorporated the new AeroAntenna GPS antenna to improve the antenna performance from L/N 8249 delivered in MAY 2022.

## Final Action

The Interchangeable Parts Drawing (IPD 244U0904, Rev. K) has been released to provide interchangeability guidance on the GPS antenna across the 737 MAX fleet.

## Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Production Incorporation: Line Number 8249, 5/06/2022

IPD Update Release : 5/3/2022

## Reference Categories

| Reference Type | Reference Number | Revision Number | Reference Date |
|---|---|---|---|
| Production Revision Record (PRR) | 3M0292 | Rev. D | 10/26/2021 |
| Airplane Configuration Bulletin (ACB) | 2021-ACB-0028 | | 12/06/2021 |

## Parts List

| Part Name | Boeing Part Number | Supplier Name | Supplier Number |
|---|---|---|---|
| GPS Antenna | AT575-343B | AeroAntenna Technology | |

## Related Categories

- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message
- Flight Operations : Flight Operations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991