FLEET TEAM DIGEST

737MAX-FTD-34-22005

Issue Title : Head Up Display (HUD) Provisions Nuisance Maintenance Message

Airplane Model	ATA	Minor Model(s)
737MAX	3436-00	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
11/07/2022	03/26/2026	01/06/2026
Estimated Completion Date	**Next Update Date**	
06/01/2026	06/01/2026	

Revision Description

Final Action has been updated with the change committed to resolve the documented issue.

Milestones have been updated to reflect the Final Action committed.

Description

Boeing has received reports from multiple operators where the Display Processing Computer (DPC) will record a nuisance ATA 34 Maintenance Message (MM) 34-90031, "HUD HAS NO OUTPUT ON MORE THAN ONE BUS"

The Nuisance MM occurs whenever the aircraft is operated with Heads Up Display (HUD) provisions without a HUD system installed.

Status

Boeing is evaluating a change where MM 34-90031 will only be annunciated if a Collins HUD system is installed on a 737 MAX aircraft.

Interim Action

If an aircraft is operating with HUD provisions installed but without a HUD system installed then MM 34-90031 can be considered nuisance and the aircraft can remain in service with the message still active until a solution is in place.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Boeing has incorporated the following note in a revision to Fault Isolation Manual (FIM) TASK 34-36-00-810-801 that was released in the October 2022 Toolbox revision.

Note: "For operators that do not have the HUD computer installed, this maintenance message is a nuisance message (Reference 737MAX-FTD-34-22005)."

The purpose of the note is to inform operators of the nuisance maintenance message condition.

Final Action

Boeing will continue to monitor the 737 MAX fleet for this nuisance condition.

As part of the resolution to suppress the nuisance maintenance message, Boeing has implemented an OMF OSS update (See OMF OSS Version Number 17 Part Number BCG38-0MFC-0017 via Service Bulletin 737-46-1085) incorporated starting at line number 9380, and 9424 and on. Boeing is also implementing a DFDAU programming pin change starting at line number 9600, and 9722 and on.

These two changes together will suppress the nuisance maintenance message.

Line numbers prior to 9722, with the exception of 9600, can utilize the updated FIM Task 34-36-00-810-801 to address any nuisance annunciations of MM 34-90031 "HUD HAS NO OUTPUT ON MORE THAN ONE BUS".

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.
Fault Isolation Manual TASK 34-36-00-810-801 Revision: October 2022 (Completed)
Root Cause Established: Q3 2023 (Completed)
Solution Selected: Q4 2023 (Completed)
Change Committed: January 2026 (Completed)
Production Incorporation: Q2 2026 (Target)

Affected Documents

Boeing has published a revision to FIM TASK 34-36-00-810-801 in the October 2022 Toolbox release.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fault Isolation Manual (FIM)	34-36-00-810-801		

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/09/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991